



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12458
Inspector	Len Kruizenga			Date/Time	7/6/2020 8:29 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	7/6/2020 8:29 AM	Report #	12458
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection: Sta#11788+00 to 12005+00. The row is dry and in stable condition. Permanent stabilization is acceptable with very good vegetation. Perimeter controls, silt fence, CFS, SSF are in acceptable condition. Water bars and level spreaders are in good condition. Karst ECD's are in acceptable condition. Wetland ECD's are in acceptable condition. AR- 266.03 an AR- 266.00 and Tabor RCE are in good condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/6/2020 8:29 AM	Report #	
Pictures					
					
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11788+00		Field Station#	11828+00	
Pic 1 Desc.	Tabor RCE		Pic 2 Desc.	Row vegetation, level spreaders	
					
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11836+00		Field Station#	11900+00	
Pic 3 Desc.	CFS triple stack and SSF perimeter controls		Pic 4 Desc.	AR-266.03- Access road and CFS checks in bar ditch.	
					
GPS Location	See photo GPS		GPS Location	See	
Field Station#	12942+00		Field Station#	11947+00	
Pic 5 Desc.	Karst ECD's		Pic 6 Desc.	Broad view of the row.	

A/E	124300137	Date/Time	7/6/2020 8:29 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/6/2020 8:29 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12484
Inspector	Garrett Barclay			Date/Time	7/6/2020 2:58 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+16
State	VA	Inspection Area	Partial	Station End	11600+01
County	Giles	Ground	Dry	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Flume Pipe	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/6/2020 2:58 PM	Report #	12484
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 218 - Mp 219.5 Observed damaged P1SF ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources Damaged ECD's added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	7/6/2020 2:58 PM	Report #	
Pictures					
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11530+00		Field Station#	11543+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	Damaged P1	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11566+00		Field Station#	11569+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11585+00		Field Station#	11593+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	7/6/2020 2:58 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/6/2020 2:58 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12501
Inspector	Len Kruizenga			Date/Time	7/7/2020 8:28 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/7/2020 8:28 AM	Report #	12501
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with EI's at the work trailer SWPPP inspection : LY- 29 AR-238.00- Access road that services LY-29 is in acceptable condition. The rock surface of the yard is maintained in acceptable condition. CFS triple stack perimeter controls are in acceptable condition. Arnold's stockpiled tack materials have been tarped by PPL. Culvert and drainage feature are in acceptable condition. House keeping is acceptable. Waste management is acceptable. There is no mechanical equipment stored in the yard. There has been no recent activity in the yard.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/7/2020 8:28 AM	Report #	
Pictures					
<p>Date & Time: Tue, Jul 07, 2020, 09:53:37 EDT Position: -037.365269 / -080.672338 (+98.4ft) Altitude: 1863ft (+315.0ft) Datum: WGS-84 Azimuth/Bearing: 221° S41W 3929mils True (+30°) Elevation Angle: -07.7° Horizon Angle: -01.8° Zoom: 1.0X LY-238.00- Access road serving LY-29.</p> 		<p>Date & Time: Tue, Jul 07, 2020, 09:57:07 EDT Position: -037.365204 / -080.676970 (+16.4ft) Altitude: 1720ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 220° S40W 3911mils True (+26°) Elevation Angle: -02.7° Horizon Angle: -00.1° Zoom: 1.0X LY-238- Materials stock pile has been tarred.</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	AR-238.00 - Access road serving LY-29	Pic 2 Desc.	Materials stockpiles have been tarred.		
<p>Date & Time: Tue, Jul 07, 2020, 10:02:04 EDT Position: -037.363223 / -080.676738 (+16.4ft) Altitude: 1722ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 332° N27W 5920mils True (+21°) Elevation Angle: -14.6° Horizon Angle: 0.01° Zoom: 1.0X LY-29- Rock surface of the yard is maintained in acceptable condition.</p> 		<p>Date & Time: Tue, Jul 07, 2020, 10:06:10 EDT Position: -037.363449 / -080.676530 (+16.4ft) Altitude: 1710ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 318° N42W 5653mils True (+35°) Elevation Angle: -11.3° Horizon Angle: -02.7° Zoom: 1.0X LY-29- Triple stack perimeter controls are in acceptable condition.</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	LY-29- Rock surface of the yard is maintained in acceptable condition	Pic 4 Desc.	CFS triple stack perimeter controls are in acceptable condition		
<p>Date & Time: Tue, Jul 07, 2020, 10:06:21 EDT Position: -037.365192 / -080.676594 (+16.2ft) Altitude: 1711ft (+36.5ft) Datum: WGS-84 Azimuth/Bearing: 177° S03E 3107mils True (+31°) Elevation Angle: -07.9° Horizon Angle: -00.0° Zoom: 1.0X LY-29- Uncoated pipe stored in the yard.</p> 		<p>Date & Time: Tue, Jul 07, 2020, 10:08:23 EDT Position: -037.365392 / -080.677304 (+16.4ft) Altitude: 1752ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 313° N47W 5584mils True (+25°) Elevation Angle: -21.8° Horizon Angle: -02.4° Zoom: 1.0X LY-29- Culvert and drainage feature.</p> 			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	Ncoated pipe stored in the yard.	Pic 6 Desc.	Culvert and drainage feature are in acceptable condition.		

A/E	124300137	Date/Time	7/7/2020 8:28 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/7/2020 8:28 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12511
Inspector	Jared Saunders			Date/Time	7/6/2020 1:18 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11788+50
County	Montgomery	Ground	Dry	Temperature (°F)	90.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/6/2020 1:18 PM	Report #	12511
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	7/6/2020 1:18 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11672+00		Field Station#	11693+50	
Pic 1 Desc.	ROW stabilized with mulch. Priority one silt fence in place along LOD. Waterbar and end treatments in place.		Pic 2 Desc.	Priority one silt fence in place along LOD.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11704+20		Field Station#	11705+00	
Pic 3 Desc.	Sensitive resource buffer in place at stream S-MN22.		Pic 4 Desc.	ROW stabilized with mulch.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11704+20		Field Station#	11713+25	
Pic 5 Desc.	Steam bed S-MN22.		Pic 6 Desc.	ROW stabilized with mulch. Waterbar, sump pit and waterbar end treatment in place.	

A/E	124300137	Date/Time	7/6/2020 1:18 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/6/2020 1:18 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12530
Inspector	Len Kruizenga			Date/Time	7/8/2020 8:09 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+88
State	VA	Inspection Area	Full	Station End	10930+00
County	Giles	Ground	Dry	Temperature (°F)	86.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.90
				Rain Accumulation Time (days)	1.00






1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/8/2020 8:09 AM	Report #	12530
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
<p>Met with EI's at the work trailer</p> <p>SWPPP inspection: Sta#11023+88 to 10930+00. MP- 208.6 to 206.2</p> <p>AR- 244.00 rain gauge showed 0.90". The row is muddy but in stable condition.</p> <p>Temporary stabilization is acceptable.</p> <p>Perimeter controls, CFS, SSF & silt fence are in acceptable condition. There was damaged P1 perimeter control at sta#1993+95, the contractor was informed and sent me a photo of the repairs. The item was added to the punch list.</p> <p>Water bars are in acceptable condition.</p> <p>Water bar sump pits and end treatments are in acceptable condition.</p> <p>Streams S-IJ18, S-RR5, S- E24, S-E25 are in good condition, stream equipment bridges, buffers, signage & ECD's are in acceptable condition.</p> <p>Bat habitat ECD's are in acceptable condition.</p> <p>AR-244.00 and Doe Creek RCE are in acceptable condition.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time 7/8/2020 8:09 AM	Report #
Pictures			
 <p>Date & Time: Wed, Jul 08, 2020, 09:31:15 EDT Position: +037 322441, -080 553133 (±12m) Altitude: 2350ft (±105.0ft) Datum: WGS-84 Azimuth/Bearing: 186° S06W 3307mils True (±10°) Elevation Angle: -20.4° Horizon Angle: -102.1° Zoom: 1.0x Stn#10945+00 - Stream S-IJ18 - Equipment bridge & ECD's</p>		 <p>Date & Time: Wed, Jul 08, 2020, 08:56:40 EDT Position: +037 322441, -080 552635 (±12m) Altitude: 2350ft (±105.0ft) Datum: WGS-84 Azimuth/Bearing: 282° N78W 5013mils True (±10°) Elevation Angle: -08.2° Horizon Angle: -100.2° Zoom: 1.0x Stn#10945+00 - Stream S-RR5 - Equipment bridge & ECD's</p>	
GPS Location	See photo GPS	GPS Location	See photo GPS
Field Station#	11024+00	Field Station#	11017+00
Pic 1 Desc.	Stream S-IJ18 - Equipment bridge & ECD's	Pic 2 Desc.	Stream S- RR5 and broad view of the row.
 <p>Date & Time: Wed, Jul 08, 2020, 09:05:51 EDT Position: +037 322501, -080 552527 (±10.7m) Altitude: 2374ft (±112.8ft) Datum: WGS-84 Azimuth/Bearing: 222° N67W 5249mils True (±10°) Elevation Angle: -44.2° Horizon Angle: -106.2° Zoom: 1.0x Stn#10945+00 - Perimeter control down on slope</p>		 <p>Date & Time: Wed, Jul 08, 2020, 10:04:00 EDT Position: +037 322501, -080 552500 (±10.7m) Altitude: 2374ft (±112.8ft) Datum: WGS-84 Azimuth/Bearing: 109° S41E 5186mils True (±10°) Elevation Angle: -07.7° Horizon Angle: -103.4° Zoom: 1.0x Stn#10986+00 - Stream S-E25</p>	
GPS Location	See photo GPS	GPS Location	See photo GPS
Field Station#	10993+95	Field Station#	10986+00
Pic 3 Desc.	Damaged silt fence perimeter controls, issue repaired same day.	Pic 4 Desc.	Stream S- E25 equipment bridge and ECD's.
 <p>Date & Time: Wed, Jul 08, 2020, 10:05:00 EDT Position: +037 322501, -080 552527 (±10.7m) Altitude: 2383ft (±116.4ft) Datum: WGS-84 Azimuth/Bearing: 298° N62W 5298mils True (±10°) Elevation Angle: -12.9° Horizon Angle: -103.2° Zoom: 1.0x Stn#10985+00 - Stream S-E24</p>		 <p>Date & Time: Wed, Jul 08, 2020, 10:17:14 EDT Position: +037 322501, -080 571479 (±12m) Altitude: 2388ft (±116.4ft) Datum: WGS-84 Azimuth/Bearing: 322° N14W 6116mils True (±10°) Elevation Angle: -08.2° Horizon Angle: -105.4° Zoom: 1.0x Stn#10965+00+00 - Bat habitat with ECD protection</p>	
GPS Location	See photo GPS	GPS Location	See photo GPS
Field Station#	10985+00	Field Station#	10965+00
Pic 5 Desc.	Stream S- E24 equipment bridge and ECD's.	Pic 6 Desc.	Bat habitat and ECD's

AFE	124300137	Date/Time	7/8/2020 8:09 AM	Report #	
Pictures					
 <p><small>Date & Time: Wed Jul 08 2020 11:30:54 EDT Position: +037 268986, -080 347936 (+16.4ft) Altitude: 2011ft (+13.1ft) Datum: WGS-84 Azimuth/Bearing: 169° S11E 3004mils True (+15) Elevation Angle: +42.5 Horizon Angle: +10.3 Zoom: 1.0X Tabor rain gauge reading: 0.00"</small></p>		 <p><small>Date & Time: Wed Jul 08 2020 11:52:20 EDT Position: +037 268986, -080 320071 (+16.4ft) Altitude: 1611ft (+13.1ft) Datum: WGS-84 Azimuth/Bearing: 169° S11E 3004mils True (+15) Elevation Angle: +42.5 Horizon Angle: +10.3 Zoom: 1.0X Catawba rain gauge reading: 0.00"</small></p>			
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11766+00	Field Station#	11989+00		
Pic 7 Desc.	Tabor rain gauge reading- 0.00"	Pic 8 Desc.	Catawba rain gauge reading- 0.00"		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	7/8/2020 8:09 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report










Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12541
Inspector	Jared Saunders			Date/Time	7/8/2020 3:26 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10670+00
State	VA	Inspection Area	Partial	Station End	10750+00
County	Giles	Ground	Damp	Temperature (°F)	80.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.90
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Signage	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/8/2020 3:26 PM	Report #	12541
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6 and from MP 208.6 to MP 209.56. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. CFS at waterbar end treatment needs repaired at station number 11048+50.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/8/2020 3:26 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11024+75		Field Station#	11026+00	
Pic 1 Desc.	Sensitive resource buffer in place at stream S-IJ18.		Pic 2 Desc.	ROW stabilized with natural vegetation growth.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11048+50		Field Station#	11058+00	
Pic 3 Desc.	Waterbar end treatment triple stack CFS needs repaired.		Pic 4 Desc.	Priority one silt fence LOD control in place.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10696+00		Field Station#	110670+00	
Pic 5 Desc.	RCE at Buffalo Anklets Road in place.		Pic 6 Desc.	Reinforced super silt fence in place along LOD.	

A/E	124300137	Date/Time	7/8/2020 3:26 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/8/2020 3:26 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12545
Inspector	Garrett Barclay			Date/Time	7/8/2020 4:28 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10850+00
State	VA	Inspection Area	Partial	Station End	10929+62
County	Giles	Ground	Dry	Temperature (°F)	86.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Rock Construction Entrance	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/8/2020 4:28 PM	Report #	12545
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 205 - MP 207 Observed damaged P1SF ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources Damaged ECD's added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/8/2020 4:28 PM	Report #	
Pictures					
GPS Location		See picture above for GPS coordinates		GPS Location	
Field Station#		10858+00		Field Station#	
Pic 1 Desc.		ECD's and row conditions		Pic 2 Desc.	
GPS Location		See picture above for GPS coordinates		GPS Location	
Field Station#		10920+00		Field Station#	
Pic 3 Desc.		Damaged P1		Pic 4 Desc.	
GPS Location		See picture above for GPS coordinates		GPS Location	
Field Station#		10911+00		Field Station#	
Pic 5 Desc.		ECD's and row conditions		Pic 6 Desc.	

A/E	124300137	Date/Time	7/8/2020 4:28 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/8/2020 4:28 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12568
Inspector	Len Kruizenga			Date/Time	7/9/2020 11:53 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Full	Station End	11353+67
County	Giles	Ground	Dry	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Rock-lined Channel	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/9/2020 11:53 AM	Report #	12568
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with EI's at Winding Way. SWPPP inspection: Sta#11254+99 to 21353+67 MP- 213 to 215 The row is dry and in stable condition. There is little to no vegetation in this inspection area, it has been heavily mulched helping to keep the row stable. Water bars and sump pits are in acceptable condition. Water bar end treatments are in acceptable condition. Perimeter controls, silt fence, SSF, & CFS is in acceptable condition. At sta#11327+35 the fabric on SSF is detached from the chain link, contractor notified and item added to punch list. All streams, equipment bridges, buffers and stream controls are in acceptable condition. AR-256.02 and Old Furnace RCE are in acceptable condition. Slope drain pipes and CWD pipes and plunge pools are in acceptable condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/9/2020 11:53 AM	Report #	
Pictures					
					
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11258+00	Field Station#	11262+00		
Pic 1 Desc.	Sta#11258+00 to 11237+00- Trees felled but not cleared or processed.	Pic 2 Desc.	Sta#11262+00 to 11258+00- Slope drains, water bars, end treatments, perimeter controls.		
					
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11289+00	Field Station#	11326+00		
Pic 3 Desc.	Row on steep slope, stream, equipment bridge & ECD's	Pic 4 Desc.	Stream, equipment bridge and stream controls.		
					
GPS Location	See photo GPS	GPS Location	See photo GPS		
Field Station#	11327+35	Field Station#	11332+00		
Pic 5 Desc.	SSF fabric detached from chain link at stream buffer.	Pic 6 Desc.	Rock channel and P1 perimeter controls.		

AFE	124300137	Date/Time	7/9/2020 11:53 AM	Report #	
Pictures					
		<p>Insert image here</p>			
GPS Location	See photo GPS	GPS Location			
Field Station#	11352+52	Field Station#			
Pic 7 Desc.	Stream, equipment bridge, stream controls.	Pic 8 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	7/9/2020 11:53 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12581
Inspector	Garrett Barclay			Date/Time	7/9/2020 3:19 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11064+53
State	VA	Inspection Area	Partial	Station End	11158+27
County	Giles	Ground	Dry	Temperature (°F)	88.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

- | | |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) | No |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/9/2020 3:19 PM	Report #	12581
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 209 - MP 211.5 Observed damaged P1SF ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources Damaged ECD's added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/9/2020 3:19 PM	Report #	
Pictures					
GPS Location	See picture above for GPS coordinates	GPS Location	See picture above for GPS coordinates		
Field Station#	11067+00	Field Station#	11068+00		
Pic 1 Desc.	ECD's and row conditions	Pic 2 Desc.	Damaged P1		
GPS Location	See picture above for GPS coordinates	GPS Location	See picture above for GPS coordinates		
Field Station#	11076+00	Field Station#	11046+00		
Pic 3 Desc.	ECD's and row conditions	Pic 4 Desc.	ECD's and row conditions		
GPS Location	See picture above for GPS coordinates	GPS Location	See picture above for GPS coordinates		
Field Station#	11030+00	Field Station#	11040+00		
Pic 5 Desc.	ECD's and row conditions	Pic 6 Desc.	ECD's and row conditions		

A/E	124300137	Date/Time	7/9/2020 3:19 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/9/2020 3:19 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12593
Inspector	Brian Shields			Date/Time	7/9/2020 10:10 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11158+27
State	VA	Inspection Area	Full	Station End	11254+99
County	Giles	Ground	Dry	Temperature (°F)	80.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	7/9/2020 10:10 AM	Report #	
Pictures					
	South East Elevation ● 37.301486, -80.504108 ±8m  Row conditions 11213+00 Spread G 09 Jul 2020, 09:59 AM			North East Elevation ● 37.301607, -80.50415 ±8m  Slope drain inlet 11211+00 Spread G 09 Jul 2020, 09:59 AM	
GPS Location	see photo		GPS Location	see photo	
Field Station#	11213+00		Field Station#	11211+00	
Pic 1 Desc.	Stabilized row conditions		Pic 2 Desc.	slope drain inlet	
	West Elevation ● 37.30403, -80.506697 ±6m  Waterbar into end treatment 11108+00 Spread G 09 Jul 2020, 10:08 AM			South Elevation ● 37.307376, -80.511913 ±9m  Plunge pool 11184+00 Spread G 09 Jul 2020, 10:11 AM	
GPS Location	see photo		GPS Location	see photo	
Field Station#	11108+00		Field Station#	11184+00	
Pic 3 Desc.	waterbar into end treatment		Pic 4 Desc.	installed plunge pool	
	South East Elevation ● 37.30739, -80.511969 ±15m  Row conditions 11181+00 Spread G 09 Jul 2020, 10:13 AM			South West Elevation ● 37.310377, -80.51419 ±4m  Row conditions 11165+00 Spread G 09 Jul 2020, 10:19 AM	
GPS Location	see photo		GPS Location	see photo	
Field Station#	11181+00		Field Station#	11165+00	
Pic 5 Desc.	stabilized row conditions		Pic 6 Desc.	stabilized row conditions	

A/E	124300137	Date/Time	7/9/2020 10:10 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/9/2020 10:10 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12607
Inspector	Rob Robertson			Date/Time	7/10/2020 12:58 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11670+00
County	Montgomery	Ground	Dry	Temperature (°F)	82.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00




1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/10/2020 12:58 PM	Report #	12607
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a routine VADEQ SWPPP inspection on JNF and private lands at Brush Mountain. The ROW surface is dry and stable. No forms of erosion are present and ECDs are in place. Resource crossings are stable with well vegetated buffers with ECDs in place. Slope breakers are functioning as designed with effective end treatments installed. ECD maintenance needs are being addressed. RCEs are in good condition. Equipment bridges appear to be in good condition. There was no evidence of vandalism and no housekeeping issues.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/10/2020 12:58 PM	Report #	
Pictures					
<p>Date & Time: Fri, Jul 10, 2020 10:36:50 EDT Position: +480.2494497° / +680.555124° / +2263.27m Altitude: 2263.27m Datum: WGS-84 Azimuth/Bearing: 340° N20W 604mils Magnetic (+14°) Elevation Angle: -18.6° Horizon Angle: +00.4° Zoom: 1.0X Brush Min. ROW stable currently. Annual grasses dying out. 11665+50</p> 		<p>Date & Time: Fri, Jul 10, 2020 10:37:58 EDT Position: +483.139555° / +680.555331° / +194m Altitude: 240.11m (+25.2m) Datum: WGS-84 Azimuth/Bearing: 181° S81W 3.20mils Magnetic (+13°) Elevation Angle: +3.4° Horizon Angle: +05.2° Zoom: 1.0X Brush Min. Perimeter controls in place. 11661+00</p> 			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11665+50	Field Station#	11661+00		
Pic 1 Desc.	ROW stable. Slope breakers functional.	Pic 2 Desc.	Perimeter controls in place and functioning.		
<p>Date & Time: Fri, Jul 10, 2020 10:40:28 EDT Position: +437.005264° / +680.555133° / +16.4m Altitude: 18.3ft (+19.7m) Datum: WGS-84 Azimuth/Bearing: 322° N83W 592mils Magnetic (+12°) Elevation Angle: -26.6° Horizon Angle: +03.2° Zoom: 1.0X Brush Min. Perimeter controls in place. 11660+00</p> 		<p>Date & Time: Fri, Jul 10, 2020 10:40:28 EDT Position: +437.005264° / +680.555133° / +16.4m Altitude: 18.3ft (+19.7m) Datum: WGS-84 Azimuth/Bearing: 322° N83W 592mils Magnetic (+12°) Elevation Angle: -26.6° Horizon Angle: +03.2° Zoom: 1.0X Brush Min. Perimeter controls in place. 11660+00</p> 			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11660+00	Field Station#	11650+00		
Pic 3 Desc.	Perimeter controls in place. ROW currently stable.	Pic 4 Desc.	ECDs in place and functional.		
<p>Date & Time: Fri, Jul 10, 2020 11:03:40 EDT Position: +407.213510° / +680.377597° / +32.8m Altitude: 231.4m (+39.4m) Datum: WGS-84 Azimuth/Bearing: 033° N33E 0587mils Magnetic (+12°) Elevation Angle: -23.1° Horizon Angle: +00.0° Zoom: 1.0X Brush Min. Perimeter controls in place. ROW stable 11628+50</p> 		<p>Date & Time: Fri, Jul 10, 2020 11:10:52 EDT Position: +407.213510° / +680.377597° / +32.8m Altitude: 231.4m (+39.4m) Datum: WGS-84 Azimuth/Bearing: 033° N33E 0587mils Magnetic (+12°) Elevation Angle: -23.1° Horizon Angle: +00.0° Zoom: 1.0X Brush Min. Perimeter controls in place. ROW stable 11628+50</p> 			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11631+00	Field Station#	11628+50		
Pic 5 Desc.	ROW stable. Slope breakers are functional.	Pic 6 Desc.	Perimeter controls in place and functioning.		

AFE	124300137	Date/Time	7/10/2020 12:58 PM	Report #	
Pictures					
<small> Date & Time: Fri Jul 10 2020 11:54:01 EDT Position: +037.313397 / -080.398893 (+32.8ft) Altitude: 1932ft (+39.4ft) Datum: WGS-84 Azimuth/Bearing: 107° SSW 3360mils Magnetic (+12°) Elevation Angle: -25.7° Horizon Angle: +01.7° Zoom: 1.0X Brush Mtn. S-HH18 crossing stable 11626+04 </small> 		<small> Date & Time: Fri Jul 10 2020 11:25:09 EDT Position: +037.319729 / -080.402399 (+32.8ft) Altitude: 1930ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 180° S20E 2844mils Magnetic (+12°) Elevation Angle: -25.9° Horizon Angle: -00.9° Zoom: 1.0X Brush Mtn. S-RR14 crossing stable 11614+20 </small> 			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11626+04	Field Station#	11614+20		
Pic 7 Desc.	Resource crossing at S-HH18 is stable with ECDs in place.	Pic 8 Desc.	Resource crossing at S-RR14 is stable with ECDs in place.		
<small> Date & Time: Fri Jul 10 2020 11:36:01 EDT Position: +037.313456 / -080.404454 (+32.8ft) Altitude: 1922ft (+32.5ft) Datum: WGS-84 Azimuth/Bearing: 251° S71W 4462mils Magnetic (+12°) Elevation Angle: -11.3° Horizon Angle: +01.0° Zoom: 1.0X Brush Mtn. S-006 crossing stable </small> 		<div style="text-align: center;">Insert image here</div>			
GPS Location	On photo	GPS Location			
Field Station#	11608+17	Field Station#			
Pic 9 Desc.	Resource crossing at S-is stable with ECDs in place.	Pic 10 Desc.			
<div style="text-align: center;">Insert image here</div>		<div style="text-align: center;">Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	7/10/2020 12:58 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12608
Inspector	Len Kruizenga			Date/Time	7/10/2020 1:02 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Full	Station End	12005+00
County	Montgomery	Ground	Dry	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? No
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar Outlet Protection	Acceptable			
Roadside Ditch	Acceptable			
Culvert	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/10/2020 1:02 PM	Report #	12608
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with EI's at Winding Way SWPPP inspection: Sta#11788+52 to 12005+00. MP- 223.3 to 227.3 The row is dry and in stable condition with no sediment movement. The permanent restoration is very good, vegetation has created good stability of the row. Water bars and level spreaders are in good condition. Perimeter controls, CFS, SSF are in acceptable condition. Silt fence is in acceptable condition with the exception of sta#11867+00, where three P1 stakes were broken off. The contractor has been notified and item will be added to the punch list. Karst ECD's are in acceptable condition. Tabor RCE, AR-266.03 & AR-266.00 are in acceptable condition. Wetland ECD's are in acceptable condition.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	7/10/2020 1:02 PM	Report #	
Pictures					
					
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11788+52		Field Station#	11832+00	
Pic 1 Desc.	Tabor RCE		Pic 2 Desc.	Level spreaders, CFS controls & row vegetation.	
					
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11857+00		Field Station#	11867+00	
Pic 3 Desc.	Level spreaders,ECD's, row vegetation on slope.		Pic 4 Desc.	Silt fence perimeter control stakes broken off, contractor has been informed, issue added to the punch list.	
					
GPS Location	See photo GPS		GPS Location	See photo GPS	
Field Station#	11901+00		Field Station#	11942+00	
Pic 5 Desc.	AR-266.00- Access road and CFS check dams in bar ditch.		Pic 6 Desc.	Karst ECD's	

AFE	124300137	Date/Time	7/10/2020 1:02 PM	Report #	
Pictures					
 <p> <small> Date & Time: Fri Jul 10, 2020 11:32:11 EDT Position: +037 266317° / -080 320493° (+16.4ft) Altitude: 1665ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 006° N04E 0107mils (+10°) Elevation Angle: +12.6° Horizon Angle: +08.0° Zoom: 1.0X AR-266.00- Access rd, rock check dams </small> </p>					
GPS Location	See photo GPS	GPS Location			
Field Station#	11988+00	Field Station#			
Pic 7 Desc.	AR-266.00- Access road with rock check dams in bar ditch.	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	7/10/2020 1:02 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12610
Inspector	Garrett Barclay			Date/Time	7/7/2020 1:11 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Sensitive Resource Signage	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/7/2020 1:11 PM	Report #	12610
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for LDY 28 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	7/7/2020 1:11 PM	Report #	
Pictures					
<p>Date & Time: Tue Jul 07, 2020 09:35:43 EDT Position: +037°20'2.23" / -080°48'10.78" (±40.9ft) Altitude: 1561ft (±65.1ft) Datum: WGS-84 Azimuth/Bearing: 039° N39E 0693mils True (±13.1) Elevation Grade: +023 Horizon Grade: +001 Zoom: 1.0X 28</p> 		<p>Date & Time: Tue Jul 07, 2020 09:33:50 EDT Position: +037°20'2.23" / -080°48'10.78" (±40.9ft) Altitude: 1561ft (±65.1ft) Datum: WGS-84 Azimuth/Bearing: 229° S229E 11mils True (±12.7) Elevation Grade: -016 Horizon Grade: +001 Zoom: 1.0X 28</p> 			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
<p>Date & Time: Tue Jul 07, 2020 09:35:43 EDT Position: +037°20'3.20" / -080°48'12.43" (±39.4ft) Altitude: 1558ft (±65.1ft) Datum: WGS-84 Azimuth/Bearing: 235° S55W 4178mils True (±13.1) Elevation Grade: +008 Horizon Grade: +002 Zoom: 1.0X 28</p> 		<p>Date & Time: Tue Jul 07, 2020 09:36:07 EDT Position: +037°20'3.90" / -080°48'12.06" (±40.9ft) Altitude: 1561ft (±65.1ft) Datum: WGS-84 Azimuth/Bearing: 120° S92E 2276mils True (±12.7) Elevation Grade: +000 Horizon Grade: +002 Zoom: 1.0X 2</p> 			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions are	
<p>Date & Time: Tue Jul 07, 2020 09:29:05 EDT Position: +037°20'4.47" / -080°48'3.66" (±42.8ft) Altitude: 1555ft (±68.8ft) Datum: WGS-84 Azimuth/Bearing: 278° S22W 4942mils True (±19.1) Elevation Grade: +001 Horizon Grade: +001 Zoom: 1.0X 28</p> 		<p>Date & Time: Tue Jul 07, 2020 09:26:31 EDT Position: +037°20'5.72" / -080°48'03.67" (±42.8ft) Altitude: 1570ft (±256.4ft) Datum: WGS-84 Azimuth/Bearing: 079° N79E 1820mils True (±14.7) Elevation Grade: +000 Horizon Grade: +001 Zoom: 1.0X 28</p> 			
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	7/7/2020 1:11 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/7/2020 1:11 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12611
Inspector	Garrett Barclay			Date/Time	7/10/2020 1:26 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+16
State	VA	Inspection Area	Partial	Station End	11600+01
County	Giles	Ground	Dry	Temperature (°F)	89.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Flume Pipe	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/10/2020 1:26 PM	Report #	12611
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 218. MP 219.5 Observed no damaged ECD's during inspection ECD's are installed per spec and per E&S plans Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	7/10/2020 1:26 PM	Report #	
Pictures					
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11530+00		Field Station#	11551+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11556+00		Field Station#	11544+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11569+00		Field Station#	11585+00	
Pic 5 Desc.	ECD's and row conditions		Pic 6 Desc.	ECD's and row conditions	

A/E	124300137	Date/Time	7/10/2020 1:26 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/10/2020 1:26 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12615
Inspector	Jared Saunders			Date/Time	7/10/2020 3:11 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11788+50
County	Montgomery	Ground	Dry	Temperature (°F)	90.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	7/10/2020 3:11 PM	Report #	12615
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/10/2020 3:11 PM	Report #	
Pictures					
 <p>Date & Time: Fri, Jul 10, 2020, 11:40:59 EDT Position: +037 294567° / +080 369278° (+101.3ft) Altitude: 2022ft (+1203) Datum: WGS-84 Azimuth/Bearing: 148° S32E 2631mils True (+13°) Elevation Angle: -19.5° Horizon Angle: +00.0° Zoom: 1.0x 11767+00</p>		 <p>Date & Time: Fri, Jul 10, 2020, 11:40:59 EDT Position: +037 294567° / +080 369278° (+101.3ft) Altitude: 2022ft (+1203) Datum: WGS-84 Azimuth/Bearing: 148° S32E 2631mils True (+13°) Elevation Angle: -19.5° Horizon Angle: +00.0° Zoom: 1.0x 11767+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11670+00		Field Station#	11760+00	
Pic 1 Desc.	Triple stack compost filter sock and priority one silt fence in place as LOD controls.		Pic 2 Desc.	Waterbar, sump pit, and waterbar end treatment in place.	
 <p>Date & Time: Fri, Jul 10, 2020, 11:40:59 EDT Position: +037 294567° / +080 369278° (+101.3ft) Altitude: 2022ft (+1203) Datum: WGS-84 Azimuth/Bearing: 148° S32E 2631mils True (+13°) Elevation Angle: -19.5° Horizon Angle: +00.0° Zoom: 1.0x 11767+00</p>		 <p>Date & Time: Fri, Jul 10, 2020, 11:40:59 EDT Position: +037 294567° / +080 369278° (+101.3ft) Altitude: 2022ft (+1203) Datum: WGS-84 Azimuth/Bearing: 148° S32E 2631mils True (+13°) Elevation Angle: -19.5° Horizon Angle: +00.0° Zoom: 1.0x 11763+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11767+00		Field Station#	11763+00	
Pic 3 Desc.	RCE in place at Main Line Valve 26.		Pic 4 Desc.	ROW stabilized with mulch and vegetation growth.	
 <p>Date & Time: Fri, Jul 10, 2020, 11:47:12 EDT Position: +037 294567° / +080 369278° (+101.3ft) Altitude: 2022ft (+1203) Datum: WGS-84 Azimuth/Bearing: 148° S32E 2631mils True (+13°) Elevation Angle: -19.5° Horizon Angle: +00.0° Zoom: 1.0x 11772+00</p>		 <p>Date & Time: Fri, Jul 10, 2020, 11:48:44 EDT Position: +037 294567° / +080 369278° (+101.3ft) Altitude: 2022ft (+1203) Datum: WGS-84 Azimuth/Bearing: 148° S32E 2631mils True (+13°) Elevation Angle: -19.5° Horizon Angle: +00.0° Zoom: 1.0x 11775+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11772+00		Field Station#	11775+00	
Pic 5 Desc.	Clean water diversion pipe inlet and clean water diversion berm in place.		Pic 6 Desc.	Clean water diversion pipe and plunge pool in place.	

A/E	124300137	Date/Time	7/10/2020 3:11 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/10/2020 3:11 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12638
Inspector	Jared Saunders			Date/Time	7/9/2020 3:25 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11353+67
State	VA	Inspection Area	Partial	Station End	11524+16
County	Giles	Ground	Dry	Temperature (°F)	80.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/9/2020 3:25 PM	Report #	12638
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 215 to MP 218.3. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. Deficiencies located at; Downed priority one silt fence at station number 11413+00, 11395+00 - hole in priority one silt fence end treatment, and at 11438+75 hole in priority one silt fence from cattle.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	7/9/2020 3:25 PM	Report #	
Pictures					
<p>Date & Time: Thu, Jul 09, 2020, 09:42W EDT Position: +037.307429° / -080.490331° (+38161.8m) Altitude: 2156ft (+104.8m) Datum: WGS-84 Azimuth/Bearing: 000° N00E 0000mils True (±15°) Elevation Angle: -23.5° Horizon Angle: -26.1° Zoom: 1.0X 11507+00</p>		<p>Date & Time: Thu, Jul 09, 2020, 09:40W EDT Position: +037.311423° / -080.490331° (+38161.8m) Altitude: 2096ft (+173.7m) Datum: WGS-84 Azimuth/Bearing: 235° S55W 4170mils True (±15°) Elevation Angle: -14.7° Horizon Angle: -00.6° Zoom: 1.0X 11489+00</p>		GPS Location	See photo for GPS location.
				GPS Location	See photo for GPS location.
	Field Station#	11507+00		Field Station#	11489+00
Pic 1 Desc.	Clean water diversion pipe and plunge pool in place.		Pic 2 Desc.	RCE in place At Stevers Gap Road.	
<p>Date & Time: Thu, Jul 09, 2020, 10:11W EDT Position: +037.307429° / -080.490331° (+38161.8m) Altitude: 2156ft (+104.8m) Datum: WGS-84 Azimuth/Bearing: 281° N79W 4996mils True (±15°) Elevation Angle: -17.5° Horizon Angle: -01.6° Zoom: 1.0X 11438+50</p>		<p>Date & Time: Thu, Jul 09, 2020, 10:55W EDT Position: +037.295586° / -080.490331° (+38161.8m) Altitude: 2020ft (+146.0m) Datum: WGS-84 Azimuth/Bearing: 279° N81W 4960mils True (±15°) Elevation Angle: -19.4° Horizon Angle: -03.3° Zoom: 1.0X 11412+00</p>		GPS Location	See photo for GPS location.
				GPS Location	See photo for GPS location.
	Field Station#	11438+50		Field Station#	11412+00
Pic 3 Desc.	Holes in priority one silt fence from land owner cattle.		Pic 4 Desc.	Priority one silt fence end treatment with a broken stake.	
<p>Date & Time: Thu, Jul 09, 2020, 11:15W EDT Position: +037.295586° / -080.490331° (+38161.8m) Altitude: 2020ft (+146.0m) Datum: WGS-84 Azimuth/Bearing: 359° N01W 6382mils True (±15°) Elevation Angle: -07.6° Horizon Angle: -03.3° Zoom: 1.0X 11395+00</p>		<p>Date & Time: Thu, Jul 09, 2020, 11:20W EDT Position: +037.295586° / -080.490331° (+38161.8m) Altitude: 2020ft (+146.0m) Datum: WGS-84 Azimuth/Bearing: 186° S06W 3307mils True (±15°) Elevation Angle: -02.9° Horizon Angle: -00.7° Zoom: 1.0X 11371+00</p>		GPS Location	See photo for GPS location.
				GPS Location	See photo for GPS location.
	Field Station#	11395+00		Field Station#	11371+00
Pic 5 Desc.	Hole in priority one silt fence end treatment.		Pic 6 Desc.	Clean water diversion pipe and clean water diversion berm in place.	

A/E	124300137	Date/Time	7/9/2020 3:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/9/2020 3:25 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	12643
Inspector	Jared Saunders			Date/Time	7/7/2020 2:02 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	7/7/2020 2:02 PM	Report #	12643
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		7/7/2020 2:02 PM		Report #			
Pictures											
<p>Date & Time: Tue Jul 07, 2020 10:17:06 EDT Position: +037 318449 / -080 658042 (+13.3m) Altitude: 1792ft (+32.8m) Datum: WGS-84 Azimuth/Bearing: 290 N70W 815mils True (+10°) Elevation Angle: -04.6° Horizon Angle: -01.8° Zoom: 1.0X LDY 26</p> 								<p>Date & Time: Tue Jul 07, 2020 10:17:13 EDT Position: +037 318555 / -080 658616 (+13.5m) Altitude: 1792ft (+34.9m) Datum: WGS-84 Azimuth/Bearing: 211 S31W 375mils True (+10°) Elevation Angle: -01.2° Horizon Angle: -01.2° Zoom: 1.0X LDY 26</p> 			
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		12005+00						Field Station#		12005+00	
Pic 1 Desc.		RCE in place at LDY 26 entrance.						Pic 2 Desc.		18 inch compost filter sock in place along LOD.	
<p>Date & Time: Tue Jul 07, 2020 10:17:20 EDT Position: +037 318752 / -080 658498 (+13.2m) Altitude: 1788ft (+37.2m) Datum: WGS-84 Azimuth/Bearing: 111° S89E 308mils True (+10°) Elevation Angle: -02.1° Horizon Angle: -00.3° Zoom: 1.0X LDY 26</p> 								<p>Date & Time: Tue Jul 07, 2020 10:18:02 EDT Position: +037 319370 / -080 658181 (+15.4m) Altitude: 1787ft (+11.3m) Datum: WGS-84 Azimuth/Bearing: 281 N79W 499mils True (+10°) Elevation Angle: -11.2° Horizon Angle: -00.3° Zoom: 1.0X LDY 26</p> 			
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		12005+00						Field Station#		12005+00	
Pic 3 Desc.		Dumpsters being utilized for trash management.						Pic 4 Desc.		Triple stack 18 compost filter sock in place around drainage.	
<p>Date & Time: Tue Jul 07, 2020 10:19:26 EDT Position: +037 318353 / -080 657762 (+13.4m) Altitude: 1790ft (+11.3m) Datum: WGS-84 Azimuth/Bearing: 322 N38W 572mils True (+15°) Elevation Angle: -02.0° Horizon Angle: -01.5° Zoom: 1.0X LDY 26</p> 								<p>Date & Time: Tue Jul 07, 2020 10:19:38 EDT Position: +037 318353 / -080 657762 (+13.4m) Altitude: 1794ft (+35.7m) Datum: WGS-84 Azimuth/Bearing: 100° S81E 177mils True (+15°) Elevation Angle: -01.0° Horizon Angle: -02.5° Zoom: 1.0X LDY 26</p> 			
GPS Location		See photo for GPS location.						GPS Location		See photo for GPS location.	
Field Station#		12005+00						Field Station#		12005+00	
Pic 5 Desc.		Checked staged equipment for leaks.						Pic 6 Desc.		Secondary containment in place under fuel cell.	

A/E	124300137	Date/Time	7/7/2020 2:02 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	7/7/2020 2:02 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		