



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13199
Inspector	Jared Saunders			Date/Time	8/2/2020 1:54 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11353+00
State	VA	Inspection Area	Partial	Station End	11471+00
County	Giles	Ground	Wet	Temperature (°F)	85.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.30
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/2/2020 1:54 PM	Report #	13199
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Checked repairs made at station numbers; 11477+00 - Silt fence stake broke due to being overtopped, 11474+00 - ECB on two-tone needs repaired, 11465+00 - priority one silt fence blown out, 11441+00 - Hole in priority one silt fence end treatment, 1440+00 - silt fence removed from stake, 11428+00 - hole in priority one silt, 11404+00 - silt fence stake broken, 11395+00 - silt fence stake broken, 11365+87 - CFS overtopped and blown out resulting in sediment off ROW and rock check needs cleaned out, 11362+00 - install ECB where rilling occurred from sump pit over flowing, 11361+00 - install longer triple stack CFS end treatment to ensure water doesn't flow around it with out being filtered. All items were sufficiently repaired. Closed PAR report for off ROW sediment at land tract VA-GI-4250 station number 11365+87. Checked rain gauges at Access Road 244 - 0.05 and Stevers Gap Road - 0.2.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	8/2/2020 1:54 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11024+00		Field Station#	11489+00	
Pic 1 Desc.	Rain gauge at AR 244 reads 0.05 inches.		Pic 2 Desc.	Rain gauge at Stevers Gap Road reads 0.2 inches.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11463+00		Field Station#	11365+87	
Pic 3 Desc.	Priority one silt fence end treatment repaired.		Pic 4 Desc.	Slope drain, fill slope erosion, and triple stack CFS end treatment repaired.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11362+00		Field Station#	11365+87	
Pic 5 Desc.	Rilling raked out and area stabilized with ECB.		Pic 6 Desc.	Off ROW sediment recovered. Area disturbed during sediment retrieval stabilized with seed and mulch.	

A/E	124300137	Date/Time	8/2/2020 1:54 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	8/2/2020 1:54 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13210
Inspector	Chris Burns			Date/Time	8/3/2020 7:56 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Partial	Station End	12005+00
County	Montgomery	Ground	Wet	Temperature (°F)	73.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/3/2020 7:56 AM	Report #	13210
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 223.27 to MP 227.37 as well as assessed AR 266. No major issues were located. Five locations of minor wildlife/weather damage to controls were identified. PPL Environmental Coordinator Mike Perry was notified and the items were added to the punch list. PPL crews made the repairs prior to the end of day. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed. Accompanied by MBP representatives during the inspection of AR 266.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137		Date/Time		8/3/2020 7:56 AM		Report #							
Pictures															
				<p>Date & Time: Mon, Aug 03, 2020, 05:15:40 EDT Position: +482.257046° / -404.357842° (±11.10) Altitude: 21792 (±11.10) Datum: WGS-84 Azimuth/Heading: 135° 330W 330mils True (±15°) Elevation Angle: +04.3° Horizon Angle: +01.1° Zoom: 0.5X 11792+00</p> 								<p>Date & Time: Mon, Aug 03, 2020, 05:46:26 EDT Position: +482.257122° / -404.357822° (±11.10) Altitude: 21818 (±11.10) Datum: WGS-84 Azimuth/Heading: 135° 330W 330mils True (±15°) Elevation Angle: +04.2° Horizon Angle: +01.1° Zoom: 0.5X 11818+00</p> 			
GPS Location				1				GPS Location				2			
Field Station#				11792+00				Field Station#				11818+00			
Pic 1 Desc.				Section of restored RoW showing conditions and controls.				Pic 2 Desc.				Section of restored RoW showing conditions and controls.			
				<p>Date & Time: Mon, Aug 03, 2020, 06:04:19 EDT Position: +482.258297° / -404.361730° (±11.10) Altitude: 21770 (±11.10) Datum: WGS-84 Azimuth/Heading: 135° 330W 330mils True (±15°) Elevation Angle: +05.0° Horizon Angle: +01.4° Zoom: 0.5X 11792+00</p> 								<p>Date & Time: Mon, Aug 03, 2020, 06:14:01 EDT Position: +482.259122° / -404.359222° (±11.10) Altitude: 21906 (±11.10) Datum: WGS-84 Azimuth/Heading: 135° 330W 330mils True (±15°) Elevation Angle: +01.2° Horizon Angle: +01.2° Zoom: 0.5X 11906+00</p> 			
GPS Location				3				GPS Location				4			
Field Station#				11863+65				Field Station#				11906+00			
Pic 3 Desc.				P-KL2 and controls.				Pic 4 Desc.				Section of semi-restored RoW showing conditions and controls.			
				<p>Date & Time: Mon, Aug 03, 2020, 10:36:51 EDT Position: +482.257646° / -404.358297° (±11.10) Altitude: 21922 (±11.10) Datum: WGS-84 Azimuth/Heading: 135° 330W 330mils True (±15°) Elevation Angle: +02.4° Horizon Angle: +01.2° Zoom: 0.5X 11952+00</p> 								<p>Date & Time: Mon, Aug 03, 2020, 10:47:20 EDT Position: +482.257646° / -404.358297° (±11.10) Altitude: 21991 (±11.10) Datum: WGS-84 Azimuth/Heading: 135° 330W 330mils True (±15°) Elevation Angle: +02.4° Horizon Angle: +01.2° Zoom: 0.5X 11991+00</p> 			
GPS Location				5				GPS Location				6			
Field Station#				11952+00				Field Station#				11991+00			
Pic 5 Desc.				Section of semi-restored RoW showing conditions and controls.				Pic 6 Desc.				Section of restored RoW showing conditions and controls.			

A/E	124300137	Date/Time	8/3/2020 7:56 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	8/3/2020 7:56 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13221
Inspector	Rob Robertson			Date/Time	8/3/2020 12:22 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11670+00
County	Montgomery	Ground	Wet	Temperature (°F)	72.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)




E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/3/2020 12:22 PM	Report #	13221
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
A regular scheduled VADEQ SWPPP inspection was completed today on private and JNF property located on Brush Mountain. The ROW surface is currently stable with no erosion issues located. Perimeter ECDs are in place and functioning as designed. Contractor is completing minor maintenance needs. Slope breakers are working properly and controlling stormwater runoff. No impact to resources or movement of sediment beyond approved LOD. RCEs are in good condition. No evidence of vandalism or trespass. No environmental concerns were identified.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	8/3/2020 12:22 PM	Report #	
Pictures					
 <p>Date & Time Mon, Aug 03, 2020, 10:03:07 EDT Position: +037.309466°N / -080.397466°W (±98.4m) Altitude: 2200ft (±32.8m) Datum: WGS-84 Azimuth/Bearing: 154° 57'46" Magnetic (±13°) Elevation Angle: +12.1° Horizon Angle: -01.3° Zoom: 1.0x Brush Mats/Perimeter controls in place: 11666+50</p>		 <p>Date & Time Mon, Aug 03, 2020, 10:05:00 EDT Position: +037.309466°N / -080.397466°W (±98.4m) Altitude: 2200ft (±32.8m) Datum: WGS-84 Azimuth/Bearing: 154° 57'46" Magnetic (±13°) Elevation Angle: +12.1° Horizon Angle: -01.3° Zoom: 1.0x Brush Mats/Perimeter controls in place: 11663+00</p>			
GPS Location	On photo		GPS Location	On photo	
Field Station#	11666+50		Field Station#	11663+00	
Pic 1 Desc.	End treatments are working properly.		Pic 2 Desc.	Perimeter controls are in place and effective.	
 <p>Date & Time Mon, Aug 03, 2020, 10:13:16 EDT Position: +037.309466°N / -080.397466°W (±98.4m) Altitude: 2664ft (±32.8m) Datum: WGS-84 Azimuth/Bearing: 130° 56'57" Magnetic (±12°) Elevation Angle: +04.8° Horizon Angle: -01.3° Zoom: 1.0x Brush Mats/Perimeter controls in place: 11657+00</p>		 <p>Date & Time Mon, Aug 03, 2020, 10:27:33 EDT Position: +037.309466°N / -080.397466°W (±98.4m) Altitude: 2200ft (±32.8m) Datum: WGS-84 Azimuth/Bearing: 215° 53'39" Magnetic (±12°) Elevation Angle: +2.3° Horizon Angle: -00.5° Zoom: 1.0x Perimeter controls in place: 11650+25</p>			
GPS Location	On photo		GPS Location	On photo	
Field Station#	11657+00		Field Station#	11644+25	
Pic 3 Desc.	End treatment functioning properly.		Pic 4 Desc.	Perimeter controls and end treatments effective.	
 <p>Date & Time Mon, Aug 03, 2020, 10:28:10 EDT Position: +037.310278°N / -080.397466°W (±98.4m) Altitude: 2100ft (±32.8m) Datum: WGS-84 Azimuth/Bearing: 194° 51'49" Magnetic (±12°) Elevation Angle: +10.1° Horizon Angle: -01.1° Zoom: 1.0x Slope breakers installed, 3275' above: 11627+00</p>		 <p>Date & Time Mon, Aug 03, 2020, 10:44:06 EDT Position: +037.310278°N / -080.397466°W (±98.4m) Altitude: 1930ft (±32.8m) Datum: WGS-84 Azimuth/Bearing: 301° 51'49" Magnetic (±12°) Elevation Angle: +2.3° Horizon Angle: -00.7° Zoom: 1.0x S-H18 crossing stable: 11626+04</p>			
GPS Location	On photo		GPS Location	On photo	
Field Station#	11637+00		Field Station#	11626+04	
Pic 5 Desc.	Slope breakers functioning properly. ROW stable.		Pic 6 Desc.	S-RR18 crossing stable	

AFE	124300137	Date/Time	8/3/2020 12:22 PM	Report #	
Pictures					
 <p><small>Date & Time: Mon, Aug 03, 2020, 10:52:00 EDT Position: +037.311851° / -080.394984° (+14405.0ft) Altitude: 1942ft (+17.7ft) Datum: WGS-84 Azimuth/Bearing: 218° S38W 1876mils Magnetic (+13°) Elevation Angle: -8.4° Horizon Angle: -02.4° Zoom: 1.0X S-RR14 crossing stable</small></p>		 <p><small>Date & Time: Mon, Aug 03, 2020, 11:04:55 EDT Position: +037.314510° / -080.402278° (+16.4ft) Altitude: 1920ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 161° S19E 2032mils Magnetic (+14°) Elevation Angle: -10.3° Horizon Angle: -02.4° Zoom: 1.0X S-RR13 crossing stable</small></p>			
GPS Location	On photo	GPS Location	On photo		
Field Station#	11614+20	Field Station#	11613+69		
Pic 7 Desc.	S-RR14 crossing stable	Pic 8 Desc.	S-RR13 crossing stable access road MN-258.04		
 <p><small>Date & Time: Mon, Aug 03, 2020, 10:50:35 EDT Position: +037.313550° / -080.404567° (+32.8ft) Altitude: 1909ft (+52.5ft) Datum: WGS-84 Azimuth/Bearing: 243° S43W 4320mils Magnetic (+12°) Elevation Angle: -10.4° Horizon Angle: -01.5° Zoom: 1.0X S-006 crossing stable</small></p>		<p style="text-align: center;">Insert image here</p>			
GPS Location	On photo	GPS Location			
Field Station#	11608+17	Field Station#			
Pic 9 Desc.	S-006 crossing stable	Pic 10 Desc.			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	8/3/2020 12:22 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13229
Inspector	Garrett Barclay			Date/Time	8/3/2020 2:09 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+16
State	VA	Inspection Area	Partial	Station End	11600+01
County	Giles	Ground	Wet	Temperature (°F)	81.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.05
				Rain Accumulation Time (days)	1.00



1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Flume Pipe	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/3/2020 2:09 PM	Report #	13229
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 218 - MP 219.5 Observed damaged ECD's during inspection, items sent to Environmental coordinator Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list Damaged items added to the punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	8/3/2020 2:09 PM	Report #	
Pictures					
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	1153+00		Field Station#	11547+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	Damaged P1	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11547+60		Field Station#	11568+50	
Pic 3 Desc.	Damaged P1		Pic 4 Desc.	Damaged P1	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11567+80		Field Station#	11597+00	
Pic 5 Desc.	ECD's and row conditions @ Spp22		Pic 6 Desc.	Damaged P1	

A/E	124300137	Date/Time	8/3/2020 2:09 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	8/3/2020 2:09 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13256
Inspector	Jared Saunders			Date/Time	8/3/2020 4:58 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11788+50
County	Montgomery	Ground	Muddy	Temperature (°F)	73.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.30
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Flume Pipe	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Rock-lined Channel	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/3/2020 4:58 PM	Report #	13256
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. Deficiencies located at station number 11775+00 - clean water diversion pipe connection disconnected. Informed utility inspector and precision pipeline environmental Forman of issue. Item also added to MVP punchlist for repair. Rain gauge at Mount Tabor read 0.3 inches.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time	8/3/2020 4:58 PM	Report #	
Pictures					
					
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		11670+00		Field Station#	
Pic 1 Desc.		Triple stack CFS and priority one silt fence in place along LOD.		Pic 2 Desc.	
					
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		11767+00		Field Station#	
Pic 3 Desc.		RCE in place at Main Line Valve 26.		Pic 4 Desc.	
					
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		11775+00		Field Station#	
Pic 5 Desc.		Clean water diversion pipe disconnected. Item added to punchlist.		Pic 6 Desc.	

A/E	124300137	Date/Time	8/3/2020 4:58 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 12 Desc.	

A/E	124300137	Date/Time	8/3/2020 4:58 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13282
Inspector	Garrett Barclay			Date/Time	8/4/2020 2:13 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Damp	Temperature (°F)	78.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	1.80
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Secondary Containment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/4/2020 2:13 PM	Report #	13282
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for LDY 28 & 29 No damaged ECD's observed during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list Gathered rain gauge amounts					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	8/4/2020 2:13 PM	Report #	
Pictures					
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+1		Field Station#	+1	
Pic 1 Desc.	1.8" of rain recorded @ AR 234		Pic 2 Desc.	.2" of rain recorded @ Buffalo Anklets	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	+1		Field Station#	12005+00	
Pic 3 Desc.	.2" of rain recorded @ Kow Camp		Pic 4 Desc.	ECD's and row conditions @ LDY 28	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	ECD's and row conditions @ LDY 28		Pic 6 Desc.	ECD's and row conditions @ LDY 20	

A/E	124300137	Date/Time	8/4/2020 2:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	8/4/2020 2:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13286
Inspector	Jared Saunders			Date/Time	8/4/2020 3:03 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Partial	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	83.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.40
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/4/2020 3:03 PM	Report #	13286
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection at lay down yard 26. Checked equipment in yards for leaks. No leaks observed. All perimeter ECDs in place and functional. Secondary containment in place at stationary equipment. No deficiencies located during VA SWPPP inspection. Checked rain gauges at Mount Tabor - 0.2 inches and at Catawba Road - 0.4 inches.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	8/4/2020 3:03 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	Triple stack CFS in place around drainage feature.		Pic 2 Desc.	RCE in place at LDY 26 entrance.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	Secondary containment in place under fuel cell.		Pic 4 Desc.	Dumpsters being utilized for trash management.	
					
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11767+00		Field Station#	11990+00	
Pic 5 Desc.	Rain gauge at Mount Tabor Road reads 0.2 inches.		Pic 6 Desc.	Rain gauge at Catawba Road reads 0.4 inches.	

A/E	124300137	Date/Time	8/4/2020 3:03 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	8/4/2020 3:03 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13316
Inspector	Jared Saunders			Date/Time	8/5/2020 3:07 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10670+00
State	VA	Inspection Area	Partial	Station End	11023+80
County	Giles	Ground	Damp	Temperature (°F)	81.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/5/2020 3:07 PM	Report #	13316
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 201.7 to MP 203.6 and from MP 207 to MP 208.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. No deficiencies located during VA SWPPP inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	8/5/2020 3:07 PM	Report #	
Pictures					
 <p>Date & Time: Wed Aug 05 2020 3:07:00 EDT Position: +39.32261N -88.55577W (+88.55577) (+88.55577) Altitude: 2354ft (+161.4m) Datum: WGS-84 Azimuth/Bearing: 260 S80W 442mils True (+17.1) Elevation Angle: -05.0 Horizon Angle: +00.7 Zoom: 1.0X 11015+00 S-RR5</p>		 <p>Date & Time: Wed Aug 05 2020 3:07:00 EDT Position: +39.32261N -88.55577W (+88.55577) (+88.55577) Altitude: 2354ft (+161.4m) Datum: WGS-84 Azimuth/Bearing: 260 S80W 442mils True (+17.1) Elevation Angle: -05.0 Horizon Angle: +00.7 Zoom: 1.0X 11012+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11015+00		Field Station#	11012+00	
Pic 1 Desc.	Sensitive resource buffer in place at stream S-RR5		Pic 2 Desc.	Waterbar and end treatment in place.	
 <p>Date & Time: Wed Aug 05 2020 3:07:00 EDT Position: +39.32261N -88.55577W (+88.55577) (+88.55577) Altitude: 2354ft (+161.4m) Datum: WGS-84 Azimuth/Bearing: 260 S80W 442mils True (+17.1) Elevation Angle: -05.0 Horizon Angle: +00.7 Zoom: 1.0X 11005+00</p>		 <p>Date & Time: Wed Aug 05 2020 3:07:00 EDT Position: +39.32261N -88.55577W (+88.55577) (+88.55577) Altitude: 2354ft (+161.4m) Datum: WGS-84 Azimuth/Bearing: 260 S80W 442mils True (+17.1) Elevation Angle: -05.0 Horizon Angle: +00.7 Zoom: 1.0X 10966+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11005+00		Field Station#	10966+00	
Pic 3 Desc.	ROW stabilized with natural vegetation growth.		Pic 4 Desc.	Triple barrier ECDs in place at off ROW karst feature.	
 <p>Date & Time: Wed Aug 05 2020 3:07:00 EDT Position: +39.32261N -88.55577W (+88.55577) (+88.55577) Altitude: 2354ft (+161.4m) Datum: WGS-84 Azimuth/Bearing: 260 S80W 442mils True (+17.1) Elevation Angle: -05.0 Horizon Angle: +00.7 Zoom: 1.0X 10698+00</p>		 <p>Date & Time: Wed Aug 05 2020 3:07:00 EDT Position: +39.32261N -88.55577W (+88.55577) (+88.55577) Altitude: 2354ft (+161.4m) Datum: WGS-84 Azimuth/Bearing: 260 S80W 442mils True (+17.1) Elevation Angle: -05.0 Horizon Angle: +00.7 Zoom: 1.0X 10695+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10698+00		Field Station#	10695+00	
Pic 5 Desc.	Sensitive resource buffer in place at stream S-G32.		Pic 6 Desc.	RCE in place at Buffalo Anklets Road.	

A/E	124300137	Date/Time	8/5/2020 3:07 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	8/5/2020 3:07 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13317
Inspector	Garrett Barclay			Date/Time	8/5/2020 3:22 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10850+00
State	VA	Inspection Area	Partial	Station End	10929+62
County	Giles	Ground	Damp	Temperature (°F)	82.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/5/2020 3:22 PM	Report #	13317
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection from MP 205 - MP 207 Observed damaged ECD's during inspection Items sent to Environmental foreman and added to the punch list Row conditions are stable and showing good signs of vegetation Did not observe any signs of sediment outside of LOD or impacting any sensitive resources					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE 124300137		Date/Time	8/5/2020 3:22 PM	Report #	
Pictures					
					
GPS Location		See picture above for GPS coordinates		GPS Location	
Field Station#		10858+00		Field Station#	
Pic 1 Desc.		ECD's and row conditions		Pic 2 Desc.	
					
GPS Location		See picture above for GPS coordinates		GPS Location	
Field Station#		10885+00		Field Station#	
Pic 3 Desc.		Damaged P1		Pic 4 Desc.	
					
GPS Location		See picture above for GPS coordinates		GPS Location	
Field Station#		10898+00		Field Station#	
Pic 5 Desc.		ECD's and row conditions		Pic 6 Desc.	

A/E	124300137	Date/Time	8/5/2020 3:22 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	8/5/2020 3:22 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13320
Inspector	Chris Burns			Date/Time	8/5/2020 3:41 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Partial	Station End	11064+53
County	Giles	Ground	Dry	Temperature (°F)	83.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/5/2020 3:41 PM	Report #	13320
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 208.78 to MP 209.56 as well as assessed AR 245.01. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	8/5/2020 3:41 PM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11024+00	Field Station#	11025+50		
Pic 1 Desc.	Perimeter controls functional.	Pic 2 Desc.	S-IJ18 and controls.		
					
GPS Location	3	GPS Location	4		
Field Station#	11034+00	Field Station#	11049+00		
Pic 3 Desc.	Section of RoW showing conditions and controls.	Pic 4 Desc.	Section of RoW showing conditions and controls.		
					
GPS Location	5	GPS Location	6		
Field Station#	11050+10	Field Station#	11055+00		
Pic 5 Desc.	S-IJ16B/S-IJ17 and controls.	Pic 6 Desc.	Section of RoW showing conditions and controls.		

A/E	124300137	Date/Time	8/5/2020 3:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	8/5/2020 3:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13347
Inspector	Jared Saunders			Date/Time	8/6/2020 12:33 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11353+20
State	VA	Inspection Area	Partial	Station End	11524+25
County	Giles	Ground	Damp	Temperature (°F)	80.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/6/2020 12:33 PM	Report #	13347
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 215 to MP 218.3. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. Right of way has been stabilized using seed, mulch, and natural vegetation. Deficiencies located at station numbers 11473+25 - ECB on two-tone needs replaced, 11396+00 - Rock inlet needs cleaned out and waterbar needs built up, and from 11364+00 to 11362+00 - Waterbars need built up to ensure flow goes off ROW and CFS end treatments need replaced and extended. Checked rain gauges at Stevers Gap Road - 0.0 inches and at Mount Tabor Road - 0.1 inches.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	8/6/2020 12:33 PM	Report #	
Pictures					
					
<p>Date & Time: Thu, Aug 06, 2020, 08:48:10 EDT Position: +037.322277° / -080.439386° (+49.7m) Altitude: 2279ft (+40.6m) Datum: WGS-84 Azimuth/Bearing: 29° N59W 5173mils True (+12°) Elevation Angle: +02.6° Horizon Angle: -01.2° Zoom: 1.0X 11473+00</p>		<p>Date & Time: Thu, Aug 06, 2020, 08:57:17 EDT Position: +037.319159° / -080.440573° (+802.1m) Altitude: 2279ft (+40.6m) Datum: WGS-84 Azimuth/Bearing: 239° S59W 4249mils True (+12°) Elevation Angle: -10.0° Horizon Angle: -01.1° Zoom: 1.0X 11451+00 S-0012 & S-0013</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11473+25		Field Station#	11451+00	
Pic 1 Desc.	ECB on two tone needs replace.		Pic 2 Desc.	Sensitive resource buffer in place at stream S-0012 and S-0013.	
					
<p>Date & Time: Thu, Aug 06, 2020, 09:46:55 EDT Position: +037.316555° / -080.431409° (+490.4m) Altitude: 2183ft (+66.2m) Datum: WGS-84 Azimuth/Bearing: 35° N77W 3806mils True (+13°) Elevation Angle: -05.5° Horizon Angle: -01.4° Zoom: 1.0X 11489+00</p>		<p>Date & Time: Thu, Aug 06, 2020, 09:46:55 EDT Position: +037.316555° / -080.431409° (+490.4m) Altitude: 2183ft (+66.2m) Datum: WGS-84 Azimuth/Bearing: 35° N77W 3806mils True (+13°) Elevation Angle: -05.5° Horizon Angle: -01.4° Zoom: 1.0X 11489+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11489+00		Field Station#	11489+00	
Pic 3 Desc.	Rain gauge at Stevers Gap Road reads 0.0 inches.		Pic 4 Desc.	RCE in place at Stevers Gap Road.	
					
<p>Date & Time: Thu, Aug 06, 2020, 09:48:55 EDT Position: +037.310134° / -080.435663° (+49.6m) Altitude: 2270ft (+40.6m) Datum: WGS-84 Azimuth/Bearing: 317° N43W 5636mils True (+13°) Elevation Angle: -02.0° Horizon Angle: -00.9° Zoom: 1.0X 11396+00</p>		<p>Date & Time: Thu, Aug 06, 2020, 10:05:47 EDT Position: +037.294102° / -080.367868° (+43.6m) Altitude: 2016ft (+46.4m) Datum: WGS-84 Azimuth/Bearing: 015° N15E 0267mils True (+13°) Elevation Angle: -02.5° Horizon Angle: -01.5° Zoom: 1.0X 11767+00</p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11396+00		Field Station#	11767+00	
Pic 5 Desc.	Rock inlet needs cleaned out and waterbar needs built up to ensure water discharge off ROW.		Pic 6 Desc.	Rain gauge at Mount Tabor Road reads 0.1 inches.	

A/E	124300137	Date/Time	8/6/2020 12:33 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	8/6/2020 12:33 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13352
Inspector	Garrett Barclay			Date/Time	8/6/2020 3:35 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11064+53
State	VA	Inspection Area	Partial	Station End	11254+99
County	Giles	Ground	Damp	Temperature (°F)	80.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/6/2020 3:35 PM	Report #	13352
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection from MP 209 - MP 212.5 Observed damaged ECD's during inspection Items sent to Environmental foreman and added to the punch list Row conditions are stable and showing good signs of vegetation Did not observe any signs of sediment outside of LOD or impacting any sensitive resources					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	8/6/2020 3:35 PM	Report #	
Pictures					
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11080+00		Field Station#	11101+00	
Pic 1 Desc.	ECD's and row conditions		Pic 2 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11112+00		Field Station#	11217+00	
Pic 3 Desc.	ECD's and row conditions		Pic 4 Desc.	ECD's and row conditions	
					
GPS Location	See picture above for GPS coordinates		GPS Location	See picture above for GPS coordinates	
Field Station#	11226+00		Field Station#	11215+00	
Pic 5 Desc.	Build up on CFS end treatment		Pic 6 Desc.	Build up on CFS end treatment	

A/E	124300137	Date/Time	8/6/2020 3:35 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	8/6/2020 3:35 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13353
Inspector	Chris Burns			Date/Time	8/6/2020 3:54 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Partial	Station End	11353+67
County	Giles	Ground	Damp	Temperature (°F)	82.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.30
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock-lined Channel	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/6/2020 3:54 PM	Report #	13353
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 213.16 to MP 215.03 as well as assessed AR 256.02. No major issues were located. Nine locations of minor wildlife/weather impact to controls were identified. PPL Environmental Coordinator Mike Perry was notified and the items were added to the punch list. Crews are currently working in this area between Seven Oaks rd and AR 256.02 repairing ECDs, redressing and stabilizing the RoW. All other perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient less the areas that are being regraded and awaiting stabilization. No impact to sensitive resources observed. PM showers.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	8/6/2020 3:54 PM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11265+00	Field Station#	11309+00		
Pic 1 Desc.	Perimeter controls functional.	Pic 2 Desc.	Crews redressing RoW.		
					
GPS Location	3	GPS Location	4		
Field Station#	11327+85	Field Station#	11334+00		
Pic 3 Desc.	S-NN12 and controls.	Pic 4 Desc.	Section of RoW showing conditions and controls.		
					
GPS Location	5	GPS Location	6		
Field Station#	11349+00	Field Station#	11352+97		
Pic 5 Desc.	Perimeter controls functional.	Pic 6 Desc.	S-NN11 and controls.		

A/E	124300137	Date/Time	8/6/2020 3:54 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	8/6/2020 3:54 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13385
Inspector	Rob Robertson			Date/Time	8/7/2020 1:55 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11600+01
State	VA	Inspection Area	Full	Station End	11670+00
County	Montgomery	Ground	Damp	Temperature (°F)	82.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/7/2020 1:55 PM	Report #	13385
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
Completed a regular scheduled VADEQ SWPPP inspection on JNF and private lands at Brush Mountain. The ROW is currently stable. No erosion is taking place. No slips have occurred. ECDs are in place, functional and in acceptable condition. Resource crossings have stable, well vegetated buffers with environmental controls in place. RCEs are in good condition. There was no evidence of vandalism or trespass.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE		124300137	Date/Time		8/7/2020 1:55 PM	Report #					
Pictures											
											
Date & Time: Fri Aug 07, 2020, 09:41:00 EDT Position: +037.313798° / +080.377568° (+16.4ft) Altitude: 2231ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 120° S05E 3182mils Magnetic (+19°) Elevation Angle: -02.4° Horizon Angle: -02.3° Zoom: 1.0X Brush Mtn. ROW stable at FS188 road. 11669+87			Date & Time: Fri Aug 07, 2020, 09:58:00 EDT Position: +037.313798° / +080.376360° (+132.8ft) Altitude: 2588ft (+29.4ft) Datum: WGS-84 Azimuth/Bearing: 341° N19W 4062mils Magnetic (+12°) Elevation Angle: -21.6° Horizon Angle: -00.9° Zoom: 1.0X Brush Mtn. Slope breakers functioning properly. 11662+00								
GPS Location			On photo			GPS Location			On photo		
Field Station#			11669+87			Field Station#			11662+00		
Pic 1 Desc.			Stable conditions at top of Brush Mountain. No trespass or vandalism identified.			Pic 2 Desc.			Slope breakers and perimeter controls effective		
											
Date & Time: Fri Aug 07, 2020, 10:14:00 EDT Position: +037.313798° / +080.422233° (+16.4ft) Altitude: 2231ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 120° S01E 3182mils Magnetic (+12°) Elevation Angle: -07.3° Horizon Angle: -04.2° Zoom: 1.0X Brush Mtn. Perimeter controls in place and functioning properly. 11645+00			Date & Time: Fri Aug 07, 2020, 10:50:01 EDT Position: +037.313798° / +080.402233° (+16.4ft) Altitude: 1912ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 085° N05E 1511mils Magnetic (+13°) Elevation Angle: -14.0° Horizon Angle: -01.2° Zoom: 1.0X ROW stable. ECDs in place. 11614+75								
GPS Location			On photo			GPS Location			On photo		
Field Station#			11645+00			Field Station#			11614+75		
Pic 3 Desc.			End treatments are working as designed			Pic 4 Desc.			End treatments are working properly		
											
Date & Time: Fri Aug 07, 2020, 10:38:56 EDT Position: +037.314099° / +080.396509° (+19.4ft) Altitude: 1902ft (+157.5ft) Datum: WGS-84 Azimuth/Bearing: 191° S11W 3396mils Magnetic (+12°) Elevation Angle: -05.3° Horizon Angle: -02.3° Zoom: 1.0X S-006 crossing stable. 11626+04			Date & Time: Fri Aug 07, 2020, 10:42:08 EDT Position: +037.313554° / +080.406712° (+16.4ft) Altitude: 1918ft (+26.2ft) Datum: WGS-84 Azimuth/Bearing: 143° S37E 2542mils Magnetic (+14°) Elevation Angle: -07.2° Horizon Angle: -01.4° Zoom: 1.0X S-006 crossing stable. ECDs in place.								
GPS Location			On photo			GPS Location			On photo		
Field Station#			11626+04			Field Station#			11608+17		
Pic 5 Desc.			Resource crossings stable. ECDs in place at buffers and equipment bridges.			Pic 6 Desc.			S-006 crossing stable with no impact.		

A/E	124300137	Date/Time	8/7/2020 1:55 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	8/7/2020 1:55 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13388
Inspector	Chris Burns			Date/Time	8/7/2020 2:18 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Partial	Station End	12005+00
County	Montgomery	Ground	Damp	Temperature (°F)	82.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.50
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/7/2020 2:18 PM	Report #	13388
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
See photos for GPS coordinates. Met with environmental staff. Performed SWPPP inspection from MP 223.27 to 227.37 as well as assessed AR 266. No issues were located. All perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient, No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	8/7/2020 2:18 PM	Report #	
Pictures					
					
GPS Location	1	GPS Location	2		
Field Station#	11792+00	Field Station#	11825+00		
Pic 1 Desc.	Section of restored RoW showing conditions and controls.		Pic 2 Desc.	Section of restored RoW showing conditions and controls.	
					
GPS Location	3	GPS Location	4		
Field Station#	11863+65	Field Station#	11906+00		
Pic 3 Desc.	P-KL2 and controls.		Pic 4 Desc.	Section of semi restored RoW showing conditions and controls.	
					
GPS Location	5	GPS Location	6		
Field Station#	11973+00	Field Station#	11991+00		
Pic 5 Desc.	Section of semi restored RoW showing conditions and controls.		Pic 6 Desc.	Section of restored RoW showing conditions and controls.	

A/E	124300137	Date/Time	8/7/2020 2:18 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	8/7/2020 2:18 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13389
Inspector	Garrett Barclay			Date/Time	8/7/2020 2:41 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+16
State	VA	Inspection Area	Partial	Station End	11600+01
County	Giles	Ground	Damp	Temperature (°F)	81.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Flume Pipe	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/7/2020 2:41 PM	Report #	13389
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Arrived at LDY 26 for morning meeting Performed SWPPP inspection for MP 218 - MP 219.5 Observed no damaged ECD's during inspection Row conditions are stable and showing good signs of vegetation No signs of sediment outside of LOD or impacting any sensitive resources No new items added to punch list Gathered rain gauge amounts					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	8/7/2020 2:41 PM	Report #	
Pictures					
 <p>Date & Time: Fri, Aug 07, 2020 10:36:28 EDT Position: +037.249157° / -089.52681° (+38.4ft) Altitude: 2057ft (+36.5ft) Datum: WGS-84 Azimuth/Bearing: 158° S22E 2809mils True (+13°) Elevation Grade: -015° Horizon Grade: -005° Zoom: 10X 11530</p>		 <p>Date & Time: Fri, Aug 07, 2020, 08:45:46 EDT Position: +037.239157° / -089.519197° (+18.2ft) Altitude: 2163ft (+41.2ft) Datum: WGS-84 Azimuth/Bearing: 130° S55E 2801mils True (+16°) Elevation Grade: +124° Horizon Grade: -003° Zoom: 10X 11530</p>			
GPS Location	See picture above for GPS coordinates	GPS Location	See picture above for GPS coordinates		
Field Station#	+1	Field Station#	11530+00		
Pic 1 Desc.	No rain recorded	Pic 2 Desc.	ECD's and row conditions		
 <p>Date & Time: Fri, Aug 07, 2020, 08:45:46 EDT Position: +037.247723° / -089.515547° (+15.3ft) Altitude: 2055ft (+37.2ft) Datum: WGS-84 Azimuth/Bearing: 266° N14W 6151mils True (+13°) Elevation Grade: +044° Horizon Grade: -000° Zoom: 10X 11553</p>		 <p>Date & Time: Fri, Aug 07, 2020, 08:14:46 EDT Position: +037.222708° / -089.514311° (+18.1ft) Altitude: 2169ft (+41.3ft) Datum: WGS-84 Azimuth/Bearing: 072° S08E 3000mils True (+13°) Elevation Grade: +025° Horizon Grade: -025° Zoom: 10X 11563</p>			
GPS Location	See picture above for GPS coordinates	GPS Location	See picture above for GPS coordinates		
Field Station#	11553+00	Field Station#	11563+00		
Pic 3 Desc.	ECD's and row conditions	Pic 4 Desc.	ECD's and row conditions		
 <p>Date & Time: Fri, Aug 07, 2020, 09:21:12 EDT Position: +037.217912° / -089.512998° (+15.3ft) Altitude: 2048ft (+37.0ft) Datum: WGS-84 Azimuth/Bearing: 148° S20E 3044mils True (+10°) Elevation Grade: -032° Horizon Grade: -002° Zoom: 10X 11567 epp22</p>		 <p>Date & Time: Fri, Aug 07, 2020, 09:43:00 EDT Position: +037.217912° / -089.512998° (+15.3ft) Altitude: 2048ft (+37.0ft) Datum: WGS-84 Azimuth/Bearing: 167° S13E 2869mils True (+13°) Elevation Grade: +034° Horizon Grade: -003° Zoom: 10X 11584</p>			
GPS Location	See picture above for GPS coordinates	GPS Location	See picture above for GPS coordinates		
Field Station#	11567+00	Field Station#	11584+00		
Pic 5 Desc.	ECD's and row conditions	Pic 6 Desc.	ECD's and row conditions		

A/E	124300137	Date/Time	8/7/2020 2:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	8/7/2020 2:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	13349
Inspector	Jared Saunders			Date/Time	8/7/2020 2:48 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11788+50
County	Montgomery	Ground	Wet	Temperature (°F)	80.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.50
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Flume Pipe	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	8/7/2020 2:48 PM	Report #	13349
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted VA SWPPP inspection from MP 221 to MP 223.8. Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed. No forward progress has been completed due to FERC shut down. ROW has been stabilized using seed, mulch, and minor vegetation growth. No deficiencies located during VA SWPPP inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	8/7/2020 2:48 PM	Report #	
Pictures					
<p>Date & Time: Fri, Aug 07, 2020, 10:57:42 EDT Position: +037 2497427 / -080 390914 (+1175.6ft) Altitude: 2566ft (+1130) Datum: WGS-84 Azimuth/Bearing: 140° S40E 2489mils True (+14°) Elevation Angle: -13.1° Horizon Angle: -05.0° Zoom: 1.0X 11670+00</p>		<p>Date & Time: Fri, Aug 07, 2020, 10:57:42 EDT Position: +037 2497427 / -080 390914 (+1175.6ft) Altitude: 2566ft (+1130) Datum: WGS-84 Azimuth/Bearing: 140° S40E 2489mils True (+14°) Elevation Angle: -13.1° Horizon Angle: -05.0° Zoom: 1.0X 11670+00</p>			
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		11670+00		Field Station#	
Pic 1 Desc.		Triple stack compost filter sock and priority one silt fence in place along LOD.		Pic 2 Desc.	
<p>Date & Time: Fri, Aug 07, 2020, 11:00:09 EDT Position: +037 2497427 / -080 390914 (+1175.6ft) Altitude: 2566ft (+1130) Datum: WGS-84 Azimuth/Bearing: 140° S40E 2489mils True (+14°) Elevation Angle: -13.1° Horizon Angle: -05.0° Zoom: 1.0X 11681+00</p>		<p>Date & Time: Fri, Aug 07, 2020, 11:04:00 EDT Position: +037 2497427 / -080 390914 (+1175.6ft) Altitude: 2579ft (+1228) Datum: WGS-84 Azimuth/Bearing: 129° S01E 3182mils True (+15°) Elevation Angle: -14.9° Horizon Angle: -00.4° Zoom: 1.0X 11687+00</p>			
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		11681+00		Field Station#	
Pic 3 Desc.		ROW stabilized with mulch and vegetation growth.		Pic 4 Desc.	
<p>Date & Time: Fri, Aug 07, 2020, 11:04:53 EDT Position: +037 2497427 / -080 390914 (+1175.6ft) Altitude: 2566ft (+1130) Datum: WGS-84 Azimuth/Bearing: 130° S02E 1920mils True (+16°) Elevation Angle: -10.0° Horizon Angle: -00.0° Zoom: 1.0X 11767+00</p>		<p>Date & Time: Fri, Aug 07, 2020, 11:14:53 EDT Position: +037 2497427 / -080 390914 (+1175.6ft) Altitude: 2288ft (+1108) Datum: WGS-84 Azimuth/Bearing: 202° S22W 3591mils True (+16°) Elevation Angle: -07.0° Horizon Angle: -00.0° Zoom: 1.0X 11724+00</p>			
GPS Location		See photo for GPS location.		GPS Location	
Field Station#		11767+00		Field Station#	
Pic 5 Desc.		RCE in place at Mount Tabor Road.		Pic 6 Desc.	
				Top soil pile disturbed by landowner 3rd party contractor stabilized with seed, mulch and vegetation growth.	

A/E	124300137	Date/Time	8/7/2020 2:48 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	8/7/2020 2:48 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		