Mour Mour	tain Valley		Visua	al S	ite In	specti	on Re	epo	rt			
Project Nar	ne H-600 Pipe	eline Spread I		AF	E 12430	0139	Spre	ead	H-600 Pipe	eline	Spread I	
Contract	or Precision				•		Repoi	port # 11151				
Inspect	or Glenn Mike	e Renfro					Date/Ti	ate/Time 7/22/2020 11:4			11 AM	
Permit #	TBD		Inspection T	уре	VA SWPF)	Station	Begi	n 00000-	+00		
State	VA		Inspection A	rea	Full		Statio	n En	d 0000+	00		
County	Franklin		Gro	round Dry Temperature (°F)						90.00		
Municipality	N/A		Weat	/eather Light Rain Rain Gauge (in)						0.50		
					Rain Accumulation Time (days)						6.00	
1. Are the appre	oved (stampe	d) E&S Plan a	and PCSM Plar	n pres	ent on si	te?					Yes	
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No					
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							g	Yes				
4. E&S BMPs (is required.)						•			n is need	led,	a picture	
E	&S BMPs	С	ompliance Level	Corrective Action				Corrective Time Frame		R	Date epaired	
Compost Filter So	ock	Aco	ceptable									
Housekeeping		Aco	ceptable									
Roadside Ditch		Acc	ceptable									
Rock Constructio	n Entrance	Acc	ceptable									
Compost Sedime	nt Trap	Acc	ceptable									
Secondary Conta	inment	Acc	ceptable									
5. Site Conditi	ons	<u> </u>	<u> </u>				ļ			•		
Is an unauthoriz beyond defined a photo and imn	limits of distu	rbance resulti	ng from earth d	listurk	ance act	ivity or ine	-				No	
Have inactive di	sturbed areas	s (stockpiles, f	inal grade) bee	n sta	bilized pe	er state req	uirements	s?			N/A	
Are slopes 3:1 a	and greater sta	abilized with a	ppropriate BMF	s as	per E&S	plans?					N/A	
Has a new slip/s	slide been obs	served? (If ye	s, complete Sli	de R	eport For	m)					No	

AFE 124300139	Date	Time 7/22/2020 11:41 AM	Report # 111	Report # 11151				
6. PCSM BMPs (List BMPs and note if	installed and	maintained as per the plan. If corre	ctive action is nee	eded, a				
picture is required.) PCSM BMPs	Compliance	Corrective Action	Corrective Time Frame	Date Repaired				
				riopan oa				
7. Identify all remedial measures that h	ave been take	n since the previous inspection was	s conducted.					
Comments (Reference above question	s as appropria	e.)						
Performed SWPPP inspection of Spread I main laydown yard in Rocky Mount, Va. The location received .50" of rainfall since the last inspection. All perimeter ECD's were inspected and no issues were observed. The inlet protection for the parking lot drains in the paved yard were in good condition. All secondary containment structures were found to be in compliance at the time of inspection. The RCE at the gravel yard was in acceptable condition. The General Construction permits and contact information are posted at the entrance of the paved yard as required. The were no issues found to report during today's inspection.								
Note: It is a condition of National Pollut	ant Discharge	Flimination System and Frosion an	d Sediment nerm	ite that a				

weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a

AFE 12430013	9	Date/Time 7	7/22/2020 11:41 <i>P</i>	AM	Report #				
		Pictu	ıres						
GPS Location	00000000000		GPS Location	000000000000					
Field Station#			Field Station#						
Pic 1 Desc.	Perimeter ECD's in the northwes paved yard in good condition	et corner of	Pic 2 Desc.	Inlet protection structure near s condition	and secondar storage buildin	y containment g in acceptable			
				, ,					
GPS Location	00000000000	(GPS Location	000000000000					
Field Station#			Field Station#						
Pic 3 Desc.	Secondary containment structure in compliance	e for fuel cell	Pic 4 Desc.	RCE at gravel y	yard in good c	ondition			
			Insert image here						
GPS Location	00000000000		GPS Location						
Field Station#			Field Station#						
Pic 5 Desc.	Perimeter ECD's on west side of good condition	gravel yard in	Pic 6 Desc.						

AFE 124300139		Date/Time 7/22/2020 11:41 A	λM	Report #					
		Pictures							
	Insert image here		Insert image here						
GPS Location		GPS Location							
Field Station#		Field Station#							
Pic 7 Desc.		Pic 8 Desc.							
	Insert image here		Insert im	age here					
GPS Location		GPS Location							
Field Station#		Field Station#							
Pic 9 Desc.		Pic 10 Desc.							
	Insert image here		Insert im	age here					
GPS Location		GPS Location							
Field Station#		Field Station#							
Pic 11 Desc.		Pic 12 Desc.							

AFE 124300139		Date/Time 7/22/2020 11:4	1 AM	Report #					
		Pictures							
	Insert image here		Insert image here						
GPS Location		GPS Locatio	n						
Field Station#		Field Station	#						
Pic 13 Desc.		Pic 14 Desc							
	Insert image here			nage here					
GPS Location		GPS Locatio	n						
Field Station#		Field Station	#						
Pic 15 Desc.		Pic 16 Desc							
	Insert image here		Insert im	nage here					
GPS Location		GPS Locatio	n						
Field Station#		Field Station	#						
Pic 17 Desc.		Pic 18 Desc							

Mour Mour	ntai Va	n lley			Visu	ual S	Site	Ins	specti	on R	ерс	ort		
Project Nar	ne H-	600 Pipe	eline Sprea	d I		Al	FE 1:	24300	139	Sp	read	H-600 Pi	peline	Spread I
Contract	or Pro	ecision				•				Rep	ort #	12862		
Inspect	or Lo	gan Box								Date/1	Гime	7/22/202	0 5:1	1 PM
Permit #	TBD				Inspection	Туре	VA S	WPP		Statio	n Beg	in 1367	0+00	
State	VA				Inspection	Area	Partia	al		Stati	ion Eı	nd 1385	3+45	
County	Frankl	lin			Gı	round	Dry				Temp	erature	(°F)	94.00
Municipality	N/A				We	YeatherSunnyRain Gauge (in)				1.70				
						Rain Accumulation Time (days)						6.00		
1. Are the appr	oved (stampe	d) E&S Pla	an ar	nd PCSM PI	lan pre	sent o	on site	e?					Yes
2. Are there act (If yes, notify)		No
 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a page 1. 							Yes							
4. E&S BMPs (is required.)	(List B	MPs and	d note if in			ntained	as pe	er the	plan. If o	correctiv			ded,	a picture
E	&S BN	1Ps		Со	mpliance Level		Corr	rectiv	e Action			rective Frame	R	Date epaired
Equipment Bridge	Э			Acce	eptable									
Compost Filter So	ock			Acce	eptable									
Silt Fence (Filter	Fabric	Fence)		Acce	eptable									
5. Site Conditi	ons													
ls an unauthoriz beyond defined a photo and imn	limits (of distur	bance res	sultin	g from earth	n disturl	bance	e activ	ity or ine	-				No
Have inactive di	sturbe	d areas	(stockpile	es, fir	nal grade) b	een sta	bilize	d per	state req	luiremer	nts?			Yes
Are slopes 3:1 a				-			•							Yes
Has a new slip/s	slide b	een obs	erved? (I	f yes	, complete S	Slide R	eport	Form	1)					No

AFE 124300139	Date/Time	e 7/22/2020 5:11 PM	Report # 128	362
6. PCSM BMPs (List BMPs and n	ote if installed and main	tained as per the plan. If co	rrective action is ne	eded, a
picture is required.) PCSM BMPs	Compliance	Corrective Action	Corrective	Date
	Level		Time Frame	Repaired
_				
			+	
7. Identify all remedial measures	that have been taken sir	nce the previous inspection w	vas conducted.	
Comments (Reference above que	stions as appropriate.)			
Fraveled and inspected all ECDs thro	_			
nspected all stream and wetland cros				
Talked with environmental crews as the nstalled correctly.	ney worked to make repair	s to punch list items and inspec	ted ECDs to be sure t	hey were
Fotal measurable rainfall for this perio	od is 1.7".			

maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a

AFE 12430013	9 Date/Ti	me 7/22/2020 5:11 P	M Report #
	Pi	ctures	
GPS Location	00000	GPS Location	00000
Field Station#		Field Station#	
Pic 1 Desc.	Checked equipment bridges while monitoring row conditions.	Pic 2 Desc.	Stream crossing photo facing downstream after recent rain events
GPS Location	00000	GPS Location	0000
Field Station#	13678+71	Field Station#	13748+97
Pic 3 Desc.	Stream crossing photo facing upstream after rain events	Pic 4 Desc.	Monitored stream crossing at Green Level rd.
	Insert image here		Insert image here
GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 5 Desc.		Pic 6 Desc.	

AFE 124300139		Date/Time 7/22	ne 7/22/2020 5:11 PM Report #						
		Picture	es						
	Insert image here		Insert image here						
GPS Location		GF	PS Location						
Field Station#		Fie	eld Station#						
Pic 7 Desc.		P	Pic 8 Desc.						
	Insert image here		,	Insert im	age here				
GPS Location		GF	PS Location						
Field Station#		Fie	eld Station#						
Pic 9 Desc.		Pi	ic 10 Desc.						
	Insert image here			Insert im	age here				
GPS Location		GF	PS Location						
Field Station#		Fie	eld Station#						
Pic 11 Desc.		Pi	ic 12 Desc.						


AFE 124300139		Date/Time 7/	ne 7/22/2020 5:11 PM Report #						
		Pictu	res						
	Insert image here		Insert image here						
GPS Location		G	GPS Location						
Field Station#		F	Field Station#						
Pic 13 Desc.		1	Pic 14 Desc.						
,	Insert image here		,	Insert im	age here				
GPS Location		G	SPS Location						
Field Station#		F	Field Station#						
Pic 15 Desc.		1	Pic 16 Desc.						
	Insert image here			Insert im	age here				
GPS Location		G	GPS Location						
Field Station#		F	Field Station#		-	_			
Pic 17 Desc.		1	Pic 18 Desc.						

Mour Mour	ntain Valley		Visu	ıal S	Site	e Ins	specti	ion R	ерс	ort			
Project Nar	ne H-600 P	peline Spread	J I	Al	FE	124300)139	Spr	read	H-600 Pip	eline	Spread I	
Contract	or Precision	1						Repo	ort#	12892			
Inspect	or Justin B	ırch			Date/			Date/T	Time 7/22/2020 10:26 AM			26 AM	
Permit #	TBD		Inspection	Туре	e VA SWPP Statio			Station	n Beg	in 14694	+77		
State	VA		Inspection	Area	Full			Stati	on Eı	nd 15142	+66		
County	Franklin/Pitt	sylvania	Gr	ound	Dry			7	Temp	erature (F)	93.00	
Municipality	Chatham		We	eather Sunny Rain Gauge (in)					in)	0.10			
				Rain Accumulation Time (days)						6.00			
1. Are the appr	oved (stam	oed) E&S Pla	an and PCSM Pl	an pre	sent	on site	e?					Yes	
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)								No					
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being								Yes					
4. E&S BMPs (is required.)	(List BMPs a	nd note if in	stalled and main	tained	as p	er the	e plan. If o	corrective	e acti	on is need	led,	a picture	
Εŧ	&S BMPs		Compliance Level	I CORRECTIVE ACTION I				R	Date epaired				
Equipment Bridge	Э		Acceptable										
Waterbar			Acceptable										
Cleanwater Diver	sion Pipe		Acceptable										
Slope Drain Pipe			Acceptable										
5. Site Conditi		a /al	ا در د د مساوی	a::	<u> </u>		<u> </u>	ulus av 4 -	-4c	ا برجائمین			
beyond defined	limits of dis	urbance res	ediment, gravel, ulting from earth Environmental Pe	distur	banc	e acti	vity or ine	-				No	
Have inactive di	sturbed are	as (stockpile	es, final grade) be	een sta	abiliz	ed per	state rec	quiremen	its?			Yes	
Are slopes 3:1 a	and greater	stabilized wit	th appropriate BN	MPs as	s per	E&S	olans?					Yes	
Has a new slip/s	slide been o	bserved? (If	f yes, complete S	Slide R	epor	t Form	n)					No	

AFE 1243	00139	Date/Tir	me 7/22/2020 10:26 AM	Report # 128	92
	BMPs (List BMPs and note if ir s required.)	nstalled and ma	intained as per the plan. If corr	ective action is nee	eded, a
picture		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
		LOVOI		Time Traine	Repuired
7. Identify	L all remedial measures that have	ve been taken s	since the previous inspection wa	as conducted.	
	(Reference above questions a				
- Since las		fall was recorded	o 15142+66. I at Indian Cave Road, and 0.00" w PP which was addressed by the co		
complia	nce at the time of inspection.		ECDs, maintaining waterbars, dipp		
equipme Creek R	nt bridges, and seeding and mulc	ching denuded ar	eas of the ROW between Indian Ca	ave Road and the CI	S of Snow
		_	mination System and Erosion and Deration and maintenance of all		
			st in the space provided comme		

replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.




AFE 124300139		Date/Time 7/22/2020 10	:26 AM	Report #	
		Pictures			
	Insert image here		Insert im	nage here	
GPS Location		GPS Locat	ion		
Field Station#		Field Station	on#		
Pic 7 Desc.		Pic 8 Des	с.		
	Insert image here			nage here	
GPS Location		GPS Locat	ion		
Field Station#		Field Station	on#		
Pic 9 Desc.		Pic 10 Des	sc.		
	Insert image here		Insert im	nage here	
GPS Location		GPS Locat	ion		
Field Station#		Field Stati	on#		_
Pic 11 Desc.		Pic 12 Des	SC.		

AFE 124300139		Date/Time 7/22/2020 10:26	AM	Report #						
		Pictures								
	Insert image here		Insert image here							
GPS Location		GPS Location								
Field Station#		Field Station#	ŧ							
Pic 13 Desc.		Pic 14 Desc.								
	Insert image here			age here						
GPS Location		GPS Location								
Field Station#		Field Station#	!							
Pic 15 Desc.		Pic 16 Desc.								
	Insert image here		Insert im	age here						
GPS Location		GPS Location								
Field Station#		Field Station#	±							
Pic 17 Desc.		Pic 18 Desc.								

Mour Mour	ntair Val	ley			Visu	ual S	Site	e Ins	sp	ecti	on R	epc	ort		
Project Nar	ne H-60	00 Pipe	eline Sprea	d I		Al	FE	124300)139	9	Sp	read	H-60	0 Pipelin	e Spread I
Contract	or Pred	cision				•					Rep	ort #	1289	3	
Inspect	or Ran	dall Gr	еу								Date/	Time	7/22/	2020 3:3	0 PM
Permit #	TBD				Inspection	Туре	VA	SWPP			Statio	n Beg	jin 1	4311+57	
State	VA				Inspection	Area	Par	tial			Stat	ion Eı	nd 1	4694+77	
County	Franklir	1			Gr	ound	Dry					Temp	erati	ure (ºF)	94.00
Municipality	N/A				We	ather	ther Sunny Rain Gauge (in)						0.65		
									R	ain Ac	cumul	4.00			
1. Are the appro	oved (s	tampe	d) E&S Pl	an a	nd PCSM PI	an pre	sent	on sit	e?						Yes
2. Are there act (If yes, notify			-									-	?		No
3. Is Constructi followed? (If														being	Yes
4. E&S BMPs (is required.)	(List BM	Ps and	d note if in	nstall	led and main	ntained	as	er the	e pla	an. If o	correctiv	e acti	on is	needed,	a picture
E	&S BMF	Ps		Co	ompliance Level		Со	rrectiv	re A	Action		Cor Time	recti Fra		Date Repaired
Vegetative Stabili	ization (1	Гетро	rary)	Acce	eptable										
Equipment Bridge	Э			Acce	eptable										
Sump Pit				Acce	eptable										
Plunge Pool				Acce	eptable										
5 0 to 0 == 1111															
5. Site Conditi		L ·	/aak			-0.05	<u> </u>		- \			4			
Is an unauthoriz beyond defined a photo and imn	limits of	distu	bance res	sultin	ng from earth	disturl	ban	ce acti	vity	or ine	-				No
Have inactive di	sturbed	areas	s (stockpile	es, fii	nal grade) be	een sta	abiliz	ed pei	r sta	ate req	uiremei	nts?			Yes
Are slopes 3:1 a					•					ns?					Yes
Has a new slip/s	slide be	en obs	served? (I	f yes	s, complete S	Slide R	еро	rt Form	า)						No

AFE 124300139	Date/Ti	me 7/22/2020 3:30 PM	Report # 128	FE 124300139											
6. PCSM BMPs (List BMPs and note if	installed and ma	nintained as per the plan. If corre	ctive action is nee	eded, a											
picture is required.)															
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired											
7. Identify all remedial measures that h	ave been taken :	L since the previous inspection was	conducted.												
Comments (Reference above questions	s as appropriate.)													
Performed SWPPP inspection on portion of	Spread I.	17/47/00 0.05% T. I. D. I.	D 17/47/00 0	10"											
Rain total since Thursday 7/16/20 equals 0.0 Perimeter controls and ECDs were inspected	d and any issues	found were forwarded to the contract	or for repair.												
Sections of right of way will continuously be the punch list.	monitored checking	ng water bars, sumps, temporary stab	oilization, and ECD	s to update											
·															

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.



AFE 124300139		Date/Time 7/22/20	20 3:30 PM	Report #						
		Pictures								
	Insert image here		Insert image here							
GPS Location		GPS L	ocation							
Field Station#		Field	Station#							
Pic 7 Desc.		Pic 8	Desc.							
	Insert image here			mage here						
GPS Location		GPS L	ocation							
Field Station#		Field	Station#							
Pic 9 Desc.		Pic 10) Desc.							
	Insert image here		Insert i	mage here						
GPS Location		GPS L	ocation							
Field Station#		Field	Station#							
Pic 11 Desc.		Pic 12	2 Desc.							

AFE 124300139		Date/Time 7/22/2020 3:30 PI	7/22/2020 3:30 PM Report #							
		Pictures								
	Insert image here		Insert im	age here						
GPS Location		GPS Location								
Field Station#		Field Station#			,					
Pic 13 Desc.		Pic 14 Desc.								
	Insert image here		Insert im	age here						
GPS Location		GPS Location								
Field Station#		Field Station#								
Pic 15 Desc.		Pic 16 Desc.								
	Insert image here		Insert im	age here						
GPS Location		GPS Location								
Field Station#		Field Station#								
Pic 17 Desc.		Pic 18 Desc.								

Mour Mour	tain Valley		Visu	ıal S	Site	Ins	specti	on R	epc	rt		
Project Nar	ne H-603 Pip	eline Spread I		Al	FE 12	24300	139	Spr	ead	H-603 Pipe	line	Spread I
Contract	or Precision							Repo	ort#	12898		
Inspect	or John Whit	е						Date/T	ime	7/22/2020 :	5:00	PM
Permit #	TBD		Inspection	Туре	۷A S۱	NPP		Station	n Beg	in 00+00		
State	VA		Inspection	Area	Full			Statio	on Er	24+53		
County	Pittsylvania		Gr	ound	Dry			7	Гетр	erature (º	F)	95.00
Municipality	Chatham		We	ather	Sunny	y			Rain	Gauge (i	n)	0.00
						Rain Accumulation Time (days)						
1. Are the appro	oved (stampe	ed) E&S Plan	and PCSM Pla	an pres	sent o	n site	9?					Yes
2. Are there act (If yes, notify			the limits of dermitting Coor						ings?			No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)										Yes		
4. E&S BMPs (is required.)	(List BMPs an	d note if insta	alled and main	tained	as pe	r the	plan. If o	corrective	e actio	on is need	ed,	a picture
E	&S BMPs	C	Compliance Level		Corre	ectiv	e Action			rective Frame		Date epaired
Compost Filter So	ock	Ac	ceptable									
Housekeeping		Ac	ceptable									
Sensitive Resour	ce Signage	Ac	ceptable									
Vegetative Stabili	ization (Tempo	rary) Ac	ceptable									
Waterbar		Ac	ceptable									
Waterbar End Tre	eatment	Ac	ceptable									
5. Site Conditi	ons											
Is an unauthoriz beyond defined a photo and imn	limits of distu	rbance resulti	ing from earth	disturl	bance	activ	ity or ine	-				No
Have inactive di	sturbed areas	s (stockpiles,	final grade) be	een sta	bilize	d per	state req	uiremen	ts?			Yes
Are slopes 3:1 a					•						\Box	Yes
Has a new slip/s	slide been ob	served? (If ye	es, complete S	Slide R	eport	Form	1)					No

AFE 124300139	Date/Time	7/22/2020 5:00 PM	Report # 128	Report # 12898				
PCSM BMPs (List BMPs and note picture is required.)	if installed and main	tained as per the plan. If cor	rective action is ne	eded, a				
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired				
. Identify all remedial measures that	have been taken sin	ce the previous inspection w	as conducted.					
comments (Reference above question erformed SWPPP Inspection on this line								
enormed GWITT Inspection on this line	. There were no issues	to report at the time of inspect	OII.					

replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139	9	Date/Time	7/22/2020 5:00 PM	М	Report #	
		Pict	ures			
GPS Location	0	- HC	GPS Location	0		
Field Station#			Field Station#			
Pic 1 Desc.	Observing temporary vegetation	and signage.	Pic 2 Desc.	Observing tem	nporary vegetation	on.
GPS Location	0		GPS Location	0		
Field Station#			Field Station#			
Pic 3 Desc.	Observing water bar and end treat performing as they should.	atment	Pic 4 Desc.	Observing ECI	D's performing a	s they should.
	Insert image here			Insert im	age here	
GPS Location			GPS Location			
Field Station#			Field Station#			
Pic 5 Desc.			Pic 6 Desc.			

AFE 124300139		Date/Time 7/22/2	020 5:00 PM		Report #	
		Pictures	5			
	Insert image here			Insert ima	age here	
GPS Location		GPS	Location			
Field Station#		Field	I Station#			
Pic 7 Desc.		Pic	8 Desc.			
	Insert image here			Insert ima	age here	
GPS Location		GPS	Location			
Field Station#		Field	l Station#			
Pic 9 Desc.		Pic	10 Desc.			
	Insert image here			Insert ima	age here	
GPS Location		GPS	Location			
Field Station#		Field	I Station#			
Pic 11 Desc.		Pic	12 Desc.			

AFE 124300139		Date/Time 7/22/2020 5:00 PI	7/22/2020 5:00 PM Report #							
		Pictures								
	Insert image here		Insert im	age here						
GPS Location		GPS Location								
Field Station#		Field Station#								
Pic 13 Desc.		Pic 14 Desc.								
	Insert image here		Insert im	age here						
GPS Location		GPS Location								
Field Station#		Field Station#								
Pic 15 Desc.		Pic 16 Desc.								
	Insert image here		Insert im	age here						
GPS Location		GPS Location								
Field Station#		Field Station#								
Pic 17 Desc.		Pic 18 Desc.								

Mour Mour	ntai Va	n lley			Visu	ual S	Site	e Ins	spect	ion F	Repo	ort			
Project Nar	ne H-	-602 Pipe	line Spread	d I		Al	FE	124300	139	Sp	oread	H-602 P	ipeline	e Spread I	
Contract	or Pr	ecision				•				Rep	ort #	12899			
Inspect	or Jo	ohn White)							Date/	Time	7/22/202	20 5:0	00 PM	
Permit #	TBD				Inspection	Туре	VA S	SWPP		Statio	n Beg	jin 00+0	00		
State	VA				Inspection	Area	Full			Stat	tion E	nd 19+2	23		
County	Pittsy	Ivania			Gı	round	Dry				Temp	erature	(°F)	95.00	
Municipality	Chath	nam			We	eather	Sunny Rain Gauge (in)						0.00		
									Rain A	ccumul	ation	Time (d	ays)	4.00	
1. Are the appr	oved ((stampe	d) E&S Pla	an ar	nd PCSM PI	lan pre	sent	on site	e?					Yes	
2. Are there act (If yes, notify			-								-	>		No	
3. Is Constructi followed? (If	No, n	otify MV	P Environ	ment	al Permittin	g Coor	dina	tor and	d explain	in comr	ments.)		Yes	
4. E&S BMPs (is required.)	(List B	BMPs and	d note if in			ntained	as p	er the	plan. If	correcti			eded,	a picture	
E	&S BN	/IPs		Со	mpliance Level		Cor	rectiv	e Actior	1		rective Frame	R	Date Repaired	
Compost Filter So	ock			Acce	ptable										
Equipment Bridge	Э			Acce	ptable										
Housekeeping				Acce	ptable										
Sensitive Resour	ce Sig	nage		Acce	ptable										
Vegetative Stabili	ization	(Tempor	ary)	Acce	ptable										
5. Site Conditi	ons														
Is an unauthoriz beyond defined a photo and imn	limits	of distur	bance res	sulting	g from earth	n disturl	banc	e acti	vity or ine	-				No	
Have inactive di	sturbe	ed areas	(stockpile	es, fir	nal grade) b	een sta	abiliz	ed per	state re	quireme	nts?			Yes	
Are slopes 3:1 a									'					Yes	
Has a new slip/s	slide b	een obs	erved? (I	f yes	, complete S	Slide R	epor	t Form	1)					No	

AFE 124300139	Date/T	ime 7/22/2020 5:00 PM	Report # 128	Report # 12899				
6. PCSM BMPs (List BMPs and note picture is required.)	if installed and m	naintained as per the plan. If cor	rective action is ne	eded, a				
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired				
		 						
	+	1						
		1						
	+							
7. Identify all remedial measures that	have been taken	since the previous inspection w	vas conducted.					
Comments (Reference above question Performed SWPPP Inspection on this line.		<u> </u>	•					
Note: It is a condition of National Pollumaintenance program be conducted to	_							
veekly basis and after each stormwater								

replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 12430013	39 Date/Time 7/22/2020 5:00 PM Report #						
		Pictu	ıres				
GPS Location	0		GPS Location	0			
Field Station#			Field Station#				
Pic 1 Desc.	Observing temporary vegetation.		Pic 2 Desc.	Observing tem	iporary vegetati	ion.	
GPS Location	0		GPS Location	0			
Field Station#	10+50		Field Station#	12+65			
Pic 3 Desc.	Observing temporary vegetation a	and signage.	Pic 4 Desc.	Observing equiperforming as	ipment crossin they should.	g and ECD's	
	Insert image here			Insert im	age here		
GPS Location			GPS Location				
Field Station#			Field Station#				
Pic 5 Desc.			Pic 6 Desc.				

AFE 124300139		Date/Time 7/22/20	ime 7/22/2020 5:00 PM Report #						
		Pictures							
	Insert image here		Insert image here						
GPS Location		GPS	_ocation						
Field Station#		Field	Station#						
Pic 7 Desc.		Pic	B Desc.						
	Insert image here			nsert image here					
GPS Location		GPS	_ocation						
Field Station#		Field	Station#						
Pic 9 Desc.		Pic 1	0 Desc.						
	Insert image here		lr	nsert image here					
GPS Location		GPS	_ocation						
Field Station#		Field	Station#						
Pic 11 Desc.		Pic 1	2 Desc.						

AFE 124300139)	Date/Time 7/22/2020 5:00 PI	e 7/22/2020 5:00 PM Report #						
		Pictures							
	Insert image here		Insert image here						
GPS Location		GPS Location							
Field Station#		Field Station#							
Pic 13 Desc.		Pic 14 Desc.							
	Insert image here		Insert im	age here					
GPS Location		GPS Location							
Field Station#		Field Station#							
Pic 15 Desc.		Pic 16 Desc.							
	Insert image here		Insert im	age here					
GPS Location		GPS Location							
Field Station#		Field Station#	_	_	_				
Pic 17 Desc.		Pic 18 Desc.							

Moun	Mountain Valley Visual Site Inspection Report											
Project Nan	ne	H-600 Pipe	eline Spread	1	Al	FE 124300)139	Spre	ead	H-600 Pipe	eline	Spread I
Contract	or	Precision			•	•		Repo	rt #	12901		
Inspect	or	John White	Э						ime	7/22/2020	5:00) PM
Permit #	ТВІ	D		Inspection	Туре	VA SWPP		Station	Begin 15584+23			
State	VA			Inspection	Area	Full		Statio	on Er	16027-	+46	
County	Pitt	sylvania		Gr	ound	Dry		Т	emp	erature (º	PF)	95.00
Municipality	Cha	atham		We	ather	Sunny			Rain	Gauge (i	in)	0.30
							Rain Ac	cumulat	tion 1	Γime (day	rs)	4.00
1. Are the appro	ove	d (stampe	d) E&S Pla	n and PCSM Pl	an pre	sent on sit	e?					Yes
2. Are there act (If yes, notify			-	of the limits of d Permitting Coo					ings?			No
3. Is Construction followed? (If		•		the construction			•		•	•	g	Yes
4. E&S BMPs (is required.)	(List	BMPs and	d note if in:	stalled and main	itained	as per the	e plan. If o	corrective	actio	on is need	led,	a picture
E&	ß.	BMPs		Compliance Level		Correctiv	e Action			rective Frame	Date Repaired	
Cleanwater Diver	sion	ı Pipe	1	Acceptable								
Compost Filter So	ock			Acceptable								
Equipment Bridge	e		,	Acceptable								
Housekeeping			,	Acceptable								
Rock-lined Chanr	nel		,	Acceptable								
Rock Filter Outlet	•			Acceptable								
Silt Fence (Filter I	Fab	ric Fence)		Acceptable								
Silt Fence (Reinfo	orce	Filter Fenc	e)	Acceptable								
5. Site Condition	ons	3										
Is an unauthoriz beyond defined a photo and imm	limi	ts of distur	bance res	ulting from earth	distur	bance acti	vity or inet					No
Have inactive dis	stur	bed areas	(stockpile	s, final grade) be	een sta	ıbilized peı	r state req	uirement	ts?			Yes
Are slopes 3:1 a	ınd	greater sta	abilized wit	h appropriate Bl	MPs as	per E&S	plans?					Yes
Has a new slip/s	slide	been obs	erved? (If	yes, complete S	Slide R	eport Form	า)					No

AFE 124300139	Date/Time	e 7/22/2020 5:00 PM	Report # 12901				
PCSM BMPs (List BMPs and note picture is required.)	rective action is ne	eded, a					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired			
. Identify all remedial measures that	have been taken sir	nce the previous inspection w	as conducted.				
omments (Reference above question							
erformed SWPPP Inspection on this sec	don. There were no iss	sues to report at the time of msp	ection.				

replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 12430013	9	Date/Time 7	7/22/2020 5:00 PM	Л	Report #	
		Pictu	ires			
GPS Location	0	O	GPS Location	0		
Field Station#			Field Station#			
Pic 1 Desc.	Observing ECD's performing as t	they should.	Pic 2 Desc.	Observing CW as they should	D outlet and E0	CD's performing
GPS Location	0	0	GPS Location	0		
Field Station#	15837+00	F	Field Station#	15838+50		
Pic 3 Desc.	Observing ECD's performing as t		Pic 4 Desc.	Observing equiperforming as	ipment crossing they should.	g and ECD's
	Insert image here			Insert ima	age here	
GPS Location		G	GPS Location			
Field Station#		F	Field Station#			
Pic 5 Desc.			Pic 6 Desc.			

AFE 124300139		Date/Time 7/22/20	ime 7/22/2020 5:00 PM Report #						
		Pictures							
	Insert image here		Insert image here						
GPS Location		GPS	_ocation						
Field Station#		Field	Station#						
Pic 7 Desc.		Pic	B Desc.						
	Insert image here			nsert image here					
GPS Location		GPS	_ocation						
Field Station#		Field	Station#						
Pic 9 Desc.		Pic 1	0 Desc.						
	Insert image here		lr	nsert image here					
GPS Location		GPS	_ocation						
Field Station#		Field	Station#						
Pic 11 Desc.		Pic 1	2 Desc.						

AFE 124300139		Date/Time 7	rate/Time 7/22/2020 5:00 PM Report #					
		Pictu	ıres					
	Insert image here			Insert im	age here			
GPS Location		(GPS Location					
Field Station#			Field Station#					
Pic 13 Desc.			Pic 14 Desc.					
	Insert image here		,	Insert im	age here			
GPS Location		•	GPS Location					
Field Station#			Field Station#					
Pic 15 Desc.			Pic 16 Desc.					
	Insert image here			Insert im	age here			
GPS Location		(GPS Location					
Field Station#			Field Station#					
Pic 17 Desc.			Pic 18 Desc.					

Moun	V	ain Valley		Visu	ıal S	Site Ins	specti	on Re	epo	rt		
Project Nan	ne	H-600 Pipe	eline Spread		Al	FE 124300)139	Spre	ead	H-600 Pipe	eline	Spread I
Contract	or	Precision			•	•		Repo	rt#	12903		
Inspect	or	Charles He	ead					Date/Ti	ime	7/22/2020	11:5	53 AM
Permit #	ТВІ	D		Inspection	Туре	VA SWPP		Station				
State	VA			Inspection	Area	Full		Statio	on En	14311-	-57	
County	Fra	ınklin		Gr	ound	Dry		Т	empe	erature (º	F)	89.00
Municipality	N/A	4		We	ather	Sunny			Rain	Gauge (i	n)	0.80
							Rain Ac	cumulat	tion T	ime (day	s)	6.00
1. Are the appro	ove	d (stampe	d) E&S Pla	n and PCSM Pl	an pre	sent on site	e?					Yes
2. Are there act (If yes, notify			•	of the limits of d Permitting Coo					ings?			No
3. Is Construction followed? (If		•		the construction nental Permitting			•		•	•	9	Yes
4. E&S BMPs (is required.)	List	BMPs and	d note if in	stalled and main	tained	as per the	e plan. If o	corrective	actio	n is need	ed,	a picture
E8	&S I	BMPs		Compliance Level		Correctiv	e Action			ective Frame	R	Date epaired
Compost Filter So	ock		(Communication								
3rd Party Damage	es		(Communication								
Equipment Bridge)		,	Acceptable								
Silt Fence (Filter I	Fab	ric Fence)	,	Acceptable								
Silt Fence (Reinfo	orce	Filter Fenc	e)	Acceptable								
Vegetative Stabili	zati	on (Tempo	rary)	Acceptable								
Erosion Control B	lanl	ket		Acceptable								
Waterbar			,	Acceptable								
Waterbar End Tre	eatm	nent		Acceptable								
5. Site Condition	ons	<u> </u>										
Is an unauthorized beyond defined la photo and imm	limi	ts of distu	bance res	ulting from earth	distur	bance acti	vity or inet	-				No
Have inactive dis	stur	bed areas	s (stockpile	s, final grade) be	een sta	abilized per	state req	uirement	ts?			Yes
Are slopes 3:1 a						•						Yes
Has a new slip/s	lide	been obs	served? (If	yes, complete S	Slide R	eport Form	า)					No

AFE 124300139	Date/Ti	me 7/22/2020 11:53 AM	Report # 129	03
6. PCSM BMPs (List BMPs and note if in picture is required.)	nstalled and ma	aintained as per the plan. If corre		
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
				Tropuls.
7. Identify all remedial measures that ha	ve been taken	ı since the previous inspection was	conducted.	
Comments (Reference above questions	as appropriate.)		
SWPPP inspection of Spread I. Inspection was water bars, sumps, end treatments, CWDs, s Seeding and stabilization practices are prograstreams running clean and clear of sediment	stabilization and sessing. Contracto	seeding activities, and general ROW or has addressed and continues to ad	conditions. BMPs lis	sted above.
Note: It is a condition of National Pollutar	nt Discharge El	imination System and Erosion and	d Sediment perm	its that a

MVP-34 REV 3 Page 2 of 5

maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139	9	Date/Time	7/22/2020 11:53 A	AM	Report #	
•		Pict	ures			
GPS Location	0		GPS Location	0		
Field Station#			Field Station#			
Pic 1 Desc.	Approximately 14009+20. Overvious crossing, equipment bridge and E stream S-KL38.		Pic 2 Desc.	water bar, sum	14007+75. Ove ap and end treatment abilized and has	
GPS Location	0		GPS Location	0		
Field Station#			Field Station#			
Pic 3 Desc.	Approximately 13991+69. Overvious crossing, equipment bridge and E stream S-KL35.		Pic 4 Desc.	adjacent pond	14000+00. Ove overflow path flot te flow at time of	owing onto
GPS Location	0		GPS Location	0		
Field Station#	14157+55		Field Station#	14162+00		
Pic 5 Desc.	Approximately 14157+55. Overvious crossing, equipment bridge and E stream S-KL51.		Pic 6 Desc.			rview of ROW. d has temporary

MVP-34 REV 3 Page 3 of 5

AFE 12430013	9	Date/Time 7	7/22/2020 11:53 A	M	Report #	
		Pictu	ires			
GPS Location	0	C	GPS Location	0		
Field Station#			Field Station#			
Pic 7 Desc.	Approximately 13928+50-13939+ party has bush hogged a section this area.	+50. Third of ROW in	Pic 8 Desc.	damaged multi	13939+50. Thir ple sections of IVP-ATWS-126	CFS along the
				Cite		
GPS Location	0	C	GPS Location	0		
Field Station#			Field Station#			
Pic 9 Desc.	Approximately 13939+50. Third phogged MVP-ATWS-1263 and MVP-ATWS-1264.		Pic 10 Desc.	Approximately has bush hogg	13899+00-1390 ed entire ROW.	07. Third party
	Insert image here			Insert ima	age here	
GPS Location			GPS Location			
Field Station#		-	Field Station#			
Pic 11 Desc.			Pic 12 Desc.			

MVP-34 REV 3 Page 4 of 5

AFE 124300139		Date/Time	ne 7/22/2020 11:53 AM Report #				
		Pict	ures				
	Insert image here			Insert im	age here		
GPS Location			GPS Location				
Field Station#			Field Station#				
Pic 13 Desc.			Pic 14 Desc.				
	Insert image here			Insert im	age here		
GPS Location			GPS Location				
Field Station#			Field Station#				
Pic 15 Desc.			Pic 16 Desc.				
	Insert image here			Insert im	age here		
GPS Location			GPS Location				
Field Station#			Field Station#				
Pic 17 Desc.			Pic 18 Desc.				

MVP-34 REV 3 Page 5 of 5

Mour Mour	Ntain Valley		Visu	ıal S	Site I	ns	specti	on R	epc	ort		
Project Nar	ne H-600 Pipe	eline Spread I		Al	FE 124	300	139	Spr	ead	H-600 Pipe	eline	Spread I
Contract	or Precision			•				Repo	ort#	12915		
Inspect	or Ben Dave	nport						Date/T	ime	7/22/2020	5:00	PM
Permit #	TBD		Inspection	Туре	VA SW	PP		Station	n Beg	in 15142+	-66	
State	VA		Inspection	Area	Partial			Statio	on Er	nd 15584-	-23	
County	Pittsylvania		Gr	ound	Dry			1	Гетр	erature (º	F)	89.00
Municipality	Chatham		We	eather Sunny				Rain	Gauge (i	n)	0.30	
			•				Rain Ad	cumula	tion ⁻	Γime (day	s)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes						
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No						
	Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes						
4. E&S BMPs (is required.)	(List BMPs and	d note if insta	alled and main	tained	as per	the	plan. If o	corrective	e actio	on is need	ed,	a picture
E	RS BMPs	C	Compliance Level		Correc	ctiv	e Action			rective Frame	R	Date epaired
Equipment Bridge	Э	Ac	ceptable									
Silt Fence (Filter	Fabric Fence)	Ac	ceptable									
Compost Filter So	ock	Ac	ceptable									
Vegetative Stabili	ization (Permar	nent) Ac	ceptable									
Sediment Filter L	og	Ac	ceptable									
5. Site Conditi	ons											
Is an unauthoriz beyond defined a photo and imn	limits of distu	rbance result	ing from earth	disturl	bance a	activ	ity or ine	-				No
Have inactive di	sturbed areas	s (stockpiles,	final grade) be	een sta	bilized	per	state req	uiremen	ts?			Yes
Are slopes 3:1 a			• • •		•						\blacksquare	Yes
Has a new slip/s	siide been obs	served? (It ye	es, complete S	siide R	eport Fo	orm	1)					No

MVP-34 REV 3 Page 1 of 5

AFE 124300139	Date/Tir	ne 7/22/2020 5:00 PM	Report # 129)15
PCSM BMPs (List BMPs and note if picture is required.)	installed and ma	intained as per the plan. If cor	rective action is ne	eded, a
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
7. Identify all remedial measures that h	nave been taken s	since the previous inspection w	as conducted.	

Comments (Reference above questions as appropriate.)

- -Performed SWPPP inspection of portion of Spread I section
- -Multiple rain events occurred during inspection period; see rain log for totals in all sections
- -Sunny with dry ground conditions during inspection
- -Perimeter controls and ECD's were inspected and any maintenance was forwarded to the contractor for repair
- -Inspection observed condition of water bars, sumps, and end treatments along ROW
- -Continue to monitor ROW for signs of erosion
- -Environmental crews continue to perform environmental maintenance along entire ROW
- -Multiple environmental issues observed and items added to environmental punch list
- -Issues identified in previous SWPPP Report were communicated and continue to be addressed by contractor
- -EI team continues to travel ROW to identify environmental maintenance and compliance issues. All issues identified will continue to be communicated to contractor for completion

Snowberry Rd rain gauge rainfall totals during inspection period: 0.30 inches recorded

+7/20/20 : 0.20 inches recorded + 7/22/20 : 0.10 inches recorded

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

MVP-34 REV 3 Page 2 of 5

AFE 124300139	9	Date/Time	7/22/2020 5:00 PI	М	Report #	
		Pict	ures		•	
GPS Location	1		GPS Location	2		
Field Station#	15346+80		Field Station#	15346+80		
Pic 1 Desc.	Equipment bridge and surroundir stream crossing S-H13 and resortance and functional.	ng ECD's at urce buffer in	Pic 2 Desc.	Upstream view	v of S-H13	
GPS Location	3		GPS Location	4		
Field Station#			Field Station#			
Pic 3 Desc.	Downstream view of S-H13		Pic 4 Desc.	View of perma ROW CIS HDI place and fund	nent vegetation gro D drill exit site. Peri ctional.	owing along meter CFS in
GPS Location	5		GPS Location	6		
Field Station#			Field Station#			
Pic 5 Desc.	Equipment bridge and surroundir stream crossing S-CC5 and reso place and functional.	ng ECD's at ource buffer in	Pic 6 Desc.	Equipment brid stream crossin place and fund	dge and surrounding S-CC9 and resortional.	ig ECD's at urce buffer in

MVP-34 REV 3 Page 3 of 5

AFE 124300139		Date/Time 7/22/2	ne 7/22/2020 5:00 PM Report #				
		Pictures	5				
	Insert image here			Insert ima	age here		
GPS Location		GPS	Location				
Field Station#		Field	I Station#				
Pic 7 Desc.		Pic	8 Desc.				
	Insert image here			Insert ima	age here		
GPS Location		GPS	Location				
Field Station#		Field	l Station#				
Pic 9 Desc.		Pic	10 Desc.				
	Insert image here			Insert ima	age here		
GPS Location		GPS	Location				
Field Station#		Field	I Station#				
Pic 11 Desc.		Pic	12 Desc.				

MVP-34 REV 3 Page 4 of 5

AFE 124300139		Date/Time 7/22/2020 5:00 PI	ne 7/22/2020 5:00 PM Report #				
		Pictures					
	Insert image here		Insert im	age here			
GPS Location		GPS Location					
Field Station#		Field Station#					
Pic 13 Desc.		Pic 14 Desc.					
	Insert image here		Insert im	age here			
GPS Location		GPS Location					
Field Station#		Field Station#					
Pic 15 Desc.		Pic 16 Desc.					
	Insert image here		Insert im	age here			
GPS Location		GPS Location					
Field Station#		Field Station#					
Pic 17 Desc.		Pic 18 Desc.					

MVP-34 REV 3 Page 5 of 5

Mour Mour	nta V	alley		Visu	ual S	Site	Ins	specti	on Re	epc	ort		
Project Nar	ne	Transco In	terconnect S	Station	Al	FE 12	4300	113	Spre	ead	Transco Int	erco	onnect Sta
Contract	or	Kanahwa			•	•			Repo	rt #	12900		
Inspect	or	John White)						Date/Ti	ime	7/22/2020 5	5:00	PM
Permit #	TBE)		Inspection	Туре	VA SV	VPP		Station	Beg	in 00+00		
State	VA			Inspection	Area	Full			Statio	n Er	nd 00+00		
County	Pitts	sylvania		Gı	ound	Dry			Т	emp	erature (º	F)	95.00
Municipality	Cha	ıtham		We	ather	Sunny	,			Rain	Gauge (i	n)	0.00
					Rain Accumulation Time (days)				s)	4.00			
1. Are the appro	ovec	d (stampe	d) E&S Pla	n and PCSM Pl	an pre	sent o	n site	∍?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No							
followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes							
E&S BMPs (is required.)	List	BMPs and	d note if ins	stalled and mair	ntained	as pe	r the	plan. If o	corrective	actio	on is neede	ed,	a picture
, ,	&S E	BMPs		Compliance Level	I Corrective Action I		Corrective Action Corrective Time Frame			Re	Date epaired		
Compost Filter So	ock		,	Acceptable									
Erosion Control B	Blank	et	,	Acceptable									
Housekeeping			,	Acceptable									
Rock Check Dam	1		,	Acceptable									
Silt Fence (Filter	Fabr	ic Fence)	ı	Acceptable									
Vegetative Stabili	izatio	on (Tempoi	rary) ,	Acceptable									
Rock Constructio	n En	trance	,	Acceptable									
									$\frac{1}{2}$				
5. Site Condition	ons				<u> </u>								
Is an unauthoriz beyond defined a photo and imn	limit	s of distur	bance resi	ulting from earth	distur	bance	activ	ity or ine	-				No
Have inactive di	sturl	bed areas	(stockpile:	s, final grade) b	een sta	abilized	l per	state req	uirement	s?			Yes
Are slopes 3:1 a	and g	greater sta	abilized wit	h appropriate Bl	MPs as	per E	&S p	olans?					Yes
Has a new slip/s	slide	been obs	erved? (If	yes, complete \$	Slide R	eport F	orm	1)					No

MVP-34 REV 3 Page 1 of 5

	Date/Time	7/22/2020 5:00 PM	Report # 12900		
5. PCSM BMPs (List BMPs and note picture is required.)	if installed and main	tained as per the plan. If cor	rective action is ne	eded, a	
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
. Identify all remedial measures that	have been taken sin	ce the previous inspection w	as conducted.		
Comments (Reference above question on the Transport of the Transport		There were no icours	t- remark at the time	-f lasa action	
onomica evi i i mapecaeri en are mar	1000 Facility and Eay a	own yara. There were no issues	to roport at the time	or mopodion.	

MVP-34 REV 3 Page 2 of 5

replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 12430011	3	Date/Time	7/22/2020 5:00 Pf	M Report #
		Pict	ures	
GPS Location	0		GPS Location	0
Field Station#			Field Station#	
Pic 1 Desc.	Observing RCE.		Pic 2 Desc.	Observing storm water pond.
0001			000:	
GPS Location	0		GPS Location	0
Field Station#	00+00		Field Station#	00+00
Pic 3 Desc.	Observing emergency overflow at twater pond.	the storm	Pic 4 Desc.	Observing rock check dam and ECD's performing as they should.
				Insert image here
GPS Location	O		GPS Location	
Field Station#	00+00		Field Station#	
Pic 5 Desc.	Observing drainage channel and E performing as they should.	ECD's	Pic 6 Desc.	

MVP-34 REV 3 Page 3 of 5

AFE 124300113		Date/Time 7/	/22/2020 5:00 PM	1	Report #				
Pictures									
Insert image here			Insert image here						
GPS Location		G	SPS Location						
Field Station#		F	Field Station#						
Pic 7 Desc.			Pic 8 Desc.						
,	Insert image here		,	Insert im	age here				
GPS Location		G	SPS Location						
Field Station#		F	Field Station#						
Pic 9 Desc.		1	Pic 10 Desc.						
	Insert image here			Insert im	age here				
GPS Location		<u> </u>	GPS Location						
Field Station#		F	Field Station#						
Pic 11 Desc.		1	Pic 12 Desc.						

MVP-34 REV 3 Page 4 of 5

AFE 124300113	24300113 Date/Time		М	Report #					
Pictures									
	Insert image here		Insert image here						
GPS Location		GPS Location							
Field Station#		Field Station#			,				
Pic 13 Desc.		Pic 14 Desc.							
	Insert image here		Insert im	age here					
GPS Location		GPS Location							
Field Station#		Field Station#							
Pic 15 Desc.		Pic 16 Desc.							
	Insert image here		Insert im	age here					
GPS Location		GPS Location							
Field Station#		Field Station#							
Pic 17 Desc.		Pic 18 Desc.							

MVP-34 REV 3 Page 5 of 5