



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20551	
<b>Inspector</b> Len Kruizenga		<b>Date/Time</b> 3/1/2021 2:34 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 11254+99	
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b> 11158+27	
<b>County</b> Giles	<b>Ground</b> Muddy	<b>Temperature (°F)</b> 51.00	
<b>Municipality</b> N/A	<b>Weather</b> Light Rain	<b>Rain Gauge (in)</b> 1.95	
<b>Rain Accumulation Time (days)</b>			3.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 3/1/2021 2:34 PM	<b>Report #</b> 20551
----------------------	-----------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Met with EI's at Winding Way:  
 SWPPP inspection area: Sta# 11254+99 to 11158+27. MP- 213 to 211  
 The row received 2 inches of rain over three days leaving the row muddy. Stabilization has kept the row in good condition.  
 Perimeter controls, silt fence, CFS, SSF are in acceptable condition.  
 Water bars, sump pits, end treatments are in acceptable condition.  
 Slope drains are in acceptable condition.  
 CWD pipe and plunge pool are in acceptable condition.  
 Rock channel is in acceptable condition.  
 Access roads- Winding Way, AR-249.02, AR- 249.01 are in acceptable condition.  
 Buffalo Anklets rain gauge reading- 2.00"  
 AR-234.00 rain gauge reading- 1.80"  
 Winding Way rain gauge reading- 1.95"

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	3/1/2021 2:34 PM	<b>Report #</b>	
------------	-----------	------------------	------------------	-----------------	--

## Pictures





<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo
<b>Field Station#</b>	11232+00	<b>Field Station#</b>	11225+00
<b>Pic 1 Desc.</b>	Row and controls	<b>Pic 2 Desc.</b>	Slope drain inlet and rock channel.



<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS
<b>Field Station#</b>	11203+00	<b>Field Station#</b>	11190+00
<b>Pic 3 Desc.</b>	CFS perimeter controls and end treatments, topsoil stockpiles	<b>Pic 4 Desc.</b>	Sensitive resource/ drainage feature and ECD's.



<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS
<b>Field Station#</b>	11184+50	<b>Field Station#</b>	11184+00
<b>Pic 5 Desc.</b>	AR-249.02- Access road and rock check dams.	<b>Pic 6 Desc.</b>	CWD pipe and plunge pool

AFE 124300137		Date/Time 3/1/2021 2:34 PM		Report #	
Pictures					
<small>Date &amp; Time: Mon, March 01, 2021 13:45:09 EST            Position: +037.349151, -080.683519, 6261.410            Altitude: 2067ft (=629ft)            Datum: WGS-84            Azimuth/Bearing: 128.852E 22°/mils True (±10°)            Elevation Angle: -12.4            Horizon Angle: -00.8            Zoom: 1.0X            Buffalo Anklets rain gauge reading- 2.00"</small> 		<small>Date &amp; Time: Mon, March 01, 2021 10:58:23 EST            Position: +037.378637, -080.678170, 638.01ft            Altitude: 1770ft (=539ft)            Datum: WGS-84            Azimuth/Bearing: 004. N04E 0071mils True (±15°)            Elevation Angle: -26.2            Horizon Angle: -06.3            Zoom: 1.0X            AR-234.00-1.80"</small> 			
<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS		
<b>Field Station#</b>	11671+00	<b>Field Station#</b>	12005+00		
<b>Pic 7 Desc.</b>	Buffalo Anklets rain gauge reading- 2.00"	<b>Pic 8 Desc.</b>	AR-234.00 rain gauge reading- 1.80"		
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here			Insert image here		
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>AFE</b> 124300137	<b>Date/Time</b> 3/1/2021 2:34 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>	<b>GPS Location</b>
<b>Field Station#</b>	<b>Field Station#</b>
<b>Pic 13 Desc.</b>	<b>Pic 14 Desc.</b>

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>	<b>GPS Location</b>
<b>Field Station#</b>	<b>Field Station#</b>
<b>Pic 15 Desc.</b>	<b>Pic 16 Desc.</b>

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>	<b>GPS Location</b>
<b>Field Station#</b>	<b>Field Station#</b>
<b>Pic 17 Desc.</b>	<b>Pic 18 Desc.</b>



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20552	
<b>Inspector</b> Chris Burns		<b>Date/Time</b> 3/1/2021 2:55 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 11254+99	
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b> 11353+67	
<b>County</b> Giles	<b>Ground</b> Muddy	<b>Temperature (°F)</b> 51.00	
<b>Municipality</b> N/A	<b>Weather</b> Light Rain	<b>Rain Gauge (in)</b> 2.00	
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	Repair damaged silt fence	24 Hours	
Silt Fence (Reinforced Filter Fabric Fence)	Problem Area			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Communication	Repair end treatment	24 Hours	

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 3/1/2021 2:55 PM	<b>Report #</b> 20552
----------------------	-----------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

See photos for GPS coordinates.  
 Met with environmental staff.  
 Performed SWPPP inspection from MP 213.16 to MP 215.03 as well as assessed the Seven Oaks access road.  
 Three locations of minor damage to controls were identified. Lead EI Brian Shields, Utility Inspectors Mark Woodley and Billy Hayes as well as PPL Environmental Coordinator Mike Perry were notified and the items added to the punch list.  
 All other perimeter controls, ECDs and BMPs are functional. Vegetation or stabilization sufficient. No impact to sensitive resources observed.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	3/1/2021 2:55 PM	<b>Report #</b>	
------------	-----------	------------------	------------------	-----------------	--

## Pictures



<b>GPS Location</b>	1	<b>GPS Location</b>	2
<b>Field Station#</b>	11265+00	<b>Field Station#</b>	11292+80
<b>Pic 1 Desc.</b>	Perimeter controls functional.	<b>Pic 2 Desc.</b>	S-MM18 and controls.



<b>GPS Location</b>	3	<b>GPS Location</b>	4
<b>Field Station#</b>	11309+00	<b>Field Station#</b>	11317+05
<b>Pic 3 Desc.</b>	End treatment falling into sump.	<b>Pic 4 Desc.</b>	Wildlife/livestock damage to P-1.



<b>GPS Location</b>	5	<b>GPS Location</b>	6
<b>Field Station#</b>	11323+00	<b>Field Station#</b>	11300+00
<b>Pic 5 Desc.</b>	Perimeter controls functional.	<b>Pic 6 Desc.</b>	Section of RoW showing conditions and controls.



<b>AFE</b> 124300137	<b>Date/Time</b> 3/1/2021 2:55 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/1/2021 2:55 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20558	
<b>Inspector</b> Jared Saunders		<b>Date/Time</b> 3/1/2021 3:26 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 11353+24	
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b> 11524+16	
<b>County</b> Giles	<b>Ground</b> Muddy	<b>Temperature (°F)</b> 51.00	
<b>Municipality</b> N/A	<b>Weather</b> Light Rain	<b>Rain Gauge (in)</b> 2.00	
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Broad-Based Dip	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Communication	Repair undermined end treatment	Addressed	3/1/2021
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 3/1/2021 3:26 PM	<b>Report #</b> 20558
----------------------	-----------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from MP 215 to MP 218.3.  
 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed.  
 No forward progress has been completed due to FERC shut down.  
 Right of way has been stabilized using seed, mulch, and natural vegetation.  
 Deficiency located at station number 11484+00 - Undermined end treatment.  
 Checked rain gauges at Stevers Gap Road - 2 inches, Mount Tabor Road - 1.8 inches, and Catawba Road - 1.8 inches.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	3/1/2021 3:26 PM	Report #
<b>Pictures</b>				
 <p><small>Date &amp; Time: Mon, Mar 01, 2021, 08:43:23 EST Position: +037.326147 / -080.426841 (±19.4ft) Altitude: 2220ft (±68.1ft) Datum: WGS-84 Azimuth/Bearing: 32° N25E 048mils True (±11°) Elevation Angle: +0.1° Horizon Angle: +01.1° Zoom: 1.0X 11474+00</small></p>	 <p><small>Date &amp; Time: Mon, Mar 01, 2021, 08:44:02 EST Position: +037.326147 / -080.426841 (±19.4ft) Altitude: 2200ft (±68.0ft) Datum: WGS-84 Azimuth/Bearing: 29° N22W 529mils True (±2°) Elevation Angle: +6.9° Horizon Angle: -01.3° Zoom: 1.0X 11484+00</small></p>			
<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11474+00	<b>Field Station#</b>	11484+00	
<b>Pic 1 Desc.</b>	Two-tone stabilized with ECB and slope drains in place.	<b>Pic 2 Desc.</b>	Waterbar end treatment in undermined.	
 <p><small>Date &amp; Time: Mon, Mar 01, 2021, 08:49:31 EST Position: +037.326257 / -080.426879 (±15.8ft) Altitude: 2222ft (±68.2ft) Datum: WGS-84 Azimuth/Bearing: 005° N05E 008mils True (±1.4°) Elevation Angle: -17.9° Horizon Angle: +00.0° Zoom: 1.0X 11505+00</small></p>	 <p><small>Date &amp; Time: Mon, Mar 01, 2021, 08:49:39 EST Position: +037.326789 / -080.431442 (±17.1ft) Altitude: 2155ft (±66.2ft) Datum: WGS-84 Azimuth/Bearing: 282° N77W 503mils True (±1.0°) Elevation Angle: -06.0° Horizon Angle: +00.4° Zoom: 1.0X 11489+00</small></p>			
<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11505+00	<b>Field Station#</b>	11489+00	
<b>Pic 3 Desc.</b>	Clean water diversion pipe and plunge pool in place.	<b>Pic 4 Desc.</b>	Rain gauge at Stevers Gap Road reads 2 inches.	
 <p><small>Date &amp; Time: Mon, Mar 01, 2021, 09:07:22 EST Position: +037.326481 / -080.346979 (±38.3ft) Altitude: 2147ft (±65.8ft) Datum: WGS-84 Azimuth/Bearing: 066° N66E 117mils True (±1.4°) Elevation Angle: -16.1° Horizon Angle: -01.1° Zoom: 1.0X Tabor</small></p>	 <p><small>Date &amp; Time: Mon, Mar 01, 2021, 09:08:22 EST Position: +037.326231 / -080.323627 (±36.6ft) Altitude: 1703ft (±51.8ft) Datum: WGS-84 Azimuth/Bearing: 166° S14E 2951mils True (±1.4°) Elevation Angle: -01.3° Horizon Angle: +00.0° Zoom: 1.0X Catawba</small></p>			
<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11788+00	<b>Field Station#</b>	11980+00	
<b>Pic 5 Desc.</b>	Rain gauge at Mount Tabor Road reads 1.8 inches.	<b>Pic 6 Desc.</b>	Rain gauge at Catawba Road reads 1.8 inches.	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/1/2021 3:26 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/1/2021 3:26 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

<b>Pictures</b>
-----------------

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20559	
<b>Inspector</b> Garrett Barclay		<b>Date/Time</b> 3/1/2021 3:32 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 11064+53	
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b> 11158+27	
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b> 45.00	
<b>Municipality</b> N/A	<b>Weather</b> Light Rain	<b>Rain Gauge (in)</b> 2.00	
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |



<b>A/E</b>	124300137	<b>Date/Time</b>	3/1/2021 3:32 PM	<b>Report #</b>	20559
------------	-----------	------------------	------------------	-----------------	-------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Arrived at LDY 26 for morning meeting  
 Performed SWPPP for MP 209 - MP 211  
 No damaged ECD's observed during inspection  
 ROW conditions are stable and showing minimal signs of erosion  
 No items added to the punch list

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 3/1/2021 3:32 PM		Report #	
Pictures					
<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates
<b>Field Station#</b>	+1	<b>Field Station#</b>	11068+00	<b>Field Station#</b>	11068+00
<b>Pic 1 Desc.</b>	2" of rain recorded	<b>Pic 2 Desc.</b>	ECD's and row conditions	<b>Pic 2 Desc.</b>	ECD's and row conditions
<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates
<b>Field Station#</b>	11098+00	<b>Field Station#</b>	11119+00	<b>Field Station#</b>	11119+00
<b>Pic 3 Desc.</b>	ECD's and row conditions	<b>Pic 4 Desc.</b>	ECD's and row conditions	<b>Pic 4 Desc.</b>	ECD's and row conditions
<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates	<b>GPS Location</b>	See picture above for GPS coordinates
<b>Field Station#</b>	11130+00	<b>Field Station#</b>	11140+00	<b>Field Station#</b>	11140+00
<b>Pic 5 Desc.</b>	ECD's and row conditions	<b>Pic 6 Desc.</b>	ECD's and row conditions	<b>Pic 6 Desc.</b>	ECD's and row conditions

<b>AFE</b> 124300137	<b>Date/Time</b> 3/1/2021 3:32 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/1/2021 3:32 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20611	
<b>Inspector</b> Chris Burns		<b>Date/Time</b> 3/2/2021 10:45 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 11788+52	
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b> 11899+99	
<b>County</b> Montgomery	<b>Ground</b> Muddy	<b>Temperature (°F)</b> 45.00	
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b> 0.00	
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	Repair broken stakes	24 Hours	
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar Outlet Protection	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 3/2/2021 10:45 AM	<b>Report #</b> 20611
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

See photos for GPS coordinates.  
 Met with environmental staff.  
 Performed SWPPP inspection from MP 223.27 and MP 225.37 as well as assessed AR 266.03.  
 One location of minor wildlife damage to controls was identified.  
 Lead EI Brian Shields, Utility Inspectors Mark Woodley and Billy Hayes as well as PPL Environmental Coordinator Mike Perry were notified and the item added to the punch list.  
 All other perimeter controls, ECDs and BMPs are functional.  
 Vegetation or stabilization sufficient.  
 No impact to sensitive resources observed.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	3/2/2021 10:45 AM	<b>Report #</b>	
------------	-----------	------------------	-------------------	-----------------	--



**Pictures**

<p><small>Date &amp; Time: Tue Mar 02 2021 08:16:42 EST Position: +037 236992 / -080 340093 (+105.0ft) Altitude: 1940ft (+110.4ft) Datum: WGS-84 Azimuth/Bearing: 070° N75E 1244mils True (+13.1) Elevation Angle: +00.6 Horizon Angle: +02.2 Zoom: 1.0x 11792.00</small></p> 	<p><small>Date &amp; Time: Tue Mar 02 2021 08:39:09 EST Position: +037 236997 / -080 349742 (+210.0ft) Altitude: 2230ft (+67.6ft) Datum: WGS-84 Azimuth/Bearing: 142° S30E 2034mils True (+14.7) Elevation Angle: +10.1 Horizon Angle: +00.8 Zoom: 1.0x 11837.00</small></p> 
---	---

<b>GPS Location</b>	1	<b>GPS Location</b>	2
---------------------	---	---------------------	---

<b>Field Station#</b>	11792+00	<b>Field Station#</b>	11037+00
-----------------------	----------	-----------------------	----------


<b>Pic 1 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 2 Desc.</b>	Section of RoW showing conditions and controls.
--------------------	---	--------------------	---

<p><small>Date &amp; Time: Tue Mar 02 2021 08:37:58 EST Position: +037 288828 / -080 342885 (+1166.0ft) Altitude: 2154ft (+32.8ft) Datum: WGS-84 Azimuth/Bearing: 184° S04W 3271mils True (+14.1) Elevation Angle: +10.3 Horizon Angle: +02.7 Zoom: 1.0x 11849.00</small></p> 	<p><small>Date &amp; Time: Tue Mar 02 2021 08:46:57 EST Position: +037 286084 / -080 345552 (+1367.0ft) Altitude: 2188ft (+32.8ft) Datum: WGS-84 Azimuth/Bearing: 075° N75E 1133mils True (+12.7) Elevation Angle: +00.9 Horizon Angle: +01.1 Zoom: 1.0x 11870.00</small></p> 
--	---

<b>GPS Location</b>	3	<b>GPS Location</b>	4
---------------------	---	---------------------	---

<b>Field Station#</b>	11849+00	<b>Field Station#</b>	11870+00
-----------------------	----------	-----------------------	----------

<b>Pic 3 Desc.</b>	Section of RoW showing conditions and controls.	<b>Pic 4 Desc.</b>	Section of RoW showing conditions and controls.
--------------------	---	--------------------	---

<p><small>Date &amp; Time: Tue Mar 02 2021 08:55:21 EST Position: +037 242145 / -080 350100 (+1064.0ft) Altitude: 2168ft (+32.8ft) Datum: WGS-84 Azimuth/Bearing: 109° S34W 3536mils True (+12.7) Elevation Angle: +21.2 Horizon Angle: +01.3 Zoom: 1.0x 11878.00</small></p> 	<p><small>Date &amp; Time: Tue Mar 02 2021 08:57:38 EST Position: +037 231077 / -080 349115 (+1784.0ft) Altitude: 2158ft (+32.8ft) Datum: WGS-84 Azimuth/Bearing: 112° S68E 1991mils True (+14.7) Elevation Angle: +00.0 Horizon Angle: +00.7 Zoom: 1.0x 11885.00</small></p> 
---	--

<b>GPS Location</b>	5	<b>GPS Location</b>	6
---------------------	---	---------------------	---

<b>Field Station#</b>	11878+00	<b>Field Station#</b>	11886+00
-----------------------	----------	-----------------------	----------

<b>Pic 5 Desc.</b>	Multiple broken stakes on P-1.	<b>Pic 6 Desc.</b>	Section of RoW showing conditions and controls.
--------------------	--------------------------------	--------------------	---

<b>AFE</b> 124300137	<b>Date/Time</b> 3/2/2021 10:45 AM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	



<b>A/E</b>	124300137	<b>Date/Time</b>	3/2/2021 10:45 AM	<b>Report #</b>	
------------	-----------	------------------	-------------------	-----------------	--

<b>Pictures</b>					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20613	
<b>Inspector</b> Len Kruizenga		<b>Date/Time</b> 3/2/2021 11:57 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 11899+99	
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b> 12005+00	
<b>County</b> Montgomery	<b>Ground</b> Wet	<b>Temperature (°F)</b> 30.00	
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b> 0.00	
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Communication	Replace damaged soak	24 Hours	3/2/2021
Culvert	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 3/2/2021 11:57 AM	<b>Report #</b> 20613
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

SWPPP inspection area: Sta# 11899+99 to 12005+00. MP-225.3 to 227.3  
 At the beginning of my inspection walk the row was frozen as overnight temperature dropped below 30 degrees.  
 The row is stable with very good vegetation.  
 Perimeter controls are in acceptable condition.  
 Water bars and level spreaders are in good condition.  
 Karst ECD's are in acceptable condition.  
 Wetland ECD's are in acceptable condition.  
 AR-266.03 and AR-266.00 are maintained in acceptable condition.  
 Sta#11985+00- The CFS protecting the drainage feature has been damaged by the landowner running over it with a tractor. The contractor has been notified and made repairs same day.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	3/2/2021 11:57 AM	Report #			
Pictures							
 <p>Date &amp; Time: Tue Mar 02 2021 08:22:41 EST Position: +037 277329, +080 326472, +68.11m Altitude: 2268ft (+68.11m) Datum: WGS-84 Azimuth/Bearing: 151.533E 202mils True (+15) Elevation Angle: +02.5 Horizon Angle: +05.3 Zoom: 1.0X Sta# 11900+00- water bar &amp; water bar outlet</p>		 <p>Date &amp; Time: Tue Mar 02 2021 08:44:40 EST Position: +037 277329, +080 326472, +68.0329117, +68.03m Altitude: 2268ft (+68.03m) Datum: WGS-84 Azimuth/Bearing: 151.533E 202mils True (+15) Elevation Angle: +02.5 Horizon Angle: +05.3 Zoom: 1.0X Sta# 11930+00- water bar level spreaders</p>		<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS
<b>Field Station#</b>	11900+00	<b>Field Station#</b>	11930+00	<b>Pic 1 Desc.</b>	Water bars and water bar outlets protection	<b>Pic 2 Desc.</b>	Level spreaders
 <p>Date &amp; Time: Tue Mar 02 2021 09:56:09 EST Position: +037 277329, +080 326472, +68.11m Altitude: 2230ft (+68.11m) Datum: WGS-84 Azimuth/Bearing: 144.514E 2916mils True (+15) Elevation Angle: +23.1 Horizon Angle: +01.3 Zoom: 1.0X Sta# 11942+00- Karst ECD's</p>		 <p>Date &amp; Time: Tue Mar 02 2021 09:56:09 EST Position: +037 277329, +080 326472, +68.11m Altitude: 2089ft (+68.11m) Datum: WGS-84 Azimuth/Bearing: 151.533E 2684mils True (+15) Elevation Angle: -27.9 Horizon Angle: +02.5 Zoom: 1.0X Sta# 11950+00- Perimeter controls, level spreaders</p>		<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS
<b>Field Station#</b>	11942+00	<b>Field Station#</b>	11950+00	<b>Pic 3 Desc.</b>	Karst ECD's	<b>Pic 4 Desc.</b>	Perimeter controls and level spreaders
 <p>Date &amp; Time: Tue Mar 02 2021 09:13:14 EST Position: +037 277329, +080 326472, +68.09m Altitude: 1822ft (+68.09m) Datum: WGS-84 Azimuth/Bearing: 160.520E 2844mils True (+15) Elevation Angle: +25.1 Horizon Angle: +05.0 Zoom: 1.0X Sta# 11969+00 to 11979+00- Water bars across row, no level spreaders installed</p>		 <p>Date &amp; Time: Tue Mar 02 2021 09:32:25 EST Position: +037 268151, +080 316787, +68.203ft Altitude: 1982ft (+68.203m) Datum: WGS-84 Azimuth/Bearing: 107.530E 1902mils True (+15) Elevation Angle: +13.4 Horizon Angle: +00.0 Zoom: 1.0X Sta# 12001+00- Wetland</p>		<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	See photo GPS
<b>Field Station#</b>	11969+00	<b>Field Station#</b>	12001+00	<b>Pic 5 Desc.</b>	Sta# 11969+00 to 11979+00- Water bars across row, no level spreaders installed in this area.	<b>Pic 6 Desc.</b>	Wetland & controls.

<b>AFE</b> 124300137	<b>Date/Time</b> 3/2/2021 11:57 AM	<b>Report #</b>
----------------------	------------------------------------	-----------------



**Pictures**



<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo GPS
---------------------	-----------	---------------------	---------------

<b>Field Station#</b>	11985+00	<b>Field Station#</b>	11985+00
-----------------------	----------	-----------------------	----------



<b>Pic 7 Desc.</b>	CFS damaged by the landowner at drainage feature.	<b>Pic 8 Desc.</b>	Contractor making repairs to controls damaged by the landowner.
--------------------	---	--------------------	---



<b>GPS Location</b>		<b>GPS Location</b>	
---------------------	--	---------------------	--

<b>Field Station#</b>		<b>Field Station#</b>	
-----------------------	--	-----------------------	--

<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	
--------------------	--	---------------------	--



<b>GPS Location</b>		<b>GPS Location</b>	
---------------------	--	---------------------	--

<b>Field Station#</b>		<b>Field Station#</b>	
-----------------------	--	-----------------------	--

<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	
---------------------	--	---------------------	--

<b>AFE</b> 124300137	<b>Date/Time</b> 3/2/2021 11:57 AM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20612	
<b>Inspector</b> Rob Robertson		<b>Date/Time</b> 3/2/2021 11:43 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b>	11670+00
<b>County</b> Montgomery	<b>Ground</b> Damp	<b>Temperature (°F)</b>	38.00
<b>Municipality</b> N/A	<b>Weather</b> Cloudy	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 3/2/2021 11:43 AM	<b>Report #</b> 20612
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired







**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)

Completed a regular scheduled VADEQ SWPPP inspection on JNF and private lands on Brush Mountain. The ROW is currently stable with no erosion occurring due to runoff or other cause of sediment movement. Perimeter ECDs are in place and functional. The contractor has completed routine maintenance needs that were identified and submitted on punch list. Slope breakers remain in place and are functioning as designed. End treatments and sumps are functioning properly. Resource buffers are stable and equipment bridge ECDs are in place. RCEs are in acceptable condition. No slips were located. No evidence of vandalism was discovered.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.



AFE 124300137		Date/Time 3/2/2021 11:43 AM		Report #			
Pictures							
 <p>Date &amp; Time: Tue Mar 02 2021 09:46:31 EST Position: +037.3263747 / -080.374739 / 1598.4ft Altitude: 2912ft (+105.0ft) Datum: WGS 84 Azimuth Bearing: 110.570E 1956mils Magnetic (+13°) Elevation Angle: +05.3 Horizon Angle: +00.8 Zoom: 1.0X 11666+00</p>		 <p>Date &amp; Time: Tue Mar 02 2021 09:51:15 EST Position: +037.3265617 / -080.3746277 / 1618.6ft Altitude: 2830ft (+19.7ft) Datum: WGS 84 Azimuth Bearing: 166° 53'4E 2096mils Magnetic (+13°) Elevation Angle: +09.8 Horizon Angle: +01.8 Zoom: 1.0X 11663+00</p>		<p><b>GPS Location</b> On photo</p> <p><b>Field Station#</b> 11666+00</p> <p><b>Pic 1 Desc.</b> Top of Brush Mountain near JNF property line is stable with ECDs in place.</p>		<p><b>GPS Location</b> On photo</p> <p><b>Field Station#</b> 11663+00</p> <p><b>Pic 2 Desc.</b> Perimeter controls are functional.</p>	
 <p>Date &amp; Time: Tue Mar 02 2021 09:56:03 EST Position: +037.3261227 / -080.377284 / 1532.8ft Altitude: 3320ft (+52.0ft) Datum: WGS 84 Azimuth Bearing: 025.125E 0444mils Magnetic (+13°) Elevation Angle: +14.3 Horizon Angle: +02.4 Zoom: 1.0X 11656+00</p>		 <p>Date &amp; Time: Tue Mar 02 2021 10:00:17 EST Position: +037.3264932 / -080.377503 / 1514.6ft Altitude: 2891ft (+19.7ft) Datum: WGS 84 Azimuth Bearing: 026° 12'4E 0420mils Magnetic (+13°) Elevation Angle: +11.6 Horizon Angle: +00.3 Zoom: 4.0X 11649+00</p>		<p><b>GPS Location</b> On photo</p> <p><b>Field Station#</b> 11656+00</p> <p><b>Pic 3 Desc.</b> Slope breakers are working as designed. Perimeter controls are in place.</p>		<p><b>GPS Location</b> On photo</p> <p><b>Field Station#</b> 11649+00</p> <p><b>Pic 4 Desc.</b> ROW is stable. Perimeter controls are in place and functional.</p>	
 <p>Date &amp; Time: Tue Mar 02 2021 11:43:10 EST Position: +037.3261691 / -080.374735 / 1516.4ft Altitude: 1735ft (+23.8ft) Datum: WGS 84 Azimuth Bearing: 122.858E 2103mils Magnetic (+13°) Elevation Angle: +04.0 Horizon Angle: +01.8 Zoom: 1.0X 11628+00</p>		 <p>Date &amp; Time: Tue Mar 02 2021 11:24:55 EST Position: +037.3262295 / -080.374708 / 1511.8ft Altitude: 1820ft (+10.4ft) Datum: WGS 84 Azimuth Bearing: 049° 14'3E 1227mils Magnetic (+14°) Elevation Angle: +14.8 Horizon Angle: +00.1 Zoom: 1.0X 11618+00</p>		<p><b>GPS Location</b> On photo</p> <p><b>Field Station#</b> 11628+50</p> <p><b>Pic 5 Desc.</b> Perimeter controls are in place. ROW is stable.</p>		<p><b>GPS Location</b> On photo</p> <p><b>Field Station#</b> 11618+50</p> <p><b>Pic 6 Desc.</b> Perimeter controls are in place and functional. Sensitive resource fencing in place.</p>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/2/2021 11:43 AM	<b>Report #</b>
----------------------	------------------------------------	-----------------

<b>Pictures</b>
-----------------

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/2/2021 11:43 AM	<b>Report #</b>	
------------	-----------	------------------	-------------------	-----------------	--

<b>Pictures</b>					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20625	
<b>Inspector</b> Jared Saunders		<b>Date/Time</b> 3/2/2021 3:30 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	11788+50
<b>County</b> Montgomery	<b>Ground</b> Muddy	<b>Temperature (°F)</b>	45.00
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Flume Pipe	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>A/E</b>	124300137	<b>Date/Time</b>	3/2/2021 3:30 PM	<b>Report #</b>	20625
------------	-----------	------------------	------------------	-----------------	-------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from MP 221 to MP 223.8.  
 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed.  
 No forward progress has been completed due to FERC shut down.  
 ROW has been stabilized using seed, mulch, and minor vegetation growth.  
 No deficiencies located during VA SWPPP inspection.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	3/2/2021 3:30 PM	Report #			
Pictures							
 <p><small>Date &amp; Time: Tue Mar 02, 2021, 11:02:57 EST Position: 337° 23' 32.1" N, -83° 03' 37.7" W Altitude: 2814m (±132.8ft) Datum: WGS-84 Azimuth Bearing: 100.5382° (1.778mils True) ±13.1 Elevation Angle: -18.9 Horizon Angle: -01.9 Zoom: 1.0X 11674+00</small></p>	See photo for GPS location.	 <p><small>Date &amp; Time: Tue Mar 02, 2021, 11:02:57 EST Position: 337° 23' 32.1" N, -83° 03' 37.7" W Altitude: 2814m (±132.8ft) Datum: WGS-84 Azimuth Bearing: 265.549W (0.116mils True) ±22 Elevation Angle: -14.8 Horizon Angle: -01.8 Zoom: 1.0X 11687+00</small></p>	See photo for GPS location.	GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.
Field Station#	1167+00	Field Station#	11687+00	Pic 1 Desc.	Triple stack compost filter sock and priority one silt fence in place along LOD.	Pic 2 Desc.	Sensitive resource buffer in place at stream S-MN21.
 <p><small>Date &amp; Time: Tue Mar 02, 2021, 11:02:57 EST Position: 337° 23' 32.1" N, -83° 03' 37.7" W Altitude: 2819m (±134.8ft) Datum: WGS-84 Azimuth Bearing: 219.539W (382mils True) ±22.1 Elevation Angle: -22.9 Horizon Angle: -02.0 Zoom: 1.0X 11674+00</small></p>	See photo for GPS location.	 <p><small>Date &amp; Time: Tue Mar 02, 2021, 11:02:57 EST Position: 337° 23' 32.1" N, -83° 03' 37.7" W Altitude: 2718m (±89.2ft) Datum: WGS-84 Azimuth Bearing: 003.103E (0.053mils True) ±5.3 Elevation Angle: -10.4 Horizon Angle: -01.6 Zoom: 1.0X 11712+00</small></p>	See photo for GPS location.	GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.
Field Station#	11674+00	Field Station#	11712+00	Pic 3 Desc.	Waterbar, sump pit, and end treatment in place.	Pic 4 Desc.	ROW stabilized with seed and mulch.
 <p><small>Date &amp; Time: Tue Mar 02, 2021, 11:02:57 EST Position: 337° 23' 32.1" N, -83° 03' 37.7" W Altitude: 2146m (±109.1ft) Datum: WGS-84 Azimuth Bearing: 102.578E (183mils True) ±14.1 Elevation Angle: -16.6 Horizon Angle: -01.6 Zoom: 1.0X 11767+00</small></p>	See photo for GPS location.	 <p><small>Date &amp; Time: Tue Mar 02, 2021, 11:02:57 EST Position: 337° 23' 32.1" N, -83° 03' 37.7" W Altitude: 2518m (±82.8ft) Datum: WGS-84 Azimuth Bearing: 003.103E (0.053mils True) ±5.3 Elevation Angle: -10.4 Horizon Angle: -01.6 Zoom: 1.0X 11776+00</small></p>	See photo for GPS location.	GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.
Field Station#	11767+00	Field Station#	11776+00	Pic 5 Desc.	RCE in place at MLV 26.	Pic 6 Desc.	Clean water diversion pipe inlet and clean water diversion berm in place.

<b>AFE</b> 124300137	<b>Date/Time</b> 3/2/2021 3:30 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/2/2021 3:30 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	





# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20628	
<b>Inspector</b> Garrett Barclay		<b>Date/Time</b> 3/2/2021 3:59 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 11524+16	
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b> 11600+01	
<b>County</b> Giles	<b>Ground</b> Muddy	<b>Temperature (°F)</b> 43.00	
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b> 0.00	
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b>	124300137	<b>Date/Time</b>	3/2/2021 3:59 PM	<b>Report #</b>	20628
------------	-----------	------------------	------------------	-----------------	-------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)

Arrived at LDY 26 for morning meeting  
 Performed SWPPP for MP 218 - MP 219  
 Observed damaged ECD's observed during inspection  
 ROW conditions are stable and showing minimal signs of erosion  
 Damaged P1 added to the punch list

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	3/2/2021 3:59 PM	Report #
<b>Pictures</b>				
 <p>Date &amp; Time: Tue, Mar 02, 2021, 09:14:40 EST  Position: +397.229982 / -080.418407 (-15.24)  Altitude: 2521ft (+11.1m)  Datum: WGS-84  Azimuth/Bearing: 156 S24E 2773mils True (+12.1)  Elevation Grade: -041  Horizon Grade: +001  Zoom: 10X  11548</p>		 <p>Date &amp; Time: Tue, Mar 02, 2021, 09:21:09 EST  Position: +397.229982 / -080.418407 (-15.24)  Altitude: 2521ft (+11.1m)  Datum: WGS-84  Azimuth/Bearing: 156 S24E 2773mils True (+12.1)  Elevation Grade: -041  Horizon Grade: +001  Zoom: 10X  11553</p>		
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates
<b>Field Station#</b>	11548+00		<b>Field Station#</b>	11553+00
<b>Pic 1 Desc.</b>	ECD's and row conditions		<b>Pic 2 Desc.</b>	ECD's and row conditions
 <p>Date &amp; Time: Tue, Mar 02, 2021, 09:29:46 EST  Position: +397.229982 / -080.418407 (-15.24)  Altitude: 2521ft (+11.1m)  Datum: WGS-84  Azimuth/Bearing: 197 S07W 3324mils True (+13)  Elevation Grade: -057  Horizon Grade: +007  Zoom: 10X  11560</p>		 <p>Date &amp; Time: Tue, Mar 02, 2021, 09:39:22 EST  Position: +397.229982 / -080.418407 (-15.24)  Altitude: 2511ft (+11.1m)  Datum: WGS-84  Azimuth/Bearing: 197 S07W 3324mils True (+13)  Elevation Grade: -057  Horizon Grade: +007  Zoom: 10X  11568</p>		
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates
<b>Field Station#</b>	11560+00		<b>Field Station#</b>	11568+00
<b>Pic 3 Desc.</b>	ECD's and row conditions		<b>Pic 4 Desc.</b>	ECD's and row conditions
 <p>Date &amp; Time: Tue, Mar 02, 2021, 09:43:10 EST  Position: +397.229982 / -080.412212 (-15.154m)  Altitude: 2488ft (+11.0m)  Datum: WGS-84  Azimuth/Bearing: 313 N47W 5944mils True (+14)  Elevation Grade: +010  Horizon Grade: +012  Zoom: 14X  11573</p>		 <p>Date &amp; Time: Tue, Mar 02, 2021, 09:44:05 EST  Position: +397.229982 / -080.406537 (-15.113m)  Altitude: 2488ft (+11.0m)  Datum: WGS-84  Azimuth/Bearing: 060 N46E 1170mils True (+13)  Elevation Grade: +039  Horizon Grade: +009  Zoom: 10X  11584</p>		
<b>GPS Location</b>	See picture above for GPS coordinates		<b>GPS Location</b>	See picture above for GPS coordinates
<b>Field Station#</b>	11573+00		<b>Field Station#</b>	11584+00
<b>Pic 5 Desc.</b>	ECD's and row conditions		<b>Pic 6 Desc.</b>	ECD's and row conditions

<b>AFE</b> 124300137	<b>Date/Time</b> 3/2/2021 3:59 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	3/2/2021 3:59 PM	<b>Report #</b>	
------------	-----------	------------------	------------------	-----------------	--

<b>Pictures</b>					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20654	
<b>Inspector</b> Chris Burns		<b>Date/Time</b> 3/3/2021 8:16 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b> WV	<b>Inspection Area</b> Partial	<b>Station End</b>	12005+00
<b>County</b> Monroe	<b>Ground</b> Wet	<b>Temperature (°F)</b>	52.00
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Roadside Ditch	Acceptable			
Rock Construction Entrance	Acceptable			
Rock-lined Channel	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Temporary Diversion Berm	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waste Management	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?<br><span style="color: orange;">WV: Exceeding 7 days if to be left inactive for more than 21 days</span>  | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b>	124300137	<b>Date/Time</b>	3/3/2021 8:16 AM	<b>Report #</b>	20654
------------	-----------	------------------	------------------	-----------------	-------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

See photos for GPS coordinates.  
 Met with environmental staff.  
 Performed weekly SWPPP inspection of LDY 37.  
 No issues were located.  
 All perimeter controls, ECDs and BMPs are functional.  
 Vegetation or stabilization sufficient.  
 No impact to sensitive resources.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	3/3/2021 8:16 AM	<b>Report #</b>	
------------	-----------	------------------	------------------	-----------------	--

## Pictures



<b>GPS Location</b>	1	<b>GPS Location</b>	2
---------------------	---	---------------------	---

<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
-----------------------	----------	-----------------------	----------

<b>Pic 1 Desc.</b>	W-KL24 and controls.	<b>Pic 2 Desc.</b>	W-IJ81 and controls.
--------------------	----------------------	--------------------	----------------------



<b>GPS Location</b>	3	<b>GPS Location</b>	4
---------------------	---	---------------------	---

<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
-----------------------	----------	-----------------------	----------

<b>Pic 3 Desc.</b>	W-IJ82 and controls.	<b>Pic 4 Desc.</b>	Overview of the lower section of LDY 37 (#1).
--------------------	----------------------	--------------------	---



<b>GPS Location</b>	5	<b>GPS Location</b>	6
---------------------	---	---------------------	---

<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
-----------------------	----------	-----------------------	----------

<b>Pic 5 Desc.</b>	Overview of the lower section of LDY 37 (2).	<b>Pic 6 Desc.</b>	Roadside ditch.
--------------------	--	--------------------	-----------------



<b>AFE</b> 124300137	<b>Date/Time</b> 3/3/2021 8:16 AM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/3/2021 8:16 AM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

<b>Pictures</b>			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20655	
<b>Inspector</b> Chris Burns		<b>Date/Time</b> 3/3/2021 8:37 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	12005+00
<b>County</b> Giles	<b>Ground</b> Damp	<b>Temperature (°F)</b>	52.00
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Roadside Ditch	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Signage	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 3/3/2021 8:37 AM	<b>Report #</b> 20655
----------------------	-----------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

See photos for GPS coordinates.  
 Met with environmental staff.  
 Performed SWPPP inspection of LDY 28.  
 No issues were located.  
 All perimeter controls, ECDs and BMPs are functional.  
 Vegetation or stabilization sufficient.  
 No impact to sensitive resources.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	3/3/2021 8:37 AM	<b>Report #</b>	
------------	-----------	------------------	------------------	-----------------	--

## Pictures

<p><small>Date &amp; Time: Wed, Mar 03, 2021, 09:53:16 EST Position: -037.334131 / -080.806449 (+39.4ft) Altitude: 1420ft (+10.4ft) Datum: WGS-84 Azimuth/Bearing: 114.566E 2027mils True (+14.1) Elevation Angle: +06.6 Horizon Angle: -00.0 Zoom: 1.0X LDY: 28</small></p> 	<p><small>Date &amp; Time: Wed, Mar 03, 2021, 09:52:12 EST Position: -037.334131 / -080.806449 (+39.4ft) Altitude: 1557ft (+9.8ft) Datum: WGS-84 Azimuth/Bearing: 230.550W 4089mils True (+12.1) Elevation Angle: -13.5 Horizon Angle: -00.4 Zoom: 1.0X LDY: 28</small></p> 
--	--

<b>GPS Location</b>	1	<b>GPS Location</b>	2
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 1 Desc.</b>	Staged transport busses.	<b>Pic 2 Desc.</b>	Perimeter controls along access functional.

<p><small>Date &amp; Time: Wed, Mar 03, 2021, 09:58:07 EST Position: -037.334056 / -080.803093 (+19.7ft) Altitude: 1567ft (+9.8ft) Datum: WGS-84 Azimuth/Bearing: 249.568W 4409mils True (+10.1) Elevation Angle: -02.1 Horizon Angle: -00.9 Zoom: 1.0X LDY: 28</small></p> 	<p><small>Date &amp; Time: Wed, Mar 03, 2021, 09:58:21 EST Position: -037.334001 / -080.803393 (+19.7ft) Altitude: 1565ft (+9.8ft) Datum: WGS-84 Azimuth/Bearing: 289. N77W 5031mils True (+10.1) Elevation Angle: -01.8 Horizon Angle: -02.2 Zoom: 1.0X LDY: 28</small></p> 
--	--

<b>GPS Location</b>	3	<b>GPS Location</b>	4
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 3 Desc.</b>	Staged vehicles and portable toilets.	<b>Pic 4 Desc.</b>	Staged vehicles and trailers.

<p><small>Date &amp; Time: Wed, Mar 03, 2021, 09:59:17 EST Position: -037.334378 / -080.802949 (+109.0ft) Altitude: 1421ft (+10.4ft) Datum: WGS-84 Azimuth/Bearing: 287. N73W 5102mils True (+10.1) Elevation Angle: -03.2 Horizon Angle: -01.3 Zoom: 1.0X LDY: 28</small></p> 	<p><small>Date &amp; Time: Wed, Mar 03, 2021, 10:00:23 EST Position: -037.334378 / -080.802949 (+109.0ft) Altitude: 1565ft (+9.8ft) Datum: WGS-84 Azimuth/Bearing: 182. S82W 9439mils True (+10.1) Elevation Angle: -02.4 Horizon Angle: -00.0 Zoom: 1.0X LDY: 28</small></p> 
--	--

<b>GPS Location</b>	5	<b>GPS Location</b>	6
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 5 Desc.</b>	Perimeter controls functional.	<b>Pic 6 Desc.</b>	Lower section of LDY 28.

<b>AFE</b> 124300137	<b>Date/Time</b> 3/3/2021 8:37 AM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/3/2021 8:37 AM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20666	
<b>Inspector</b> Jared Saunders		<b>Date/Time</b> 3/3/2021 3:10 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	12005+00
<b>County</b> Giles	<b>Ground</b> Damp	<b>Temperature (°F)</b>	52.00
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Roadside Ditch	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |



<b>A/E</b>	124300137	<b>Date/Time</b>	3/3/2021 3:10 PM	<b>Report #</b>	20666
------------	-----------	------------------	------------------	-----------------	-------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Conducted VA SWPPP inspection at lay down yard 26 and lay down yard 29.  
 Checked equipment in yards for leaks. No leaks observed.  
 All perimeter ECDs in place and functional.  
 Secondary containment in place at stationary equipment.  
 No deficiencies located during VA SWPPP inspection.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	3/3/2021 3:10 PM	<b>Report #</b>	
------------	-----------	------------------	------------------	-----------------	--

## Pictures



<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 1 Desc.</b>	Triple stack compost filter sock in place along LOD.	<b>Pic 2 Desc.</b>	Checked staged equipment for leaks.



<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 3 Desc.</b>	Triple stack compost filter sock in place around drainage.	<b>Pic 4 Desc.</b>	RCE in place at LDY 26 entrance.



<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 5 Desc.</b>	Secondary containment in place under fuel cell.	<b>Pic 6 Desc.</b>	Dumpsters being utilized for trash management.

<b>AFE</b> 124300137	<b>Date/Time</b> 3/3/2021 3:10 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/3/2021 3:10 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>	<b>GPS Location</b>
<b>Field Station#</b>	<b>Field Station#</b>
<b>Pic 13 Desc.</b>	<b>Pic 14 Desc.</b>

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>	<b>GPS Location</b>
<b>Field Station#</b>	<b>Field Station#</b>
<b>Pic 15 Desc.</b>	<b>Pic 16 Desc.</b>

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>	<b>GPS Location</b>
<b>Field Station#</b>	<b>Field Station#</b>
<b>Pic 17 Desc.</b>	<b>Pic 18 Desc.</b>



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20717	
<b>Inspector</b> Jared Saunders		<b>Date/Time</b> 3/4/2021 2:38 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	10670+00
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	10750+00
<b>County</b> Giles	<b>Ground</b> Damp	<b>Temperature (°F)</b>	50.00
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Flume Pipe	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>A/E</b>	124300137	<b>Date/Time</b>	3/4/2021 2:38 PM	<b>Report #</b>	20717
------------	-----------	------------------	------------------	-----------------	-------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from MP 201.7 to MP 203.6.  
 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed.  
 No forward progress has been completed due to FERC shut down.  
 Right of way has been stabilized using seed, mulch, and natural vegetation.  
 No deficiencies located during VA SWPPP inspection.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	3/4/2021 2:38 PM	Report #
<b>Pictures</b>				
				
<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10710+00	<b>Field Station#</b>	10710+00	
<b>Pic 1 Desc.</b>	CFS in place along access road 241.04.	<b>Pic 2 Desc.</b>	ROW stabilized with seed and mulch.	
				
<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10710+00	<b>Field Station#</b>	10711+00	
<b>Pic 3 Desc.</b>	Priority one silt fence checks in place.	<b>Pic 4 Desc.</b>	ROW stabilized with natural vegetation growth.	
				
<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	10698+00	<b>Field Station#</b>	10696+00	
<b>Pic 5 Desc.</b>	Sensitive resource buffer in place at stream S-G32.	<b>Pic 6 Desc.</b>	RCE in place at Buffalo Anklets Road.	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/4/2021 2:38 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	



<b>AFE</b> 124300137	<b>Date/Time</b> 3/4/2021 2:38 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20706	
<b>Inspector</b> Len Kruizenga		<b>Date/Time</b> 3/4/2021 1:40 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11023+88
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b>	10930+00
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b>	55.00
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 3/4/2021 1:40 PM	<b>Report #</b> 20706
----------------------	-----------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

SWPPP inspection area: Sta#11923+88 to 10930+00. MP-208.6 to 206.2  
 The row is drying and in stable condition, temporary stabilization is acceptable.  
 Perimeter controls, silt fence, CFS, SSF are in acceptable condition.  
 Water bars sump pits and end treatments are in acceptable condition.  
 Sensitive resource area ECD's are in acceptable condition.  
 Stream crossing bridges and ECD's are in acceptable condition.  
 AR-244.00 and Doe Creek RCE are maintained in acceptable condition.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 3/4/2021 1:40 PM		Report #			
Pictures							
 <p>Date &amp; Time: Thu, Mar 04, 2021 11:20:40 CST Position: 327323228, -880338387, 106.670 Altitude: 246.011 (+55.4m) Datum: WGS 84 Azimuth Bearing: 477.593E 9147mils True (+12.1) Elevation Angle: -39.4 Horizon Angle: +06.5 Zoom: 1.0X Stream S: IJ18</p>		 <p>Date &amp; Time: Thu, Mar 04, 2021 11:20:40 CST Position: 327323228, -880338387, 106.670 Altitude: 246.011 (+55.4m) Datum: WGS 84 Azimuth Bearing: 477.593E 9147mils True (+12.1) Elevation Angle: -39.4 Horizon Angle: +06.5 Zoom: 1.0X Stream S: RR5</p>		<p><b>GPS Location</b> See photo GPS</p> <p><b>Field Station#</b> 11023+88</p> <p><b>Pic 1 Desc.</b> Stream S- IJ18- Bridge and ECD's</p>		<p><b>GPS Location</b> See photo GPS</p> <p><b>Field Station#</b> 11017+00</p> <p><b>Pic 2 Desc.</b> Stream S-RR5</p>	
 <p>Date &amp; Time: Thu, Mar 04, 2021 11:28:38 CST Position: 327323228, -880338387, 106.670 Altitude: 238.511 (+55.4m) Datum: WGS 84 Azimuth Bearing: 311.824W 3592mils True (+12.1) Elevation Angle: -11.2 Horizon Angle: +00.2 Zoom: 1.0X Stream S: E25</p>		 <p>Date &amp; Time: Thu, Mar 04, 2021 11:38:59 CST Position: 327323228, -880338387, 106.670 Altitude: 238.511 (+55.4m) Datum: WGS 84 Azimuth Bearing: 311.824W 3592mils True (+12.1) Elevation Angle: -11.2 Horizon Angle: +02.2 Zoom: 1.0X Stream S: E24</p>		<p><b>GPS Location</b> See photo GPS</p> <p><b>Field Station#</b> 10986+00</p> <p><b>Pic 3 Desc.</b> Stream S- E25</p>		<p><b>GPS Location</b> See photo GPS</p> <p><b>Field Station#</b> 10985+00</p> <p><b>Pic 4 Desc.</b> Stream S- E24</p>	
 <p>Date &amp; Time: Thu, Mar 04, 2021 11:46:15 CST Position: 327323228, -880338387, 106.670 Altitude: 246.011 (+55.4m) Datum: WGS 84 Azimuth Bearing: 118.552E 2098mils True (+12.1) Elevation Angle: -22.7 Horizon Angle: +01.4 Zoom: 1.0X Site: 10968-00- Mats protecting private water line</p>		 <p>Date &amp; Time: Thu, Mar 04, 2021 11:50:07 CST Position: 327323228, -880338387, 106.670 Altitude: 238.511 (+55.4m) Datum: WGS 84 Azimuth Bearing: 076.124E 1316mils True (+12.1) Elevation Angle: -30.8 Horizon Angle: +05.7 Zoom: 1.0X Site: 10965-00- Sensitive resource area</p>		<p><b>GPS Location</b> See photo GPS</p> <p><b>Field Station#</b> 10968+00</p> <p><b>Pic 5 Desc.</b> Mats protecting private water line</p>		<p><b>GPS Location</b> See photo GPS</p> <p><b>Field Station#</b> 10965+00</p> <p><b>Pic 6 Desc.</b> Sensitive resource area</p>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/4/2021 1:40 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/4/2021 1:40 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

<b>Pictures</b>			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20713	
<b>Inspector</b> Chris Burns		<b>Date/Time</b> 3/4/2021 3:25 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11023+80
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	11064+53
<b>County</b> Giles	<b>Ground</b> Damp	<b>Temperature (°F)</b>	48.00
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Temporary Diversion Berm	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Housekeeping	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 3/4/2021 3:25 PM	<b>Report #</b> 20713
----------------------	-----------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

See photos for GPS coordinates.  
 Met with environmental staff.  
 Performed SWPPP inspection from MP 208.78 to MP 209.56 as well as assessed AR 245.01.  
 No issues were located.  
 All perimeter controls, ECDs and BMPs are functional.  
 Vegetation or stabilization sufficient.  
 No impact to sensitive resources observed.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.



AFE 124300137		Date/Time 3/4/2021 3:25 PM		Report #	
Pictures					
<b>GPS Location</b> 1		<b>GPS Location</b> 2			
<b>Field Station#</b> 11025+50		<b>Field Station#</b> 11034+00			
<b>Pic 1 Desc.</b> S-IJ18 and controls.		<b>Pic 2 Desc.</b> Section of RoW showing conditions and controls.			
<b>GPS Location</b> 3		<b>GPS Location</b> 4			
<b>Field Station#</b> 11049+00		<b>Field Station#</b> 11050+10			
<b>Pic 3 Desc.</b> Section of RoW showing conditions and controls.		<b>Pic 4 Desc.</b> S-IJ16B/S-IJ17 and controls.			
<b>GPS Location</b> 5		<b>GPS Location</b> 6			
<b>Field Station#</b> 11058+00		<b>Field Station#</b> 11064+53			
<b>Pic 5 Desc.</b> Section of RoW showing conditions and controls.		<b>Pic 6 Desc.</b> Section of RoW showing conditions and controls.			

<b>AFE</b> 124300137	<b>Date/Time</b> 3/4/2021 3:25 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/4/2021 3:25 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20716	
<b>Inspector</b> Garrett Barclay		<b>Date/Time</b> 3/4/2021 3:37 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 10850+00	
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b> 10929+62	
<b>County</b> Giles	<b>Ground</b> Muddy	<b>Temperature (°F)</b> 44.00	
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b> 0.00	
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b>	124300137	<b>Date/Time</b>	3/4/2021 3:37 PM	<b>Report #</b>	20716
------------	-----------	------------------	------------------	-----------------	-------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Arrived at LDY 26 for morning meeting  
 Performed SWPPP for MP 205 - MP 207  
 No damaged ECD's observed during inspection  
 ROW conditions are stable and showing minimal signs of erosion  
 No items added to the punch list

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 3/4/2021 3:37 PM		Report #	
Pictures					
<p>Date &amp; Time: Thu, Mar 04, 2021, 09:55:45 EST  Position: +037 334579 / -080 591986 (+3661.0ft)  Altitude: 5270ft (+1628m)  Datum: WGS-84  Azimuth/Bearing: 108.574E 1920mils True (+12.1)  Elevation Grade: -001%  Horizon Grade: -000%  Zoom: 1.0X  10894</p> 				<p>Date &amp; Time: Thu, Mar 04, 2021, 10:01:01 EST  Position: +037 334729 / -080 596172 (+2113.3ft)  Altitude: 2018ft (+622.8m)  Datum: WGS-84  Azimuth/Bearing: 106.574E 1884mils True (+12.1)  Elevation Grade: -043%  Horizon Grade: -004%  Zoom: 1.0X  10875</p> 	
<b>GPS Location</b>		See picture above for GPS coordinates		<b>GPS Location</b>	
<b>Field Station#</b>		10864+00		<b>Field Station#</b>	
<b>Pic 1 Desc.</b>		ECD's and row conditions		<b>Pic 2 Desc.</b>	
<p>Date &amp; Time: Thu, Mar 04, 2021, 10:19:52 EST  Position: +037 334611 / -080 591467 (+1513ft)  Altitude: 2565ft (+782.7m)  Datum: WGS-84  Azimuth/Bearing: 266.594W 4336mils True (+13.1)  Elevation Grade: -002%  Horizon Grade: -002%  Zoom: 1.0X  10888</p> 				<p>Date &amp; Time: Thu, Mar 04, 2021, 10:19:52 EST  Position: +037 334611 / -080 591467 (+1513ft)  Altitude: 2565ft (+782.7m)  Datum: WGS-84  Azimuth/Bearing: 086.574E 1529mils True (+13.1)  Elevation Grade: -000%  Horizon Grade: -006%  Zoom: 1.0X  10898</p> 	
<b>GPS Location</b>		See picture above for GPS coordinates		<b>GPS Location</b>	
<b>Field Station#</b>		10888+00		<b>Field Station#</b>	
<b>Pic 3 Desc.</b>		ECD's and row conditions		<b>Pic 4 Desc.</b>	
<p>Date &amp; Time: Thu, Mar 04, 2021, 10:24:01 EST  Position: +037 334742 / -080 588402 (+1513ft)  Altitude: 2621ft (+801.4m)  Datum: WGS-84  Azimuth/Bearing: 102.578E 1813mils True (+13.1)  Elevation Grade: -002%  Horizon Grade: -001%  Zoom: 1.0X  10917</p> 				<p>Date &amp; Time: Thu, Mar 04, 2021, 10:28:27 EST  Position: +037 334521 / -080 588842 (+1512ft)  Altitude: 2391ft (+729.3m)  Datum: WGS-84  Azimuth/Bearing: 117.503E 2080mils True (+13.1)  Elevation Grade: -013%  Horizon Grade: -000%  Zoom: 1.0X  10922</p> 	
<b>GPS Location</b>		See picture above for GPS coordinates		<b>GPS Location</b>	
<b>Field Station#</b>		10917+00		<b>Field Station#</b>	
<b>Pic 5 Desc.</b>		ECD's and row conditions		<b>Pic 6 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/4/2021 3:37 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/4/2021 3:37 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	





# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20783	
<b>Inspector</b> Chris Burns		<b>Date/Time</b> 3/5/2021 8:03 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 11254+99	
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b> 11353+67	
<b>County</b> Giles	<b>Ground</b> Damp	<b>Temperature (°F)</b> 45.00	
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b> 0.00	
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Plunge Pool	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 3/5/2021 8:03 AM	<b>Report #</b> 20783
----------------------	-----------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)

See photos for GPS coordinates.  
 Met with environmental staff.  
 Performed SWPPP inspection from MP 213.16 to MP 215.03 as well as assessed AR 256.02.  
 No issues were located.  
 All perimeter controls, ECDs and BMPs are functional.  
 Vegetation or stabilization sufficient.  
 No impact to sensitive resources observed.  
 PPL environmental crews were replacing P-1 as needed between AR 256.02 and Old Furnace rd.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 3/5/2021 8:03 AM		Report #			
Pictures							
 <p>Date &amp; Time: Fri, Mar 05, 2021, 07:22:42 EST Position: -037.299582 / -080.476123 (+32810.0ft) Altitude: 2101ft (+32.8ft) Datum: WGS-84 Azimuth/Bearing: 022° N22E 0747mils True (+1.2°) Elevation Angle: +03.0° Horizon Angle: +09.4° Zoom: 1.0X S-MM18</p>		 <p>Date &amp; Time: Fri, Mar 05, 2021, 08:03:07 EST Position: -037.300244 / -080.475358 (+32810.0ft) Altitude: 2239ft (+32.8ft) Datum: WGS-84 Azimuth/Bearing: 138° S42E 2453mils True (+1.4°) Elevation Angle: +10.3° Horizon Angle: +00.5° Zoom: 1.0X S-MM18</p>		<p><b>GPS Location</b> 1</p> <p><b>Field Station#</b> 11265+00</p> <p><b>Pic 1 Desc.</b> Perimeter controls functional.</p>		<p><b>GPS Location</b> 2</p> <p><b>Field Station#</b> 11292+80</p> <p><b>Pic 2 Desc.</b> S-MM18 and controls.</p>	
 <p>Date &amp; Time: Fri, Mar 05, 2021, 09:40:05 EST Position: -037.299582 / -080.476123 (+32810.0ft) Altitude: 2101ft (+32.8ft) Datum: WGS-84 Azimuth/Bearing: 101° S79E 1796mils True (+1.4°) Elevation Angle: +09.4° Horizon Angle: +01.9° Zoom: 1.0X 11300+00</p>		 <p>Date &amp; Time: Fri, Mar 05, 2021, 09:52:17 EST Position: -037.311852 / -080.467451 (+2374.2ft) Altitude: 2194ft (+39.0ft) Datum: WGS-84 Azimuth/Bearing: 186° S84W 3271mils True (+1.3°) Elevation Angle: +07.9° Horizon Angle: +06.4° Zoom: 1.0X S-NN12</p>		<p><b>GPS Location</b> 3</p> <p><b>Field Station#</b> 11300+00</p> <p><b>Pic 3 Desc.</b> Section of RoW showing conditions and controls.</p>		<p><b>GPS Location</b> 4</p> <p><b>Field Station#</b> 11327+85</p> <p><b>Pic 4 Desc.</b> S-NN12 and controls.</p>	
 <p>Date &amp; Time: Fri, Mar 05, 2021, 08:55:19 EST Position: -037.302645 / -080.470426 (+19.7ft) Altitude: 2255ft (+9.9ft) Datum: WGS-84 Azimuth/Bearing: 294° N66W 5227mils True (+12.1°) Elevation Angle: +00.4° Horizon Angle: +02.5° Zoom: 1.0X 11340+00</p>		 <p>Date &amp; Time: Fri, Mar 05, 2021, 09:01:08 EST Position: -037.305449 / -080.467207 (+2945.0ft) Altitude: 1991ft (+10.4ft) Datum: WGS-84 Azimuth/Bearing: 115° S69E 2042mils True (+0.2°) Elevation Angle: +21.2° Horizon Angle: +01.9° Zoom: 1.0X S-NN11</p>		<p><b>GPS Location</b> 5</p> <p><b>Field Station#</b> 11340+00</p> <p><b>Pic 5 Desc.</b> PPL crews replacing P-1.</p>		<p><b>GPS Location</b> 6</p> <p><b>Field Station#</b> 11352+97</p> <p><b>Pic 6 Desc.</b> S-NN11.</p>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/5/2021 8:03 AM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/5/2021 8:03 AM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20785	
<b>Inspector</b> Jared Saunders		<b>Date/Time</b> 3/5/2021 2:34 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11353+50
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	11524+16
<b>County</b> Giles	<b>Ground</b> Damp	<b>Temperature (°F)</b>	45.00
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b>	124300137	<b>Date/Time</b>	3/5/2021 2:34 PM	<b>Report #</b>	20785
------------	-----------	------------------	------------------	-----------------	-------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from MP 215 to MP 218.3.  
 Since last inspection Precision Pipeline has conducted ECD maintenance and ECD upgrades where needed.  
 No forward progress has been completed due to FERC shut down.  
 Right of way has been stabilized using seed, mulch, and natural vegetation.  
 No deficiencies located during VA SWPPP inspection.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	3/5/2021 2:34 PM	<b>Report #</b>	
------------	-----------	------------------	------------------	-----------------	--

## Pictures



<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.
<b>Field Station#</b>	11506+00	<b>Field Station#</b>	11506+00
<b>Pic 1 Desc.</b>	Clean water diversion pipe and plunge pool in place.	<b>Pic 2 Desc.</b>	Clean water diversion pipe inlet and clean water diversion berm in place.



<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.
<b>Field Station#</b>	11490+00	<b>Field Station#</b>	11488+00
<b>Pic 3 Desc.</b>	RCE in place at Stevers Gap Road.	<b>Pic 4 Desc.</b>	Rock lined channel in place.



<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.
<b>Field Station#</b>	11477+00	<b>Field Station#</b>	11380+00
<b>Pic 5 Desc.</b>	Two tone stabilized with ECB and slope drain pipe in place.	<b>Pic 6 Desc.</b>	Triple barrier ECDs in place at off ROW karst feature.



<b>AFE</b> 124300137	<b>Date/Time</b> 3/5/2021 2:34 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/5/2021 2:34 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20786	
<b>Inspector</b> Len Kruizenga		<b>Date/Time</b> 3/5/2021 1:41 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 11254+99	
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b> 11158+27	
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b> 41.00	
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b> 0.00	
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 3/5/2021 1:41 PM	<b>Report #</b> 20786
----------------------	-----------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)


SWPPP inspection area: Sta#11254+99 to 11158+27. MP-213 to 211  
 The row is drying and temporary stabilization is acceptable.  
 Perimeter controls are in acceptable condition.  
 Slope drains are in acceptable condition.  
 CWD pipe and plunge pool are in good condition.  
 Water bars, sump pits and end treatments are in acceptable condition.  
 Sensitive resource area ECD's are in acceptable condition.  
 ACCESS roads, Winding Way, AR-249.02, AR-249.01 are maintained in acceptable condition.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 3/5/2021 1:41 PM		Report #	
Pictures					
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11225+00		<b>Field Station#</b>	11217+00	
<b>Pic 1 Desc.</b>	P1 silt fence is in acceptable condition		<b>Pic 2 Desc.</b>	Temporary stabilization is acceptable	
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11204+00		<b>Field Station#</b>	11191+00	
<b>Pic 3 Desc.</b>	Water bar & end treatment.		<b>Pic 4 Desc.</b>	Sensitive resource area ECD's	
					
<b>GPS Location</b>	See photo GPS		<b>GPS Location</b>	See photo GPS	
<b>Field Station#</b>	11184+50		<b>Field Station#</b>	11184+00	
<b>Pic 5 Desc.</b>	AR-249.02 is maintained in acceptable condition.		<b>Pic 6 Desc.</b>	CWD pipe and plunge pool	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/5/2021 1:41 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

	Insert image here	Insert image here
---	-------------------	-------------------

<b>GPS Location</b>	See photo GPS	<b>GPS Location</b>	
---------------------	---------------	---------------------	--

<b>Field Station#</b>	11177+00	<b>Field Station#</b>	
-----------------------	----------	-----------------------	--

<b>Pic 7 Desc.</b>	Row is stable.	<b>Pic 8 Desc.</b>	
--------------------	----------------	--------------------	--

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
---------------------	--	---------------------	--

<b>Field Station#</b>		<b>Field Station#</b>	
-----------------------	--	-----------------------	--

<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	
--------------------	--	---------------------	--

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
---------------------	--	---------------------	--

<b>Field Station#</b>		<b>Field Station#</b>	
-----------------------	--	-----------------------	--

<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	
---------------------	--	---------------------	--

<b>AFE</b> 124300137	<b>Date/Time</b> 3/5/2021 1:41 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 20787	
<b>Inspector</b> Garrett Barclay		<b>Date/Time</b> 3/5/2021 3:46 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11064+53
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	11158+27
<b>County</b> Giles	<b>Ground</b> Damp	<b>Temperature (°F)</b>	37.00
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |



<b>AFE</b> 124300137	<b>Date/Time</b> 3/5/2021 3:46 PM	<b>Report #</b> 20787
----------------------	-----------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Arrived at LDY 26 for morning meeting  
 Performed SWPPP for MP 209 - MP 211  
 No damaged ECD's observed during inspection  
 ROW conditions are stable and showing minimal signs of erosion  
 No items added to the punch list  
 Observed crews hand felling trees @ AR 245.01 & Mt Tabor

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 3/5/2021 3:46 PM		Report #	
Pictures					
					
<b>GPS Location</b>		See picture above for GPS coordinates		<b>GPS Location</b>	
				See picture above for GPS coordinates	
<b>Field Station#</b>		110660+00		<b>Field Station#</b>	
				11080+00	
<b>Pic 1 Desc.</b>		ECD's and row conditions		<b>Pic 2 Desc.</b>	
				ECD's and row conditions	
					
<b>GPS Location</b>		See picture above for GPS coordinates		<b>GPS Location</b>	
				See picture above for GPS coordinates	
<b>Field Station#</b>		11098+00		<b>Field Station#</b>	
				+1	
<b>Pic 3 Desc.</b>		ECD's and row conditions		<b>Pic 4 Desc.</b>	
				Crews cutting trees	
					
<b>GPS Location</b>		See picture above for GPS coordinates		<b>GPS Location</b>	
				See picture above for GPS coordinates	
<b>Field Station#</b>		111+25		<b>Field Station#</b>	
				11140+00	
<b>Pic 5 Desc.</b>		ECD's and row conditions		<b>Pic 6 Desc.</b>	
				ECD's and row conditions	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/5/2021 3:46 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 3/5/2021 3:46 PM	<b>Report #</b>
----------------------	-----------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	