









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25093
Inspector	Charles Head			Date/Time	6/28/2021 3:38 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Full	Station End	14546+75
County	Franklin	Ground	Dry	Temperature (°F)	92.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
3rd Party Damages	Communication	Repair livestock damage to P-1			
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Repair livestock damage			
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/28/2021 3:38 PM	Report #	25093
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/28/2021 3:38 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14546+33	Field Station#	14531+58		
Pic 1 Desc.	Approximately 14546+33. Overview of stream crossing, equipment bridge and ECDs at stream S-G17.		Pic 2 Desc.	Approximately 14531+58. Overview of stream crossing, equipment bridge and ECDs at stream S-G18.	
					
GPS Location	0	GPS Location	0		
Field Station#	14524+50	Field Station#	14518+00		
Pic 3 Desc.	Approximately 14524+50. Overview of road crossing and RCEs.		Pic 4 Desc.	Approximately 14518+00. Overview of ROW.	
					
GPS Location	0	GPS Location	0		
Field Station#	14484+50	Field Station#	14457+00		
Pic 5 Desc.	Approximately 14484+50. P-1 requires maintenance. Damaged by livestock.		Pic 6 Desc.	Approximately 14457+00. Overview of ROW.	

A/E	124300139	Date/Time	6/28/2021 3:38 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/28/2021 3:38 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25085
Inspector	John White			Date/Time	6/28/2021 10:10 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Full	Station End	15772+27
County	Pittsylvania	Ground	Dry	Temperature (°F)	87.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Communication	Contractor repaired (3rd party dama		Addressed	6/28/2021
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/28/2021 10:10 AM	Report #	25085
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There was one issue identified and resolved at MVP-ATWS-631, STA # 15740+00. This was 3rd party damage by the Asphalt Contractor (Thompson Arthur) that is repaving US 29. The Contractor (Thompson Arthur) removed the asphalt tack from MVP-ATWS-631 and installed new rock. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/28/2021 10:10 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15740+00	Field Station#	15740+00		
Pic 1 Desc.	Observing asphalt tack left by Contractor paving US 29. (3rd party damage)	Pic 2 Desc.	Observing asphalt tack left by the Contractor paving US 29. (3rd party damage)		
					
GPS Location	O	GPS Location	O		
Field Station#	15740+00	Field Station#	15740+00		
Pic 3 Desc.	Observing the Contractor removing asphalt tack from the ATWS/RCE.	Pic 4 Desc.	Observing the Contractor regrading area where the asphalt tack was removed		
					
GPS Location	O	GPS Location	O		
Field Station#	15766+00	Field Station#	15670+00		
Pic 5 Desc.	Observing temporary vegetation	Pic 6 Desc.	Observing equipment crossing and ECD's		

AFE 124300139		Date/Time 6/28/2021 10:10 AM		Report #	
Pictures					
 <p>GPS photo showing a dirt road with trees and a blue marker. GPS coordinates: 40°NE (T) 36°52'37"N, 79°24'57"W ±78ft ▲780ft. Date/Time: 28 Jun 2021, 08:40:03.</p>		 <p>GPS photo showing a grassy area with a black pipe. GPS coordinates: 96°E (T) 36°52'13"N, 79°24'32"W ±18366ft ▲795ft. Date/Time: 28 Jun 2021, 08:38:34.</p>			
GPS Location O		GPS Location O			
Field Station# 15713+52		Field Station# 15720+00			
Pic 7 Desc. Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		Pic 8 Desc. Observing temporary stabilization, CWD outlet and ECD's			
 <p>GPS photo showing a grassy area with a black pipe. GPS coordinates: 65°NE (T) 36°52'19"N, 79°24'39"W ±72ft ▲865ft. Date/Time: 28 Jun 2021, 08:33:27.</p>		 <p>GPS photo showing a red dump truck. GPS coordinates: 236°SW (T) 36°52'23"N, 79°24'35"W ±13ft ▲875ft. Date/Time: 28 Jun 2021, 11:05:56.</p>			
GPS Location O		GPS Location O			
Field Station# 15738+00		Field Station# 15740+00			
Pic 9 Desc. Observing temporary vegetation, sump and end treatment.		Pic 10 Desc. Observing the Contractor (Thompson Arthur) delivering new rock to replace what was removed from the RCE/ ATWS.			
 <p>GPS photo showing a yellow tractor. GPS coordinates: 279°W (T) 36°52'24"N, 79°24'35"W ±101ft ▲877ft. Date/Time: 28 Jun 2021, 11:15:49.</p>		Insert image here			
GPS Location O		GPS Location			
Field Station# 15740+00		Field Station#			
Pic 11 Desc. Observing the Contractor installing new rock.		Pic 12 Desc.			







A/E	124300139	Date/Time	6/28/2021 10:10 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25089
Inspector	Justin Burch			Date/Time	6/28/2021 11:49 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Full	Station End	14062+17
County	Franklin	Ground	Dry	Temperature (°F)	90.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Compost Filter Sock	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/28/2021 11:49 AM	Report #	25089
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13958+31 to 14062+17 (Foggy Ridge Road to Bonbrook Mill Road #2). The contractor had an Environmental Straw Foreman walk with the EI on his inspection. No issues were submitted for the punch because inspected ECDs were found to be in compliance at the time of inspection. The EI did not observe that the contractor has worked in the inspection area since the last inspection. Since the last SWPPP inspection the inspection area has not received any rainfall events. The ROW ground condition is dry. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 14011+00 to 14018+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/28/2021 11:49 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14005+00	Field Station#	14002+00		
Pic 1 Desc.	Temporary vegetative stabilization in acceptable condition	Pic 2 Desc.	P1 silt fence and CFS in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	14008+00	Field Station#	14008+00		
Pic 3 Desc.	Waterbar in acceptable condition	Pic 4 Desc.	Waterbar end treatment in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	14021+00	Field Station#	14014+00		
Pic 5 Desc.	Perimeter CFS in acceptable condition	Pic 6 Desc.	Permanent vegetative stabilization in acceptable condition		

A/E	124300139	Date/Time	6/28/2021 11:49 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		


A/E	124300139	Date/Time	6/28/2021 11:49 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25017
Inspector	Ben Davenport			Date/Time	6/28/2021 10:29 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Partial	Station End	14928+52
County	Franklin	Ground	Dry	Temperature (°F)	90.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Equipment Bridge	Acceptable				
Compost Filter Sock	Acceptable				
Sediment Filter Log	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Temporary Diversion Berm	Acceptable				
Sump Pit	Acceptable				
Slope Drain Pipe	Acceptable				
Waterbar End Treatment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/28/2021 10:29 AM	Report #	25017
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14802+19 — 14928+52 (MVP-FR-323 to Ramsey Memorial Rd) -Walked ROW with environmental foreman looking for potential environmental issues or maintenance requirements -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of equipment bridges and ECDs at resource buffers around stream crossings -Observed condition of vegetation in section both permanent and temporary areas of ROW -Continue to monitor ROW for signs of erosion -No items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/28/2021 10:29 AM	Report #	
Pictures					
					
36°58'23" N 79°40'10" W 238°SW COURSE 269' GPS 355 Listening Hill Rd, Penhook, VA 24137, United States 06.28.2021 10:13:18 Accur +/-147.0 Ft ALT 969 Ft			36°58'22" N 79°40'0" W 312°NW COURSE 283' GPS 355 Listening Hill Rd, Penhook, VA 24137, United States 06.28.2021 10:10:21 Accur +/-43.8 Ft ALT 946 Ft		
GPS Location	1	GPS Location	2		
Field Station#	14832+61	Field Station#	14842+00		
Pic 1 Desc.	Equipment bridge and surrounding ECDs in good condition at stream crossing.		Pic 2 Desc.	Temporary diversion berm performing intended function.	
					
36°58'19" N 79°39'49" W 275°W COURSE 23' GPS 355 Listening Hill Rd, Penhook, VA 24137, United States 06.28.2021 10:06:52 Accur +/-16.6 Ft ALT 947 Ft			36°58'19" N 79°39'49" W 131°SE COURSE 348' GPS 355 Listening Hill Rd, Penhook, VA 24137, United States 06.28.2021 10:06:45 Accur +/-27.6 Ft ALT 949 Ft		
GPS Location	3	GPS Location	4		
Field Station#	14851+00	Field Station#	14852+00		
Pic 3 Desc.	Slope drain tile outlet into sump in good condition. Sump CFS end treatment performing intended function.		Pic 4 Desc.	CWD pipe in good condition. CFS and P1 silt fence surrounding outlet in good condition.	
					
36°58'16" N 79°39'33" W 134°SE COURSE 53' GPS 1760 Bar Ridge Rd, Penhook, VA 24137, United States 06.28.2021 11:46:18 Accur +/-54.6 Ft ALT 975 Ft			36°58'15" N 79°39'28" W 88°E COURSE 106' GPS 1760 Bar Ridge Rd, Penhook, VA 24137, United States 06.28.2021 11:48:02 Accur +/-49.3 Ft ALT 918 Ft		
GPS Location	5	GPS Location	6		
Field Station#	14864+00	Field Station#	14868+00		
Pic 5 Desc.	ROW stabilized in temporary area but limited vegetative growth observed.		Pic 6 Desc.	Slope drain tile inlet and surrounding CFS ECDs performing intended functions.	

A/E	124300139	Date/Time	6/28/2021 10:29 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







AFE	124300139	Date/Time	6/28/2021 10:29 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25102
Inspector	Ben Farmer			Date/Time	6/28/2021 6:53 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Partial	Station End	15370+62
County	Pittsylvania	Ground	Dry	Temperature (°F)	80.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)		Communication	P1 has been damaged and needs to be replaced	Addressed	6/28/2021
Cleanwater Diversion Pipe		Acceptable			
Compost Filter Sock		Acceptable			
Equipment Bridge		Acceptable			
Rock Construction Entrance		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Waterbar		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/28/2021 6:53 PM	Report #	25102
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 80 F) Rain Gauge= 0.0" 15260+00-15370+62 -EI began inspection at Snowberry Rd. -RCEs are in good condition at all road crossings. -MVP-PI-332 is in good condition with controls in place. -Equipment bridge ECDs are in place and functioning. -P1 is in good condition at all stream and wetland buffers. -Waterbars are in good condition throughout this section. -CWDs are functioning as intended. -P1 has been damaged at 15335+00 and needs to be replaced. Environmental crew has corrected this issue. -Wetland ECDs are in good condition at 15311+78. -CFS in good condition on slope at 15310+00. -Vegetation continuing to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/28/2021 6:53 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15335+00		Field Station#	15335+00	
Pic 1 Desc.	P1 has been damaged and needs to be replaced.		Pic 2 Desc.	Environmental crew has corrected this issue.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15370+00		Field Station#	15350+00	
Pic 3 Desc.	Vegetation continues to fill in throughout this section.		Pic 4 Desc.	MVP-PI-332 is in good condition with controls in place.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15347+00		Field Station#	15346+20	
Pic 5 Desc.	Equipment bridge ECDs are in good condition.		Pic 6 Desc.	P1 is in good condition at all stream and wetland buffers.	

AFE	124300139	Date/Time	6/28/2021 6:53 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15343+73		Field Station#	15338+00	
Pic 7 Desc.	Waterbars are in good condition.		Pic 8 Desc.	CWDs are functioning as intended.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15323+24		Field Station#	15311+78	
Pic 9 Desc.	RCEs are in good condition at all road crossings.		Pic 10 Desc.	Wetland buffer P1 is in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15310+00		Field Station#	15299+00	
Pic 11 Desc.	CFS in good condition on this slope.		Pic 12 Desc.	CWD is functioning as intended.	







A/E	124300139	Date/Time	6/28/2021 6:53 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25135
Inspector	Logan Box			Date/Time	6/29/2021 4:13 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13670+00
State	VA	Inspection Area	Partial	Station End	13748+30
County	Franklin	Ground	Dry	Temperature (°F)	90.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Equipment Bridge	Acceptable				
Sump Pit	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/29/2021 4:13 PM	Report #	25135
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored Sump pits and end treatment , observed vegetation stabilization on spoil piles .</p> <p>Throughout today's inspections there were no environmental issues observed at the time of inspection.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/29/2021 4:13 PM	Report #	
Pictures					
	East Elevation <small>305°NW (T) • 37.075477, -79.940419 ±3 m ▲ 326 m</small> 			East Elevation <small>284°W (T) • 37.088518, -79.950259 ±3 m ▲ 319 m</small> 	
GPS Location	00000	GPS Location	00000		
Field Station#	13743+90	Field Station#	13678+60		
Pic 1 Desc.	Vegetation observation photo showing temporary grass in permanent area. Some new vegetation growing.		Pic 2 Desc.	Row photo showing vegetation, good coverage observed.	
	East Elevation <small>292°W (T) • 37.078716, -79.94112 ±10 m ▲ 331 m</small> 			East Elevation <small>289°W (T) • 37.077292, -79.93949 ±3 m ▲ 345 m</small> 	
GPS Location	00000	GPS Location	00000		
Field Station#	13728+88	Field Station#	13738+60		
Pic 3 Desc.	Photo showing stabilization on hill side at stream crossing. No issues observed at the time of inspection.		Pic 4 Desc.	Vegetation observation photo. Good coverage noted with some new vegetation growing.	
	South West Elevation <small>35°NE (T) • 37.08854, -79.950267 ±3 m ▲ 319 m</small> 			North Elevation <small>208°S (T) • 37.088518, -79.950263 ±3 m ▲ 319 m</small> 	
GPS Location	00000	GPS Location	00000		
Field Station#	13678+71	Field Station#	13678+71		
Pic 5 Desc.	Stream observation photo facing upstream during routine inspection today , no environmental issues observed at the time of inspection		Pic 6 Desc.	Stream observation photo facing downstream during routine inspection today. No environmental issues observed at the time of inspection	

A/E	124300139	Date/Time	6/29/2021 4:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/29/2021 4:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25134
Inspector	John White			Date/Time	6/29/2021 9:58 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15772+27
State	VA	Inspection Area	Full	Station End	15947+64
County	Pittsylvania	Ground	Dry	Temperature (°F)	80.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe		Acceptable			
Compost Filter Sock		Acceptable			
Equipment Bridge		Acceptable			
Housekeeping		Acceptable			
Rock Filter Outlet		Acceptable			
Sediment Filter Log		Acceptable			
Sensitive Resource Buffer		Acceptable			
Sensitive Resource Signage		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/29/2021 9:58 AM	Report #	25134
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/29/2021 9:58 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15923+49	Field Station#	15878+08		
Pic 1 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15866+00	Field Station#	15825+00		
Pic 3 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 4 Desc.	Observing temporary stabilization,plunge pool and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15789+00	Field Station#	15794+77		
Pic 5 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 6 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		







A/E	124300139	Date/Time	6/29/2021 9:58 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location			
Field Station#	15807+00	Field Station#			
Pic 7 Desc.	Observing temporary stabilization	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	6/29/2021 9:58 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25141
Inspector	Ben Farmer			Date/Time	6/29/2021 12:28 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15370+62
State	VA	Inspection Area	Partial	Station End	15480+67
County	Pittsylvania	Ground	Dry	Temperature (°F)	78.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter	Acceptable				
Rock Filter Outlet	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
Sensitive Resource Buffer	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	6/29/2021 12:28 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15475+00		Field Station#	15465+00	
Pic 1 Desc.	3rd party rock outlet appears to be in good condition.		Pic 2 Desc.	No evidence of sedimentation from 3rd party rock outlet.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15460+81		Field Station#	15460+81	
Pic 3 Desc.	No evidence of sedimentation from 3rd party rock outlet.		Pic 4 Desc.	CWD is in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15457+00		Field Station#	15453+00	
Pic 5 Desc.	Drainage ECDs are in good condition with no evidence of sedimentation from 3rd party disturbance.		Pic 6 Desc.	CWD remains in good condition.	

AFE	124300139	Date/Time	6/29/2021 12:28 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15445+00		Field Station#	15427+43	
Pic 7 Desc.	Vegetation continues to fill in throughout this section.		Pic 8 Desc.	P1 is in good condition at all stream and wetland buffers.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15405+00		Field Station#	15385+00	
Pic 9 Desc.	Vegetation continues to fill in throughout this section.		Pic 10 Desc.	Sensitive resource buffer is in good condition at this location.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15384+74		Field Station#	15380+00	
Pic 11 Desc.	Equipment bridge ECDs are in place and functioning.		Pic 12 Desc.	Waterbars are functioning as intended.	

AFE	124300139	Date/Time	6/29/2021 12:28 PM	Report #	
Pictures					
		<p>Insert image here</p>			
GPS Location	See photo	GPS Location			
Field Station#	15375+00	Field Station#			
Pic 13 Desc.	Drainage ECDs are in place and functioning.	Pic 14 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25149
Inspector	Charles Head			Date/Time	6/29/2021 3:28 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14546+75
State	VA	Inspection Area	Full	Station End	14649+67
County	Franklin	Ground	Dry	Temperature (°F)	90.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/29/2021 3:28 PM	Report #	25149
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/29/2021 3:28 PM	Report #	
Pictures					
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 1 Desc.		Pic 2 Desc.			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 3 Desc.		Pic 4 Desc.			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300139	Date/Time	6/29/2021 3:28 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/29/2021 3:28 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25136
Inspector	Justin Burch			Date/Time	6/29/2021 10:48 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14062+57
State	VA	Inspection Area	Full	Station End	14171+36
County	Franklin	Ground	Dry	Temperature (°F)	91.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Equipment Bridge	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/29/2021 10:48 AM	Report #	25136
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 14062+17 to 14171+36 (Bonbrook Mill Road #2 to Angle Plantation Road). An Environmental Straw Foreman from Precision walked with the EI on his inspection. Inspected ECDs were found to be in compliance at the time of inspection so no issues were submitted for the punch. • The EI did not observe that the contractor has worked in the inspection area since the last inspection. • Since the last SWPPP inspection the inspection area has not received any rainfall events. • The ROW ground condition is dry. • At the time of inspection permanent vegetative stabilization was observed as adequately established to inhibit erosion from 14112+00 to 14120+00 and from 14164+00 to 14167+00. • At the time of inspection temporary vegetative stabilization was observed as adequately established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/29/2021 10:48 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14065+00	Field Station#	14084+00		
Pic 1 Desc.	perimeter CFS in acceptable condition		Pic 2 Desc.	Waterbar in acceptable condition	
					
GPS Location	0	GPS Location	0		
Field Station#	14084+00	Field Station#	14105+26		
Pic 3 Desc.	Waterbar end treatment in acceptable condition		Pic 4 Desc.	Equipment bridge in acceptable condition	
					
GPS Location	0	GPS Location	0		
Field Station#	14115+00	Field Station#	14157+00		
Pic 5 Desc.	Permanent vegetative stabilization in acceptable condition		Pic 6 Desc.	P1 silt fence in acceptable condition	

A/E	124300139	Date/Time	6/29/2021 10:48 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/29/2021 10:48 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25091
Inspector	Ben Davenport			Date/Time	6/29/2021 11:37 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14928+52
State	VA	Inspection Area	Partial	Station End	15063+85
County	Franklin/Pittsylvania	Ground	Dry	Temperature (°F)	92.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance			
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Plunge Pool	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sediment Filter Log	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/29/2021 11:37 AM	Report #	25091
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14928+52 — 15063+85 (Ramsey Memorial Rd to Armstrong Rd) -Walked ROW with environmental foreman making note of condition of ROW and environmental controls -Perimeter controls and ECD's were inspected; 1 issue identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Continue to monitor ROW for signs of erosion -1 item added to environmental punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/29/2021 11:37 AM	Report #	
Pictures					
					
36°58'2" N 79°37'51" W 75°E COURSE 279° GPS Sorry no results found 06.29.2021 08:40:47 Accur +/-46.2 Ft ALT 827 Ft			36°58'4" N 79°38'12" W 65°NE COURSE 174° GPS Sorry no results found 06.29.2021 08:32:02 Accur +/-85.7 Ft ALT 823 Ft		
GPS Location	1		GPS Location	2	
Field Station#	14949+48		Field Station#	14932+00	
Pic 1 Desc.	Routine maintenance. Replace damaged panels of P1 silt fence.		Pic 2 Desc.	P1 silt fence at resource buffer in good condition.	
					
36°58'3" N 79°38'3" W 24°NE COURSE 112° GPS Sorry no results found 06.29.2021 08:35:09 Accur +/-87.8 Ft ALT 827 Ft			36°57'57" N 79°37'21" W 222°SW COURSE 290° GPS Penhook, VA 24137, United States 06.29.2021 09:07:18 Accur +/-25.0 Ft ALT 934 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14938+00		Field Station#	14975+00	
Pic 3 Desc.	Natural drainage area in good condition. Equipment bridge and surrounding ECDs in place and functional.		Pic 4 Desc.	Plunge pool, CFS, and perimeter SSF in good condition and performing intended functions.	
					
36°57'56" N 79°37'10" W 216°SW COURSE 214° GPS 101-119 Ashworth Rd, Penhook, VA 24137, United States 06.29.2021 09:03:22 Accur +/-65.3 Ft ALT 938 Ft			36°57'51" N 79°35'43" W 345°N COURSE 267° GPS 1923-2165 Armstrong Rd, Penhook, VA 24137, United States 06.29.2021 08:00:59 Accur +/-50.5 Ft ALT 929 Ft		
GPS Location	5		GPS Location	6	
Field Station#	14983+00		Field Station#	15056+50	
Pic 5 Desc.	Plunge pool and CWD pipe in place and functional.		Pic 6 Desc.	ROW stabilized in temporary area. CFS triple stack at resource buffer in good condition.	

A/E	124300139	Date/Time	6/29/2021 11:37 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/29/2021 11:37 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25193
Inspector	John White			Date/Time	6/30/2021 10:45 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15947+27
State	VA	Inspection Area	Full	Station End	16027+46
County	Pittsylvania	Ground	Dry	Temperature (°F)	82.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/30/2021 10:45 AM	Report #	25193
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/30/2021 10:45 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	16005+00	Field Station#	16007+00		
Pic 1 Desc.	Observing temporary vegetation, sump and end treatment	Pic 2 Desc.	Observing temporary vegetation, water bar, sump and end treatment		
					
GPS Location	O	GPS Location	O		
Field Station#	16004+00	Field Station#	16010+00		
Pic 3 Desc.	Observing temporary vegetation, signage and buffer	Pic 4 Desc.	Observing temporary vegetation, CWD outlet and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	16016+36	Field Station#	16022+00		
Pic 5 Desc.	Observing temporary vegetation, signage, buffer, equipment crossing and ECD's	Pic 6 Desc.	Observing temporary stabilization and water bars.		

A/E	124300139	Date/Time	6/30/2021 10:45 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/30/2021 10:45 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25199
Inspector	Ben Farmer			Date/Time	6/30/2021 12:59 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15480+67
State	VA	Inspection Area	Partial	Station End	15584+23
County	Pittsylvania	Ground	Dry	Temperature (°F)	83.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	6/30/2021 12:59 PM	Report #	25199
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 82 F) Rain Gauge= 0.0" 15480+67-15584+23 -EI began inspection at Toshes Rd. -RCEs are in good condition at all road crossings. -CFS has been damaged at 15498+19 along ATWS-819/820 by 3rd party. Issue to be addressed with 3rd party contractor before adding to punch list. LEI has been notified of this issue. -EI will continue to monitor 3rd party disturbance at 15505+00. -P1 is in good condition at all stream and wetland crossings. -3rd party ECDs appear to be in good condition condition with no evidence of sedimentation at 15510+00. -CWDs are in good condition throughout this section. -Equipment bridge ECDs are in place and functioning. -Waterbars are in good condition throughout this section. -3rd party disturbance occurring upslope from ROW at 15556+83. This disturbance is upslope from S-CC9 with no ECDs in place. EI will continue to monitor this area. -Slope drain functioning as intended at 15575+27. -Vegetation continuing to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/30/2021 12:59 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15495+00		Field Station#	15496+70	
Pic 1 Desc.	Vegetation continues to fill in throughout this section.		Pic 2 Desc.	RCEs are in good condition at all road crossings.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15498+19		Field Station#	15498+19	
Pic 3 Desc.	CFS has been damaged by 3rd party. 3rd party to be made aware of this issue.		Pic 4 Desc.	CFS has been damaged by 3rd party. 3rd party to be made aware of this issue.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15498+19		Field Station#	15505+00	
Pic 5 Desc.	CFS has been damaged by 3rd party. 3rd party to be made aware of this issue.		Pic 6 Desc.	3rd party disturbance occurring next to MVP ROW. EI will continue to monitor this area.	

AFE	124300139	Date/Time	6/30/2021 12:59 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15506+41		Field Station#	15510+00	
Pic 7 Desc.	P1 is in good condition at all stream and wetland buffers.		Pic 8 Desc.	3rd party ECDs appear to be in good condition with no evidence of sedimentation.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15515+00		Field Station#	15540+00	
Pic 9 Desc.	CWDs are in good condition throughout this section.		Pic 10 Desc.	Equipment bridge ECDs are in place and functioning.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15547+37		Field Station#	15556+83	
Pic 11 Desc.	Warerbars are in good condition.		Pic 12 Desc.	3rd party disturbance occurring upslope of stream S-CC9. EI will continue to monitor this area.	

AFE	124300139	Date/Time	6/30/2021 12:59 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location			
Field Station#	15575+27	Field Station#			
Pic 13 Desc.	Slope drain is functioning as intended.	Pic 14 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	25196	
Inspector	Glenn Mike Renfro			Date/Time	6/30/2021 11:51 AM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0000+00	
State	VA	Inspection Area	Full	Station End	0000+00	
County	Franklin	Ground	Dry	Temperature (°F)	84.00	
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable					
Housekeeping	Acceptable					
Rock Construction Entrance	Acceptable					
Secondary Containment	Acceptable					
Other - Explain in Comments	Acceptable	Inlet protection for catch basins				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

AFE	124300139	Date/Time	6/30/2021 11:51 AM	Report #	25196
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> - Performed SWPPP inspection of Spread I main laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va. - The locations have not received any rainfall since the last inspection and site conditions were dry. - All perimeter ECD's were inspected and no problems were found. - The inlet protection for the catch basins at LY-046 were in good condition. - All secondary containment structures at both locations were found to be in good condition. - All equipment at both locations were inspected and no leaks were observed at the time of the inspections. - The RCE at LY-045 was in good condition at the time of inspection. - The contact information and General Construction permits are posted at the main entrance of LY-046 as required. - There were no issues found to report during today's inspections. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/30/2021 11:51 AM	Report #	
Pictures					
					
GPS Location	000000000000	GPS Location	000000000000		
Field Station#	0000+00	Field Station#	0000+00		
Pic 1 Desc.	Inlet protection for catch basin on north end of LY-046 in good condition.	Pic 2 Desc.	Secondary containment structure for fuel cell at LY-046 in good condition.		
					
GPS Location	000000000000	GPS Location	000000000000		
Field Station#	0000+00	Field Station#	0000+00		
Pic 3 Desc.	Perimeter ECD's and secondary containment structure for light plant on south end of LY-046 in good condition.	Pic 4 Desc.	Secondary containment structure on northwest corner of LY-045 near conex box in good condition.		
		Insert image here			
GPS Location	000000000000	GPS Location			
Field Station#	0000+00	Field Station#			
Pic 5 Desc.	RCE at LY-045 in good condition.	Pic 6 Desc.			

A/E	124300139	Date/Time	6/30/2021 11:51 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/30/2021 11:51 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25205
Inspector	Charles Head			Date/Time	6/30/2021 3:21 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14649+67
State	VA	Inspection Area	Full	Station End	14694+77
County	Franklin	Ground	Dry	Temperature (°F)	93.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/30/2021 3:21 PM	Report #	25205
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/30/2021 3:21 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14652+00	Field Station#	14656+90		
Pic 1 Desc.	Approximately 14652+00. Observed area where it appears a third party has clipped vegetation around log pile.		Pic 2 Desc.	Approximately 14656+90. Overview of stream crossing, equipment bridge and ECDs at stream S-H38.	
GPS Location	0	GPS Location	0		
Field Station#	14667+00	Field Station#	14673+10		
Pic 3 Desc.	Approximately 14667+00. Overview of ROW.		Pic 4 Desc.	Approximately 14673+10. Overview of stream crossing, equipment bridge and ECDs at stream S-H37.	
GPS Location	0	GPS Location	0		
Field Station#	14689+36	Field Station#	14694+50		
Pic 5 Desc.	Approximately 14689+36. Overview of stream crossing, equipment bridge and ECDs at stream S-H34.		Pic 6 Desc.	Approximately 14694+50. Overview of road crossing and RCE.	

A/E	124300139	Date/Time	6/30/2021 3:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/30/2021 3:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25132
Inspector	Ben Davenport			Date/Time	6/30/2021 9:25 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15063+85
State	VA	Inspection Area	Partial	Station End	15142+66
County	Pittsylvania	Ground	Dry	Temperature (°F)	91.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication	Routine maintenance	Addressed	6/30/2021	
Waterbar End Treatment	Communication	Routine maintenance	Addressed	6/30/2021	
Vegetative Stabilization (Temporary)	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/30/2021 9:25 AM	Report #	25132
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 15063+85 — 15142+66 (Armstrong Rd to Rock Creek Rd) -Walked ROW with environmental foreman making note of condition of ROW and environmental controls -Observed contractor performing environmental maintenance between Armstrong Rd and Museville Rd -Perimeter controls and ECD's were inspected; multiple issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Continue to monitor ROW for signs of erosion -2 items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/30/2021 9:25 AM	Report #	
Pictures					
					
36 57 36" N 79 35 10" W 232°SW COURSE 210° GPS Sandy Level, VA 24161, United States 06.30.2021 09:54:27 Accur +/-15.4 Ft ALT 842 Ft		36 57 35" N 79 35 10" W 121°SE COURSE 171° GPS Sandy Level, VA 24161, United States 06.30.2021 09:55:11 Accur +/-15.4 Ft ALT 842 Ft			
GPS Location	1	GPS Location	2		
Field Station#	14989+00	Field Station#	14992+00		
Pic 1 Desc.	Routine maintenance. Replace damaged/worn perimeter CFS and CFS end treatments on low side of ROW		Pic 2 Desc.	Routine maintenance. Replace damaged/worn perimeter CFS and CFS end treatments on low side of ROW	
					
36 57 37" N 79 35 11" W 183°S COURSE 275° GPS Sandy Level, VA 24161, United States 06.30.2021 09:47:28 Accur +/-17.5 Ft ALT 869 Ft		36 57 33" N 79 35 10" W 301°NW COURSE 0° GPS Sandy Level, VA 24161, United States 06.30.2021 09:00:03 Accur +/-71.0 Ft ALT 0 Ft			
GPS Location	3	GPS Location	4		
Field Station#	14990+00	Field Station#	14993+50		
Pic 3 Desc.	Contractor removing damaged/worn perimeter CFS as needed		Pic 4 Desc.	Contractor replaced perimeter CFS per punch list items	
					
36 57 32" N 79 35 7" W 261°W COURSE 122° GPS Sandy Level, VA 24161, United States 06.30.2021 09:06:22 Accur +/-87.8 Ft ALT 828 Ft		36 57 17" N 79 34 53" W 166°S COURSE 160° GPS 8850-8968 Museville Rd, Sandy Level, VA 24161, United States 06.30.2021 09:20:54 Accur +/-230.8 Ft ALT 928 Ft			
GPS Location	5	GPS Location	6		
Field Station#	14998+00	Field Station#	15117+00		
Pic 5 Desc.	Contractor replaced perimeter CFS per punch list items		Pic 6 Desc.	ROW stabilized and vegetated in temporary area	

A/E	124300139	Date/Time	6/30/2021 9:25 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/30/2021 9:25 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25197
Inspector	Justin Burch			Date/Time	6/30/2021 12:24 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14171+36
State	VA	Inspection Area	Full	Station End	14311+57
County	Franklin	Ground	Dry	Temperature (°F)	91.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Other - Explain in Comments	Communication				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Compost Filter Sock	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/30/2021 12:24 PM	Report #	25197
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 14171+36 to 14311+57 (Angle Plantation Road to Farm View Road). Two issues were submitted for the punch list consisting of two locations where electric fence was damaged by livestock. Other inspected ECDs were in compliance at the time of inspection. The EI observed the contractor has performed anode installation on buried pipe in the inspection area. The disturbed areas were temporarily stabilized. Since the last SWPPP inspection the inspection area has not received any rainfall events. The ROW ground condition is dry. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 14258+00 to 14277+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	6/30/2021 12:24 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14195+00	Field Station#	14195+00		
Pic 1 Desc.	Waterbar in acceptable condition		Pic 2 Desc.	Waterbar end treatment in acceptable condition 1420500	
					
GPS Location	0	GPS Location	0		
Field Station#	14205+00	Field Station#	14251+00		
Pic 3 Desc.	Electric fence damaged by livestock		Pic 4 Desc.	P1 silt fence in acceptable condition	
					
GPS Location	0	GPS Location	0		
Field Station#	14295+00	Field Station#	14301+00		
Pic 5 Desc.	Electric fence damaged by livestock		Pic 6 Desc.	Perimeter CFS in acceptable condition	

A/E	124300139	Date/Time	6/30/2021 12:24 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/30/2021 12:24 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-603 Pipeline Spread I	AFE	124300139	Spread	H-603 Pipeline Spread I	
Contractor	Precision			Report #	25188	
Inspector	John White			Date/Time	6/30/2021 10:25 AM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	24+53	
County	Pittsylvania	Ground	Dry	Temperature (°F)	82.00	
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Communication	Contractor repaired upon discovery	Addressed	6/30/2021	
Housekeeping		Acceptable				
Sensitive Resource Buffer		Acceptable				
Sensitive Resource Signage		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	6/30/2021 10:25 AM	Report #	25188
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There was one issue identified and repaired upon discovery by the Contractor. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/30/2021 10:25 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	12+00	Field Station#	12+00		
Pic 1 Desc.	Observing CFS that required maintenance		Pic 2 Desc.	Observing CFS that received maintenance	
GPS Location	O	GPS Location	O		
Field Station#	20+00	Field Station#	15+73		
Pic 3 Desc.	Observing temporary vegetation, signage and buffer		Pic 4 Desc.	Observing temporary vegetation, signage and buffer	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.			Pic 6 Desc.		

A/E	124300139	Date/Time	6/30/2021 10:25 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	6/30/2021 10:25 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-602 Pipeline Spread I	AFE	124300139	Spread	H-602 Pipeline Spread I	
Contractor	Precision			Report #	25191	
Inspector	John White			Date/Time	6/30/2021 10:39 AM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00	
State	VA	Inspection Area	Full	Station End	19+25	
County	Pittsylvania	Ground	Dry	Temperature (°F)	82.00	
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Equipment Bridge		Acceptable				
Housekeeping		Acceptable				
Sediment Filter Log		Acceptable				
Sensitive Resource Buffer		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	6/30/2021 10:39 AM	Report #	25191
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/30/2021 10:39 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	19+00	Field Station#	15+00		
Pic 1 Desc.	Observing temporary vegetation and ECD's		Pic 2 Desc.	Observing temporary vegetation and matt travel lane	
GPS Location	O	GPS Location	O		
Field Station#	12+65	Field Station#	6+00		
Pic 3 Desc.	Observing temporary vegetation,buffer, equipment crossing and ECD's		Pic 4 Desc.	Observing temporary vegetation and access road	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.			Pic 6 Desc.		

A/E	124300139	Date/Time	6/30/2021 10:39 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	6/30/2021 10:39 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25187
Inspector	Logan Box			Date/Time	6/30/2021 4:00 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13748+30
State	VA	Inspection Area	Partial	Station End	13853+45
County	Franklin	Ground	Dry	Temperature (°F)	93.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Plunge Pool	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Equipment Bridge	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	6/30/2021 4:00 PM	Report #	25187
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI Traveled and inspected all ECDs throughout the row, monitored vegetation growth throughout.</p> <p>Inspected all stream and wetland crossings, checked equipment bridges and protection.</p> <p>Monitored clean water diversion and plunge pool , observed vegetation stabilization on spoil piles .</p> <p>Throughout today's inspections there were no environmental issues observed at the time of inspection.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/30/2021 4:00 PM	Report #	
Pictures					
	North West Elevation <small>125°SE (T) 37.070798, -79.937014 ±3 m 304 m</small> 			North East Elevation <small>220°SW (T) 37.05917, -79.92114 ±3 m 309 m</small> 	
GPS Location	00000	GPS Location	00000		
Field Station#	13770+69	Field Station#	13850+00		
Pic 1 Desc.	Stream observation photo facing downstream during routine inspection today. No issues observed at the time of inspection. Good vegetation noted.		Pic 2 Desc.	Row photo showing stabilization. No issues observed at the time of inspection.	
	West Elevation <small>111°E (T) 37.062363, -79.921224 ±3 m 283 m</small> 			North Elevation <small>187°S (T) 37.069731, -79.93302 ±3 m 307 m</small> 	
GPS Location	00000	GPS Location	00000		
Field Station#	13840+00	Field Station#	13784+35		
Pic 3 Desc.	Monitored clean water diversion pipe and plunge pool. No environmental issues observed at the time of inspection.		Pic 4 Desc.	Row photo showing stabilization above stream crossing . No environmental issues observed at the time of inspection.	
	North Elevation <small>192°S (T) 37.070844, -79.937063 ±3 m 304 m</small> 			North West Elevation <small>129°SE (T) 37.069311, -79.926949 ±3 m 313 m</small> 	
GPS Location	0000	GPS Location	00000		
Field Station#	13770+60	Field Station#	13803+00		
Pic 5 Desc.	Monitored equipment bridge and protection at stream crossing . No issues observed at the time of inspection.		Pic 6 Desc.	Photo showing good stabilization on hill side above stream crossing. ECDs in place and functioning.	

A/E	124300139	Date/Time	6/30/2021 4:00 PM	Report #	
Pictures					
		<p>Insert image here</p>		<p>Insert image here</p>	
GPS Location	00000	GPS Location			
Field Station#	13770+69	Field Station#			
Pic 7 Desc.	Stream observation photo facing upstream during routine inspection today. No environmental issues observed at the time of inspection. <i>Q. alba</i> not detected.		Pic 8 Desc.		
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
<p>Insert image here</p>		<p>Insert image here</p>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	6/30/2021 4:00 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		











Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25255
Inspector	Ben Farmer			Date/Time	7/1/2021 1:02 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15142+66
State	VA	Inspection Area	Partial	Station End	15260+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	84.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication	CFS has been displaced and needs			
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter	Acceptable				
Rock Filter Outlet	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	7/1/2021 1:02 PM	Report #	25255
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 84 F) Rain Gauge= 0.0" 15142+66-15260+00 -EI began inspection at HDD Exit. (15260+00) -RCEs are in good condition at all road crossings. -CFS needs to be restaked at 15197+00. -Fence gap remains open by 3rd party allowing livestock onto ROW at 15195+50. -Drainage ECDs are in good condition at 15195+00. -Slope drain is functioning as intended at 15170+00. -Waterbars are in good condition throughout this section. -Equipment bridge ECDs are in place and functioning. -P1 is in good condition at all stream and wetland crossings. -Rock inlet/outlet is in good condition and functioning at 15165+57/15166+00. -Previously replaced CFS is in good condition at 15147+00. -Vegetation continuing to fill in throughout this section. *Issues identified in the field have been added to the punch list to be addressed by the contractor.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	7/1/2021 1:02 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15197+00		Field Station#	15260+00	
Pic 1 Desc.	CFS needs to be restaked at this location.		Pic 2 Desc.	Vegetation continues to fill in throughout this section.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15240+00		Field Station#	15209+00	
Pic 3 Desc.	Vegetation continues to fill in throughout this section.		Pic 4 Desc.	Vegetation continues to fill in throughout this section.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15195+50		Field Station#	15195+00	
Pic 5 Desc.	Fence gap remains open by 3rd party allowing livestock onto ROW.		Pic 6 Desc.	Drainage ECDs are in good condition.	

AFE	124300139	Date/Time	7/1/2021 1:02 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15170+00		Field Station#	15170+00	
Pic 7 Desc.	Waterbars are in good throughout this section.		Pic 8 Desc.	Slope drain is functioning as intended.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15167+95		Field Station#	15167+95	
Pic 9 Desc.	Equipment bridge ECDs are in place and functioning.		Pic 10 Desc.	P1 is in good condition at this stream crossings.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15166+00		Field Station#	15165+57	
Pic 11 Desc.	Rock outlet remains in good condition.		Pic 12 Desc.	Rock inlet remains in good condition.	







AFE	124300139	Date/Time	7/1/2021 1:02 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15147+00	Field Station#	15142+66		
Pic 13 Desc.	Previously replaced CFS remains in good condition.	Pic 14 Desc.	RCE is in good condition at Rockcreek Rd.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25253
Inspector	Justin Burch			Date/Time	7/1/2021 11:20 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13853+45
State	VA	Inspection Area	Full	Station End	13958+31
County	Franklin	Ground	Dry	Temperature (°F)	87.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Waterbar End Treatment	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	7/1/2021 11:20 AM	Report #	25253
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 13853+45 to 13958+31 (access road MVP-FR-303.01 to Foggy Ridge Road). Inspected ECDs were found to be in compliance at the time of inspection so no issues were submitted for the punch. • The EI did not observe that the contractor has worked in the inspection area since the last inspection. • Since the last SWPPP inspection the inspection area has not received any rainfall events. A rain event began at 1:50 P.M. Gauges will be read at the end of the event. • The ROW ground condition was dry at the time of inspection. • At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 13900+00 to 13910+00 and from 13921+00 to 13940+00. • At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	7/1/2021 11:20 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	13953+00	Field Station#	13955+00		
Pic 1 Desc.	Waterbar end treatment in acceptable condition	Pic 2 Desc.	Sump pit in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	13930+00	Field Station#	13878+00		
Pic 3 Desc.	Permanent vegetative stabilization in acceptable condition	Pic 4 Desc.	Temporary vegetative stabilization in acceptable condition		
					
GPS Location	0	GPS Location	0		
Field Station#	13889+00	Field Station#	13862+00		
Pic 5 Desc.	P1 silt fence in acceptable condition	Pic 6 Desc.	Super silt fence in acceptable condition		

A/E	124300139	Date/Time	7/1/2021 11:20 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	7/1/2021 11:20 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25202
Inspector	Ben Davenport			Date/Time	7/1/2021 12:42 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14694+77
State	VA	Inspection Area	Partial	Station End	14802+19
County	Franklin	Ground	Dry	Temperature (°F)	90.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Temporary)	Acceptable				
Sump Pit	Acceptable				
Rock Construction Entrance	Acceptable				
Compost Filter Sock	Acceptable				
Waterbar End Treatment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	7/1/2021 12:42 PM	Report #	25202
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with dry ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14694+77 - 14802+19 (Jacks Creek Rd to MVP-FR-323) -Walked ROW with environmental foreman making note of condition of ROW and environmental controls -Perimeter controls and ECDs were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Continue to monitor ROW for signs of erosion -No items added to punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	7/1/2021 12:42 PM	Report #	
Pictures					
					
<small>36°59'11" N 79°41'24" W 24°NE COURSE 287' GPS Union Hall, VA 24176, United States 07.01.2021 10:00:43 Accur +/-126.8 Ft ALT 983 Ft</small>			<small>36°59'0" N 79°41'23" W 102°E COURSE 294' GPS 701-1081 Indian Cave Rd, Union Hall, VA 24176, United States 07.01.2021 09:54:49 Accur +/-15.5 Ft ALT 949 Ft</small>		
GPS Location	1		GPS Location	2	
Field Station#	14756+00		Field Station#	14758+16	
Pic 1 Desc.	ROW stabilized but limited vegetative growth observed or dying out		Pic 2 Desc.	RCE at Indian Cave Rd in good condition	
					
<small>36°59'0" N 79°41'23" W 157°SE COURSE -1' GPS 701-1081 Indian Cave Rd, Union Hall, VA 24176, United States 07.01.2021 09:55:11 Accur +/-15.3 Ft ALT 952 Ft</small>			<small>36°58'59" N 79°41'22" W 145°SE COURSE -1' GPS 701-1081 Indian Cave Rd, Union Hall, VA 24176, United States 07.01.2021 09:55:55 Accur +/-15.5 Ft ALT 1020 Ft</small>		
GPS Location	3		GPS Location	4	
Field Station#	14761+00		Field Station#	14777+00	
Pic 3 Desc.	Spoil piles stabilized and vegetated		Pic 4 Desc.	Sump and CFS end treatment in good condition	
					
<small>36°58'37" N 79°40'42" W 335°NW COURSE 197' GPS Union Hall, VA 24176, United States 07.01.2021 09:47:37 Accur +/-716.5 Ft ALT 951 Ft</small>			<small>36°58'37" N 79°40'41" W 300°NW COURSE 238' GPS Union Hall, VA 24176, United States 07.01.2021 09:46:06 Accur +/-48.6 Ft ALT 955 Ft</small>		
GPS Location	5		GPS Location	6	
Field Station#	14798+00		Field Station#	14801+00	
Pic 5 Desc.	ROW stabilized but limited vegetative growth observed or dying out		Pic 6 Desc.	ROW stabilized but limited vegetative growth observed or dying out	

A/E	124300139	Date/Time	7/1/2021 12:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		


A/E	124300139	Date/Time	7/1/2021 12:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		





Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	25225	
Inspector	Frank Craycroft			Date/Time	6/30/2021 10:42 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0+00	
State	VA	Inspection Area	Full	Station End	0+00	
County	Franklin	Ground	Dry	Temperature (°F)	90.00	
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Rock Construction Entrance		Acceptable				
Secondary Containment		Acceptable				
Timber Mat		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waste Management		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	6/30/2021 10:42 PM	Report #	25225
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Conducted SWPPP inspection of LY-032, -033, -048 and ANC-006. All perimeter ECDs were functional and in good condition. All portable equipment and hazardous materials were maintained within secondary containment. All storm drain inlets had proper protection around them which were free of debris and excess vegetation. All trash were within bulk dumpsters with adequate additional storage. No issues were observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	6/30/2021 10:42 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 1 Desc.	LY-032 Equipment staging		Pic 2 Desc.	LY-032 Secondary containment & waste management	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 3 Desc.	LY-033 Materials staging		Pic 4 Desc.	LY-033 Timber mats and RCE	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 5 Desc.	ANC-006 South perimeter CFS		Pic 6 Desc.	ANC-006 Inlet protection and secondary containment	

A/E	124300139	Date/Time	6/30/2021 10:42 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 7 Desc.	LY-048 Waste management & temporary stabilization		Pic 8 Desc.	LY-048 North perimeter CFS	
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	6/30/2021 10:42 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25245
Inspector	John White			Date/Time	7/1/2021 9:22 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15584+23
State	VA	Inspection Area	Full	Station End	15647+03
County	Pittsylvania	Ground	Dry	Temperature (°F)	82.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	7/1/2021 9:22 AM	Report #	25245
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	7/1/2021 9:22 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15646+00	Field Station#	15636+45		
Pic 1 Desc.	Observing temporary stabilization, sump and end treatment	Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15624+00	Field Station#	15619+48		
Pic 3 Desc.	Observing temporary stabilization and water bars	Pic 4 Desc.	Observing road crossing and RCE's		
					
GPS Location	O	GPS Location	O		
Field Station#	15596+79	Field Station#	15590+00		
Pic 5 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 6 Desc.	Observing temporary stabilization and water bars		

A/E	124300139	Date/Time	7/1/2021 9:22 AM	Report #	
Pictures					
		<div style="border: 1px solid black; height: 150px; width: 100%;"></div>			
GPS Location	O	GPS Location			
Field Station#	15630+00	Field Station#			
Pic 7 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 8 Desc.			
<div style="border: 1px solid black; height: 150px; width: 100%;"></div>		<div style="border: 1px solid black; height: 150px; width: 100%;"></div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
<div style="border: 1px solid black; height: 150px; width: 100%;"></div>		<div style="border: 1px solid black; height: 150px; width: 100%;"></div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	7/1/2021 9:22 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I		AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision				Report #	25269	
Inspector	Charles Head				Date/Time	7/1/2021 3:30 PM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	14311+57	
State	VA	Inspection Area	Full		Station End	14454+22	
County	Franklin	Ground	Dry		Temperature (°F)	84.00	
Municipality	N/A	Weather	Sunny		Rain Gauge (in)	0.00	
					Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable					
Equipment Bridge		Acceptable					
Rock Construction Entrance		Acceptable					
Sensitive Resource Buffer		Acceptable					
Sensitive Resource Signage		Acceptable					
Silt Fence (Filter Fabric Fence)		Acceptable					
Silt Fence (Reinforce Filter Fence)		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300139	Date/Time	7/1/2021 3:30 PM	Report #	25269
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	7/1/2021 3:30 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14438+49	Field Station#	14430+00		
Pic 1 Desc.	Approximately 14438+49. Overview of stream crossing, equipment bridge and ECDs at stream S-IJ47.		Pic 2 Desc.	Approximately 14430+00. Overview of ROW.	
					
GPS Location	0	GPS Location	0		
Field Station#	14391+50	Field Station#	14353+53		
Pic 3 Desc.	Approximately 14391+50. Overview of stream crossing, equipment bridge and ECDs at stream S-A41.		Pic 4 Desc.	Approximately 14353+53. Overview of stream crossing, equipment bridge and ECDs at stream S-A38.	
					
GPS Location	0	GPS Location	0		
Field Station#	14333+20	Field Station#	14318+00		
Pic 5 Desc.	Approximately 14333+20. Overview of road crossing and RCEs.		Pic 6 Desc.	Approximately 14318+00. Overview of ROW.	

A/E	124300139	Date/Time	7/1/2021 3:30 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	7/1/2021 3:30 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25284
Inspector	Ben Davenport			Date/Time	7/2/2021 9:35 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Partial	Station End	14928+52
County	Franklin	Ground	Muddy	Temperature (°F)	72.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	2.10
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Communication	Routine maintenance	Addressed	7/2/2021	
Sediment Filter Log	Communication	Routine maintenance	Addressed	7/2/2021	
Vegetative Stabilization (Temporary)	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Equipment Bridge	Acceptable				
Vegetative Stabilization (Permanent)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	7/2/2021 9:35 AM	Report #	25284
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px; border: 1px solid black;"></div>					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> -Available for work -Checked rain gauges in covered area -Received instruction from Lead EI for daily tasks -Light rain then cloudy with muddy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14802+19 — 14928+52 (MVP-FR-323 to Ramsey Memorial Rd) -Walked ROW with environmental foreman looking for potential environmental issues or maintenance requirements -Perimeter controls and ECD's were inspected; 2 issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of equipment bridges and ECDs at resource buffers around stream crossings -Observed condition of vegetation in section both permanent and temporary areas of ROW -Continue to monitor ROW for signs of erosion -2 items added to punch list -Indian Cave Rd rain gauge: 2.10 inches recorded -Armstrong Rd rain gauge: 1.90 inches recorded 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	7/2/2021 9:35 AM	Report #	
Pictures					
					
36°58'31" N 79°40'30" W 130°SE COURSE 38' GPS Penhook, VA 24137, United States 07.02.2021 09:18:31 Accur +/-110.5 Ft ALT 965 Ft			36°58'31" N 79°40'30" W 155°SE COURSE 140' GPS Penhook, VA 24137, United States 07.02.2021 09:19:58 Accur +/-1254.6 Ft ALT 947 Ft		
GPS Location	1		GPS Location	2	
Field Station#	14812+00		Field Station#	14816+07	
Pic 1 Desc.	Routine maintenance. Replace damaged perimeter CFS with wattles where landowner is crossing ROW.		Pic 2 Desc.	Routine maintenance. Remove sediment from wattles at equipment bridge. Seed and stabilize denuded area.	
					
36°58'35" N 79°40'40" W 189°S COURSE 128' GPS Penhook, VA 24137, United States 07.02.2021 09:14:03 Accur +/-50.4 Ft ALT 928 Ft			36°58'10" N 79°38'57" W 103°E COURSE 127' GPS Penhook, VA 24137, United States 07.02.2021 10:00:20 Accur +/-35.8 Ft ALT 947 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14804+00		Field Station#	14893+00	
Pic 3 Desc.	Perimeter P1 silt fence and SSF in good condition.		Pic 4 Desc.	ROW stabilized and limited vegetation observed in temporary area.	
					
36°58'11" N 79°38'57" W 170°S COURSE 71' GPS Penhook, VA 24137, United States 07.02.2021 10:10:26 Accur +/-304.7 Ft ALT 905 Ft			36°58'5" N 79°38'24" W 131°SE COURSE 142' GPS Sorry no results found 07.02.2021 10:13:18 Accur +/-46.1 Ft ALT 825 Ft		
GPS Location	5		GPS Location	6	
Field Station#	14907+52		Field Station#	14923+00	
Pic 5 Desc.	Stream running clear downstream at ROW crossing.		Pic 6 Desc.	ROW stabilized and vegetated in final cleanup area. Travel lane regrowing where seeded.	

A/E	124300139	Date/Time	7/2/2021 9:35 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	7/2/2021 9:35 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25305
Inspector	Justin Burch			Date/Time	7/2/2021 11:00 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Full	Station End	14062+17
County	Franklin	Ground	Wet	Temperature (°F)	82.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	2.25
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Slope Drain Pipe	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	7/2/2021 11:00 AM	Report #	25305
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13958+31 to 14062+17 (Foggy Ridge Road to Bonbrook Mill Road #2). The contractor had an Environmental laborer walk with the EI on his inspection. At station 14040+00 a dead tree (approximately 10" diameter) had fallen on P1 silt fence damaging one panel. Per the Lead EI, the FERC approved cutting the dead tree to allow maintenance of the P1 silt fence, but submission of this item to the punch list is pending completion of a bird survey, therefore no issues were submitted for the punch because other inspected ECDs were found to be in compliance at the time of inspection. The EI did not observe that the contractor has worked in the inspection area since the last inspection. Since the last SWPPP inspection the area has received one rainfall event totaling 2.25". The ROW ground condition is wet. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 14011+00 to 14018+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	7/2/2021 11:00 AM	Report #	
Pictures					
GPS Location			0		
Field Station#			13967+00		
Pic 1 Desc.			Sump pit in acceptable condition		
GPS Location			0		
Field Station#			14008+00		
Pic 3 Desc.			Waterbar in acceptable condition		
GPS Location			0		
Field Station#			14057+00		
Pic 5 Desc.			Slope drain and sump pit in acceptable condition		
GPS Location			0		
Field Station#			14057+00		
Pic 6 Desc.			P1 silt fence in acceptable condition		







A/E	124300139	Date/Time	7/2/2021 11:00 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

AFE	124300139	Date/Time	7/2/2021 11:00 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25322
Inspector	Ben Farmer			Date/Time	7/2/2021 4:27 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Partial	Station End	15370+62
County	Pittsylvania	Ground	Wet	Temperature (°F)	73.00
Municipality	Chatham	Weather	Light Rain	Rain Gauge (in)	3.10
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Filter Fabric Fence)	Communication	P1 has been damaged and needs to			
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	7/2/2021 4:27 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15342+00		Field Station#	15335+00	
Pic 1 Desc.	P1 has been damaged and needs to be replaced.		Pic 2 Desc.	P1 has been damaged and needs to be replaced.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15299+00		Field Station#	15299+00	
Pic 3 Desc.	P1 has been damaged and needs to be restaked.		Pic 4 Desc.	Environmental crew has corrected this issue.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15370+00		Field Station#	15370+00	
Pic 5 Desc.	Rain gauge showing 3.1".		Pic 6 Desc.	Vegetation continues to fill in throughout this section.	

AFE	124300139	Date/Time	7/2/2021 4:27 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15350+00		Field Station#	15346+90	
Pic 7 Desc.	MVP-PI-332 remains in good condition with controls in place.		Pic 8 Desc.	Equipment bridge ECDs are in place and functioning.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15338+00		Field Station#	15311+78	
Pic 9 Desc.	CWD is functioning as intended		Pic 10 Desc.	Wetland buffer P1 is in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15310+00		Field Station#	15299+50	
Pic 11 Desc.	CFS is in good condition on this slope.		Pic 12 Desc.	CWD is functioning as intended	







A/E	124300139	Date/Time	7/2/2021 4:27 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

















Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25310
Inspector	John White			Date/Time	7/2/2021 12:24 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Full	Station End	15772+27
County	Pittsylvania	Ground	Wet	Temperature (°F)	74.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	4.10
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock		Communication	Contractor repaired upon discovery		7/2/2021
Cleanwater Diversion Pipe		Acceptable			
Equipment Bridge		Acceptable			
Erosion Control Blanket		Acceptable			
Housekeeping		Acceptable			
Rock Filter Outlet		Acceptable			
Sediment Filter Log		Acceptable			
Sensitive Resource Buffer		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	7/2/2021 12:24 PM	Report #	25310
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Checked rain gauges, Anderson Mill #2=4.1", Mill Creek =3.5", Transco =4.1". Performed SWPPP Inspection on this section. There were issues identified and repaired upon discovery by the Contractor and added to the punch list. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	7/2/2021 12:24 PM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15745+00	Field Station#	15745+00		
Pic 1 Desc.	Observing CFS that required maintenance	Pic 2 Desc.	Observing CFS that received maintenance		
					
GPS Location	O	GPS Location	O		
Field Station#	15747+00	Field Station#	15747+00		
Pic 3 Desc.	Observing safety fence that required maintenance	Pic 4 Desc.	Observing safety fence that received maintenance		
					
GPS Location	O	GPS Location	O		
Field Station#	15763+80	Field Station#	15665+50		
Pic 5 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 6 Desc.	Observing signage, buffer equipment crossing and ECD's		

AFE	124300139	Date/Time	7/2/2021 12:24 PM	Report #	
Pictures					
 		 			
GPS Location	O	GPS Location	O		
Field Station#	15696+00	Field Station#	15696+00		
Pic 7 Desc.	Observing CFS check that required maintenance	Pic 8 Desc.	Observing CFS check that received maintenance		
 		 			
GPS Location	O	GPS Location	O		
Field Station#	15696+00	Field Station#	15696+00		
Pic 9 Desc.	Observing CFS check that required maintenance	Pic 10 Desc.	Observing CFS check that received maintenance		
 		 			
GPS Location	O	GPS Location	O		
Field Station#	15695+59	Field Station#	15690+00		
Pic 11 Desc.	Observing CFS check that required maintenance	Pic 12 Desc.	Observing temporary stabilization, sump and end treatment		







AFE	124300139	Date/Time	7/2/2021 12:24 PM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15706+00	Field Station#	15720+00		
Pic 13 Desc.	Observing water bar,temporary stabilization,erosion control blanket and CFS checks	Pic 14 Desc.	Observing temporary stabilization,CWD outlet and ECD's		
					
GPS Location	O	GPS Location			
Field Station#	15695+59	Field Station#			
Pic 15 Desc.	Observing CFS check that received maintenance	Pic 16 Desc.			
					
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	25303
Inspector	Charles Head			Date/Time	7/2/2021 8:52 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Full	Station End	14546+75
County	Franklin	Ground	Wet	Temperature (°F)	73.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	3.20
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Communication	Reconnect piping damaged by faller			
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Communication	Reattach fabric to fence			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	7/2/2021 8:52 AM	Report #	25303
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	7/2/2021 8:52 AM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14546+33	Field Station#	14496+60		
Pic 1 Desc.	Approximately 14546+33. Overview of stream crossing, equipment bridge and ECDs at stream S-G17.		Pic 2 Desc.	Approximately 14496+60. Overview of stream crossing, equipment bridge and ECDs at stream S-G20.	
					
GPS Location	0	GPS Location	0		
Field Station#	14524+50	Field Station#	14486+60		
Pic 3 Desc.	Approximately 14524+50. Overview of road crossing and RCEs.		Pic 4 Desc.	Approximately 14486+60. Overview of stream crossing, equipment bridge and ECDs at stream S-G22.	
					
GPS Location	0	GPS Location	0		
Field Station#	14510+00	Field Station#	14473+00		
Pic 5 Desc.	Approximately 14510+00. CWD piping requires maintenance. Damaged by fallen trees during overnight storm's.		Pic 6 Desc.	Approximately 14473+00. SSF requires maintenance.	

A/E	124300139	Date/Time	7/2/2021 8:52 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	7/2/2021 8:52 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	Transco Interconnect Station	AFE	124300113	Spread	Transco Interconnect Sta
Contractor	Kanahwa			Report #	25190
Inspector	John White			Date/Time	6/30/2021 10:34 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	00+00
County	Pittsylvania	Ground	Dry	Temperature (°F)	82.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Housekeeping	Acceptable			
Rock Filter Outlet	Acceptable			
Rock Filter	Acceptable			
Sediment Basin	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300113	Date/Time	6/30/2021 10:34 AM	Report #	25190
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300113	Date/Time	6/30/2021 10:34 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 1 Desc.	Observing temporary vegetation and sediment basin	Pic 2 Desc.	Observing temporary vegetation rock drain and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 3 Desc.	Observing temporary vegetation and emergency overflow at the storm water pond.	Pic 4 Desc.	Observing temporary vegetation, storm water pond and ECD's		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300113	Date/Time	6/30/2021 10:34 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300113	Date/Time	6/30/2021 10:34 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		