



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32662
Inspector	Eric Hanlon			Date/Time	12/27/2021 9:27 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	48.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Culvert	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/27/2021 9:27 AM	Report #	32662
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection on yard 26. No compliance issues noted. Observance: Yard 26 has reduced activity during the winter curtailment. Perimeter controls in place & functioning as designed. RCE was clean, no mud or other debris on road. Secondary containment in place & functional as designed. All other ECDs and BMPs functional at time of inspection. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/27/2021 9:27 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	Secondary containment functional	Pic 2 Desc.	CFS perimeter controls functional		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	CFS perimeter controls functional	Pic 4 Desc.	Secondary containment functional		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	Secondary containment functional	Pic 6 Desc.	Disposal area functional		

A/E	124300137	Date/Time	12/27/2021 9:27 AM	Report #	
Pictures					
		<div>Insert image here</div>			
GPS Location	See photo	GPS Location			
Field Station#	12005+00	Field Station#			
Pic 7 Desc.	CFS perimeter controls functional	Pic 8 Desc.			
<div>Insert image here</div>		<div>Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
<div>Insert image here</div>		<div>Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	12/27/2021 9:27 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32674
Inspector	Clint Sears			Date/Time	12/27/2021 2:46 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Full	Station End	11899+89
County	Montgomery	Ground	Damp	Temperature (°F)	59.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/27/2021 2:46 PM	Report #	32674
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
<p>Met with Environmental staff. Completed VA SWPPP inspection from Sta#11788+52 to Sta#11899+89 (MP 223.27 to MP 225.37) No deficiencies found at this time. There are crews currently removing ECD's along the LOD This section of Row has undergone restoration and has ample amounts of vegetation throughout. CFS perimeter controls, water bar end treatments, temporary CFS water bars, permanent water bars and level spreaders, SSF, and broad based dips along AR266.03 are in acceptable condition. RCE at Mt Tabor road is in acceptable condition. Karst ECD's are in acceptable condition. Row is dry and in stable condition. No sensitive resource have been impacted</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/27/2021 2:46 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11899+89		Field Station#	11788+84	
Pic 1 Desc.	Broad based dips and P1 are in acceptable condition		Pic 2 Desc.	RCE is maintained and in acceptable condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11820+55		Field Station#	11854+00	
Pic 3 Desc.	Temporary stabilization is acceptable		Pic 4 Desc.	Vegetation is in acceptable condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11871+00		Field Station#	11873+00	
Pic 5 Desc.	P1 silt fence is in acceptable condition		Pic 6 Desc.	CFS perimeter controls are in acceptable condition	

AFE	124300137	Date/Time	12/27/2021 2:46 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11881+00	Field Station#	11899+89		
Pic 7 Desc.	Temporary stabilization has been applied	Pic 8 Desc.	AR266.03 is maintained in acceptable condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	12/27/2021 2:46 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32680
Inspector	Daniel Fortune			Date/Time	12/27/2021 6:09 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11600+01
County	Montgomery	Ground	Damp	Temperature (°F)	60.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Energy Dissipater	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Check Dam	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	12/27/2021 6:09 PM	Report #	32680
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>A regular scheduled VADEQ SWPPP inspection was completed today on JNF and private property at Brush Mountain. (MP 219.70 to MP 221.02) 11600+01 to 11670+00. The ROW surface remains stable with no erosion issues discovered. Perimeter ECDs are in place and functional. No ECD maintenance needs were identified today. Stream crossing buffers are well vegetated with environmental controls installed. No impact has occurred at any resources. Slope breakers, sumps and end treatments are working properly. There are no issues from runoff and no rilling is present. Housekeeping is acceptable and no new evidence of vandalism was discovered.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/27/2021 6:09 PM	Report #	
Pictures					
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11632+00		Field Station#	11626+70	
Pic 1 Desc.	Temporary stabilization of row conditions. temporary water bars installed and functioning as intended.		Pic 2 Desc.	S-HH18 Equipment bridge condition	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11630+00		Field Station#	11625+88	
Pic 3 Desc.	P1 Silt fence condition.		Pic 4 Desc.	View looking downstream at the rock bottom stream bed. No water flowing at this time.	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11624+00		Field Station#	11615+89	
Pic 5 Desc.	View looking at super silt fence along the LOD perimeter. No Issues at this time.		Pic 6 Desc.	View of stabilized temporary water bar condition. No Issues at this time.	

AFE	124300137	Date/Time	12/27/2021 6:09 PM	Report #	
Pictures					
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11614+50	Field Station#	11615+00		
Pic 7 Desc.	View of timber mat travel lane to the S-RR14.	Pic 8 Desc.	Equipment bridge condition over the S-RR14 stream resource. No water flowing at this time.		
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11610+00	Field Station#	11608+04		
Pic 9 Desc.	Plunge Pool condition. No Issues at this time.	Pic 10 Desc.	S-OO6 (Sinking Creek) stream resource. Stream flowing slightly. No Issues at this time.		
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11613+69	Field Station#	11613+69		
Pic 11 Desc.	Correct Stream ID is S-RR13. Current equipment bridge condition over the resource.	Pic 12 Desc.	RCE access road leading to the private section of row.		

A/E	124300137	Date/Time	12/27/2021 6:09 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32677
Inspector	Clint Sears			Date/Time	12/27/2021 4:11 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Damp	Temperature (°F)	59.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Waste Management	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/27/2021 4:11 PM	Report #	32677
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection of LDY-29 They were no deficiencies found at this time. There are no crews currently working at this location. AR-238.00 - Access road and RCE are maintained in acceptable condition. CFS triple stack perimeter controls and overhead utility flagging are in place. Waste management and housekeeping are acceptable. Culvert is in place and functional. Equipment has been inspected and no visible leaks or spills at this time Yard mainly used for 798 welders to store materials and equipment as well as park vehicles.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/27/2021 4:11 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	Culvert is in place	Pic 2 Desc.	No visible leaks or spills		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	Secondary containment in place	Pic 4 Desc.	Rock surface of RCE is in acceptable condition		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	CFS perimeter controls in place	Pic 6 Desc.	Dumpsters in place		

A/E	124300137	Date/Time	12/27/2021 4:11 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	12/27/2021 4:11 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32665
Inspector	David Schoolcraft			Date/Time	12/27/2021 10:56 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+89
State	VA	Inspection Area	Full	Station End	12005+00
County	Montgomery	Ground	Dry	Temperature (°F)	48.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Berm	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/27/2021 10:56 AM	Report #	32665
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental staff. Preformed SWPPP inspection from MP 225.37 (11899+89) and MP 227.37 (12005+00) accompanied by fellow EI Joe Sweeden No deficiencies found. Vegetation or stabilization sufficient. No sensitive resources have been impacted Environmental crews were in the area working on general maintenance. Parameter controls and end treatments in place.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/27/2021 10:56 AM	Report #	
Pictures					
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11917+00		Field Station#	11929+78	
Pic 1 Desc.	Section of ROW showing conditions and controls		Pic 2 Desc.	AR 266	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11978+86		Field Station#	11990+00	
Pic 3 Desc.	Karst Protection ECDs		Pic 4 Desc.	Stabilization	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11960+00		Field Station#	12005+00	
Pic 5 Desc.	Parameter controls		Pic 6 Desc.	Stabilization	

A/E	124300137	Date/Time	12/27/2021 10:56 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	12/27/2021 10:56 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report



Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32673
Inspector	Patrick Shields			Date/Time	12/27/2021 2:28 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Full	Station End	11788+52
County	Montgomery	Ground	Dry	Temperature (°F)	50.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

- | | |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) | No |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/27/2021 2:28 PM	Report #	32673
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11670+00 (Brush Mt) to ST# 11788+52 (Mt Tabor) MP 221.02 to MP 223.27 Accompanied on inspection by fellow EI Jared Saunders. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews on this section of ROW at time of inspection. This section of ROW has undergone temporary stabilization. Topsoil stock piles and clean water diversion berms have been stabilized. Slope drains with stone inlet protection are in place where needed. Perimeter controls and waterbars with end treatments are in place. Sensitive resource buffers are in place at stream crossings S-MN21, S-MN22, S-EF65, S-EF62, and S-IJ52. MLV-AR-26 and MT. Tabor road crossing RCEs are maintained in acceptable condition. The ROW is dry and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	12/27/2021 2:28 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11670+00	Field Station#	11679+00		
Pic 1 Desc.	P1 silt fence perimeter control in place	Pic 2 Desc.	End treatments in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11685+00	Field Station#	11688+50		
Pic 3 Desc.	Slope drain in place	Pic 4 Desc.	Erosion control blanket in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11689+50	Field Station#	11705+00		
Pic 5 Desc.	Stone inlet protection in place	Pic 6 Desc.	Sediment filter logs in place		

AFE	124300137	Date/Time	12/27/2021 2:28 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11713+00		Field Station#	11720+00	
Pic 7 Desc.	Waterbars in place		Pic 8 Desc.	CFS perimeter control in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11741+50		Field Station#	11751+50	
Pic 9 Desc.	Stream buffer in place		Pic 10 Desc.	End treatments in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11758+00		Field Station#	11766+25	
Pic 11 Desc.	Supersilt fence perimeter control in place		Pic 12 Desc.	RCE in place	

A/E	124300137	Date/Time	12/27/2021 2:28 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report





Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32661
Inspector	Eric Hanlon			Date/Time	12/27/2021 8:19 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Dry	Temperature (°F)	46.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00


- | | |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) | No |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/27/2021 8:19 AM	Report #	32661
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection on yard 28 No compliance issues noted. Observance: Yard 28 has reduced activity during the winter curtailment. Aged Perimeter controls have been replaced & functioning as designed. RCE was clean, no mud or other debris on road. All other ECDs and BMPs functional at time of inspection. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/27/2021 8:19 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 1 Desc.	CFS perimeter controls functional		Pic 2 Desc.	CFS perimeter controls functional	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 3 Desc.	CFS refreshed & rock clean and functional		Pic 4 Desc.	CFS functional	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	12005+00		Field Station#	12005+00	
Pic 5 Desc.	RCE refreshed and functional		Pic 6 Desc.	CFS in good condition	

AFE	124300137	Date/Time	12/27/2021 8:19 AM	Report #	
Pictures					
		<div style="text-align: center;">Insert image here</div>			
GPS Location	See photo	GPS Location			
Field Station#	12005+00	Field Station#			
Pic 7 Desc.	Rock is clean and functional	Pic 8 Desc.			
<div style="text-align: center;">Insert image here</div>		<div style="text-align: center;">Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
<div style="text-align: center;">Insert image here</div>		<div style="text-align: center;">Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	12/27/2021 8:19 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32690
Inspector	Eric Hanlon			Date/Time	12/28/2021 7:44 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10655+00
State	VA	Inspection Area	Full	Station End	10749+92
County	Giles	Ground	Wet	Temperature (°F)	60.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.15
				Rain Accumulation Time (days)	1.00







1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/28/2021 7:44 AM	Report #	32690
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 10655+00 (MP 201.6) to ST# 10749+92 (MP 203.6). No Compliance issues noted: Observance: Perimeter controls in place & functioning as designed. ROW has been temporary stabilized. No areas with open ditch. All other ECDs and BMPs functional at time of inspection. 50' buffers in place at stream crossings S-G33, S-G32, S-G30 and W-Z11. AR-240, 241.04, 241.01, 241, Hendrickson and Big Stony creek road crossing RCEs are maintained in acceptable condition. Buffalo Anklets rain gauge measured 0.15" of rainfall accumulated on 12/27/21. The ROW is dry and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/28/2021 7:44 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10698+00		Field Station#	10708+10	
Pic 1 Desc.	Equipment bridge functional		Pic 2 Desc.	RCE & AR 241.01 in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10712+21		Field Station#	10717+00	
Pic 3 Desc.	P1 in place		Pic 4 Desc.	ET functional	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10694+54		Field Station#	10680+00	
Pic 5 Desc.	Clean water drainage feature functional		Pic 6 Desc.	Equipment bridge functional	

AFE	124300137	Date/Time	12/28/2021 7:44 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10728+00		Field Station#	10732+21	
Pic 7 Desc.	Water bars in place and functional		Pic 8 Desc.	50' buffers in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10740+00		Field Station#	10742+69	
Pic 9 Desc.	Stone inlets functional		Pic 10 Desc.	Clean water drainage feature functional	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10749+00		Field Station#	10742+09	
Pic 11 Desc.	RCE functional		Pic 12 Desc.	Inlet in good condition	

A/E	124300137	Date/Time	12/28/2021 7:44 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32709
Inspector	Clint Sears			Date/Time	12/28/2021 12:15 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10749+92
State	VA	Inspection Area	Full	Station End	10798+92
County	Giles	Ground	Damp	Temperature (°F)	63.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	1.00







- Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
- Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
- Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
- E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Signage	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Sump Pit	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/28/2021 12:15 PM	Report #	32709
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>Met with Environmental staff.</p> <p>Completed VA SWPPP inspection from Sta#10749+92 to Sta#10798+92 (MP 203.6 to MP 204.53)</p> <p>No deficiencies were found at this time.</p> <p>This section of Row has undergone temporary vegetation and stabilization.</p> <p>Water bars, stone inlet protections, slope drain pipes, P1 silt fence are in acceptable condition.</p> <p>Equipment bridges, sensitive resource signage, sensitive resource buffer zones, clean water diversion pipe, rock surface of RCE and level spreaders are maintained in acceptable condition.</p> <p>There are no crews actively working on this section of Row.</p> <p>Row is damp and in stable condition after rain amount of 0.2" inches</p> <p>No sensitive resource have been impacted.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/28/2021 12:15 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	see photo	
Field Station#	10751+50		Field Station#	10770+00	
Pic 1 Desc.	Stone inlet protection is in acceptable condition		Pic 2 Desc.	Sump pit and CFS perimeter controls are in acceptable condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10780+00		Field Station#	10766+00	
Pic 3 Desc.	Sensitive resource signage functional and buffer zones are in acceptable condition		Pic 4 Desc.	Clean water diversion pipe and level spreader are in acceptable condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10758+00		Field Station#	10754+50	
Pic 5 Desc.	Equipment bridge is maintained in acceptable condition		Pic 6 Desc.	Daylight drain and water bars are in acceptable condition	

A/E	124300137	Date/Time	12/28/2021 12:15 PM	Report #	
Pictures					
					
GPS Location		See photo		GPS Location	
Field Station#		10782+00		Field Station#	
Pic 7 Desc.		Temporary stabilization is acceptable		Pic 8 Desc.	
Insert image here		Insert image here			
GPS Location				GPS Location	
Field Station#				Field Station#	
Pic 9 Desc.				Pic 10 Desc.	
Insert image here		Insert image here			
GPS Location				GPS Location	
Field Station#				Field Station#	
Pic 11 Desc.				Pic 12 Desc.	

A/E	124300137	Date/Time	12/28/2021 12:15 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32716
Inspector	Joe Sweeden			Date/Time	12/28/2021 5:29 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10859+46
State	VA	Inspection Area	Partial	Station End	10929+80
County	Giles	Ground	Damp	Temperature (°F)	45.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	1.00

- | | |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings?
(If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) | No |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	12/28/2021 5:29 PM	Report #	32716
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed Virginia SWPP inspection from station # 10859+46-10929+80. (MP 205.67-207.0. Kow Camp gravel to Doe Creek, with El David Schoolcraft No Deficiencies found today. Observances: ROW conditions were damp The ROW had received 0.20" of rain overnight. The ROW has been temporarily stabilized. The water bars and compost sock are in good condition. Vegetation is sufficient. Slope drains are functioning as designed. Checked PL items from previous walks No trash on the ROW. No sensitive resources were impacted. All perimeter controls, ECDs and BMPs were functional at time of inspection. No other crews were working in the area. Rock Road approaches are clean and free of loose rock.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	12/28/2021 5:29 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	see photo	
Field Station#	10868+00		Field Station#	10879+00	
Pic 1 Desc.	Stabilized ROW		Pic 2 Desc.	Water bars	
					
GPS Location	see photo		GPS Location	see photo	
Field Station#	10882+40		Field Station#	10899+00	
Pic 3 Desc.	S-A 32		Pic 4 Desc.	Vegetated ROW	
					
GPS Location	see photo		GPS Location	see photo	
Field Station#	10926+30		Field Station#	10938+00	
Pic 5 Desc.	Water body		Pic 6 Desc.	S-Y 3	

A/E	124300137	Date/Time	12/28/2021 5:29 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	12/28/2021 5:29 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32715
Inspector	Patrick Shields			Date/Time	12/28/2021 5:10 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10798+92
State	VA	Inspection Area	Full	Station End	10859+46
County	Giles	Ground	Wet	Temperature (°F)	60.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	1.00

- | | |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) | No |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	12/28/2021 5:10 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10859+00	Field Station#	10858+00		
Pic 1 Desc.	Supersilt fence perimeter control in place	Pic 2 Desc.	End treatment in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10855+00	Field Station#	10848+50		
Pic 3 Desc.	Stream buffer in place	Pic 4 Desc.	CFS perimeter control in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10843+75	Field Station#	10840+15		
Pic 5 Desc.	Cleanwater diversion pipe in place	Pic 6 Desc.	Daylight drain in place		

AFE	124300137	Date/Time	12/28/2021 5:10 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10833+00		Field Station#	10815+00	
Pic 7 Desc.	Waterbars in place		Pic 8 Desc.	Erosion control blanket in in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10812+00		Field Station#	10808+15	
Pic 9 Desc.	Cleanwater diversion outlet protection in place		Pic 10 Desc.	Stone inlet protection in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	10806+00		Field Station#	10803+00	
Pic 11 Desc.	End treatments in place		Pic 12 Desc.	RCE in place	

A/E	124300137	Date/Time	12/28/2021 5:10 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32740
Inspector	Clint Sears			Date/Time	12/29/2021 1:55 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	10929+80
State	VA	Inspection Area	Full	Station End	11023+80
County	Giles	Ground	Wet	Temperature (°F)	61.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/29/2021 1:55 PM	Report #	32740
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with Environmental staff. Completed VA SWPPP inspection from Sta#10929+80 to Sta#11023+80 (MP 207 to MP 208.78) Light rain throughout the day. No deficiencies found at this time There is currently no construction on the Row. AR242.01 is not completed, perimeter controls are in place and denuded soils have been stabilized. Stone inlets have been installed with outlet protection. This area has undergone temporary stabilization and permanent restoration. Clean water diversion pipe, CFS perimeter controls, erosion control blanket, equipment bridges, water bar end treatments, slope drain pipes, RCE at Doe creek and access roads are maintained in acceptable condition. Karst ECD's and daylight drains with outlet protection are in acceptable condition. Row is wet and in stable condition No sensitive resource have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	12/29/2021 1:55 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10971+74	Field Station#	10930+45		
Pic 1 Desc.	AR242.01 is in acceptable condition, denuded soils have been stabilized.	Pic 2 Desc.	Rock surface of RCE is in acceptable condition		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10937+00	Field Station#	10949+72		
Pic 3 Desc.	Temporary vegetation and stabilization are acceptable	Pic 4 Desc.	CFS perimeter controls are in acceptable condition		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10977+72	Field Station#	10984+92		
Pic 5 Desc.	Equipment bridge and erosion control blanket are in acceptable condition	Pic 6 Desc.	Slope drain pipe is in place		

AFE	124300137	Date/Time	12/29/2021 1:55 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	10993+57	Field Station#	11003+75		
Pic 7 Desc.	Water bars and perimeter controls are in acceptable condition	Pic 8 Desc.	Clean water diversion pipe is in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11011+00	Field Station#	11017+36		
Pic 9 Desc.	Clean water diversion pipe and level spreader are acceptable	Pic 10 Desc.	P1 silt fence at buffer zones is in acceptable condition		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11019+87	Field Station#	11023+80		
Pic 11 Desc.	Sump pit and CFS perimeter controls are in place	Pic 12 Desc.	AR244 is maintained in acceptable condition		

A/E	124300137	Date/Time	12/29/2021 1:55 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32732
Inspector	David Schoolcraft			Date/Time	12/29/2021 10:20 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11023+80
State	VA	Inspection Area	Full	Station End	11098+47
County	Giles	Ground	Wet	Temperature (°F)	54.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

- Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
- Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
- Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
- E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/29/2021 10:20 AM	Report #	32732
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental staff. Performed SWPPP inspection, from MP 208.78 (11023+80) and MP 210.2 (11098+47). This section of ROW has no current construction. No deficiencies found One area with ATV tracks from land owner. Did not affect waterbars (picture below) All perimeter controls, ECDs and BMPs functional at time of inspection. Vegetation or stabilization sufficient. Stream buffers and controls in place at the time of inspection. No sensitive resources have been impacted Accessed access road 258.02					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/29/2021 10:20 AM	Report #	
Pictures					
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11025+54		Field Station#	11029+00	
Pic 1 Desc.	S-IJ18		Pic 2 Desc.	Section of ROW showing conditions and controls	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11050+10		Field Station#	11055+00	
Pic 3 Desc.	S-IJ 16B & 17		Pic 4 Desc.	Karst Protection ECDs	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11084+50		Field Station#	11098+43	
Pic 5 Desc.	CFS waterbars and restoration overview		Pic 6 Desc.	AR 245.02	

AFE	124300137	Date/Time	12/29/2021 10:20 AM	Report #	
Pictures					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11038+00		Field Station#	11078+50	
Pic 7 Desc.	Land owner ATV tracks on ROW		Pic 8 Desc.	Restoration overview of conditions and controls	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 9 Desc.			Pic 10 Desc.		
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300137	Date/Time	12/29/2021 10:20 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report


Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32728
Inspector	Eric Hanlon			Date/Time	12/29/2021 7:59 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11184+85
State	VA	Inspection Area	Full	Station End	11254+99
County	Giles	Ground	Wet	Temperature (°F)	55.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/29/2021 7:59 AM	Report #	32728
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection from ST# 11184+85 (MP 210.0) to ST# 11254+99 (MP 213.6). No Compliance issues noted: Observance: Perimeter controls in place & functioning as designed Permanent & temporary stabilization in place. All other ECDs and BMPs functional at time of inspection. AR-249.02 & 244 RCE's are maintained in acceptable condition. The ROW is wet and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	12/29/2021 7:59 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11191+00		Field Station#	11194+00	
Pic 1 Desc.	Clean water drainage feature functional		Pic 2 Desc.	Permanent stabilization functional	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11190+00		Field Station#	11250+00	
Pic 3 Desc.	Erosion control blanket in place		Pic 4 Desc.	ET & water bars functional	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11250+00		Field Station#	11245+00	
Pic 5 Desc.	Erosion control blanket in place		Pic 6 Desc.	ET functional	

AFE	124300137	Date/Time	12/29/2021 7:59 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11207+21		Field Station#	11239+00	
Pic 7 Desc.	Day light drain in place		Pic 8 Desc.	Inlet in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11237+00		Field Station#	11234+00	
Pic 9 Desc.	Water bars in place		Pic 10 Desc.	P1 perimeter controls functional	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11233+00		Field Station#	11227+59	
Pic 11 Desc.	ET functional		Pic 12 Desc.	RCE functional	

A/E	124300137	Date/Time	12/29/2021 7:59 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		









Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32744
Inspector	Patrick Shields			Date/Time	12/29/2021 3:44 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11098+47
State	VA	Inspection Area	Full	Station End	11184+85
County	Giles	Ground	Wet	Temperature (°F)	57.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	12/29/2021 3:44 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11112+00	Field Station#	11123+00		
Pic 1 Desc.	Triple stack CFS perimeter control	Pic 2 Desc.	Erosion control blanket in place at drainage feature		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11120+00	Field Station#	11134+00		
Pic 3 Desc.	Temporary CFS waterbars in place	Pic 4 Desc.	Permanent waterbars in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11146+20	Field Station#	11147+00		
Pic 5 Desc.	Cleanwater diversion pipe in place	Pic 6 Desc.	Stone inlet protection in place		

AFE	124300137	Date/Time	12/29/2021 3:44 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11148+00	Field Station#	11163+00		
Pic 7 Desc.	Supersilt fence perimeter control in place	Pic 8 Desc.	Silt fence perimeter control in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11167+00	Field Station#	11168+00		
Pic 9 Desc.	Cleanwater diversion outlet protection in place	Pic 10 Desc.	RCE in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11178+00	Field Station#	11184+15		
Pic 11 Desc.	Level spreader in place	Pic 12 Desc.	Daylight drain in place		

A/E	124300137	Date/Time	12/29/2021 3:44 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32776
Inspector	Joe Sweeden			Date/Time	12/30/2021 1:48 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11254+99
State	VA	Inspection Area	Partial	Station End	11353+67
County	Giles	Ground	Damp	Temperature (°F)	45.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.25
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Flume Pipe	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	Yes
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	No
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	No
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	Yes

AFE	124300137	Date/Time	12/30/2021 1:48 PM	Report #	32776
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed Virginia SWPP inspection from station # 11254+99-11353+67 (MP 2213.6-215.04) Rte 42 - Old Furnace, with El David Schoolcraft No Deficiencies found today. Observances: ROW conditions were damp The ROW had received 0.25" of rain overnight. The ROW has been temporarily stabilized. The water bars and compost sock are in good condition. Steep slopes have had erosion control fabric placed on them. Vegetation is sufficient. Slope drains are functioning as designed. ECs at streams are in compliance. Checked PL items from previous walks No trash on the ROW. No sensitive resources were impacted. All perimeter controls, ECDs and BMPs were functional at time of inspection. No other crews were working in the area. Rock Road approaches are clean and free of loose rock.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	12/30/2021 1:48 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	see photo	
Field Station#	11258+00		Field Station#	11262+75	
Pic 1 Desc.	Erosion blanket		Pic 2 Desc.	Sump/ ETs	
					
GPS Location	see photo		GPS Location	see photo	
Field Station#	11286+00		Field Station#	11292+66	
Pic 3 Desc.	Stabilized ROW		Pic 4 Desc.	S-SM 18	
					
GPS Location	see photo		GPS Location	see photo	
Field Station#	11298+28		Field Station#	11309+54	
Pic 5 Desc.	AR Seven Oaks		Pic 6 Desc.	Water bar	

AFE	124300137	Date/Time	12/30/2021 1:48 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	see photo		
Field Station#	11328+00	Field Station#	11351+00		
Pic 7 Desc.	S-NN 12	Pic 8 Desc.	Controls at Sensitive area		
					
GPS Location	see photo	GPS Location			
Field Station#	11352+97	Field Station#			
Pic 9 Desc.	S-NN 11, Old Furnace	Pic 10 Desc.			
					
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	12/30/2021 1:48 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32767
Inspector	Clint Sears			Date/Time	12/30/2021 11:40 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11471+56
State	VA	Inspection Area	Full	Station End	11524+16
County	Giles	Ground	Wet	Temperature (°F)	60.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.25
				Rain Accumulation Time (days)	1.00





1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/30/2021 11:40 AM	Report #	32767
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with Environmental staff. Completed VA SWPPP inspection from Sta#11471+56 to Sta#11524+16 (MP 217.26 to MP 218.26) No deficiencies were found at this time. This section of Row has been temporarily stabilized and is in acceptable condition. Temporary water bars, stone inlet protection, P1 silt fence, sump pits, sensitive resource signage, sensitive resource buffer, clean water diversion pipe, equipment bridges, slope drain pipe, rock surface of AR258.02 and RCE at AR258.01 are maintained in acceptable condition. Karst ECDs are in place and in acceptable condition Row is wet and in stable condition after rain amount of 0.25". No sensitive resource were impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/30/2021 11:40 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11524+16		Field Station#	11521+35	
Pic 1 Desc.	AR258.02 is maintained in acceptable condition		Pic 2 Desc.	Sump pit and other ECD's are in acceptable condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11519+15		Field Station#	11472+43	
Pic 3 Desc.	Buffer zones are in acceptable condition		Pic 4 Desc.	Temporary vegetation and stabilization are acceptable	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11507+00		Field Station#	11497+55	
Pic 5 Desc.	Equipment bridge is maintained in acceptable condition		Pic 6 Desc.	CFS perimeter controls are in place	

A/E	124300137	Date/Time	12/30/2021 11:40 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11490+02	Field Station#	11494+00		
Pic 7 Desc.	Rock surface of RCE is in acceptable condition	Pic 8 Desc.	P1 silt fence is in acceptable condition		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11490+02	Field Station#	11486+87		
Pic 9 Desc.	Rain gage at Stevers Gap with 0.25" inches of rain	Pic 10 Desc.	Inlet to clean water diversion pipe is in acceptable condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	12/30/2021 11:40 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32756
Inspector	Eric Hanlon			Date/Time	12/30/2021 7:23 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11524+16
State	VA	Inspection Area	Full	Station End	11600+01
County	Giles	Ground	Wet	Temperature (°F)	53.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/30/2021 7:23 AM	Report #	32756
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
Completed aVA SWPPP inspection from ST# 11524+16 to ST# 11600+01 (MP 218.26 to 219.70) No Deficiencies noted: The ROW from 258.02 to the JNF Forest has been fully restored. The Forest has been temporarily stabilized Observed: The aged P1 on the JNF from the top of the Mtn down to Craig Creek road has been replaced. The restored area is in good shape and the vegetation is sufficient. The environmental controls in the forest are aged, but functional. The ECDs at WBs, S-PP 20,21,22 are new and in good shape. No construction being performed in the area. RCE's functional, highway at Craig Creek station 11600+01, was clean and free of any loose rock. LOD ECDs were in place and functional. Water bars have been installed to specifications. The ROW is wet but in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/30/2021 7:23 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11530+00		Field Station#	11533+00	
Pic 1 Desc.	Permanent stabilization functional		Pic 2 Desc.	CFS perimeter controls functional	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11535+00		Field Station#	11528+33	
Pic 3 Desc.	Water bars in place		Pic 4 Desc.	Erosion control blanket in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11527+00		Field Station#	11526+00	
Pic 5 Desc.	Water bars in place		Pic 6 Desc.	Clean water drainage feature functional	

AFE	124300137	Date/Time	12/30/2021 7:23 AM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11583+00		Field Station#	11584+72	
Pic 7 Desc.	Perimeter P1 functional		Pic 8 Desc.	Equipment bridge functional	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11587+42		Field Station#	11587+42	
Pic 9 Desc.	P1 in good condition		Pic 10 Desc.	50' buffers in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11593+00		Field Station#	11597+00	
Pic 11 Desc.	ET functional		Pic 12 Desc.	Perimeter controls functional	

A/E	124300137	Date/Time	12/30/2021 7:23 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11598+34	Field Station#	11600+01		
Pic 13 Desc.	ET functional	Pic 14 Desc.	RCE functional		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32779
Inspector	Patrick Shields			Date/Time	12/30/2021 4:21 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11353+67
State	VA	Inspection Area	Full	Station End	11471+56
County	Giles	Ground	Wet	Temperature (°F)	58.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.25
				Rain Accumulation Time (days)	1.00

- | | |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) | No |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/30/2021 4:21 PM	Report #	32779
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
<p>Completed VA SWPPP inspection from ST# 11353+67 (Old Furnace) to ST# 11471+56 (Steele Acres) MP 215.04 to MP 217.26 Accompanied on inspection by fellow EI Jared Saunders. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews actively working on this section of ROW at time of inspection. ST# 11353+67 to ST# 11367+00 and ST# 11443+50 to ST# 11471+56 have undergone temporary stabilization. Clean water diversion berms and topsoil piles have been stabilized. Perimeter controls and end treatments are in place. Triple protection ECDs are in place at karst feature. Final restoration has occurred between ST# 11367+00 and ST# 11443+50. CFS perimeter controls, end treatments and temporary waterbars are in place. Permanent waterbars with level spreaders are in place. Sensitive resource buffers are in place at stream crossings S-KL43, S-0014, S-0013, S-0012, and S-CD14. AR-256 and 258.01 RCEs are maintained in acceptable condition. The ROW is wet and in stable condition. No sensitive resources have been impacted. Steele Acres rain gauge measured 0.25" of rainfall accumulated on 12/29/21.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	12/30/2021 4:21 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11353+50		Field Station#	11362+00	
Pic 1 Desc.	RCE in place		Pic 2 Desc.	Erosion control blanket in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11363+00		Field Station#	11397+00	
Pic 3 Desc.	End treatments in place		Pic 4 Desc.	Level spreader in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11412+00		Field Station#	11431+00	
Pic 5 Desc.	Temporary CFS waterbars in place		Pic 6 Desc.	Permanent waterbar in place	

AFE	124300137	Date/Time	12/30/2021 4:21 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11448+00		Field Station#	11452+00	
Pic 7 Desc.	Cleanwater diversion berm in place		Pic 8 Desc.	Stream buffer in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11458+00		Field Station#	11461+00	
Pic 9 Desc.	Stone inlet protection in place		Pic 10 Desc.	CFS perimeter control in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11467+00		Field Station#	11469+00	
Pic 11 Desc.	Plunge pool in place		Pic 12 Desc.	Triple protection ECDs in place at karst feature	

A/E	124300137	Date/Time	12/30/2021 4:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32800
Inspector	David Schoolcraft			Date/Time	12/31/2021 11:52 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11899+89
State	VA	Inspection Area	Full	Station End	12005+00
County	Montgomery	Ground	Wet	Temperature (°F)	54.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00






1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Housekeeping	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/31/2021 11:52 AM	Report #	32800
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with environmental staff. Performed SWPPP inspection from MP 225.37 (11899+89) and MP 227.37 (12005+00) accompanied by fellow EI Joe Sweeden No deficiencies found. Vegetation or stabilization sufficient. No sensitive resources have been impacted Environmental crews were in the area working on general maintenance. Parameter controls and end treatments in place.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/31/2021 11:52 AM	Report #	
Pictures					
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11905+00		Field Station#	11918+00	
Pic 1 Desc.	Section of ROW showing conditions and controls		Pic 2 Desc.	Waterbars	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11929+78		Field Station#	11961+25	
Pic 3 Desc.	AR 266		Pic 4 Desc.	Parameter Controls	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11978+86		Field Station#	11990+25	
Pic 5 Desc.	Karst Protection ECDs		Pic 6 Desc.	Section of ROW showing conditions and controls	

A/E	124300137	Date/Time	12/31/2021 11:52 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	12/31/2021 11:52 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32809
Inspector	Daniel Fortune			Date/Time	12/31/2021 6:25 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Partial	Station End	11600+01
County	Montgomery	Ground	Wet	Temperature (°F)	59.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00





1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	12/31/2021 6:25 PM	Report #	32809
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>A regular scheduled VADEQ SWPPP inspection was completed today on JNF and private property at Brush Mountain. (MP 219.70 to MP 221.02) 11600+01 to 11670+00. The ROW surface remains stable with no erosion issues discovered. Perimeter ECDs are in place and functional. No ECD maintenance needs were identified today. Stream crossing buffers are well vegetated with environmental controls installed. No impact has occurred at any resources. Slope breakers, sumps and end treatments are working properly. There are no issues from runoff and no rilling is present. Housekeeping is acceptable and no new evidence of vandalism was discovered.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	12/31/2021 6:25 PM	Report #	
Pictures					
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11614+00		Field Station#	11614+00	
Pic 1 Desc.	Perimeter P1 silt fence along the RCE		Pic 2 Desc.	RCE conditions. No Issues.	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11614+00		Field Station#	11614+00	
Pic 3 Desc.	AR 258.04 S-RR13		Pic 4 Desc.	Access Road at 258.04	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11606+00		Field Station#	11608+04	
Pic 5 Desc.	temporary stabilization of row.		Pic 6 Desc.	S-006 Current stream conditions.	

AFE	124300137	Date/Time	12/31/2021 6:25 PM	Report #	
Pictures					
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11610+00		Field Station#	11613+80	
Pic 7 Desc.	View of the plunge pool conditions.		Pic 8 Desc.	Refreshed CFS around the S-RR14 buffer zone.	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11614+20		Field Station#	11615+29	
Pic 9 Desc.	Equipment bridge condition over the S-RR14 stream resource.		Pic 10 Desc.	Current water bar condition. Additional Stabilization will be added after the Holiday break.	
					
GPS Location	See Photo		GPS Location	See Photo	
Field Station#	11618+33		Field Station#	11619+54	
Pic 11 Desc.	Temporary stabilization of row		Pic 12 Desc.	CWD stone inlet condition. Forrest litter has built up but storm water continues to function properly.	

AFE	124300137	Date/Time	12/31/2021 6:25 PM	Report #	
Pictures					
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11625+10	Field Station#	11625+10		
Pic 13 Desc.	View of S-HH18 stream resource buffer zones.	Pic 14 Desc.	View of functioning perimeter super silt fence prior to the S-HH18 stream resource.		
					
GPS Location	See Photo	GPS Location	See Photo		
Field Station#	11626+24	Field Station#	11630+00		
Pic 15 Desc.	S-HH18 equipment bridge condition. No Issues at this time.	Pic 16 Desc.	Stone inlet protection condition.		
		Insert image here			
GPS Location	See Photo	GPS Location			
Field Station#	11631+00	Field Station#			
Pic 17 Desc.	View of temporary vegetated row conditions with P1 silt fencing along the LOD perimeter.	Pic 18 Desc.			



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32807
Inspector	Clint Sears			Date/Time	12/31/2021 4:22 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	60.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

- | | |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings?
(If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) | No |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock				
Culvert				
Housekeeping				
Rock Construction Entrance				
Secondary Containment				
Waste Management				

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/31/2021 4:22 PM	Report #	32807
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection of LDY-29 They were no deficiencies found at this time. There are no crews currently working at this location. AR-238.00 - Access road and RCE are maintained in acceptable condition. CFS triple stack perimeter controls and overhead utility flagging are in place. Waste management and housekeeping are acceptable. Culvert is in place and functional. Equipment has been inspected and no visible leaks or spills at this time Yard mainly used for 798 welders to store materials and equipment as well as park vehicles.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	12/31/2021 4:22 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	Culvert in place	Pic 2 Desc.	Dumpsters in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	Rock surface of RCE is in acceptable condition	Pic 4 Desc.	Secondary containment in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	No visible leaks or spills	Pic 6 Desc.	CFS perimeter controls are in acceptable condition		

A/E	124300137	Date/Time	12/31/2021 4:22 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	12/31/2021 4:22 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32805
Inspector	Patrick Shields			Date/Time	12/31/2021 3:45 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11670+00
State	VA	Inspection Area	Full	Station End	11788+52
County	Montgomery	Ground	Wet	Temperature (°F)	47.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

- | | |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) | No |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	12/31/2021 3:45 PM	Report #	32805
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed VA SWPPP inspection from ST# 11670+00 (Brush Mt) to ST# 11788+52 (Mt Tabor) MP 221.02 to MP 223.27 Accompanied on inspection by fellow EI Jared Saunders. No compliance issues found. Active construction site; additional deficiencies may be identified by other EIs. Observed no environmental maintenance crews on this section of ROW at time of inspection. This section of ROW has undergone temporary stabilization. Topsoil stock piles and clean water diversion berms have been stabilized. Slope drains with stone inlet protection are in place where needed. Perimeter controls and waterbars with end treatments are in place. Sensitive resource buffers are in place at stream crossings S-MN21, S-MN22, S-EF65, S-EF62, and S-IJ52. MLV-AR-26 and MT. Tabor road crossing RCEs are maintained in acceptable condition. The ROW is wet and in stable condition. No sensitive resources have been impacted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/31/2021 3:45 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11766+30		Field Station#	11758+00	
Pic 1 Desc.	RCE in place		Pic 2 Desc.	Supersilt fence perimeter control in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11749+50		Field Station#	11741+00	
Pic 3 Desc.	End treatments in place		Pic 4 Desc.	Stream buffer in place	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11720+00		Field Station#	11716+00	
Pic 5 Desc.	CFS perimeter control in place		Pic 6 Desc.	Waterbars in place	

AFE	124300137	Date/Time	12/31/2021 3:45 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11704+75	Field Station#	11690+50		
Pic 7 Desc.	Sediment filter logs in place	Pic 8 Desc.	Stone inlet protection in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11689+00	Field Station#	11679+00		
Pic 9 Desc.	Erosion control blanket in place	Pic 10 Desc.	End treatments in place		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	11670+00	Field Station#	11683+00		
Pic 11 Desc.	P1 silt fence perimeter control in place	Pic 12 Desc.	Slope drain in place		

A/E	124300137	Date/Time	12/31/2021 3:45 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32806
Inspector	Clint Sears			Date/Time	12/31/2021 4:14 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	11788+52
State	VA	Inspection Area	Full	Station End	11899+89
County	Montgomery	Ground	Wet	Temperature (°F)	56.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00


1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Check Dam	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300137	Date/Time	12/31/2021 4:14 PM	Report #	32806
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Met with Environmental staff. Completed VA SWPPP inspection from Sta#11788+52 to Sta#11899+89 (MP 223.27 to MP 225.37) No deficiencies found at this time. There are no crews actively working on this section of ROW. This section of Row has undergone restoration and has ample amounts of vegetation throughout. CFS perimeter controls, water bar end treatments, temporary CFS water bars, permanent water bars and level spreaders, SSF, and broad based dips along AR266.03 are in acceptable condition. RCE at Mt Tabor road is in acceptable condition. Karst ECD's are in acceptable condition. Row is wet and in stable condition. No sensitive resource have been impacted					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/31/2021 4:14 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11788+84		Field Station#	11793+00	
Pic 1 Desc.	Rock surface of RCE is in acceptable condition		Pic 2 Desc.	Karst ECD's are in acceptable condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11835+00		Field Station#	11850+00	
Pic 3 Desc.	Level spreader are in acceptable condition and some ECD's have been removed		Pic 4 Desc.	Vegetation is in acceptable condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	11865+00		Field Station#	11866+65	
Pic 5 Desc.	P1 silt fence is in acceptable condition		Pic 6 Desc.	Permanent water bar and level spreader are in place	

A/E	124300137	Date/Time	12/31/2021 4:14 PM	Report #	
Pictures					
		<div style="text-align: center;">Insert image here</div>			
GPS Location	See photo	GPS Location			
Field Station#	11899+89	Field Station#			
Pic 7 Desc.	Ar266.03 is maintained in acceptable condition	Pic 8 Desc.			
<div style="text-align: center;">Insert image here</div>		<div style="text-align: center;">Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
<div style="text-align: center;">Insert image here</div>		<div style="text-align: center;">Insert image here</div>			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	12/31/2021 4:14 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32794
Inspector	Eric Hanlon			Date/Time	12/31/2021 9:38 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	46.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

- | | |
|---|-----|
| 1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? | Yes |
| 2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings?
(If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) | No |
| 3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) | Yes |
| 4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.) | |

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/31/2021 9:38 AM	Report #	32794
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection on yard 28 No compliance issues noted. Observance: Yard 28 has reduced activity during the winter curtailment. Aged Perimeter controls have been replaced & functioning as designed. RCE was clean, no mud or other debris on road. All other ECDs and BMPs functional at time of inspection. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300137	Date/Time	12/31/2021 9:38 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	CFS perimeter controls functional	Pic 2 Desc.	CFS perimeter controls functional		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	RCE functional	Pic 4 Desc.	RCE functional		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	CFS perimeter controls functional	Pic 6 Desc.	RCE functional		

A/E	124300137	Date/Time	12/31/2021 9:38 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	12/31/2021 9:38 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report







Project Name	H-600 Pipeline Spread G	AFE	124300137	Spread	H-600 Pipeline Spread G
Contractor	Precision			Report #	32789
Inspector	Eric Hanlon			Date/Time	12/31/2021 7:44 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	12005+00
State	VA	Inspection Area	Full	Station End	12005+00
County	Giles	Ground	Wet	Temperature (°F)	45.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300137	Date/Time	12/31/2021 7:44 AM	Report #	32789
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed a VA SWPPP inspection on yard 26. No compliance issues noted. Observance: Yard 26 has reduced activity during the winter curtailment. Perimeter controls in place & functioning as designed. RCE was clean, no mud or other debris on road. Secondary containment in place & functional as designed. All other ECDs and BMPs functional at time of inspection. No impact to sensitive resources observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300137	Date/Time	12/31/2021 7:44 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 1 Desc.	Secondary containment functional	Pic 2 Desc.	Perimeter controls functional		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 3 Desc.	Secondary containment functional	Pic 4 Desc.	RCE functional		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	12005+00	Field Station#	12005+00		
Pic 5 Desc.	CFS perimeter controls functional	Pic 6 Desc.	CFS perimeter controls functional		

A/E	124300137	Date/Time	12/31/2021 7:44 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300137	Date/Time	12/31/2021 7:44 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		