



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33331
Inspector	Charles Head			Date/Time	1/18/2022 10:11 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Full	Station End	14546+75
County	Franklin	Ground	Frozen	Temperature (°F)	36.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	1/18/2022 10:11 AM	Report #	33331
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection. On 01/16/2022 there was approximately 4-6 inches of snow and sleet accumulation.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/18/2022 10:11 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14455+50	Field Station#	14465+00		
Pic 1 Desc.	Approximately 14555+50. Overview of ROW.	Pic 2 Desc.	Approximately 14465+00. Overview of ROW.		
GPS Location	0	GPS Location	0		
Field Station#	14520+00	Field Station#	14524+50		
Pic 3 Desc.	Approximately 14520+00. Overview of ROW.	Pic 4 Desc.	Approximately 14524+50. Overview of road crossing and RCEs.		
GPS Location	0	GPS Location	0		
Field Station#	14528+00	Field Station#	14546+33		
Pic 5 Desc.	Approximately 14528+00. Overview of ROW.	Pic 6 Desc.	Approximately 14546+33. Overview of stream crossing, equipment bridge and ECDs at stream S-G17.		

A/E	124300139	Date/Time	1/18/2022 10:11 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	1/18/2022 10:11 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33343
Inspector	Ben Farmer			Date/Time	1/18/2022 1:07 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15370+62
State	VA	Inspection Area	Partial	Station End	15480+67
County	Pittsylvania	Ground	Frozen	Temperature (°F)	34.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/18/2022 1:07 PM	Report #	33343
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 34F) Rain Gauge= 0.0" 15370+62-15480+67 -EI began inspection at Snowberry Rd. -Drainage feature ECDs are in good condition at 15375+00. -Waterbars are in good condition. -Perimeter SSF is in good condition throughout this section. -P1 is in good condition at all stream and wetland buffers. -Resource buffers are in good condition. -Equipment bridge ECDs are in place and functioning. -Stockpiles remain stabilized -Drainage feature and 3rd party rock outlet appear to be in good condition. -RCEs are in good condition at all road crossings.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/18/2022 1:07 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15375+00		Field Station#	15380+00	
Pic 1 Desc.	Drainage feature ECDs are in good condition.		Pic 2 Desc.	Waterbars are in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15381+00		Field Station#	15383+00	
Pic 3 Desc.	Stockpiles remain stabilized.		Pic 4 Desc.	Perimeter SSF is in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15384+00		Field Station#	15384+74	
Pic 5 Desc.	P1 is in good condition at stream and wetland buffers.		Pic 6 Desc.	Resource buffers remain in good condition.	

AFE	124300139	Date/Time	1/18/2022 1:07 PM	Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15384+74	Field Station#	15474+00		
Pic 7 Desc.	Equipment bridge ECDs are in place and functioning.	Pic 8 Desc.	Stockpiles remain stabilized.		
GPS Location	See photo	GPS Location	See photo		
Field Station#	15475+00	Field Station#	15480+67		
Pic 9 Desc.	Drainage feature ECDs and 3rd party rock outlet appear to be in good condition.	Pic 10 Desc.	RCEs are in good condition at all road crossings.		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	1/18/2022 1:07 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33346
Inspector	Ben Davenport			Date/Time	1/18/2022 1:15 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14928+52
State	VA	Inspection Area	Partial	Station End	15063+85
County	Franklin/Pittsylvania	Ground	Frozen	Temperature (°F)	37.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/18/2022 1:15 PM	Report #	33346
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Performed SWPPP inspection on portion of MVP Spread I project -Inspection covered area between station# 14928+52–15063+85 (Ramsey Memorial Rd to Armstrong Rd) -Sunny with frozen/snowy ground conditions during inspection -ECDs we're unable to be inspected due to snow cover -ROW stabilized by solid snow cover -No issues observed at the time of inspection					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/18/2022 1:15 PM	Report #	
Pictures					
					
36°58'41" N 79°38'17" W 288°W COURSE 291° GPS 2019 Ramsey Memorial Rd, Penhook, VA 24137, United States 01.18.2022 13:05:08 Accur +/-15.4 Ft ALT 868 Ft			36°58'41" N 79°38'17" W 237°SW COURSE 291° GPS 2019 Ramsey Memorial Rd, Penhook, VA 24137, United States 01.18.2022 13:05:11 Accur +/-15.4 Ft ALT 868 Ft		
GPS Location	1		GPS Location	2	
Field Station#	14928+52		Field Station#	14930+00	
Pic 1 Desc.	ROW covered in snow; no issues observed		Pic 2 Desc.	ROW covered in snow; no issues observed	
					
36°57'43" N 79°36'58" W 202°S COURSE 162° GPS 176-198 Ashworth Rd, Penhook, VA 24137, United States 01.18.2022 13:12:36 Accur +/-98.4 Ft ALT 779 Ft			36°57'47" N 79°35'36" W 354°N COURSE 41° GPS 1918-2164 Armstrong Rd, Penhook, VA 24137, United States 01.18.2022 13:19:53 Accur +/-15.4 Ft ALT 909 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14995+21		Field Station#	15063+85	
Pic 3 Desc.	ROW covered in snow; no issues observed		Pic 4 Desc.	ROW covered in snow; no issues observed	
					
36°57'47" N 79°35'36" W 297°NW COURSE 41° GPS 1918-2164 Armstrong Rd, Penhook, VA 24137, United States 01.18.2022 13:19:58 Accur +/-33.7 Ft ALT 908 Ft			36°57'47" N 79°35'36" W 52°NE COURSE 41° GPS 1918-2164 Armstrong Rd, Penhook, VA 24137, United States 01.18.2022 13:20:01 Accur +/-37.2 Ft ALT 909 Ft		
GPS Location	5		GPS Location	6	
Field Station#	15061+00		Field Station#	15060+00	
Pic 5 Desc.	ROW covered in snow; no issues observed		Pic 6 Desc.	ROW covered in snow; no issues observed	

A/E	124300139	Date/Time	1/18/2022 1:15 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	1/18/2022 1:15 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33344
Inspector	Charles Head			Date/Time	1/18/2022 12:22 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14546+75
State	VA	Inspection Area	Full	Station End	14649+67
County	Franklin	Ground	Frozen	Temperature (°F)	36.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	1/18/2022 12:22 PM	Report #	33344
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection. On 01/16/2022 there was approximately 4-6 inches of snow and sleet accumulation.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/18/2022 12:22 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14550+00	Field Station#	14557+00		
Pic 1 Desc.	Approximately 14550+00. Overview of ROW.		Pic 2 Desc.	Approximately 14557+00. Overview of ROW.	
					
GPS Location	0	GPS Location	0		
Field Station#	14563+00	Field Station#	14568+10		
Pic 3 Desc.	Approximately 14563+00. Overview of ROW. Third party vehicles tracks observed crossing and traveling on ROW.		Pic 4 Desc.	Approximately 14568+10. Overview of stream crossing, equipment bridge and ECDs at stream S-E18.	
					
GPS Location	0	GPS Location	0		
Field Station#	14599+00	Field Station#	14604+00		
Pic 5 Desc.	Approximately 14599+00. Overview of road crossing and RCEs.		Pic 6 Desc.	Approximately 14604+00. Overview of ROW.	

A/E	124300139	Date/Time	1/18/2022 12:22 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/18/2022 12:22 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33340
Inspector	John White			Date/Time	1/18/2022 12:41 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15772+27
State	VA	Inspection Area	Full	Station End	15947+64
County	Pittsylvania	Ground	Frozen	Temperature (°F)	34.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Plunge Pool	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	Contractor is working on repairs			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/18/2022 12:41 PM	Report #	33340
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There was one issue identified and added to the punch list. The Contractor is working on repairing the identified issue. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/18/2022 12:41 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15794+77	Field Station#	15781+22		
Pic 1 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15825+00	Field Station#	15839+00		
Pic 3 Desc.	Observing temporary stabilization,plunge pool and ECD's	Pic 4 Desc.	Observing CWD pipe and outlet		
GPS Location	O	GPS Location	O		
Field Station#	15851+55	Field Station#	15862+00		
Pic 5 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 6 Desc.	Observing temporary stabilization,CWD outlet and ECD's		

AFE	124300139	Date/Time	1/18/2022 12:41 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15878+08	Field Station#	15885+00		
Pic 7 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 8 Desc.	Observing P1 that requires maintenance		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	1/18/2022 12:41 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33332
Inspector	Logan Box			Date/Time	1/18/2022 3:13 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13670+00
State	VA	Inspection Area	Partial	Station End	13748+30
County	Franklin	Ground	Frozen	Temperature (°F)	40.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Rock Construction Entrance	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Erosion Control Blanket	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300139	Date/Time	1/18/2022 3:13 PM	Report #	33332
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI traveled road crossings that were accessible and monitored row conditions and ECDs where possible.</p> <p>The EI observed stream and wetland areas that were accessible near road crossings, all ECDs were functioning prior to the recent snow events.</p> <p>The EI monitored RCEs throughout the inspection area today. All RCEs were covered in snow and froze from the recent snow events making some areas of row not possible to access .</p> <p>Throughout the areas inspected there were no environmental issues observed at the time of inspection.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/18/2022 3:13 PM	Report #	
Pictures					
	East Elevation 				
GPS Location	00000	GPS Location	0000		
Field Station#	13690+74	Field Station#	13691+20		
Pic 1 Desc.	Photo showing RCE covered in snow from recent snow events. No environmental issues observed at the time of inspection.		Pic 2 Desc.	Row photo showing snow, all ECDs functioning around wetland area prior to snow event, no environmental issues observed at the time of inspection.	
	West Elevation 			North East Elevation 	
GPS Location	0000	GPS Location	00000		
Field Station#	13692+64	Field Station#	13692+64		
Pic 3 Desc.	Stream observation photo facing upstream during routine inspection after recent snow events. No environmental issues observed at the time of inspection.		Pic 4 Desc.	Stream observation photo facing upstream during routine inspection, no environmental issues observed at the time of inspection.	
				North West Elevation 	
GPS Location	0000	GPS Location	0000		
Field Station#	13689+00	Field Station#	13692+64		
Pic 5 Desc.	Row photo showing snow covered conditions, equipment mats in place. No environmental issues observed at the time of inspection.		Pic 6 Desc.	Monitored stream crossing , all ECDs in place prior to snow events, no environmental issues observed at the time of inspection.	

A/E	124300139	Date/Time	1/18/2022 3:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/18/2022 3:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		




Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	33338		
Inspector	Justin Burch	Date/Time	1/18/2022 12:12 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14062+17
State	VA	Inspection Area	Full	Station End	14171+36
County	Franklin	Ground	Wet	Temperature (°F)	40.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.80
			Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Reinforce Filter Fence)		Acceptable			
Cleanwater Diversion Pipe		Acceptable			
Plunge Pool		Acceptable			
Waterbar		Acceptable			
Waterbar End Treatment		Acceptable			
Equipment Bridge		Acceptable			
Compost Filter Sock		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/18/2022 12:12 PM	Report #	33338
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> • The EI performed a SWPPP inspection from 14062+17 to 14171+36 (Bonbrook Mill Road #2 to Angle Plantation Road). No issues were submitted for the punch list due to inspected ECDs being in compliance at the time of inspection. • The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. • Since the last SWPPP inspection the area received one precipitation event with a total of 0.80" at Bonbrook Mill Road #1. • The ROW ground condition is wet and snow covered. • At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 14112+00 to 14120+00 and from 14164+00 to 14167+00. • At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/18/2022 12:12 PM	Report #	
Pictures					
GPS Location	0		GPS Location	0	
Field Station#	14171+00		Field Station#	14133+00	
Pic 1 Desc.	P1 silt fence in acceptable condition		Pic 2 Desc.	Clean water diversion pipe and plunge pool in acceptable conditions	
GPS Location	0		GPS Location	0	
Field Station#	14063+00		Field Station#	14067+00	
Pic 3 Desc.	Waterbar in acceptable condition		Pic 4 Desc.	Waterbar end treatment in acceptable condition	
GPS Location	0		GPS Location	0	
Field Station#	14066+77		Field Station#	14066+77	
Pic 5 Desc.	Equipment bridge in acceptable condition		Pic 6 Desc.	Stream S-EF48 looking downstream	

AFE	124300139	Date/Time	1/18/2022 12:12 PM	Report #	
Pictures					
				Insert image here	
GPS Location	0	GPS Location			
Field Station#	14131+00	Field Station#			
Pic 7 Desc.	CFS in acceptable condition	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	1/18/2022 12:12 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33318
Inspector	Ben Davenport			Date/Time	1/18/2022 10:21 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Partial	Station End	14928+52
County	Franklin	Ground	Frozen	Temperature (°F)	37.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/18/2022 10:21 AM	Report #	33318
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Performed SWPPP inspection on portion of MVP Spread I project -Inspection covered area between station# 14802+19–14928+52 (MVP-FR-323 to Ramsey Memorial Rd) -Sunny with frozen/snowy ground conditions during inspection -ECDs we're unable to be inspected due to snow cover -ROW stabilized by solid snow cover -No issues observed at the time of inspection					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/18/2022 10:21 AM	Report #	
Pictures					
					
36°58'21" N 79°39'56" W 7°N COURSE -1° GPS 168-344 Listening Hill Rd, Penhook, VA 24137, United States 01.18.2022 12:53:39 Accur +/-15.4 Ft ALT 973 Ft			36°58'20" N 79°39'56" W 186°S COURSE 135° GPS 168-344 Listening Hill Rd, Penhook, VA 24137, United States 01.18.2022 12:53:46 Accur +/-15.4 Ft ALT 972 Ft		
GPS Location	1		GPS Location	2	
Field Station#	14843+00		Field Station#	14847+00	
Pic 1 Desc.	ROW covered in snow; no issues observed		Pic 2 Desc.	ROW covered in snow; no issues observed	
					
36°58'17" N 79°39'37" W 358°N COURSE 183° GPS 2201 Bar Ridge Rd, Penhook, VA 24137, United States 01.18.2022 12:56:31 Accur +/-15.5 Ft ALT 976 Ft			36°58'17" N 79°39'37" W 159°SE COURSE 111° GPS 2201 Bar Ridge Rd, Penhook, VA 24137, United States 01.18.2022 12:56:36 Accur +/-15.5 Ft ALT 976 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14861+00		Field Station#	14863+00	
Pic 3 Desc.	ROW covered in snow; no issues observed		Pic 4 Desc.	ROW covered in snow; no issues observed	
					
36°58'4" N 79°38'17" W 99°E COURSE 189° GPS 2019 Ramsey Memorial Rd, Penhook, VA 24137, United States 01.18.2022 13:04:52 Accur +/-15.4 Ft ALT 861 Ft			36°58'4" N 79°38'17" W 40°NE COURSE -1° GPS 2019 Ramsey Memorial Rd, Penhook, VA 24137, United States 01.18.2022 13:05:02 Accur +/-15.4 Ft ALT 863 Ft		
GPS Location	5		GPS Location	6	
Field Station#	14927+00		Field Station#	14928+52	
Pic 5 Desc.	ROW covered in snow; no issues observed		Pic 6 Desc.	ROW covered in snow; no issues observed	

A/E	124300139	Date/Time	1/18/2022 10:21 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	1/18/2022 10:21 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33341
Inspector	Ben Farmer			Date/Time	1/18/2022 1:03 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Partial	Station End	15370+62
County	Pittsylvania	Ground	Frozen	Temperature (°F)	34.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/18/2022 1:03 PM	Report #	33341
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Sunny, 34F) Rain Gauge= 0.0" 15260+00-15370+62 -EI began inspection at Oxford Rd. -RCEs are in good condition at all road crossings. -P1 is in good condition along drainage at 15299+00. -CWD is in good condition and functioning at 15299+00. -Equipment bridge ECDs are in place and functioning. -Resource buffers are in good condition. -P1 is in good condition at all stream and wetland buffers. -MVP-PI-332 is in good condition with controls in place. -ROW remains stabilized.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/18/2022 1:03 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15299+00		Field Station#	15299+00	
Pic 1 Desc.	P1 is in good condition along this drainage feature.		Pic 2 Desc.	CWD remains in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15347+00		Field Station#	15347+00	
Pic 3 Desc.	Equipment bridge ECDs are in place and functioning.		Pic 4 Desc.	Resource buffers remain in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15349+00		Field Station#	15349+50	
Pic 5 Desc.	P1 is in good condition at all stream and wetland buffers.		Pic 6 Desc.	Waterbars are in good condition.	

AFE	124300139	Date/Time	1/18/2022 1:03 PM	Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15350+00	Field Station#	15370+00		
Pic 7 Desc.	MVP-PI-332 remains in good condition with controls in place.	Pic 8 Desc.	ROW remains stabilized.		
GPS Location	See photo	GPS Location			
Field Station#	15370+62	Field Station#			
Pic 9 Desc.	RCEs are in good condition at all road crossings.	Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	1/18/2022 1:03 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33335
Inspector	Justin Burch			Date/Time	1/18/2022 11:27 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Full	Station End	14062+17
County	Franklin	Ground	Wet	Temperature (°F)	40.00
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.80
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Slope Drain Pipe	Acceptable				
Sump Pit	Acceptable				
Waterbar	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Waterbar End Treatment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/18/2022 11:27 AM	Report #	33335
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13958+31 to 14062+17 (Foggy Ridge Road to Bonbrook Mill Road #2). No issues were submitted for the punch list due to inspected ECDs being in compliance at the time of inspection. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area received one precipitation event with a total of 0.80" at Bonbrook Mill Road #1. The ROW ground condition is wet and snow covered. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 14011+00 to 14018+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/18/2022 11:27 AM	Report #			
Pictures							
<div>333°NW (T) 37°3'56"N, 79°52'33"W ±29ft ▲1198ft</div>  <div>14061+00 01-18-2022, 10:54:18</div>			<div>357°N (T) 37°3'56"N, 79°52'31"W ±272ft ▲1203ft</div>  <div>14061+00 01-18-2022, 10:55:19</div>				
GPS Location		0		GPS Location		0	
Field Station#		14061+00		Field Station#		14061+00	
Pic 1 Desc.		Slope drain and sump pit in acceptable conditions		Pic 2 Desc.		Waterbar in acceptable condition	
<div>76°E (T) 37°3'21"N, 79°52'59"W ±380ft ▲1038ft</div>  <div>14009+20 01-18-2022, 11:04:01</div>			<div>135°SE (T) 37°3'21"N, 79°52'59"W ±32ft ▲1029ft</div>  <div>14009+20 01-18-2022, 11:04:35</div>				
GPS Location		0		GPS Location		0	
Field Station#		14009+20		Field Station#		14009+20	
Pic 3 Desc.		Equipment bridge and P1 silt fence in acceptable conditions		Pic 4 Desc.		Stream S-KL38 looking downstream in acceptable condition	
<div>138°SE (T) 37°2'49"N, 79°53'40"W ±400ft ▲1104ft</div>  <div>13961+00 01-18-2022, 11:16:33</div>			<div>142°SE (T) 37°2'54"N, 79°53'37"W ±16ft ▲1106ft</div>  <div>13962+00 01-18-2022, 11:17:40</div>				
GPS Location		0		GPS Location		0	
Field Station#		13961+00		Field Station#		13962+00	
Pic 5 Desc.		Clean water diversion pipe in acceptable condition		Pic 6 Desc.		Waterbar end treatment pit in acceptable condition	

A/E	124300139	Date/Time	1/18/2022 11:27 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/18/2022 11:27 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33333
Inspector	John White			Date/Time	1/18/2022 10:21 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Full	Station End	15772+27
County	Pittsylvania	Ground	Frozen	Temperature (°F)	33.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Communication	Contractor is working on repairs			
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/18/2022 10:21 AM	Report #	33333
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There was one issue identified and added to the punch list. The Contractor is working on repairing the identified item. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/18/2022 10:21 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15671+93	Field Station#	15668+26		
Pic 1 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 2 Desc.	Observing stream		
GPS Location	O	GPS Location	O		
Field Station#	15658+43	Field Station#	15655+00		
Pic 3 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 4 Desc.	Observing water bar, sump and end treatment		
GPS Location	O	GPS Location	O		
Field Station#	15679+00	Field Station#	15685+00		
Pic 5 Desc.	Observing temporary stabilization, CWD outlet and ECD's	Pic 6 Desc.	Observing temporary stabilization and water bars		

AFE	124300139	Date/Time	1/18/2022 10:21 AM	Report #	
Pictures					
GPS Location	O	GPS Location			
Field Station#	15766+00	Field Station#			
Pic 7 Desc.	Observing tree that needs to be removed from the CFS	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	1/18/2022 10:21 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		








Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	33395		
Inspector	Ben Farmer	Date/Time	1/19/2022 1:01 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15480+67
State	VA	Inspection Area	Partial	Station End	15584+23
County	Pittsylvania	Ground	Frozen	Temperature (°F)	35.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe		Acceptable			
Compost Filter Sock		Acceptable			
Equipment Bridge		Acceptable			
Rock Construction Entrance		Acceptable			
Sensitive Resource Buffer		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
Slope Drain Pipe		Acceptable			
Vegetative Stabilization (Temporary)		Acceptable			
Waterbar		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	1/19/2022 1:01 PM	Report #	33395
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Cloudy, 35F) Rain Gauge= 0.0" 15480+67-15584+23 -EI began inspection at Toshes Rd. -RCEs are in good condition at all road crossings. -Perimeter CFS is in good condition throughout this section. -No evidence of sedimentation from 3rd party disturbance at 15501+00. -3rd party ECDs appear to be in good condition at 15510+00. -CWDs are in good condition and functioning. -Equipment bridge ECDs are in good condition and functioning. -Waterbars are in good condition throughout this section. -Resource buffers are in good condition -Slope drain is in good condition and functioning at 15575+00 -ROW remains stabilized.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/19/2022 1:01 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15490+00		Field Station#	15494+00	
Pic 1 Desc.	Perimeter CFS is in good condition.		Pic 2 Desc.	ROW remains stabilized.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15496+70		Field Station#	15501+00	
Pic 3 Desc.	RCEs are in good condition at all road crossings.		Pic 4 Desc.	No evidence of sedimentation from 3rd party disturbance.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15507+00		Field Station#	15510+00	
Pic 5 Desc.	P1 is in good condition at all stream and wetland buffers.		Pic 6 Desc.	3rd party ECDs appear to be in good condition.	

AFE	124300139	Date/Time	1/19/2022 1:01 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15515+00		Field Station#	15540+00	
Pic 7 Desc.	CWDs are functioning as intended.		Pic 8 Desc.	Equipment bridge ECDs are in place and functioning.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15570+00		Field Station#	15573+54	
Pic 9 Desc.	Waterbars are in good condition.		Pic 10 Desc.	Resource buffers remain in good condition.	
				<p>Insert image here</p>	
GPS Location	See photo		GPS Location		
Field Station#	15575+00		Field Station#		
Pic 11 Desc.	Slope drain is in good condition and functioning.		Pic 12 Desc.		

A/E	124300139	Date/Time	1/19/2022 1:01 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-602 Pipeline Spread I		AFE	124300139	Spread	H-602 Pipeline Spread I	
Contractor	Precision				Report #	33386	
Inspector	John White				Date/Time	1/19/2022 11:57 AM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	00+00	
State	VA	Inspection Area	Full		Station End	19+25	
County	Pittsylvania	Ground	Frozen		Temperature (°F)	42.00	
Municipality	Chatham	Weather	Cloudy		Rain Gauge (in)	0.00	
					Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable					
Equipment Bridge		Acceptable					
Housekeeping		Acceptable					
Sediment Filter Log		Acceptable					
Sensitive Resource Buffer		Acceptable					
Sump Pit		Acceptable					
Vegetative Stabilization (Temporary)		Acceptable					
Waterbar		Acceptable					
Waterbar End Treatment		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300139	Date/Time	1/19/2022 11:57 AM	Report #	33386
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/19/2022 11:57 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	6+00	Field Station#	12+65		
Pic 1 Desc.	Observing temporary stabilization and access road	Pic 2 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	13+50	Field Station#	19+00		
Pic 3 Desc.	Observing temporary stabilization,water bar, sump and end treatment	Pic 4 Desc.	Observing temporary stabilization and ECD's		
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300139	Date/Time	1/19/2022 11:57 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	1/19/2022 11:57 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33393
Inspector	Justin Burch			Date/Time	1/19/2022 12:54 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14171+36
State	VA	Inspection Area	Full	Station End	14311+57
County	Franklin	Ground	Wet	Temperature (°F)	47.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Plunge Pool	Acceptable				
Cleanwater Diversion Berm	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Compost Filter Sock	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/19/2022 12:54 PM	Report #	33393
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 14171+36 to 14311+57 (Angle Plantation Road to Farm View Road). No issues were submitted for the punch list due to inspected ECDs being in compliance at the time of inspection. The EI observed that the contractor has worked in the area since the last SWPPP inspection and addressed the items on the punch list. Since the last SWPPP inspection the area has received one precipitation event with 6" of snow at Bonbrook Mill Road #1 and 5" of snow at Farm View Road. The ROW ground condition is wet and snow covered. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 14258+00 to 14277+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/19/2022 12:54 PM	Report #	
Pictures					
50°NE (T) 37°2'35"N, 79°48'37"W ±42ft ▲1063ft  14308+00 01-19-2022, 09:29:42		148°SE (T) 37°2'38"N, 79°48'33"W ±114ft ▲1060ft  14308+00 01-19-2022, 09:31:34			
GPS Location	0	GPS Location	0		
Field Station#	14308+00	Field Station#	14308+00		
Pic 1 Desc.	Plunge pool in acceptable condition	Pic 2 Desc.	Clean water diversion berm in acceptable condition		
67°NE (T) 37°2'55"N, 79°49'2"W ±374ft ▲954ft  14279+00 01-19-2022, 09:59:14		119°SE (T) 37°3'12"N, 79°49'38"W ±5803ft ▲897ft  14248+50 01-19-2022, 11:18:39			
GPS Location	0	GPS Location	0		
Field Station#	14279+00	Field Station#	14248+50		
Pic 3 Desc.	Equipment bridge in acceptable condition	Pic 4 Desc.	P1 silt fence and super silt fence in acceptable conditions		
331°NW (T) 37°2'58"N, 79°49'7"W ±59ft ▲968ft  14273+00 01-19-2022, 10:32:36		188°S (T) 37°3'30"N, 79°50'39"W ±39ft ▲976ft  14177+00 01-19-2022, 14:31:40			
GPS Location	0	GPS Location	0		
Field Station#	14273+00	Field Station#	14177+00		
Pic 5 Desc.	Perimeter CFS in acceptable condition	Pic 6 Desc.	Waterbar in acceptable condition		

AFE	124300139	Date/Time	1/19/2022 12:54 PM	Report #	
Pictures					
				Insert image here	
GPS Location	0	GPS Location			
Field Station#	14175+50	Field Station#			
Pic 7 Desc.	Waterbar end treatment in acceptable condition	Pic 8 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	1/19/2022 12:54 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33401
Inspector	Charles Head			Date/Time	1/19/2022 2:23 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14649+67
State	VA	Inspection Area	Full	Station End	14694+77
County	Franklin	Ground	Frozen	Temperature (°F)	47.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/19/2022 2:23 PM	Report #	33401
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection. On 01/16/2022 there was approximately 4-6 inches of snow and sleet accumulation. Accumulated precipitation from 01/16/2022 has not melted.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/19/2022 2:23 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	14654+00	Field Station#	14680+50		
Pic 1 Desc.	Approximately 14654+00. Overview of ROW.		Pic 2 Desc.	Approximately 14680+50. Overview of stream crossing, equipment bridge and ECDs at stream S-H36.	
					
GPS Location	0	GPS Location	0		
Field Station#	14673+10	Field Station#	14689+36		
Pic 3 Desc.	Approximately 14673+10. Overview of stream crossing, equipment bridge and ECDs at stream S-H37.		Pic 4 Desc.	Approximately 14689+36. Overview of stream crossing, equipment bridge and ECDs at stream S-H34.	
					
GPS Location	0	GPS Location	0		
Field Station#	14694+50	Field Station#	14670+00		
Pic 5 Desc.	Approximately 14694+50. Overview of road crossing and RCE. VDOT snowplow activity has turned rock and mud up onto approach.		Pic 6 Desc.	Approximately 14670+00. Overview of ROW. Livestock are still active and present in area.	

A/E	124300139	Date/Time	1/19/2022 2:23 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/19/2022 2:23 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33387
Inspector	John White			Date/Time	1/19/2022 12:04 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15947+64
State	VA	Inspection Area	Full	Station End	16027+46
County	Pittsylvania	Ground	Frozen	Temperature (°F)	42.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/19/2022 12:04 PM	Report #	33387
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/19/2022 12:04 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	16023+00	Field Station#	16020+00		
Pic 1 Desc.	Observing temporary stabilization and water bar	Pic 2 Desc.	Observing temporary stabilization, sump and end treatment		
GPS Location	O	GPS Location	O		
Field Station#	16016+36	Field Station#	16010+00		
Pic 3 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's	Pic 4 Desc.	Observing temporary stabilization, CWD outlet and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	16004+00	Field Station#	16007+00		
Pic 5 Desc.	Observing temporary stabilization, signage and buffer	Pic 6 Desc.	Observing temporary stabilization, sump and end treatment		

A/E	124300139	Date/Time	1/19/2022 12:04 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/19/2022 12:04 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-603 Pipeline Spread I	AFE	124300139	Spread	H-603 Pipeline Spread I
Contractor	Precision			Report #	33383
Inspector	John White			Date/Time	1/19/2022 11:43 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	24+53
County	Pittsylvania	Ground	Frozen	Temperature (°F)	41.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable				
Housekeeping	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Sump Pit	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/19/2022 11:43 AM	Report #	33383
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/19/2022 11:43 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	14+50	Field Station#	22+00		
Pic 1 Desc.	Observing temporary stabilization, signage and buffer	Pic 2 Desc.	Observing temporary stabilization, signage and buffer		
GPS Location	O	GPS Location	O		
Field Station#	10+00	Field Station#	6+00		
Pic 3 Desc.	Observing temporary stabilization	Pic 4 Desc.	Observing temporary stabilization, water bar, sump and end treatment		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 5 Desc.		Pic 6 Desc.			

A/E	124300139	Date/Time	1/19/2022 11:43 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	1/19/2022 11:43 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33347
Inspector	Ben Davenport			Date/Time	1/19/2022 11:07 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15063+85
State	VA	Inspection Area	Partial	Station End	15142+66
County	Pittsylvania	Ground	Frozen	Temperature (°F)	46.00
Municipality	Chatham	Weather	Sunny	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance; cattle damage			
Vegetative Stabilization (Temporary)	Acceptable				
Compost Filter Sock	Acceptable				
Rock Construction Entrance	Acceptable				
Sump Pit	Acceptable				
Waterbar End Treatment	Acceptable				
Equipment Bridge	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Sediment Filter Log	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/19/2022 11:07 AM	Report #	33347
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Sunny with frozen/snowy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 15063+85 — 15142+66 (Armstrong Rd to Rock Creek Rd) -ROW still covered in 4-6 inches of snow -Walked ROW looking for potential environmental issues or maintenance requirements -Perimeter controls and ECD's were inspected; 1 issue identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of equipment bridges and ECDs at resource buffers around stream crossings; no issues observed -Observed of stabilization and vegetation in section both permanent and temporary areas of ROW; no issues observed -Continue to monitor ROW for signs of erosion -1 item added to environmental punch list					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/19/2022 11:07 AM	Report #	
Pictures					
					
36°57'17" N 79°34'59" W 273°W COURSE 335° GPS 8850-8968 Museville Rd, Sandy Level, VA 24161, United States 01.19.2022 12:51:10 Accur +/-30.7 Ft ALT 930 Ft			36°57'19" N 79°34'55" W 152°SE COURSE -1° GPS 8850-8968 Museville Rd, Sandy Level, VA 24161, United States 01.19.2022 12:49:16 Accur +/-15.5 Ft ALT 914 Ft		
GPS Location	1		GPS Location	2	
Field Station#	15113+25		Field Station#	15113+50	
Pic 1 Desc.	Routine maintenance. Replace damaged panels of P1 silt fence in extra workspace. Cattle damage.		Pic 2 Desc.	Made note of area where vehicle left RCE. Will monitor area.	
					
36°57'25" N 79°35'0" W 17°N COURSE 314° GPS Sandy Level, VA 24161, United States 01.19.2022 13:07:10 Accur +/-85.2 Ft ALT 915 Ft			36°57'8" N 79°34'50" W 179°S COURSE -1° GPS Sandy Level, VA 24161, United States 01.19.2022 12:58:08 Accur +/-15.5 Ft ALT 876 Ft		
GPS Location	3		GPS Location	4	
Field Station#	15103+45		Field Station#	15126+40	
Pic 3 Desc.	Equipment bridge and surrounding ECDs appear to be in place and functional at stream crossing and resource buffer.		Pic 4 Desc.	Equipment bridge and surrounding ECDs appear to be in place and functional at stream crossing and resource buffer.	
					
36°57'13" N 79°34'50" W 19°N COURSE 358° GPS Sandy Level, VA 24161, United States 01.19.2022 13:00:13 Accur +/-41.3 Ft ALT 907 Ft			36°57'9" N 79°34'49" W 168°S COURSE 154° GPS Sandy Level, VA 24161, United States 01.19.2022 12:57:38 Accur +/-103.2 Ft ALT 909 Ft		
GPS Location	5		GPS Location	6	
Field Station#	15120+00		Field Station#	15128+00	
Pic 5 Desc.	Plunge pool appears to be performing intended function.		Pic 6 Desc.	Sump pit and CFS end treatment in good condition.	

A/E	124300139	Date/Time	1/19/2022 11:07 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	1/19/2022 11:07 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I		AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision				Report #	33377	
Inspector	Logan Box				Date/Time	1/19/2022 4:38 PM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	13748+30	
State	VA	Inspection Area	Partial		Station End	13853+45	
County	Franklin	Ground	Frozen		Temperature (°F)	50.00	
Municipality	N/A	Weather	Sunny		Rain Gauge (in)	0.00	
					Rain Accumulation Time (days)	0.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?							Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)							
E&S BMPs		Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable					
Sump Pit		Acceptable					
Rock Construction Entrance		Acceptable					
Vegetative Stabilization (Temporary)		Acceptable					
Silt Fence (Filter Fabric Fence)		Acceptable					
5. Site Conditions							
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.							No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?							Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)							No

A/E	124300139	Date/Time	1/19/2022 4:38 PM	Report #	33377
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<p>The EI traveled road crossings that were accessible due to snow and ice conditions.</p> <p>The EI monitored sump pits and end treatments all functioning at the time of inspection.</p> <p>The EI observed all visible ECDs and vegetation on spoil piles. All ECDs throughout were up to date and functioning prior to snow events.</p> <p>Most RCEs were covered in snow and ice making access limited in areas.</p>					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/19/2022 4:38 PM	Report #	
Pictures					
	South Elevation <small>10°N (T) • 37.065938, -79.922662 ±8 m ▲ 307 m</small> 			South Elevation <small>7°N (T) • 37.065856, -79.922041 ±7 m ▲ 309 m</small> 	
GPS Location	00000	GPS Location	00000		
Field Station#	13826+15	Field Station#	13827+80		
Pic 1 Desc.	Photo showing snow on top soil piles, no environmental issues observed at the time of inspection.		Pic 2 Desc.	Monitored sump pits and ECDs that were visible after recent snow events, row still frozen. No environmental issues observed at the time of inspection.	
	North Elevation <small>177°S (T) • 37.065856, -79.922041 ±7 m ▲ 309 m</small> 			South East Elevation <small>317°NW (T) • 37.068965, -79.932806 ±3 m ▲ 314 m</small> 	
GPS Location	00000	GPS Location	00000		
Field Station#	13830+00	Field Station#	13784+35		
Pic 3 Desc.	Row photo showing snow covered conditions, no environmental issues observed at the time of inspection, row still frozen.		Pic 4 Desc.	Monitored sump pits and end treatment, no environmental issues observed at the time of inspection, row still frozen.	
	South Elevation <small>352°N (T) • 37.06896, -79.932803 ±3 m ▲ 314 m</small> 			South West Elevation <small>39°NE (T) • 37.068799, -79.932846 ±3 m ▲ 315 m</small> 	
GPS Location	00000	GPS Location	00000		
Field Station#	13784+40	Field Station#	13784+38		
Pic 5 Desc.	Monitored visible vegetation and ECDs, no environmental issues observed at the time of inspection.		Pic 6 Desc.	Row photo showing snow covered conditions, no environmental issues observed at the time of inspection, row still frozen.	

A/E	124300139	Date/Time	1/19/2022 4:38 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/19/2022 4:38 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	33413	
Inspector	Glenn Mike Renfro			Date/Time	1/19/2022 8:16 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0000+00	
State	VA	Inspection Area	Full	Station End	0000+00	
County	Franklin	Ground	Frozen	Temperature (°F)	44.00	
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.60	
				Rain Accumulation Time (days)	6.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Housekeeping		Acceptable				
Other - Explain in Comments		Acceptable	Inlet protection for catch basins			
Rock Construction Entrance		Acceptable				
Secondary Containment		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						N/A
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

A/E	124300139	Date/Time	1/19/2022 8:16 PM	Report #	33413
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> - Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va. - The locations received. 6" of snowfall and site conditions were frozen - All perimeter ECD's were inspected and no problems were found. - The inlet protection for the catch basins at LY-046 were found to be in good condition. - All secondary containment structures were inspected and no issues were identified during the time of inspection. - The RCE, at LY-045 was in good condition. - All equipment at both locations were inspected and no leaks were observed at the time of inspection. - The General Construction permits and contact information are posted at the entrance of LY-046 as required. - There were no issues found to report during today's inspection. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/19/2022 8:16 PM	Report #	
Pictures					
GPS Location	See picture	GPS Location	See picture		
Field Station#	0000+00	Field Station#	0000+00		
Pic 1 Desc.	Perimeter ECD's on northwest perimeter of LY-046 in good condition.	Pic 2 Desc.	Inlet protection for catch basin near storage building at perimeter ECD's on west side of LY-046 in good condition.		
GPS Location	See picture	GPS Location	See picture		
Field Station#	0000+00	Field Station#	0000+00		
Pic 3 Desc.	Secondary containment structure for fuel cell at LY-046 in good condition.	Pic 4 Desc.	Secondary containment structure for light plant behind office building at LY-045 in good condition.		
		Insert image here			
GPS Location	See picture	GPS Location			
Field Station#	0000+00	Field Station#			
Pic 5 Desc.	RCE at LY-045 in good condition.	Pic 6 Desc.			

A/E	124300139	Date/Time	1/19/2022 8:16 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		






A/E	124300139	Date/Time	1/19/2022 8:16 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor	Precision			Report #	33396	
Inspector	Frank Craycroft			Date/Time	1/19/2022 1:07 PM	
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	0+00	
State	VA	Inspection Area	Full	Station End	0+00	
County	Franklin	Ground	Muddy	Temperature (°F)	45.00	
Municipality	N/A	Weather	Sunny	Rain Gauge (in)	0.00	
				Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?						Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)						No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)						Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)						
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock		Acceptable				
Rock Construction Entrance		Acceptable				
Housekeeping		Communication	ANC-006 Remove snow stockpile in	Addressed	1/19/2022	
Secondary Containment		Communication	LY-032 secondary containment arou	Addressed	1/19/2022	
Timber Mat		Acceptable				
Vegetative Stabilization (Temporary)		Acceptable				
Waste Management		Acceptable				
5. Site Conditions						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.						No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?						Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?						N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)						No

AFE	124300139	Date/Time	1/19/2022 1:07 PM	Report #	33396
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Completed SWPPP inspection of LY-032, -033, -048 and ANC-006. Secondary containment around light plant in LY-032 had been damaged by construction activities in yard. Crew completed repairs to containment today. Snow removal at ANC-006 had stockpiled snow inside Stormwater drain inlet perimeter. Contacted contractor and snow within perimeter CFS was removed. Otherwise, all portable equipment and hazardous materials were maintained within secondary containment. Remainder of stormwater drain inlets were free of debris and vegetation and had proper perimeter protection. All perimeter ECDs were functional and in good. Areas without equipment traffic had snow remaining which is melting moderately, but no signs of runoff were observed.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/19/2022 1:07 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 1 Desc.	LY-032 Damaged CFS of secondary containment		Pic 2 Desc.	LY-032 Equipment staging	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 3 Desc.	LY-033 Staging area		Pic 4 Desc.	LY-033 Stormwater drain inlet	
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 5 Desc.	ANC-006 Snow stockpile with Stormwater drain inlet protection		Pic 6 Desc.	ANC-006 Southeast perimeter CFS	

A/E	124300139	Date/Time	1/19/2022 1:07 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 7 Desc.	LY-048 Housekeeping	Pic 8 Desc.	LY-048 Staging area		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	1/19/2022 1:07 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33438
Inspector	John White			Date/Time	1/20/2022 12:14 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15584+23
State	VA	Inspection Area	Full	Station End	15647+03
County	Pittsylvania	Ground	Frozen	Temperature (°F)	40.00
Municipality	Chatham	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Construction Entrance	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Sump Pit	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/20/2022 12:14 PM	Report #	33438
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/20/2022 12:14 PM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15584+23	Field Station#	15586+00		
Pic 1 Desc.	Observing road crossing and RCE.	Pic 2 Desc.	Observing temporary stabilization, water bar, sump and end treatment		
GPS Location	O	GPS Location	O		
Field Station#	15617+00	Field Station#	15614+94		
Pic 3 Desc.	Observing temporary stabilization, water bar, sump and end treatment	Pic 4 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15648+00	Field Station#	15636+45		
Pic 5 Desc.	Observing temporary stabilization and ECD's	Pic 6 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		

A/E	124300139	Date/Time	1/20/2022 12:14 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/20/2022 12:14 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33440
Inspector	Justin Burch			Date/Time	1/20/2022 12:27 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13853+45
State	VA	Inspection Area	Full	Station End	13958+31
County	Franklin	Ground	Wet	Temperature (°F)	40.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar		Acceptable			
Sump Pit		Acceptable			
Slope Drain Pipe		Acceptable			
Cleanwater Diversion Pipe		Acceptable			
Plunge Pool		Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)		Communication	Silt fence was repaired	Immediate	1/20/2022
Silt Fence (Reinforce Filter Fence)		Acceptable			
Waterbar End Treatment		Acceptable			
Equipment Bridge		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/20/2022 12:27 PM	Report #	33440
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13853+45 to 13958+31 (access road MVP-FR-303.01 to Foggy Ridge Road). One issue was submitted for the punch list consisting of location where super silt fence fabric was detached from the wire fence. The contractor addressed this issue immediately. Other inspected ECDs were observed as being in compliance at the time of inspection. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area received one precipitation event with snowfall totals of 6" at Grassy Hill Road and 6" at Bonbrook Mill Road #1. Intermittent rain fell today. The ROW ground condition is wet and snow covered. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 13900+00 to 13910+00 and from 13921+00 to 13940+00. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/20/2022 12:27 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	13955+00	Field Station#	13955+00		
Pic 1 Desc.	Waterbar in acceptable condition		Pic 2 Desc.	Sump pit and slope drain pipe in acceptable condition	
					
GPS Location	0	GPS Location	0		
Field Station#	13943+00	Field Station#	13893+00		
Pic 3 Desc.	Clean water diversion pipe and plunge pool in acceptable conditions		Pic 4 Desc.	Super silt fence fabric detached from wire fence; contractor repaired immediately	
					
GPS Location	0	GPS Location	0		
Field Station#	13893+00	Field Station#	13903+00		
Pic 5 Desc.	Super Silt fence after maintenance.		Pic 6 Desc.	P1 silt fence in acceptable condition	

A/E	124300139	Date/Time	1/20/2022 12:27 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	13862+00	Field Station#	13862+80		
Pic 7 Desc.	Waterbar end treatment in acceptable condition	Pic 8 Desc.	Equipment bridge in acceptable condition		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			







A/E	124300139	Date/Time	1/20/2022 12:27 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		








Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33458
Inspector	Ben Farmer			Date/Time	1/20/2022 1:59 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15142+66
State	VA	Inspection Area	Partial	Station End	15260+00
County	Pittsylvania	Ground	Frozen	Temperature (°F)	39.00
Municipality	Chatham	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Rock Filter	Acceptable				
Rock Filter Outlet	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Slope Drain Pipe	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/20/2022 1:59 PM	Report #	33458
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation in good condi			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Rain, 39F) Rain Gauge= 0.0" 15142+66-15260+00 -EI began inspection at Rockcreek Rd. -RCEs are in good condition at all road crossings. -Perimeter CFS/P1 is in good condition. -Rock inlet/outlet is in good condition and functioning at 15165+57/15166+00 -P1 is in good condition at stream buffer. -Equipment bridge ECDs are in place and functioning at 15168+19. -Slope drain is functioning as intended at 15170+00. -Waterbars are in good condition throughout this section. -Drainage feature ECDs are in good condition and functioning at 15195+00. -Vegetation continues to fill in throughout this section.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/20/2022 1:59 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15142+66		Field Station#	15150+00	
Pic 1 Desc.	RCEs is in good condition at Rockcreek.		Pic 2 Desc.	Perimeter CFS is in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15160+00		Field Station#	15165+57	
Pic 3 Desc.	Perimeter P1 is in good condition.		Pic 4 Desc.	Rock filter inlet remains in good condition.	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15166+00		Field Station#	15168+00	
Pic 5 Desc.	Rock filter outlet remains in good condition.		Pic 6 Desc.	P1 is in good condition at stream buffer.	

AFE	124300139	Date/Time	1/20/2022 1:59 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15168+43	Field Station#	15168+43		
Pic 7 Desc.	Equipment bridge ECDs are in place and functioning.	Pic 8 Desc.	Stream buffer is in good condition.		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15170+00	Field Station#	15170+00		
Pic 9 Desc.	Slope drain is in good condition and functioning.	Pic 10 Desc.	Waterbars are functioning as intended.		
		<p style="text-align: center;">Insert image here</p>			
GPS Location	See photo	GPS Location			
Field Station#	15223+00	Field Station#			
Pic 11 Desc.	Permanent vegetation remains in good condition.	Pic 12 Desc.			







A/E	124300139	Date/Time	1/20/2022 1:59 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33398
Inspector	Ben Davenport			Date/Time	1/20/2022 11:30 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14694+77
State	VA	Inspection Area	Partial	Station End	14802+19
County	Franklin	Ground	Frozen	Temperature (°F)	38.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Temporary Diversion Berm	Acceptable				
Equipment Bridge	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Compost Filter Sock	Acceptable				
Sump Pit	Acceptable				
Waterbar	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

AFE	124300139	Date/Time	1/20/2022 11:30 AM	Report #	33398
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Light rain with frozen/snowy ground conditions during inspection -Performed SWPPP inspection on portion of MVP Spread I section -Covered territory between station# 14694+77 — 14802+19 (Jacks Creek Rd to MVP-FR-323) -Walked ROW making note of condition of ROW and environmental controls -Many ECDs unable to be inspected due to snow cover -Perimeter controls and ECD's were inspected; no issues identified -Inspection observed condition of RCEs and culverts in section; no issues identified -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified -Continue to monitor ROW for signs of erosion -No issues identified at the time of inspection					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/20/2022 11:30 AM	Report #	
Pictures					
					
36°59'17" N 79°42'34" W 90°E COURSE 72' GPS 01.20.2022 12:19:25 Accur +/-18.3 Ft ALT 949 Ft			36°59'17" N 79°42'32" W 120°SE COURSE 109' GPS 01.20.2022 12:20:33 1558-2498 Jacks Creek Rd, Union Hall, VA 24176, United States Accur +/-15.4 Ft ALT 950 Ft		
GPS Location	1		GPS Location	2	
Field Station#	14696+00		Field Station#	14700+80	
Pic 1 Desc.	Temporary diversion berm stabilized and vegetated; covered in snow.		Pic 2 Desc.	Equipment bridge and surrounding ECDs appear to be in place and functional at stream crossing and resource buffer; signage visible and intact.	
					
36°59'17" N 79°42'34" W 163°S COURSE 175' GPS 01.20.2022 12:19:18 Accur +/-39.0 Ft ALT 950 Ft			36°59'4" N 79°41'29" W 329°NW COURSE 307' GPS 01.20.2022 12:33:14 700-1080 Indian Cave Rd, Union Hall, VA 24176, United States Accur +/-151.7 Ft ALT 948 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14705+00		Field Station#	14749+89	
Pic 3 Desc.	Sump pit and CFS end treatment performing intended functions.		Pic 4 Desc.	Equipment bridge and surrounding ECDs appear to be in place and functional at stream crossing and resource buffer; signage visible and intact.	
					
36°59'2" N 79°41'25" W 355°N COURSE 348' GPS 01.20.2022 12:30:57 700-1080 Indian Cave Rd, Union Hall, VA 24176, United States Accur +/-103.5 Ft ALT 950 Ft			36°59'1" N 79°41'24" W 304°NW COURSE 0' GPS 01.20.2022 12:30:01 700-1080 Indian Cave Rd, Union Hall, VA 24176, United States Accur +/-48.6 Ft ALT 0 Ft		
GPS Location	5		GPS Location	6	
Field Station#	14755+00		Field Station#	14757+00	
Pic 5 Desc.	Water bars performing intended functions; ROW stabilized by snow cover.		Pic 6 Desc.	Perimeter SSF in good condition.	

A/E	124300139	Date/Time	1/20/2022 11:30 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/20/2022 11:30 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision	Report #	33461		
Inspector	Charles Head	Date/Time	1/20/2022 2:40 PM		
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14311+57
State	VA	Inspection Area	Full	Station End	14454+22
County	Franklin	Ground	Frozen	Temperature (°F)	37.00
Municipality	N/A	Weather	Light Rain	Rain Gauge (in)	0.00
			Rain Accumulation Time (days)	1.00	
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs		Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock		Acceptable			
Equipment Bridge		Acceptable			
Rock Construction Entrance		Acceptable			
Sensitive Resource Buffer		Acceptable			
Sensitive Resource Signage		Acceptable			
Silt Fence (Filter Fabric Fence)		Acceptable			
Silt Fence (Reinforce Filter Fence)		Acceptable			
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/20/2022 2:40 PM	Report #	33461
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. ROW still covered from winter storm event on 01/16/2022.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/20/2022 2:40 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14314+79	Field Station#	14333+50		
Pic 1 Desc.	Approximately 14314+79. Overview of stream crossing, equipment bridge and ECDs at stream S-GG4.		Pic 2 Desc.	Approximately 14333+50. Overview of road crossing and RCEs.	
GPS Location	0	GPS Location	0		
Field Station#	14367+00	Field Station#	14360+00		
Pic 3 Desc.	Approximately 14367+00. Overview of ROW.		Pic 4 Desc.	Approximately 14360+00. Overview of ROW.	
GPS Location	0	GPS Location	0		
Field Station#	14407+00	Field Station#	14451+00		
Pic 5 Desc.	Approximately 14407+00. Overview of ROW.		Pic 6 Desc.	Approximately 14451+00. Overview of ROW.	

A/E	124300139	Date/Time	1/20/2022 2:40 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/20/2022 2:40 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33443
Inspector	Ben Davenport			Date/Time	1/21/2022 12:53 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14802+19
State	VA	Inspection Area	Partial	Station End	14928+52
County	Franklin	Ground	Frozen	Temperature (°F)	28.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable				
Plunge Pool	Acceptable				
Compost Filter Sock	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Temporary Diversion Berm	Acceptable				
Sump Pit	Acceptable				
Waterbar End Treatment	Acceptable				
Slope Drain Pipe	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/21/2022 12:53 PM	Report #	33443
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
-Available for work -Received instruction from Lead EI for daily tasks -Replaced rain gauges in section -Checked rain gauges in covered area -Performed SWPPP inspection on portion of MVP Spread I project -Inspection covered area between station# 14802+19–14928+52 (MVP-FR-323 to Ramsey Memorial Rd) -Cloudy with frozen/snowy ground conditions during inspection -ROW stabilized by solid snow/ice cover -Inspection observed condition of perimeter controls and ECDs in section that were visible under snow; no issues observed -Inspection observed condition of equipment bridges and ECDs around stream crossings and resource buffers; no issues observed -No issues observed at the time of inspection -Rain Gauge Totals: +Indian Cave rain gauge: 0.10 inches recorded +Armstrong rain gauge: 0.10 inches recorded					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/21/2022 12:53 PM	Report #	
Pictures					
					
36°58'35" N 79°40'40" W 191°S COURSE 221° GPS Penhook, VA 24137, United States 01.21.2022 11:25:50 Accur +/-119.8 Ft ALT 953 Ft			36°58'36" N 79°40'41" W 271°W COURSE 225° GPS Union Hall, VA 24176, United States 01.21.2022 11:22:51 Accur +/-57.3 Ft ALT 951 Ft		
GPS Location	1		GPS Location	2	
Field Station#	14805+00		Field Station#	14802+25	
Pic 1 Desc.	Perimeter SSF in place and functional.		Pic 2 Desc.	P1 silt fence in good condition.	
					
36°58'23" N 79°40'6" W 310°NW COURSE 225° GPS 1120 Listening Hill Rd, Penhook, VA 24137, United States 01.21.2022 11:41:12 Accur +/-54.9 Ft ALT 974 Ft			36°58'20" N 79°39'56" W 331°NW COURSE 272° GPS 355 Listening Hill Rd, Penhook, VA 24137, United States 01.21.2022 11:36:05 Accur +/-34.9 Ft ALT 984 Ft		
GPS Location	3		GPS Location	4	
Field Station#	14830+00		Field Station#	14845+68	
Pic 3 Desc.	Plunge pool performing intended function.		Pic 4 Desc.	RCE in good condition.	
					
36°58'20" N 79°39'55" W 91°E COURSE 112° GPS 1120 Listening Hill Rd, Penhook, VA 24137, United States 01.21.2022 11:52:24 Accur +/-656.2 Ft ALT 988 Ft			36°58'20" N 79°39'54" W 80°E COURSE -1° GPS 1120 Listening Hill Rd, Penhook, VA 24137, United States 01.21.2022 11:52:38 Accur +/-16.2 Ft ALT 981 Ft		
GPS Location	5		GPS Location	6	
Field Station#	14848+00		Field Station#	14850+00	
Pic 5 Desc.	Sump pit and CFS end treatment performing intended functions.		Pic 6 Desc.	ROW stabilized in snow cover.	

A/E	124300139	Date/Time	1/21/2022 12:53 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/21/2022 12:53 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33494
Inspector	Justin Burch			Date/Time	1/21/2022 12:03 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	13958+31
State	VA	Inspection Area	Full	Station End	14062+17
County	Franklin	Ground	Frozen	Temperature (°F)	29.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Waterbar	Acceptable				
Waterbar End Treatment	Acceptable				
Cleanwater Diversion Berm	Acceptable				
Vegetative Stabilization (Temporary)	Acceptable				
Sump Pit	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/21/2022 12:03 PM	Report #	33494
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent Vegetation			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
<ul style="list-style-type: none"> The EI performed a SWPPP inspection from 13958+31 to 14062+17 (Foggy Ridge Road to Bonbrook Mill Road #2). No issues were submitted for the punch list due to inspected ECDs being in compliance at the time of inspection. The EI did not observe that the contractor has worked in the area since the last SWPPP inspection. Since the last SWPPP inspection the area received one precipitation event with totals of 0.10" at Bonbrook Mill Road #1. The ROW ground condition is frozen and snow/ice covered. At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion. At the time of inspection permanent vegetative stabilization was sufficiently established to inhibit erosion from 14011+00 to 14018+00. 					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/21/2022 12:03 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14027+00	Field Station#	13982+00		
Pic 1 Desc.	Perimeter CFS in acceptable condition	Pic 2 Desc.	Waterbar in acceptable condition		
GPS Location	0	GPS Location	0		
Field Station#	13982+00	Field Station#	13970+00		
Pic 3 Desc.	Waterbar end treatment in acceptable condition	Pic 4 Desc.	Clean water diversion berm and temporary vegetative stabilization in acceptable conditions		
GPS Location	0	GPS Location	0		
Field Station#	13967+00	Field Station#	14054+00		
Pic 5 Desc.	Sump and pit and CFS in acceptable conditions	Pic 6 Desc.	P1 silt fence in acceptable condition		

A/E	124300139	Date/Time	1/21/2022 12:03 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		







A/E	124300139	Date/Time	1/21/2022 12:03 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33495
Inspector	Ben Farmer			Date/Time	1/21/2022 12:13 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15260+00
State	VA	Inspection Area	Partial	Station End	15370+62
County	Pittsylvania	Ground	Frozen	Temperature (°F)	27.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.20
				Rain Accumulation Time (days)	0.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Silt Fence (Filter Fabric Fence)	Communication	P1 has been damaged and needs to			
Vegetative Stabilization (Temporary)	Acceptable				
Waterbar	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/21/2022 12:13 PM	Report #	33495
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Other	Acceptable	Permanent vegetation remains in go			
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
<div style="height: 100px;"></div>					
Comments (Reference above questions as appropriate.)					
SWPPP Inspection (Cloudy, 27F) Rain Gauge= 0.2" 15260+00-15370+62 -EI began inspection at Snowberry Rd. -RCEs are in good condition at all road crossings. -ROW remains stabilized -MVP-PI-332 is in good condition with controls in place. -Waterbars are functioning as intended. -Resource buffers are in good condition. -Equipment bridge ECDs are in place and functioning. -P1 is in good condition at all stream and wetland buffers. -P1 is damaged and needs to be replaced along drainage at 15300+00. -CWD is in good condition and functioning at 15299+00.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/21/2022 12:13 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15370+62	Field Station#	15370+00		
Pic 1 Desc.	RCEs are in good condition at all road crossings.	Pic 2 Desc.	ROW remains stabilized.		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15350+00	Field Station#	15349+00		
Pic 3 Desc.	MVP-PI-332 remains in good condition with controls in place.	Pic 4 Desc.	Waterbars are functioning as intended.		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	15348+50	Field Station#	15348+21		
Pic 5 Desc.	P1 is in good condition at all stream and wetland buffers.	Pic 6 Desc.	Resource buffers remain in good condition.		

AFE 124300139		Date/Time 1/21/2022 12:13 PM		Report #	
Pictures					
GPS Location	See photo		GPS Location	See photo	
Field Station#	15348+00		Field Station#	15300+00	
Pic 7 Desc.	Equipment bridge ECDs are in place and functioning		Pic 8 Desc.	P1 has been damaged and needs to be replaced.	
GPS Location	See photo		GPS Location	See photo	
Field Station#	15299+00		Field Station#	15298+00	
Pic 9 Desc.	CWD is in good condition and functioning.		Pic 10 Desc.	Stockpiles remain stabilized.	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300139	Date/Time	1/21/2022 12:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33489
Inspector	Charles Head			Date/Time	1/21/2022 10:59 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	14454+22
State	VA	Inspection Area	Full	Station End	14546+75
County	Franklin	Ground	Frozen	Temperature (°F)	23.00
Municipality	N/A	Weather	Cloudy	Rain Gauge (in)	0.10
				Rain Accumulation Time (days)	1.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action		Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable				
Compost Filter Sock	Acceptable				
Equipment Bridge	Acceptable				
Rock Construction Entrance	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Silt Fence (Filter Fabric Fence)	Acceptable				
Silt Fence (Reinforce Filter Fence)	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/21/2022 10:59 AM	Report #	33489
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection. Precipitation from 01/16/2022 winter weather event still covers the ROW.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300139	Date/Time	1/21/2022 10:59 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14546+33	Field Station#	14541+50		
Pic 1 Desc.	Approximately 14546+33. Overview of stream crossing, equipment bridge and ECDs at stream S-G17.		Pic 2 Desc.	Approximately 14541+50. Overview of ROW.	
GPS Location	0	GPS Location	0		
Field Station#	14528+00	Field Station#	14519+00		
Pic 3 Desc.	Approximately 14528+00. Overview of ROW.		Pic 4 Desc.	Approximately 14519+00. Overview of ROW.	
GPS Location	0	GPS Location	0		
Field Station#	14456+50	Field Station#	14524+00		
Pic 5 Desc.	Approximately 14456+50. Overview of ROW.		Pic 6 Desc.	Approximately 14524+00. Overview of road crossing and RCEs.	

A/E	124300139	Date/Time	1/21/2022 10:59 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/21/2022 10:59 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	H-600 Pipeline Spread I	AFE	124300139	Spread	H-600 Pipeline Spread I
Contractor	Precision			Report #	33441
Inspector	John White			Date/Time	1/21/2022 12:52 PM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	15647+03
State	VA	Inspection Area	Full	Station End	15772+27
County	Pittsylvania	Ground	Frozen	Temperature (°F)	30.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.40
				Rain Accumulation Time (days)	4.00
1. Are the approved (stamped) E&S Plan and PCSM Plan present on site?					Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)					No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)					Yes
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
Compost Filter Sock	Acceptable				
Cleanwater Diversion Pipe	Acceptable				
Equipment Bridge	Acceptable				
Housekeeping	Acceptable				
Rock Filter Outlet	Acceptable				
Sediment Filter Log	Acceptable				
Sensitive Resource Buffer	Acceptable				
Sensitive Resource Signage	Acceptable				
Sump Pit	Acceptable				
5. Site Conditions					
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.					No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?					Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)					No

A/E	124300139	Date/Time	1/21/2022 12:52 PM	Report #	33441
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection. Checked rain gauges, Anderson Mill #2=.4", Mill Creek =.5", Transco =.5".					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

AFE	124300139	Date/Time	1/21/2022 12:52 PM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15654+00	Field Station#	15658+43		
Pic 1 Desc.	Observing temporary stabilization, sump and end treatment	Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15652+00	Field Station#	15678+57		
Pic 3 Desc.	Observing temporary stabilization, water bar, sump and end treatment	Pic 4 Desc.	Observing access road and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15679+00	Field Station#	15695+00		
Pic 5 Desc.	Observing temporary stabilization, CWD outlet and ECD's	Pic 6 Desc.	Observing water bar and CFS checks		

A/E	124300139	Date/Time	1/21/2022 12:52 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		

A/E	124300139	Date/Time	1/21/2022 12:52 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Insert image here			Insert image here		
Insert image here			Insert image here		



Visual Site Inspection Report

Project Name	Transco Interconnect Station	AFE	124300113	Spread	Transco Interconnect Sta
Contractor	Kanahwa			Report #	33385
Inspector	John White			Date/Time	1/19/2022 11:50 AM
Permit #	TBD	Inspection Type	VA SWPP	Station Begin	00+00
State	VA	Inspection Area	Full	Station End	00+00
County	Pittsylvania	Ground	Frozen	Temperature (°F)	41.00
Municipality	Chatham	Weather	Cloudy	Rain Gauge (in)	0.00
				Rain Accumulation Time (days)	6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Sediment Basin	Acceptable			
Housekeeping	Acceptable			
Rock Filter Outlet	Communication	Contractor is working repairs (3rd p		
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

A/E	124300113	Date/Time	1/19/2022 11:50 AM	Report #	33385
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)					
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired	
7. Identify all remedial measures that have been taken since the previous inspection was conducted.					
Comments (Reference above questions as appropriate.)					
Performed SWPPP Inspection on the Transco Facility and Lay down yard. There was one issue identified and added to the punch list. (The issue was 3rd party damage) The Contractor is working on repairing the identified issue. Other than that there were no issues to report at the time of Inspection.					
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.					

A/E	124300113	Date/Time	1/19/2022 11:50 AM	Report #	
Pictures					
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 1 Desc.			Pic 2 Desc.		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 3 Desc.			Pic 4 Desc.		
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 5 Desc.			Pic 6 Desc.		

A/E	124300113	Date/Time	1/19/2022 11:50 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Insert image here			Insert image here		

A/E	124300113	Date/Time	1/19/2022 11:50 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			