



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 40994	
<b>Inspector</b> Eric Hanlon		<b>Date/Time</b> 8/15/2022 6:54 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 11899+89	
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b> 12005+00	
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b> 65.00	
<b>Municipality</b> N/A	<b>Weather</b> Heavy Rain	<b>Rain Gauge (in)</b> 0.50	
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Broad-Based Dip	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 6:54 AM	<b>Report #</b> 40994
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Level Spreader	Acceptable			
Other	Acceptable			

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)

Completed on a VA SWPPP inspection from ST# 11899+89 (MP 225.37) to ST# 12005+00 (MP 227.37).  
 No Compliance issues noted:  
 Observance:  
 Active rain event at the time of inspection.  
 Perimeter controls in place but are very aged.  
 Permanent water bars (other) and level spreader in place. Some are of an earlier design.  
 ROW has temporary and permanent stabilization.  
 No areas with open ditch.  
 All other ECDs and BMPs functional at time of inspection.  
 AR-266.03, 266 Catawba road crossing RCEs are maintained in acceptable condition.  
 The ROW is wet and in stable condition.  
 No sensitive resources have been impacted.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	8/15/2022 6:54 AM	<b>Report #</b>	
------------	-----------	------------------	-------------------	-----------------	--

## Pictures




<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	11956+00	<b>Field Station#</b>	11914+00
<b>Pic 1 Desc.</b>	Picture showing condition of row	<b>Pic 2 Desc.</b>	Permanent water bars and level spreader



<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	11910+00	<b>Field Station#</b>	11899+89
<b>Pic 3 Desc.</b>	Stabilization in place	<b>Pic 4 Desc.</b>	RCE functional



<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	11978+54	<b>Field Station#</b>	11979+00
<b>Pic 5 Desc.</b>	Rain gauge	<b>Pic 6 Desc.</b>	Picture showing condition of row

AFE 124300137		Date/Time 8/15/2022 6:54 AM		Report #	
<b>Pictures</b>					
				Insert image here	
<b>GPS Location</b>	See photo	<b>GPS Location</b>			
<b>Field Station#</b>	11995+00	<b>Field Station#</b>			
<b>Pic 7 Desc.</b>	Stabilization in place	<b>Pic 8 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>			
Insert image here		Insert image here			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>			

<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 6:54 AM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41005	
<b>Inspector</b> Joe Sweeden		<b>Date/Time</b> 8/15/2022 11:40 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b>	12005+00
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b>	67.00
<b>Municipality</b> N/A	<b>Weather</b> Light Rain	<b>Rain Gauge (in)</b>	1.10
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			
Broad-Based Dip	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 11:40 AM	<b>Report #</b> 41005
----------------------	-------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)

Performed VA SWPP at Yard 29.  
 Observances:  
 The Yard received 1.10" of precipitation in the last 24 hours.  
 An Environmental crew was doing routine maintenance in the Yard at time of inspection.  
 Equipment in the yard was free of leaks.  
 The perimeter compost sock was in place and functioning as designed.  
 The rock road approach was clean, no mud or other debris on road.  
 The yard was free of debris. No trash was seen.  
 Trash receptacles in the Yard were clearly labeled.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	8/15/2022 11:40 AM	<b>Report #</b>	
------------	-----------	------------------	--------------------	-----------------	--


## Pictures



<b>GPS Location</b>	See photo	<b>GPS Location</b>	see photo
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 1 Desc.</b>	Broad base dip	<b>Pic 2 Desc.</b>	Equipment



<b>GPS Location</b>	see photo	<b>GPS Location</b>	see photo
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 3 Desc.</b>	Perimeter controls	<b>Pic 4 Desc.</b>	Compost sock



<b>GPS Location</b>	see photo	<b>GPS Location</b>	see photo
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 5 Desc.</b>	RCE	<b>Pic 6 Desc.</b>	Environmental controls



<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 11:40 AM	<b>Report #</b>
----------------------	-------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 11:40 AM	<b>Report #</b>
----------------------	-------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>	<b>GPS Location</b>
<b>Field Station#</b>	<b>Field Station#</b>
<b>Pic 13 Desc.</b>	<b>Pic 14 Desc.</b>

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>	<b>GPS Location</b>
<b>Field Station#</b>	<b>Field Station#</b>
<b>Pic 15 Desc.</b>	<b>Pic 16 Desc.</b>

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>	<b>GPS Location</b>
<b>Field Station#</b>	<b>Field Station#</b>
<b>Pic 17 Desc.</b>	<b>Pic 18 Desc.</b>



# Visual Site Inspection Report

<b>Project Name</b>		H-600 Pipeline Spread G		<b>AFE</b>	124300137	<b>Spread</b>	H-600 Pipeline Spread G
<b>Contractor</b>		Precision				<b>Report #</b>	41008
<b>Inspector</b>		David Schoolcraft				<b>Date/Time</b>	8/15/2022 12:14 PM
<b>Permit #</b>	TBD	<b>Inspection Type</b>	VA SWPP		<b>Station Begin</b>	12005+00	
<b>State</b>	VA	<b>Inspection Area</b>	Full		<b>Station End</b>	12005+00	
<b>County</b>	Giles	<b>Ground</b>	Wet		<b>Temperature (°F)</b>	67.00	
<b>Municipality</b>	N/A	<b>Weather</b>	Heavy Rain		<b>Rain Gauge (in)</b>	1.10	
						<b>Rain Accumulation Time (days)</b>	1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Housekeeping	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b>	124300137	<b>Date/Time</b>	8/15/2022 12:14 PM	<b>Report #</b>	41008
------------	-----------	------------------	--------------------	-----------------	-------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)

Completed a VA SWPPP at LY 026.  
 The perimeter controls CFS functioning properly.  
 RCE was clean and functioning  
 The yard was free of debris. Used oils were stored properly in secondary containment. The generator and air compressor were in secondary containment that was maintained properly.  
 All other ECDs were clean of sediment and functioning properly.  
 Trash bns clearly identified and in good condition  
 Housekeeping was in good condition.  
 Construction of a neighboring company ongoing  
 Giles county is currently installing stormwater system and any damaged ECDs will be replaced upon completion off project.  
 inspection was conducted during ongoing rain event

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 8/15/2022 12:14 PM		Report #			
Pictures							
<p>Date &amp; Time Mon, Aug 15, 2022 11:07:21 EDT Position: +38.9131832° / -80.52888° (-13.31) Altitude: 1793' (-11.17) Datum: WGS-84 Azimuth Bearing: 338° NADN 3027mils True (-10°) Elevation Angle: -13.0° Horizon Angle: -01.3° Zoom: 1.0X YZ6</p> 		<p>Date &amp; Time Mon, Aug 15, 2022 11:07:25 EDT Position: +38.9131832° / -80.52888° (-13.31) Altitude: 1793' (-11.17) Datum: WGS-84 Azimuth Bearing: 338° NADN 3027mils True (-10°) Elevation Angle: -13.0° Horizon Angle: -00.5° Zoom: 1.0X YZ6</p> 		<p>GPS Location See Photo</p>		<p>GPS Location See Photo</p>	
<p>Field Station# 12005+00</p>		<p>Field Station# 12005+00</p>		<p>Pic 1 Desc. RCE</p>		<p>Pic 2 Desc. Fuel containment</p>	
<p>Date &amp; Time Mon, Aug 15, 2022 11:07:46 EDT Position: +38.9131832° / -80.52888° (-13.31) Altitude: 1800' (-11.17) Datum: WGS-84 Azimuth Bearing: 318° NADN 3026mils True (-10°) Elevation Angle: -14.3° Horizon Angle: -01.6° Zoom: 1.0X YZ6</p> 		<p>Date &amp; Time Mon, Aug 15, 2022 11:08:39 EDT Position: +38.9131832° / -80.52888° (-13.31) Altitude: 1793' (-11.17) Datum: WGS-84 Azimuth Bearing: 327° NADN 3071mils True (-10°) Elevation Angle: -10.3° Horizon Angle: -00.5° Zoom: 1.0X YZ6</p> 		<p>GPS Location See Photo</p>		<p>GPS Location See Photo</p>	
<p>Field Station# 12005+00</p>		<p>Field Station# 12005+00</p>		<p>Pic 3 Desc. Secondary containment</p>		<p>Pic 4 Desc. Trash bins and housekeeping</p>	
<p>Date &amp; Time Mon, Aug 15, 2022 11:11:47 EDT Position: +38.9131832° / -80.52888° (-13.31) Altitude: 1793' (-11.17) Datum: WGS-84 Azimuth Bearing: 363° NADN 1173mils True (-10°) Elevation Angle: -5.7° Horizon Angle: -03.3° Zoom: 1.0X YZ6</p> 		<p>Date &amp; Time Mon, Aug 15, 2022 11:16:38 EDT Position: +38.9131832° / -80.52888° (-13.31) Altitude: 1793' (-11.17) Datum: WGS-84 Azimuth Bearing: 283° NADN 3026mils True (-10°) Elevation Angle: -10.0° Horizon Angle: -01.3° Zoom: 1.0X YZ6</p> 		<p>GPS Location See Photo</p>		<p>GPS Location See Photo</p>	
<p>Field Station# 12005+00</p>		<p>Field Station# 12005+00</p>		<p>Pic 5 Desc. CFS perimeter control</p>		<p>Pic 6 Desc. CFS and construction my Giles county</p>	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 12:14 PM	<b>Report #</b>
----------------------	-------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 12:14 PM	<b>Report #</b>
----------------------	-------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41009	
<b>Inspector</b> David Schoolcraft		<b>Date/Time</b> 8/15/2022 12:17 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b>	11788+52
<b>County</b> Montgomery	<b>Ground</b> Wet	<b>Temperature (°F)</b>	67.00
<b>Municipality</b> N/A	<b>Weather</b> Heavy Rain	<b>Rain Gauge (in)</b>	1.10
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |



<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 12:17 PM	<b>Report #</b> 41009
----------------------	-------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired




**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Met with environmental team  
 Performed Va SWPPP inspection from MP 221.02 (11670+00) to MP 223.27 (11788+52)  
 This section of ROW has no current construction.  
 No deficiencies found.  
 All perimeter controls, ECDs and BMPs functional at time of inspection. Stream buffers and controls in place at the time of inspection.  
 No sensitive resources have been impacted  
 Inspection was conducted during ongoing rain event

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 8/15/2022 12:17 PM		Report #			
Pictures							
 <p>Date &amp; Time: Mon, Aug 15, 2022, 05:43:27 EDT Position: +38.928983° / -98.328114° (-98.370) Altitude: 2320' (708.30) Datum: WGS-84 Azimuth/Bearing: 132° S08W 3922mils True (+13°) Elevation Angle: -13.5° Horizon Angle: -03.3° Zoom: 0.5X 11671</p>		 <p>Date &amp; Time: Mon, Aug 15, 2022, 05:45:58 EDT Position: +38.928983° / -98.328114° (-98.370) Altitude: 2320' (708.30) Datum: WGS-84 Azimuth/Bearing: 132° S08W 3922mils True (+13°) Elevation Angle: -13.5° Horizon Angle: -03.3° Zoom: 0.5X 11678</p>		<p><b>GPS Location</b> See Photo</p> <p><b>Field Station#</b> 11671+00</p> <p><b>Pic 1 Desc.</b> Temporary vegetation</p>		<p><b>GPS Location</b> See Photo</p> <p><b>Field Station#</b> 11678+00</p> <p><b>Pic 2 Desc.</b> Slope Drain Inlet</p>	
 <p>Date &amp; Time: Mon, Aug 15, 2022, 08:52:41 EDT Position: +38.928983° / -98.328114° (-98.370) Altitude: 2320' (708.30) Datum: WGS-84 Azimuth/Bearing: 132° S08W 3922mils True (+13°) Elevation Angle: -13.5° Horizon Angle: -03.3° Zoom: 0.5X 11687 S mn 21</p>		 <p>Date &amp; Time: Mon, Aug 15, 2022, 09:51:03 EDT Position: +38.928983° / -98.328114° (-98.370) Altitude: 2320' (708.30) Datum: WGS-84 Azimuth/Bearing: 132° S08W 3922mils True (+13°) Elevation Angle: -13.5° Horizon Angle: -03.3° Zoom: 0.5X 11674 S MN22</p>		<p><b>GPS Location</b> See Photo</p> <p><b>Field Station#</b> 11587+00</p> <p><b>Pic 3 Desc.</b> S-MN21</p>		<p><b>GPS Location</b> See Photo</p> <p><b>Field Station#</b> 11074+10</p> <p><b>Pic 4 Desc.</b> S-MN22</p>	
 <p>Date &amp; Time: Mon, Aug 15, 2022, 05:43:27 EDT Position: +38.928983° / -98.328114° (-98.370) Altitude: 2320' (708.30) Datum: WGS-84 Azimuth/Bearing: 132° S08W 3922mils True (+13°) Elevation Angle: -13.5° Horizon Angle: -03.3° Zoom: 0.5X 11705</p>		 <p>Date &amp; Time: Mon, Aug 15, 2022, 05:43:27 EDT Position: +38.928983° / -98.328114° (-98.370) Altitude: 2320' (708.30) Datum: WGS-84 Azimuth/Bearing: 071° N71E 1242mils True (+2°) Elevation Angle: -01.5° Horizon Angle: -00.7° Zoom: 0.5X 11740-55 S-EF65</p>		<p><b>GPS Location</b> See Photo</p> <p><b>Field Station#</b> 11705+00</p> <p><b>Pic 5 Desc.</b> Section of ROW showing conditions and controls</p>		<p><b>GPS Location</b> See Photo</p> <p><b>Field Station#</b> 11740+55</p> <p><b>Pic 6 Desc.</b> S-EF65</p>	

AFE	124300137	Date/Time	8/15/2022 12:17 PM	Report #	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Mon, Aug 15, 2022, 09:25:49 EDT Position: +037.236811° / -080.374368° (±19.1ft) Altitude: 2089ft (±8.4ft) Datum: WGS-84 Azimuth/Bearing: 073° N73E 1327mils True (±12°) Elevation Angle: +12.3° Horizon Angle: -01.5° Zoom: 1.0X 11745+75</small></p>				 <p><small>Date &amp; Time: Mon, Aug 15, 2022, 09:26:15 EDT Position: +037.236821° / -080.374378° (±24.0ft) Altitude: 2072ft (±8.9ft) Datum: WGS-84 Azimuth/Bearing: 073° N73E 1298mils True (±12°) Elevation Angle: +12.3° Horizon Angle: -02.5° Zoom: 1.0X 11747+00</small></p>	
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11745+75	<b>Field Station#</b>	11747+00		
<b>Pic 7 Desc.</b>	Waterbars	<b>Pic 8 Desc.</b>	Perimeter Controls		
 <p><small>Date &amp; Time: Mon, Aug 15, 2022, 09:33:07 EDT Position: +037.236831° / -080.374381° (±19.1ft) Altitude: 2097ft (±8.4ft) Datum: WGS-84 Azimuth/Bearing: 065° N65E 1080mils True (±12°) Elevation Angle: +02.5° Horizon Angle: -03.6° Zoom: 1.0X 11757+00</small></p>				 <p><small>Date &amp; Time: Mon, Aug 15, 2022, 09:35:48 EDT Position: +037.236850° / -080.387721° (±19.1ft) Altitude: 1927ft (±11.7ft) Datum: WGS-84 Azimuth/Bearing: 065° N65E 1156mils True (±12°) Elevation Angle: +05.3° Horizon Angle: -00.6° Zoom: 1.0X 11757+44 s-1J52 W-1J46</small></p>	
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11757+00	<b>Field Station#</b>	11767+44		
<b>Pic 9 Desc.</b>	Section of Row showing conditions and controls	<b>Pic 10 Desc.</b>	RCE S-IJ52 W-IJ46		
 <p><small>Date &amp; Time: Mon, Aug 15, 2022, 10:05:42 EDT Position: +037.236854° / -080.383739° (±20.0ft) Altitude: 2114ft (±4.1ft) Datum: WGS-84 Azimuth/Bearing: 201° S21W 3573mils True (±13°) Elevation Angle: -13.4° Horizon Angle: -01.6° Zoom: 1.0X 11777+00</small></p>				 <p><small>Date &amp; Time: Mon, Aug 15, 2022, 10:05:59 EDT Position: +037.236857° / -080.383839° (±19.1ft) Altitude: 2134ft (±3.2ft) Datum: WGS-84 Azimuth/Bearing: 339° N32W 6009mils True (±12°) Elevation Angle: -05.4° Horizon Angle: -00.8° Zoom: 1.0X 11788+00</small></p>	
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	11777+00	<b>Field Station#</b>	11788+00		
<b>Pic 11 Desc.</b>	Clean water diversion pipe	<b>Pic 12 Desc.</b>	RCE		

<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 12:17 PM	<b>Report #</b>
----------------------	-------------------------------------	-----------------

<b>Pictures</b>			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41018	
<b>Inspector</b> Daniel Fortune		<b>Date/Time</b> 8/15/2022 4:04 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	12005+00
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b>	63.00
<b>Municipality</b> N/A	<b>Weather</b> Light Rain	<b>Rain Gauge (in)</b>	0.40
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 4:04 PM	<b>Report #</b> 41018
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)

Comments (Reference above questions as appropriate.)  
 Completed a SWPPP inspection for LY 028 (12005+00) There was ongoing light rain during this inspection. No erosion issues at this time.  
 No Deficiencies recorded for repairs today.  
 Waste management control bin on site with no trash or debris in the yard. Perimeter controls in place and functional as intended. The yard area received approximately 0."of precipitation over the last 24 hours. This yard has porta- Jon's stored throughout. No Trash or debris around. The Transit busses remain parked with no leaks visible at the time of inspection. Entry to the yard has functional CFS installed. No Issues At this time.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	8/15/2022 4:04 PM	<b>Report #</b>	
------------	-----------	------------------	-------------------	-----------------	--

## Pictures



<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 1 Desc.</b>	Perimeter CFS and RCE condition.	<b>Pic 2 Desc.</b>	Haul trucks, Transit busses, and utility trailer found without leaks at time of inspection.



<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 3 Desc.</b>	Truck parking and storage area. No issues at the time of inspection	<b>Pic 4 Desc.</b>	RCE and Trash receptacle area.



<b>GPS Location</b>	See photo	<b>GPS Location</b>	
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	
<b>Pic 5 Desc.</b>	RCE to LY 28. Perimeter CFS and ECDs found functional.	<b>Pic 6 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 4:04 PM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	



<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 4:04 PM	<b>Report #</b>
----------------------	------------------------------------	-----------------

<b>Pictures</b>
-----------------

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41021	
<b>Inspector</b> Jared Saunders		<b>Date/Time</b> 8/15/2022 4:46 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 11788+52	
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b> 11899+89	
<b>County</b> Montgomery	<b>Ground</b> Wet	<b>Temperature (°F)</b> 75.00	
<b>Municipality</b> N/A	<b>Weather</b> Heavy Rain	<b>Rain Gauge (in)</b> 1.10	
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 4:46 PM	<b>Report #</b> 41021
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Level Spreader	Acceptable			
Other	Acceptable			

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from ST# 11788+52 (Mount Tabor Road) to ST# 11899+89 (AR 266.03) MP 223.27 to MP 225.37.  
 No compliance issues found.  
 Environmental crew was observed working on AR 266.03 conducting vegetative maintenance.  
 Active construction site; additional deficiencies may be identified by other EIs.  
 This section of ROW has undergone permanent restoration. Permanent waterbars (section 6 other) with level spreaders in place where designated on E&S sheets. Perimeter controls have been removed due to final restoration vegetation growth. The only remaining ECDs exist around the Mount tabor RCE and along AR 266.03.  
 AR 266.03 and Mount Tabor road crossing RCEs are maintained in acceptable condition.  
 No sensitive resources have been impacted.  
 Checked rain gauge at Mount Tabor Road. Gauge read 1.1 inches.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/15/2022 4:46 PM	Report #		
<b>Pictures</b>						
<p>Date &amp; Time: Mon, Aug 15, 2022, 09:26:46 EDT  Position: +39° 29' 22.1" / -80° 34' 58.0" (+19.31)  Altitude: 2139ft (+650ft)  Datum: WGS-84  Azimuth/Bearing: 080° N80E 1022mils True (+18°)  Elevation Angle: -03.3°  Horizon Angle: +00.8°  Zoom: 1.0X  Tabor</p>				<p>Date &amp; Time: Mon, Aug 15, 2022, 09:26:46 EDT  Position: +39° 29' 53.8" / -80° 34' 57.7" (+1189.20)  Altitude: 2243ft (+683.20)  Datum: WGS-84  Azimuth/Bearing: 330° S33W 4415mils True (+18°)  Elevation Angle: -01.1°  Horizon Angle: +05.7°  Zoom: 1.0X  11889+00</p>		
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.		
<b>Field Station#</b>	11790+00		<b>Field Station#</b>	11889+00		
<b>Pic 1 Desc.</b>	Rain gauges at Mount Tabor reads 1.1 inches.		<b>Pic 2 Desc.</b>	ROW permanently restored.		
<p>Date &amp; Time: Mon, Aug 15, 2022, 09:35:48 EDT  Position: +037° 28' 58.7" / -80° 34' 22.7" (+15.30)  Altitude: 2179ft (+661.10)  Datum: WGS-84  Azimuth/Bearing: 354° N54W 6329mils True (+18°)  Elevation Angle: -13.2°  Horizon Angle: +00.3°  Zoom: 1.0X  11864+00</p>			<p>Date &amp; Time: Mon, Aug 15, 2022, 09:35:48 EDT  Position: +037° 28' 58.7" / -80° 34' 58.8" (+18.30)  Altitude: 2183ft (+663.10)  Datum: WGS-84  Azimuth/Bearing: 335° N25W 5793mils True (+17°)  Elevation Angle: -14.8°  Horizon Angle: +00.1°  Zoom: 1.0X  11853+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.		
<b>Field Station#</b>	11864+00		<b>Field Station#</b>	11853+00		
<b>Pic 3 Desc.</b>	Sensitive resource P-KL2.		<b>Pic 4 Desc.</b>	Permanent waterbars with level spreaders in place.		
<p>Date &amp; Time: Mon, Aug 15, 2022, 10:01:58 EDT  Position: +39° 29' 19.7" / -80° 34' 59.9" (+18.30)  Altitude: 2230ft (+677.00)  Datum: WGS-84  Azimuth/Bearing: 341° N39W 6045mils True (+18°)  Elevation Angle: -04.5°  Horizon Angle: -01.1°  Zoom: 1.0X  11819+00</p>			<p>Date &amp; Time: Mon, Aug 15, 2022, 10:01:58 EDT  Position: +39° 29' 13.1" / -80° 34' 07.2" (+35.50)  Altitude: 2134ft (+647.70)  Datum: WGS-84  Azimuth/Bearing: 322° N38W 5724mils True (+13°)  Elevation Angle: -12.5°  Horizon Angle: +00.0°  Zoom: 1.0X  11789+00</p>			
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.		
<b>Field Station#</b>	11819+00		<b>Field Station#</b>	11789+00		
<b>Pic 5 Desc.</b>	ROW permanently restored.		<b>Pic 6 Desc.</b>	RCE in place at Mount Tabor Road crossing.		

<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 4:46 PM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 4:46 PM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41007	
<b>Inspector</b> Rob Robertson		<b>Date/Time</b> 8/15/2022 12:10 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	11670+00
<b>County</b> Montgomery	<b>Ground</b> Wet	<b>Temperature (°F)</b>	65.00
<b>Municipality</b> N/A	<b>Weather</b> Light Rain	<b>Rain Gauge (in)</b>	1.60
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 12:10 PM	<b>Report #</b> 41007
----------------------	-------------------------------------	-----------------------

6. **PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Completed a regular scheduled VADEQ SWPPP inspection on JNF and private property at Brush Mountain. This area of ROW received approximately 1.6" of rainfall in the past 24 hours. The ROW was found in stable condition. No issues from runoff or ECD maintenance needs were discovered. There is no impact occurring at resource crossings. Slope breakers are functional. Worn CFS will be replaced before any ground disturbance occurs. Access points are in good condition. There were no environmental concerns identified.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.



AFE	124300137	Date/Time	8/15/2022 12:10 PM	Report #	
Pictures					
<p>Date &amp; Time: Mon, Aug 15, 2022, 05:39:49 EDT  Position: +037.3024007° / -080.394673° (+30.0m)  Altitude: 575m (+12.0m)  Datum: WGS-84  Azimuth/Bearing: 112° 58'55" 3022mils Magnetic (+12°)  Elevation Angle: -83.5°  Horizon Angle: -05.2°  Zoom: 1.0X  11668+00</p>			<p>Date &amp; Time: Mon, Aug 15, 2022, 05:37:21 EDT  Position: +037.3024007° / -080.397328° (+10.0m)  Altitude: 775m (+12.0m)  Datum: WGS-84  Azimuth/Bearing: 305° 00'00" 3307mils Magnetic (+12°)  Elevation Angle: -13.0°  Horizon Angle: +00.1°  Zoom: 1.0X  11658+00</p>		
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11668+75	<b>Field Station#</b>	11658+00		
<b>Pic 1 Desc.</b>	Top of Brush Mountain is stable.		<b>Pic 2 Desc.</b>	ROW stable with ECDs in place.	
<p>Date &amp; Time: Mon, Aug 15, 2022, 10:10:57 EDT  Position: +037.306212° / -080.397335° (+110.0m)  Altitude: 707m (+24.0m)  Datum: WGS-84  Azimuth/Bearing: 355° 00'00" 3811mils Magnetic (+12°)  Elevation Angle: -24.3°  Horizon Angle: +01.5°  Zoom: 1.0X  11647+00</p>			<p>Date &amp; Time: Mon, Aug 15, 2022, 10:19:00 EDT  Position: +037.307265° / -080.397311° (+2001.0m)  Altitude: 459m (+24.0m)  Datum: WGS-84  Azimuth/Bearing: 605° 00'00" 3936mils Magnetic (+12°)  Elevation Angle: -16.1°  Horizon Angle: -02.5°  Zoom: 1.0X  11643+00</p>		
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11647+00	<b>Field Station#</b>	11643+00		
<b>Pic 3 Desc.</b>	ROW stable with ECDs in place.		<b>Pic 4 Desc.</b>	No erosion of any type.	
<p>Date &amp; Time: Mon, Aug 15, 2022, 10:35:53 EDT  Position: +037.313922° / -080.392521° (+5.0m)  Altitude: 580m (+4.0m)  Datum: WGS-84  Azimuth/Bearing: 283° 00'00" 3031mils Magnetic (+12°)  Elevation Angle: -14.3°  Horizon Angle: -02.5°  Zoom: 1.0X  11626+04, S-HH18</p>			<p>Date &amp; Time: Mon, Aug 15, 2022, 10:37:55 EDT  Position: +037.314211° / -080.398570° (+5.0m)  Altitude: 575m (+8.0m)  Datum: WGS-84  Azimuth/Bearing: 047° 00'00" 0836mils Magnetic (+14°)  Elevation Angle: -20.6°  Horizon Angle: -04.0°  Zoom: 1.0X  11625+00</p>		
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11626+04	<b>Field Station#</b>	11625+00		
<b>Pic 5 Desc.</b>	No impact at the S-HH18 crossing.		<b>Pic 6 Desc.</b>	ECDs in place and functional.	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/15/2022 12:10 PM	<b>Report #</b>
----------------------	-------------------------------------	-----------------

**Pictures**



<b>GPS Location</b>	On photo
<b>Field Station#</b>	11614+75
<b>Pic 7 Desc.</b>	Slope breakers, sumps and end treatments are functioning.

<b>GPS Location</b>	On photo
<b>Field Station#</b>	11614+20
<b>Pic 8 Desc.</b>	No impact occurring at the S-RR14 crossing.



<b>GPS Location</b>	On photo
<b>Field Station#</b>	11613+00
<b>Pic 9 Desc.</b>	ROW stable on private property.

<b>GPS Location</b>	On photo
<b>Field Station#</b>	11607+81
<b>Pic 10 Desc.</b>	The S-006 crossing is stable with no impact to stream.



Insert image here

<b>GPS Location</b>	On photo
<b>Field Station#</b>	11601+00
<b>Pic 11 Desc.</b>	ROW stable with ECDs in place.

<b>GPS Location</b>	
<b>Field Station#</b>	
<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/15/2022 12:10 PM	<b>Report #</b>	
------------	-----------	------------------	--------------------	-----------------	--

<b>Pictures</b>					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41037	
<b>Inspector</b> Chris Burns		<b>Date/Time</b> 8/16/2022 7:28 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	12005+00
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b>	64.00
<b>Municipality</b> N/A	<b>Weather</b> Light Rain	<b>Rain Gauge (in)</b>	0.20
			<b>Rain Accumulation Time (days)</b> 2.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waste Management	Acceptable			
Flume Pipe	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 7:28 AM	<b>Report #</b> 41037
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.


**Comments** (Reference above questions as appropriate.)

See photos for GPS coordinates.  
 Met with environmental staff.  
 Performed SWPPP inspection of LDY 29.  
 All perimeter controls, ECDs and BMPs functional at time of inspection.  
 Vegetation or stabilization sufficient.  
 No impact to sensitive resources observed.  
 No visual leaks from staged equipment.  
 Observed recent ground disturbance, by others, impacting access road.


**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	8/16/2022 7:28 AM	<b>Report #</b>	
------------	-----------	------------------	-------------------	-----------------	--

## Pictures



<b>GPS Location</b>	1	<b>GPS Location</b>	2
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 1 Desc.</b>	Impact to access road by others.	<b>Pic 2 Desc.</b>	Overview of LDY 29.



<b>GPS Location</b>	3	<b>GPS Location</b>	4
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 3 Desc.</b>	Upper auxiliary to LDY 29.	<b>Pic 4 Desc.</b>	Overview main part of LDY 29.



<b>GPS Location</b>	5	<b>GPS Location</b>	6
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 5 Desc.</b>	Perimeter controls functional.	<b>Pic 6 Desc.</b>	Staged equipment.

<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 7:28 AM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 7:28 AM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>	<b>GPS Location</b>
<b>Field Station#</b>	<b>Field Station#</b>
<b>Pic 13 Desc.</b>	<b>Pic 14 Desc.</b>

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>	<b>GPS Location</b>
<b>Field Station#</b>	<b>Field Station#</b>
<b>Pic 15 Desc.</b>	<b>Pic 16 Desc.</b>

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>	<b>GPS Location</b>
<b>Field Station#</b>	<b>Field Station#</b>
<b>Pic 17 Desc.</b>	<b>Pic 18 Desc.</b>





# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41042	
<b>Inspector</b> Joe Sweeden		<b>Date/Time</b> 8/16/2022 10:19 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b>	12005+00
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b>	69.00
<b>Municipality</b> N/A	<b>Weather</b> Cloudy	<b>Rain Gauge (in)</b>	0.40
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 10:19 AM	<b>Report #</b> 41042
----------------------	-------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Performed SWPP inspection at Yard 28  
 Yard 28 received 0.40" of precipitation over the last 24 hours.  
 No deficiencies found.  
 Observances:  
 The perimeter P1 and compost sock was in place and functioning as designed. The rock road approach was clean, no mud or other debris on road.  
 The yard was free of debris.  
 The perimeter controls were in place and functioning as designed. No activity in the yard.  
 Trucks and Porta-Johns are stacked in the yard  
 Equipment in the yard was free of leaks.


**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	8/16/2022 10:19 AM	<b>Report #</b>	
------------	-----------	------------------	--------------------	-----------------	--

## Pictures



<b>GPS Location</b>	See photo	<b>GPS Location</b>	see photo
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 1 Desc.</b>	Equipment	<b>Pic 2 Desc.</b>	RCE



<b>GPS Location</b>	see photo	<b>GPS Location</b>	see photo
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 3 Desc.</b>	Equipment	<b>Pic 4 Desc.</b>	Waste management



<b>GPS Location</b>	see photo	<b>GPS Location</b>	see photo
<b>Field Station#</b>	120050+00	<b>Field Station#</b>	12005+00
<b>Pic 5 Desc.</b>	Yard 28	<b>Pic 6 Desc.</b>	RCE

<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 10:19 AM	<b>Report #</b>
----------------------	-------------------------------------	-----------------

<b>Pictures</b>			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 10:19 AM	<b>Report #</b>
----------------------	-------------------------------------	-----------------

<b>Pictures</b>
-----------------

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41042	
<b>Inspector</b> Joe Sweeden		<b>Date/Time</b> 8/16/2022 10:19 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b>	12005+00
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b>	69.00
<b>Municipality</b> N/A	<b>Weather</b> Cloudy	<b>Rain Gauge (in)</b>	0.40
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Waste Management	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 10:19 AM	<b>Report #</b> 41042
----------------------	-------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Performed SWPP inspection at Yard 28  
 Yard 28 received 0.40" of precipitation over the last 24 hours.  
 No deficiencies found.  
 Observances:  
 The perimeter P1 and compost sock was in place and functioning as designed. The rock road approach was clean, no mud or other debris on road.  
 The yard was free of debris.  
 The perimeter controls were in place and functioning as designed. No activity in the yard.  
 Trucks and Porta-Johns are stacked in the yard  
 Equipment in the yard was free of leaks.


**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	8/16/2022 10:19 AM	<b>Report #</b>	
------------	-----------	------------------	--------------------	-----------------	--

## Pictures



<b>GPS Location</b>	See photo	<b>GPS Location</b>	see photo
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 1 Desc.</b>	Equipment	<b>Pic 2 Desc.</b>	RCE



<b>GPS Location</b>	see photo	<b>GPS Location</b>	see photo
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00
<b>Pic 3 Desc.</b>	Equipment	<b>Pic 4 Desc.</b>	Waste management



<b>GPS Location</b>	see photo	<b>GPS Location</b>	see photo
<b>Field Station#</b>	120050+00	<b>Field Station#</b>	12005+00
<b>Pic 5 Desc.</b>	Yard 28	<b>Pic 6 Desc.</b>	RCE



<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 10:19 AM	<b>Report #</b>
----------------------	-------------------------------------	-----------------

<b>Pictures</b>			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 10:19 AM	<b>Report #</b>
----------------------	-------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Roberts Corrosion		<b>Report #</b> 41051	
<b>Inspector</b> David Schoolcraft		<b>Date/Time</b> 8/16/2022 12:22 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	12005+00
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b>	12005+00
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b>	64.00
<b>Municipality</b> N/A	<b>Weather</b> Cloudy	<b>Rain Gauge (in)</b>	0.30
<b>Rain Accumulation Time (days)</b>			1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Secondary Containment	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 12:22 PM	<b>Report #</b> 41051
----------------------	-------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Completed a VA SWPPP at LY 26.  
 The perimeter controls CFS functioning properly.  
 RCE was clean and functioning  
 The yard was free of debris. Used oils were stored properly in secondary containment. The generator and air compressor were in secondary containment that was maintained properly.  
 All other ECDs were clean of sediment and functioning properly.  
 Trash bns clearly identified and in good condition  
 Housekeeping was in good condition.  
 Construction of a neighboring company ongoing  
 Giles county is currently installing stormwater system and any damaged ECDs will be replaced upon completion off project.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/16/2022 12:22 PM	Report #	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Tue, Aug 16, 2022, 11:24:06 EDT Position: +037.318370° / +080.572397° (-63.21) Altitude: 1755ft (-33.4ft) Datum: WGS-84 Azimuth Bearing: 286° N74W 508mils True (+2°) Elevation Angle: +38.3° Horizon Angle: -01.1° Zoom: 1.0X Y26</small></p>		 <p><small>Date &amp; Time: Tue, Aug 16, 2022, 11:18:05 EDT Position: +037.318362° / +080.572447° (-63.21) Altitude: 1757ft (-33.0ft) Datum: WGS-84 Azimuth Bearing: 136° S64E 273mils True (+2°) Elevation Angle: +38.0° Horizon Angle: -01.0° Zoom: 2.0X Y26</small></p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 1 Desc.</b>	Fuel containment	<b>Pic 2 Desc.</b>	Secondary containment		
 <p><small>Date &amp; Time: Tue, Aug 16, 2022, 11:22:28 EDT Position: +037.318570° / +080.572670° (-63.11) Altitude: 1756ft (-33.8ft) Datum: WGS-84 Azimuth Bearing: 278° N82W 492mils True (+2°) Elevation Angle: +11.9° Horizon Angle: -00.4° Zoom: 0.5X Y26</small></p>		 <p><small>Date &amp; Time: Tue, Aug 16, 2022, 11:20:05 EDT Position: +037.318562° / +080.572702° (-63.11) Altitude: 1750ft (-31.5ft) Datum: WGS-84 Azimuth Bearing: 310° N30W 501mils True (+2°) Elevation Angle: +11.0° Horizon Angle: -01.0° Zoom: 2.0X Y26</small></p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 3 Desc.</b>	Trash bins and house keeping	<b>Pic 4 Desc.</b>	Giles county construction		
 <p><small>Date &amp; Time: Tue, Aug 16, 2022, 11:20:00 EDT Position: +037.318310° / +080.568117° (-63.21) Altitude: 1751ft (-31.1ft) Datum: WGS-84 Azimuth Bearing: 052° N52E 057mils True (+2°) Elevation Angle: +15.5° Horizon Angle: +05.3° Zoom: 1.0X Y26</small></p>		 <p><small>Date &amp; Time: Tue, Aug 16, 2022, 11:22:42 EDT Position: +037.318367° / +080.568117° (-63.11) Altitude: 1753ft (-32.2ft) Datum: WGS-84 Azimuth Bearing: 032° N32E 053mils True (+2°) Elevation Angle: +11.0° Horizon Angle: -01.2° Zoom: 0.5X Y26</small></p>			
<b>GPS Location</b>	See Photo	<b>GPS Location</b>	See Photo		
<b>Field Station#</b>	12005+00	<b>Field Station#</b>	12005+00		
<b>Pic 5 Desc.</b>	Cfs controls	<b>Pic 6 Desc.</b>	RCE		

<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 12:22 PM	<b>Report #</b>
----------------------	-------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 12:22 PM	<b>Report #</b>
----------------------	-------------------------------------	-----------------

<b>Pictures</b>
-----------------

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41052	
<b>Inspector</b> David Schoolcraft		<b>Date/Time</b> 8/16/2022 12:21 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	10798+92
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b>	10859+46
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b>	63.00
<b>Municipality</b> N/A	<b>Weather</b> Cloudy	<b>Rain Gauge (in)</b>	0.60
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |



<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 12:21 PM	<b>Report #</b> 41052
----------------------	-------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)






<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)

Met with environmental staff.  
 Performed Va SWPPP inspection from MP 204.53 (10798+92) and MP 205.67 (10859+46)  
 No deficiencies found  
 All perimeter controls, ECDs and BMPs functional at time of inspection.  
 Stream buffers and controls in place at the time of inspection.  
 No sensitive resources have been impacted  
 ROW is wet but in stable condition

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 8/16/2022 12:21 PM		Report #			
Pictures							
 <p>Date &amp; Time: Tue, Aug 16, 2022, 09:10:55 EDT Position: +39.288361° / -88.656938° (+4993.37) Altitude: 2205ft (+68.77) Datum: WGS-84 Azimuth/Bearing: 327° N11W 620mils True (+12°) Elevation Angle: -12.2° Horizon Angle: -02.4° Zoom: 0.5X 10859+26</p>		 <p>Date &amp; Time: Tue, Aug 16, 2022, 09:12:10 EDT Position: +39.288361° / -88.656938° (+4993.37) Altitude: 2205ft (+68.77) Datum: WGS-84 Azimuth/Bearing: 334° N26W 593mils True (+12°) Elevation Angle: -01.1° Horizon Angle: -00.8° Zoom: 0.5X 10854+70</p>		 <p>Date &amp; Time: Tue, Aug 16, 2022, 09:54:37 EDT Position: +39.289796° / -88.656610° (+4993.47) Altitude: 2201ft (+68.77) Datum: WGS-84 Azimuth/Bearing: 310° N33W 492mils True (+12°) Elevation Angle: +01.3° Horizon Angle: +01.3° Zoom: 0.5X 10844+00</p>		 <p>Date &amp; Time: Tue, Aug 16, 2022, 09:55:44 EDT Position: +39.289796° / -88.656610° (+4993.47) Altitude: 2201ft (+68.77) Datum: WGS-84 Azimuth/Bearing: 337° N26W 580mils True (+12°) Elevation Angle: +00.5° Horizon Angle: +00.5° Zoom: 0.5X 10835+00</p>	
<b>GPS Location</b> See Photo		<b>GPS Location</b> See Photo		<b>GPS Location</b> See Photo			
<b>Field Station#</b> 10759+26		<b>Field Station#</b> 10854+70		<b>Field Station#</b> 10844+00			
<b>Pic 1 Desc.</b> RCE		<b>Pic 2 Desc.</b> S-A34		<b>Pic 3 Desc.</b> Stone outlet			
 <p>Date &amp; Time: Tue, Aug 16, 2022, 09:59:56 EDT Position: +39.289187° / -88.656441° (+4993.50) Altitude: 2410ft (+73.77) Datum: WGS-84 Azimuth/Bearing: 354° N44W 524mils True (+12°) Elevation Angle: -03.6° Horizon Angle: +03.6° Zoom: 0.5X 10820+00</p>		 <p>Date &amp; Time: Tue, Aug 16, 2022, 10:21:06 EDT Position: +39.289187° / -88.656441° (+4993.50) Altitude: 1929ft (+59.87) Datum: WGS-84 Azimuth/Bearing: 030° N33E 060mils True (+12°) Elevation Angle: +03.2° Horizon Angle: +03.1° Zoom: 0.5X 10802+00</p>		 <p>Date &amp; Time: Tue, Aug 16, 2022, 10:21:06 EDT Position: +39.289187° / -88.656441° (+4993.50) Altitude: 1929ft (+59.87) Datum: WGS-84 Azimuth/Bearing: 030° N33E 060mils True (+12°) Elevation Angle: +03.2° Horizon Angle: +03.1° Zoom: 0.5X 10802+00</p>			
<b>GPS Location</b> See Photo		<b>GPS Location</b> See Photo		<b>GPS Location</b> See Photo			
<b>Field Station#</b> 10820+00		<b>Field Station#</b> 10802+00		<b>Field Station#</b> 10802+00			
<b>Pic 5 Desc.</b> Section of ROW showing conditions and controls		<b>Pic 6 Desc.</b> RCE		<b>Pic 5 Desc.</b> Section of ROW showing conditions and controls			

<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 12:21 PM	<b>Report #</b>
----------------------	-------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>	<b>GPS Location</b>
<b>Field Station#</b>	<b>Field Station#</b>
<b>Pic 7 Desc.</b>	<b>Pic 8 Desc.</b>

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>	<b>GPS Location</b>
<b>Field Station#</b>	<b>Field Station#</b>
<b>Pic 9 Desc.</b>	<b>Pic 10 Desc.</b>

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>	<b>GPS Location</b>
<b>Field Station#</b>	<b>Field Station#</b>
<b>Pic 11 Desc.</b>	<b>Pic 12 Desc.</b>

<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 12:21 PM	<b>Report #</b>
----------------------	-------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41061	
<b>Inspector</b> Daniel Fortune		<b>Date/Time</b> 8/16/2022 3:02 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	10655+00
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	10749+92
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b>	64.00
<b>Municipality</b> N/A	<b>Weather</b> Cloudy	<b>Rain Gauge (in)</b>	1.60
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other - Explain in Comments	Acceptable	Added to punch list		
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	Added to punch list		
Rock Construction Entrance	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 3:02 PM	<b>Report #</b> 41061
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)

Completed a VA SWPPP inspection from ST# 10655+00 to ST# 10749+92 (MP 201.6 to MP 203.6). There had been recent rain events over the last 24 hours that produced about 1.6" of precipitation in the areas of inspection. There were minor deficiencies observed for repairs today. These items were communicated to the contractor and the respective UI covering the environmental crew (1706). These deficiencies have been added to todays punch list. Damaged silt fence 10712+46 and damaged foam dike (other) near 10726+15.

Drainage features, waterbodies, equipment crossings, perimeter controls, sump pits, and end treatments have been inspected today. A few sump pits have water standing but no issues at this time. Will continue to monitor receding water levels. Upon arrival to the row, the row conditions were wet from yesterday's rain events. The temporary water bars remain stable and functional. The perimeter ECDs remain without displacement and are functional according to design. There were a few resources (W-Z11 wetland near 10732+50, S-G33 10712+73, and S-G32 10698+15, that remain functional without impacts at this time. There is visible new vegetation emerging from fresh areas of temporary stabilization throughout the areas of inspection aforementioned above. The drainage features, and stream buffer zones, do have abundant vegetation without erosion issues.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	8/16/2022 3:02 PM	<b>Report #</b>	
------------	-----------	------------------	-------------------	-----------------	--

## Pictures



<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	10699+00	<b>Field Station#</b>	10699+50
<b>Pic 1 Desc.</b>	S-G32 stream resource area and equipment bridge conditions. No Issues at this time.	<b>Pic 2 Desc.</b>	TLS conditions.






<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	10679+36	<b>Field Station#</b>	10667+00
<b>Pic 3 Desc.</b>	Over view of well vegetated stream resource of S-G30	<b>Pic 4 Desc.</b>	TLS and storm water filled sump pits.



<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	10687+00	<b>Field Station#</b>	10709+75
<b>Pic 5 Desc.</b>	TLS conditions.	<b>Pic 6 Desc.</b>	Perimeter super silt fence condition. No Issues.

AFE 124300137		Date/Time 8/16/2022 3:02 PM		Report #	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Tue Aug 16, 2022 09:34:19 EDT Position: +037.248333° / -89.448197° (-14.31) Altitude: 2273ft (-69.21) Datum: WGS-84 Azimuth/Bearing: 010° N70E 000mils True (-12°) Elevation Grade: -003 Horizon Grade: -003 Zoom: 0.5X 10709+75</small></p>		 <p><small>Date &amp; Time: Tue Aug 16, 2022 09:38:37 EDT Position: +037.248333° / -89.448197° (-14.31) Altitude: 2273ft (-69.21) Datum: WGS-84 Azimuth/Bearing: 074° N74E 111mils True (-12°) Elevation Grade: -003 Horizon Grade: -003 Zoom: 0.5X 10712+45 S-G33</small></p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10709+75	<b>Field Station#</b>	10712+46		
<b>Pic 7 Desc.</b>	Temporary stabilization of row. No Issues at this time.		<b>Pic 8 Desc.</b>	S-G33 equipment bride condition.	
 <p><small>Date &amp; Time: Tue Aug 16, 2022 09:41:52 EDT Position: +037.248333° / -89.448197° (-14.31) Altitude: 2273ft (-69.21) Datum: WGS-84 Azimuth/Bearing: 066° N66E 1173mils True (-12°) Elevation Grade: -034 Horizon Grade: -007 Zoom: 0.5X 10712+46</small></p>		 <p><small>Date &amp; Time: Tue Aug 16, 2022 09:43:42 EDT Position: +037.248333° / -89.448197° (-14.31) Altitude: 2273ft (-69.21) Datum: WGS-84 Azimuth/Bearing: 098° N78E 000mils True (-12°) Elevation Grade: -004 Horizon Grade: -001 Zoom: 1.0X 10717+00</small></p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10712+46	<b>Field Station#</b>	10717+00		
<b>Pic 9 Desc.</b>	Damaged P1 silt fence by local wild life. Added to punch list 8/16/22.		<b>Pic 10 Desc.</b>	Temporary stabilization of row. Vegetation root system established. Sparse areas visible. No erosion at this time.	
 <p><small>Date &amp; Time: Tue Aug 16, 2022 09:15:41 EDT Position: +037.248333° / -89.448197° (-14.31) Altitude: 2367ft (-72.51) Datum: WGS-84 Azimuth/Bearing: 087° N87E 019mils True (-12°) Elevation Grade: -011 Horizon Grade: -008 Zoom: 1.0X 10726+15</small></p>		 <p><small>Date &amp; Time: Tue Aug 16, 2022 09:15:41 EDT Position: +037.248333° / -89.448197° (-14.31) Altitude: 2368ft (-72.21) Datum: WGS-84 Azimuth/Bearing: 030° N30E 0533mils True (-12°) Elevation Grade: -005 Horizon Grade: -008 Zoom: 0.5X 10728+69</small></p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10726+15	<b>Field Station#</b>	10728+69		
<b>Pic 11 Desc.</b>	View of damaged foam dike diversions. This has been added to the punch list for replacement.		<b>Pic 12 Desc.</b>	View of storm water filled sump pit with functional end treatment.	



AFE 124300137		Date/Time 8/16/2022 3:02 PM		Report #	
Pictures					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	10732+00	<b>Field Station#</b>	10742+40		
<b>Pic 13 Desc.</b>	Over view of the W-Z11 wetland conditions. No disturbances and no issues.	<b>Pic 14 Desc.</b>	View of well vegetated drainage feature.		
		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>			
<b>Field Station#</b>	10748+04	<b>Field Station#</b>			
<b>Pic 15 Desc.</b>	View of ECB to a row drain path to a sump pit. No issues at this time .	<b>Pic 16 Desc.</b>			
<p style="text-align: center;">Insert image here</p>		<p style="text-align: center;">Insert image here</p>			
<b>GPS Location</b>		<b>GPS Location</b>			
<b>Field Station#</b>		<b>Field Station#</b>			
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>			



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41065	
<b>Inspector</b> Jared Saunders		<b>Date/Time</b> 8/16/2022 4:24 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	10749+92
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b>	10797+92
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b>	70.00
<b>Municipality</b> N/A	<b>Weather</b> Cloudy	<b>Rain Gauge (in)</b>	0.50
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b>	124300137	<b>Date/Time</b>	8/16/2022 4:24 PM	<b>Report #</b>	41065
------------	-----------	------------------	-------------------	-----------------	-------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Completed VA SWPPP inspection from ST# 10749+92 (Hendrickson) to ST# 10798+92 (Cascade)  
 VA SWPPP inspection of MP 203.6 to MP 204.53.  
 No deficiencies were located during inspection.  
 Active construction site; additional deficiencies may be identified by other EIs.  
 Observed no environmental maintenance crews actively working on this section of ROW during inspection.  
 This section of ROW is temporarily stabilized with seed and mulch. Vegetation growth is present throughout section.  
 Clean water diversion berms, pipes and level spreaders are in place. ECDs in place per E&S sheets.  
 Sensitive resource buffers are in place at stream crossings S-G35, S-SS4, S-Z9, S-Z7 braid 1, and S-Z7 braid 2.  
 Hendrickson Road, Big Branch Hollow Road, and Cascade Road crossing RCEs are maintained in acceptable condition.  
 No sensitive resources have been impacted.  
 Checked rain gauge at Catawba Road- 0.3 inches and Mount Tabor Road - 0.5 inches.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 8/16/2022 4:24 PM		Report #			
Pictures							
 <p>Date &amp; Time: Tue, Aug 16, 2022, 11:05:36 EDT Position: +037.340322 / -080.623992 (+7283.8ft) Altitude: 2277ft (+69.9ft) Datum: WGS-84 Azimuth/Bearing: 039° N39E 0593mils True (+13°) Elevation Angle: -26.3° Horizon Angle: -00.5° Zoom: 1.0x 10753+00</p>		 <p>Date &amp; Time: Tue, Aug 16, 2022, 11:11:05 EDT Position: +037.340393 / -080.624452 (+7283.8ft) Altitude: 2257ft (+68.9ft) Datum: WGS-84 Azimuth/Bearing: 049° N49E 1227mils True (+13°) Elevation Angle: -16.3° Horizon Angle: -01.4° Zoom: 1.0x 10758+00</p>		<p><b>GPS Location</b> See photo for GPS location.</p> <p><b>Field Station#</b> 10753+00</p> <p><b>Pic 1 Desc.</b> Waterbars in place. ROW temporarily stabilized.</p>		<p><b>GPS Location</b> See photo for GPS location.</p> <p><b>Field Station#</b> 10758+00</p> <p><b>Pic 2 Desc.</b> Sensitive resource buffer in place at stream S-G35.</p>	
 <p>Date &amp; Time: Tue, Aug 16, 2022, 11:14:34 EDT Position: +037.344955 / -080.632362 (+728.7ft) Altitude: 2158ft (+65.1ft) Datum: WGS-84 Azimuth/Bearing: 176° S94E 3129mils True (+13°) Elevation Angle: -32° Horizon Angle: -02.1° Zoom: 1.0x 10762+00</p>		 <p>Date &amp; Time: Tue, Aug 16, 2022, 11:19:45 EDT Position: +037.345264 / -080.630044 (+743.6ft) Altitude: 2213ft (+68.2ft) Datum: WGS-84 Azimuth/Bearing: 189° S09W 3360mils True (+13°) Elevation Angle: -27.1° Horizon Angle: -03.4° Zoom: 1.0x 10772+00</p>		<p><b>GPS Location</b> See photo for GPS location.</p> <p><b>Field Station#</b> 10762+00</p> <p><b>Pic 3 Desc.</b> Rock inlet protection at slope drain pipe.</p>		<p><b>GPS Location</b> See photo for GPS location.</p> <p><b>Field Station#</b> 10772+00</p> <p><b>Pic 4 Desc.</b> Clean water diversion pipe and level spreader in place.</p>	
 <p>Date &amp; Time: Tue, Aug 16, 2022, 11:26:01 EDT Position: +037.342071 / -080.624607 (+7369.0ft) Altitude: 2134ft (+63.9ft) Datum: WGS-84 Azimuth/Bearing: 076° N76E 1783mils True (+13°) Elevation Angle: -07.8° Horizon Angle: -03.6° Zoom: 1.0x 10777+00</p>		 <p>Date &amp; Time: Tue, Aug 16, 2022, 11:26:01 EDT Position: +037.342289 / -080.624607 (+7369.0ft) Altitude: 2159ft (+64.9ft) Datum: WGS-84 Azimuth/Bearing: 082° N82E 1458mils True (+13°) Elevation Angle: -13.1° Horizon Angle: -02.2° Zoom: 1.0x 10783+00</p>		<p><b>GPS Location</b> See photo for GPS location.</p> <p><b>Field Station#</b> 10777+00</p> <p><b>Pic 5 Desc.</b> Clean water drainage feature in place.</p>		<p><b>GPS Location</b> See photo for GPS location.</p> <p><b>Field Station#</b> 10783+00</p> <p><b>Pic 6 Desc.</b> ROW temporarily stabilized.</p>	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/16/2022 4:24 PM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/16/2022 4:24 PM	<b>Report #</b>	
------------	-----------	------------------	-------------------	-----------------	--

<b>Pictures</b>					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41083	
<b>Inspector</b> Chris Burns		<b>Date/Time</b> 8/17/2022 7:12 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 11098+47	
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b> 11184+85	
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b> 71.00	
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b> 0.00	
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Communication	See punch list.	24 Hours	
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Communication	See punch list.		
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b>	124300137	<b>Date/Time</b>	8/17/2022 7:12 AM	<b>Report #</b>	41083
------------	-----------	------------------	-------------------	-----------------	-------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Level Spreader	Acceptable			
Other	Acceptable			

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**







**Comments** (Reference above questions as appropriate.)

See photos for GPS coordinates.  
 Met with environmental staff.  
 Performed SWPPP inspection from MP 210.2 (11098+47) and MP 211.83 (11184+85).  
 Accompanied by fellow EI David Schoolcraft.  
 Discussed RoW/ECD conditions, within this section, with fellow EI David Schoolcraft.  
 This section of RoW is partially restored.  
 All perimeter controls, ECDs and BMPs functional at time of inspection.  
 Vegetation or stabilization sufficient.  
 No impact to sensitive resources observed.  
 Section 6 - other (waterbars)  
 Assessed AR 245.02, AR 249.02 and AR 249.  
 Robert's Corrosion crews installing temporary anode bed near 11178+25.  
 Crews accessing, through restored area, from AR 249.01.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.



AFE 124300137		Date/Time 8/17/2022 7:12 AM		Report #	
Pictures					
					
<b>GPS Location</b> 1		<b>GPS Location</b> 2			
<b>Field Station#</b> 11183+00		<b>Field Station#</b> 11176+00			
<b>Pic 1 Desc.</b> Representative photo of permanent waterbar and level spreaders installed.		<b>Pic 2 Desc.</b> Section of restored RoW showing conditions and controls.			
					
<b>GPS Location</b> 3		<b>GPS Location</b> 4			
<b>Field Station#</b> 11167+83		<b>Field Station#</b> 11158+68			
<b>Pic 3 Desc.</b> RCE off of AR 249.01.		<b>Pic 4 Desc.</b> S-NN17.			
					
<b>GPS Location</b> 5		<b>GPS Location</b> 6			
<b>Field Station#</b> 11104+00		<b>Field Station#</b> 11118+00			
<b>Pic 5 Desc.</b> Section of restored RoW showing conditions and controls.		<b>Pic 6 Desc.</b> Section of restored RoW showing conditions and controls.			

AFE	124300137	Date/Time	8/17/2022 7:12 AM	Report #	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Wed Aug 17, 2022, 09:12:50 EDT Position: 2042373.485 E / 2523567.822 N (e15.4M) Altitude: 1939ft (e11.2M) Datum: WGS-84 Azimuth/Bearing: 171° S09E 3840mils True (e12°) Elevation Angle: -18.0° Horizon Angle: -80.0° Zoom: 0.5X 11122+00 repair rilling, seed and stabilize (blanket recommended)</small></p>			 <p><small>Date &amp; Time: Wed Aug 17, 2022, 09:19:34 EDT Position: 2044211.337 E / 2523527.697 N (e15.1M) Altitude: 1934ft (e11.0M) Datum: WGS-84 Azimuth/Bearing: 132° S28E 2347mils True (e12°) Elevation Angle: -11.9° Horizon Angle: -82.6° Zoom: 0.5X 11131+00</small></p>		
<b>GPS Location</b>	7	<b>GPS Location</b>	8	<b>Field Station#</b>	11122+00
<b>Field Station#</b>	11122+00	<b>Field Station#</b>	11131+00	<b>Pic 7 Desc.</b>	Punch list item, repair rilling, seed and stabilize.
<b>Pic 7 Desc.</b>	Punch list item, repair rilling, seed and stabilize.	<b>Pic 8 Desc.</b>	Section of restored RoW showing conditions and controls.		
 <p><small>Date &amp; Time: Wed Aug 17, 2022, 09:31:19 EDT Position: 2045033.679 E / 2523908.525 N (e15.2M) Altitude: 2122ft (e1.78.7M) Datum: WGS-84 Azimuth/Bearing: 031° N21E 0378mils True (e12°) Elevation Angle: -07.1° Horizon Angle: -61.0° Zoom: 0.5X 11138+00</small></p>			 <p><small>Date &amp; Time: Wed Aug 17, 2022, 09:35:06 EDT Position: 2045530.235 E / 2523938.818 N (e15.4M) Altitude: 2108ft (e11.2M) Datum: WGS-84 Azimuth/Bearing: 132° S09W 3936mils True (e12°) Elevation Angle: -20.5° Horizon Angle: -80.1° Zoom: 0.5X 11146+00</small></p>		
<b>GPS Location</b>	9	<b>GPS Location</b>	10	<b>Field Station#</b>	11139+00
<b>Field Station#</b>	11139+00	<b>Field Station#</b>	11146+00	<b>Pic 9 Desc.</b>	Section of restored RoW showing conditions and controls.
<b>Pic 9 Desc.</b>	Section of restored RoW showing conditions and controls.	<b>Pic 10 Desc.</b>	CWDP outlet protection functional.		
 <p><small>Date &amp; Time: Wed Aug 17, 2022, 10:15:25 EDT Position: 2007257.803 E / 2521920.235 N (e15.2M) Altitude: 1773ft (e1.51M) Datum: WGS-84 Azimuth/Bearing: 180° S00E 3200mils True (e10°) Elevation Angle: -27.5° Horizon Angle: -80.6° Zoom: 0.5X 11098+47 repair CFS</small></p>			 <p><small>Date &amp; Time: Wed Aug 17, 2022, 09:56:08 EDT Position: 2047837.342 E / 2521197.376 N (e15.0M) Altitude: 1934ft (e11.0M) Datum: WGS-84 Azimuth/Bearing: 052° N34E 0940mils True (e12°) Elevation Angle: -07.3° Horizon Angle: -66.6° Zoom: 0.5X 11178+36</small></p>		
<b>GPS Location</b>	11	<b>GPS Location</b>	12	<b>Field Station#</b>	11098+47
<b>Field Station#</b>	11098+47	<b>Field Station#</b>	11178+36	<b>Pic 11 Desc.</b>	Representative photo of damaged CFS along AR 245.02.
<b>Pic 11 Desc.</b>	Representative photo of damaged CFS along AR 245.02.	<b>Pic 12 Desc.</b>	Crews installing temporary anode bed.		

<b>A/E</b>	124300137	<b>Date/Time</b>	8/17/2022 7:12 AM	<b>Report #</b>	
------------	-----------	------------------	-------------------	-----------------	--

<b>Pictures</b>					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41080	
<b>Inspector</b> Eric Hanlon		<b>Date/Time</b> 8/17/2022 6:58 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 11023+80	
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b> 11098+47	
<b>County</b> Giles	<b>Ground</b> Damp	<b>Temperature (°F)</b> 63.00	
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b> 0.00	
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar	Communication			
Broad-Based Dip	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Filter Log	Acceptable			
Sediment Filter Log	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/17/2022 6:58 AM	<b>Report #</b> 41080
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable			

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)

Completed a VA SWPPP inspection from ST# 11023+80 (MP 208.78) to ST# 11098+47 (MP 210.02)  
 Compliance issues noted @ 11024+50 rilling in throat of water bar  
 Observance:  
 Crews working on vegetative maintenance in the area @11050+00 to 11065+00  
 Perimeter controls in place & functioning as designed.  
 ROW has temporary and section of it permanent stabilization. Section 6 (other) CFS water bars in permanent restored area.  
 Open ditch @ 11059+00.  
 All other ECDs and BMPs functional at time of inspection.  
 50' buffers in place at stream crossings S-IJ19, S-IJ18, S-IJ17 and S-IJ16-B  
 AR-244,245.01 and 245.02 road crossing RCEs are maintained in acceptable condition.  
 The ROW is damp and in stable condition.  
 No sensitive resources have been impacted.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/17/2022 6:58 AM	Report #	
<b>Pictures</b>					
<p>Date &amp; Time: Wed Aug 17, 2022, 06:58 EDT  Position: -037.315360 / -080.541198 (-25.0ft)  Altitude: 2195ft (+13.1ft)  Datum: WGS-84  Azimuth/Bearing: 110.570E 190mils True (+13.1)  Elevation Angle: -13.6  Horizon Angle: +05.5  Zoom: 1.0X  11098+47</p>			<p>Date &amp; Time: Wed Aug 17, 2022, 06:58 EDT  Position: -037.315557 / -080.542260 (-12.5ft)  Altitude: 2222ft (+11.7ft)  Datum: WGS-84  Azimuth/Bearing: 129.558E 2222mils True (+11.7)  Elevation Angle: -13.7  Horizon Angle: +07.7  Zoom: 1.0X  11085+00</p>		
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11098+47		<b>Field Station#</b>	11085+00	
<b>Pic 1 Desc.</b>	Picture showing condition of row		<b>Pic 2 Desc.</b>	CFS water bars	
<p>Date &amp; Time: Wed Aug 17, 2022, 08:56 EDT  Position: -037.315360 / -080.541198 (-25.0ft)  Altitude: 2195ft (+13.1ft)  Datum: WGS-84  Azimuth/Bearing: 089.889E 1582mils True (+13.1)  Elevation Angle: -09.0  Horizon Angle: -03.0  Zoom: 1.0X  11073+00</p>		<p>Date &amp; Time: Wed Aug 17, 2022, 08:49 EDT  Position: -037.315557 / -080.542260 (-12.5ft)  Altitude: 2688ft (+19.7ft)  Datum: WGS-84  Azimuth/Bearing: 129.558E 2222mils True (+13.1)  Elevation Angle: -21.8  Horizon Angle: -03.1  Zoom: 1.0X  11065+00</p>			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11073+00		<b>Field Station#</b>	11065+00	
<b>Pic 3 Desc.</b>	Permanent stabilization in place		<b>Pic 4 Desc.</b>	Equipment bridge functional	
<p>Date &amp; Time: Wed Aug 17, 2022, 08:40 EDT  Position: -037.315779 / -080.542114 (-12.9ft)  Altitude: 2185ft (+17.7ft)  Datum: WGS-84  Azimuth/Bearing: 023.587E 1653mils True (+13.1)  Elevation Angle: -19.7  Horizon Angle: +03.3  Zoom: 1.0X  11056+00</p>		<p>Date &amp; Time: Wed Aug 17, 2022, 08:32 EDT  Position: -037.315557 / -080.542110 (-12.9ft)  Altitude: 2033ft (+9.6ft)  Datum: WGS-84  Azimuth/Bearing: 112.568E 1991mils True (+15.1)  Elevation Angle: -16.7  Horizon Angle: +00.3  Zoom: 0.5X  11050+00</p>			
<b>GPS Location</b>	See photo		<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11056+00		<b>Field Station#</b>	11050+00	
<b>Pic 5 Desc.</b>	Perimeter controls in place		<b>Pic 6 Desc.</b>	Resource buffers in place	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/17/2022 6:58 AM	<b>Report #</b>
----------------------	------------------------------------	-----------------

## Pictures



Date & Time: Wed, Aug 17, 2022, 08:26:09 EDT  
 Position: -037.318668 / -80.549517 (-37.318668, -80.549517)  
 Altitude: 2279ft (±39.4ft)  
 Datum: WGS-84  
 Azimuth/Bearing: 092.588E 183.36mils True (±15.7)  
 Elevation Angle: -22.0  
 Horizon Angle: -01.8  
 Zoom: 0.5X  
 11044+00



Date & Time: Wed, Aug 17, 2022, 08:28:58 EDT  
 Position: -037.322277 / -80.502277 (-37.322277, -80.502277)  
 Altitude: 1920ft (±103.0ft)  
 Datum: WGS-84  
 Azimuth/Bearing: 329.831W 54.0mils True (±14.4)  
 Elevation Angle: -05.4  
 Horizon Angle: -06.7  
 Zoom: 0.5X  
 11026+00

<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	11044+00	<b>Field Station#</b>	11026+00
<b>Pic 7 Desc.</b>	Water bars and ET in place	<b>Pic 8 Desc.</b>	Wattles in place



Date & Time: Wed, Aug 17, 2022, 08:13:50 EDT  
 Position: -037.322714 / -80.552813 (-37.322714, -80.552813)  
 Altitude: 2402ft (±17.2ft)  
 Datum: WGS-84  
 Azimuth/Bearing: 112.568E 199.1mils True (±17)  
 Elevation Angle: -32.7  
 Horizon Angle: -02.7  
 Zoom: 0.5X  
 11024+50



Date & Time: Wed, Aug 17, 2022, 08:08:28 EDT  
 Position: -037.322777 / -80.502277 (-37.322777, -80.502277)  
 Altitude: 1920ft (±103.0ft)  
 Datum: WGS-84  
 Azimuth/Bearing: 329.831W 54.0mils True (±14.4)  
 Elevation Angle: -05.4  
 Horizon Angle: -06.7  
 Zoom: 0.5X  
 11023+80

<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	11024+50	<b>Field Station#</b>	11023+80
<b>Pic 9 Desc.</b>	Rilling in throat of water bar	<b>Pic 10 Desc.</b>	Broad base dips functional

Insert image here

Insert image here

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b>	124300137	<b>Date/Time</b>	8/17/2022 6:58 AM	<b>Report #</b>	
------------	-----------	------------------	-------------------	-----------------	--

<b>Pictures</b>					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	





# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41092	
<b>Inspector</b> Daniel Fortune		<b>Date/Time</b> 8/17/2022 10:36 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11184+85
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	11254+99
<b>County</b> Giles	<b>Ground</b> Damp	<b>Temperature (°F)</b>	63.00
<b>Municipality</b> N/A	<b>Weather</b> Cloudy	<b>Rain Gauge (in)</b>	0.00
<b>Rain Accumulation Time (days)</b>			0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Permanent)	Communication	Added to punch list		
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Stone Inlet Protection	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/17/2022 10:36 AM	<b>Report #</b> 41092
----------------------	-------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Level Spreader	Acceptable			
Other	Acceptable			

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)







Completed VA SWPPP inspection from ST# 11184+85 to ST# 11254+99 (MP 211.83 to MP 213.6)  
 The Row received 0.0" precipitation in the last 24 hours. No erosion or sediment migration has been observed today. The section of row has been final stabilized from 11184+85 to near station 11222+43. Permanent water bars, level spreaders, and perimeter ECDs remain installed and functioning to design. There is good vegetation throughout. There are some spots with sparse vegetation but will continue to grow. May need additional over seeding prior to the fall this year. Final restoration did not start until early fall 2021. A full growing season has not been established. There is temporary stabilization between 11222+43 to 11253+50. This section of row has been temporarily stabilized with no issues observed during todays inspection. There are temporary water bars and temporary ECDs throughout this area that appear to function as intended. Temporary vegetation remains visible with sparse areas of little to poor, to no growth between Stations 11226+00 to near 11251+00. Prior to the fall of this year, additional vegetation will need to be established. This has been previously reported by other EIs. No sensitive resources have been impacted. No activity observed in the area.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/17/2022 10:36 AM	Report #	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	see photo		
<b>Field Station#</b>	11186+00	<b>Field Station#</b>	11189+00		
<b>Pic 1 Desc.</b>	Heavy vegetation in final restoration area.	<b>Pic 2 Desc.</b>	Heavy vegetated permanent water bar and functional level spreader. Adequate vegetation coverage of row.		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11191+41	<b>Field Station#</b>	11192+40		
<b>Pic 3 Desc.</b>	Heavily vegetated row through the drainage feature area. CFS functional as a water bar.	<b>Pic 4 Desc.</b>	Perimeter CFS controls in final restoration area.		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11194+10	<b>Field Station#</b>	11199+00		
<b>Pic 5 Desc.</b>	Area of slight subsidence in final restoration area. Depression not visible in photo.	<b>Pic 6 Desc.</b>	Steep side slope heavy vegetation in final restoration area.		

<b>AFE</b>	124300137	<b>Date/Time</b>	8/17/2022 10:36 AM	<b>Report #</b>	
------------	-----------	------------------	--------------------	-----------------	--

## Pictures

			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	11206+45	<b>Field Station#</b>	11212+73
<b>Pic 7 Desc.</b>	Daylight drain within the final restoration area.	<b>Pic 8 Desc.</b>	Area of depression at the test lead site location. This area is in the final restoration area.
			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	11214+00	<b>Field Station#</b>	11225+70
<b>Pic 9 Desc.</b>	Area of no permanent vegetation. This has been added to the punch list. (PL 8/17/22)	<b>Pic 10 Desc.</b>	Stone inlet protection condition in the temporary restored row.
			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
<b>Field Station#</b>	11225+70	<b>Field Station#</b>	11227+50
<b>Pic 11 Desc.</b>	Slope drain pipe leading to functional sump pit.	<b>Pic 12 Desc.</b>	Adequate Stone inlet protection.

AFE 124300137		Date/Time 8/17/2022 10:36 AM		Report #	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Wed, Aug 17, 2022, 09:22:49 EDT Position: +07 227562 / -080 476266 (±33.4ft) Altitude: 2231ft (±6.8ft) Datum: WGS 84 Azimuth/Bearing: 110° 53'01" 591 (±12°) Elevation Grade: +008 Horizon Grade: +002 Zoom: 0.5X 11231+00</small></p>			 <p><small>Date &amp; Time: Wed, Aug 17, 2022, 09:42:28 EDT Position: +07 227562 / -080 476266 (±33.4ft) Altitude: 2231ft (±6.8ft) Datum: WGS 84 Azimuth/Bearing: 111° 53'01" 592 (±12°) Elevation Grade: +008 Horizon Grade: +001 Zoom: 0.5X 11241+25</small></p>		
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11231+00		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		Temporary stabilization of row.		<b>Pic 14 Desc.</b>	
				View of adequately installed P1 silt fencing.	
 <p><small>Date &amp; Time: Wed, Aug 17, 2022, 09:48:10 EDT Position: +07 227562 / -080 476266 (±33.3ft) Altitude: 2131ft (±5.9ft) Datum: WGS 84 Azimuth/Bearing: 332° N28W 5902mils True (±12°) Elevation Grade: +008 Horizon Grade: +001 Zoom: 0.5X 11248+00</small></p>			Insert image here		
<b>GPS Location</b>		See photo		<b>GPS Location</b>	
<b>Field Station#</b>		11248+00		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		View of steep slope temporary stabilization.		<b>Pic 16 Desc.</b>	
Insert image here			Insert image here		
<b>GPS Location</b>				<b>GPS Location</b>	
<b>Field Station#</b>				<b>Field Station#</b>	
<b>Pic 17 Desc.</b>				<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41147	
<b>Inspector</b> Chris Burns		<b>Date/Time</b> 8/18/2022 7:02 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11353+67
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	11471+56
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b>	73.00
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/18/2022 7:02 AM	<b>Report #</b> 41147
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)





<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Level Spreader	Acceptable			
Other	Acceptable			

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**







**Comments** (Reference above questions as appropriate.)

See photos for GPS coordinates.  
 Met with environmental staff.  
 Performed SWPPP inspection from MP 215.04 (11353+67) and MP 217.26 (11471+56).  
 Accompanied by fellow EI David Schoolcraft.  
 PPL crews conducting vegetative maintenance in this area.  
 Robert's Corrosion currently installing temporary anode beds at three locations, 11462+15, 11446+46 and 11410+00.  
 This section of RoW is partially restored.  
 All perimeter controls, ECDs and BMPs functional at time of inspection.  
 Vegetation or stabilization sufficient.  
 No impact to sensitive resources observed.  
 Section 6 - other (waterbars).

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 8/18/2022 7:02 AM		Report #			
Pictures							
 <p>Date &amp; Time: Thu, Aug 18, 2022, 06:45:42 EDT  Position: 2070106.589 E / 3527692.126 N (+11.1M)  Altitude: 222.62 (+11.1M)  Datum: WGS-84  Azimuth/Bearing: 311° 59'10" W 591mils True (+12°)  Elevation Angle: +08.8°  Horizon Angle: -01.1°  Zoom: 0.5X  11469+00</p>		 <p>Date &amp; Time: Thu, Aug 18, 2022, 09:18:14 EDT  Position: 2069389.782 E / 2526546.825 N (+11.2M)  Altitude: 224.51 (+11.2M)  Datum: WGS-84  Azimuth/Bearing: 318° N42W 595mils True (+12°)  Elevation Angle: -31.6°  Horizon Angle: -01.2°  Zoom: 0.5X  11462+00</p>		 <p>Date &amp; Time: Thu, Aug 18, 2022, 09:37:50 EDT  Position: 2068697.422 E / 2526231.319 N (+11.1M)  Altitude: 208.61 (+11.1M)  Datum: WGS-84  Azimuth/Bearing: 163° S17E 2898mils True (+12°)  Elevation Angle: -05.0°  Horizon Angle: -00.7°  Zoom: 0.5X  11451+87 S-0012</p>		 <p>Date &amp; Time: Thu, Aug 18, 2022, 09:38:18 EDT  Position: 2069722.428 E / 2526248.882 N (+11.5M)  Altitude: 215.91 (+11.5M)  Datum: WGS-84  Azimuth/Bearing: 168° S12E 2997mils True (+12°)  Elevation Angle: -14.5°  Horizon Angle: -01.6°  Zoom: 0.5X  11451+08 S-0013</p>	
GPS Location 1		GPS Location 2		GPS Location 3			
Field Station# 11469+00		Field Station# 11462+00		Field Station# 11451+87			
Pic 1 Desc. Section of RoW showing conditions and controls.		Pic 2 Desc. Crews performing vegetative maintenance.		Pic 3 Desc. S-0012.			
GPS Location 5		GPS Location 6		GPS Location 5			
Field Station# 11448+93		Field Station# 11438+75		Field Station# 11448+93			
Pic 5 Desc. S-0014/W-CD12.		Pic 6 Desc. Section of restored RoW showing conditions and controls.		Pic 5 Desc. S-0014/W-CD12.			



AFE 124300137		Date/Time 8/18/2022 7:02 AM		Report #	
Pictures					
 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 09:55:49 EDT Position: 2064789.766 E / 2522744.268 N (±135.8m) Altitude: 2330ft (±420.0ft) Datum: WGS-84 Azimuth/Bearing: 261° S81W 4692mils True (±12°) Elevation Angle: -98.2° Horizon Angle: -02.3° Zoom: 0.5X 11397+00</small></p>			 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 10:05:49 EDT Position: 2081111.111 E / 2522645.768 N (±15.4m) Altitude: 2081ft (±11.3ft) Datum: WGS-84 Azimuth/Bearing: 202° S22W 3591mils True (±12°) Elevation Angle: -01.4° Horizon Angle: -01.5° Zoom: 0.5X 11387+00</small></p>		
<b>GPS Location</b> 7		<b>GPS Location</b> 8			
<b>Field Station#</b> 11431+00		<b>Field Station#</b> 11413+00			
<b>Pic 7 Desc.</b> Representative photo of permanent waterbar and level spreaders installed.		<b>Pic 8 Desc.</b> Section of restored RoW showing conditions and controls.			
 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 10:23:02 EDT Position: 2064789.766 E / 2522744.268 N (±135.8m) Altitude: 2330ft (±420.0ft) Datum: WGS-84 Azimuth/Bearing: 261° S81W 4692mils True (±12°) Elevation Angle: -98.2° Horizon Angle: -02.3° Zoom: 0.5X 11397+00</small></p>			 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 10:33:34 EDT Position: 2081111.111 E / 2522645.768 N (±15.4m) Altitude: 2081ft (±11.3ft) Datum: WGS-84 Azimuth/Bearing: 202° S22W 3591mils True (±12°) Elevation Angle: -01.4° Horizon Angle: -01.5° Zoom: 0.5X 11387+00</small></p>		
<b>GPS Location</b> 9		<b>GPS Location</b> 10			
<b>Field Station#</b> 11397+00		<b>Field Station#</b> 11387+00			
<b>Pic 9 Desc.</b> Section of restored RoW showing conditions and controls.		<b>Pic 10 Desc.</b> Section of restored RoW showing conditions and controls.			
 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 10:39:05 EDT Position: 2061888.277 E / 2522054.576 N (±15.5m) Altitude: 2022ft (±111.1ft) Datum: WGS-84 Azimuth/Bearing: 218° S38W 3876mils True (±12°) Elevation Angle: -06.6° Horizon Angle: -00.5° Zoom: 0.5X 11367+00</small></p>			 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 10:43:25 EDT Position: 2061888.277 E / 2522054.576 N (±15.5m) Altitude: 2022ft (±111.1ft) Datum: WGS-84 Azimuth/Bearing: 172° S38E 3055mils True (±12°) Elevation Angle: -09.4° Horizon Angle: -00.3° Zoom: 0.5X 11360+54 S-KL43</small></p>		
<b>GPS Location</b> 11		<b>GPS Location</b> 12			
<b>Field Station#</b> 11367+00		<b>Field Station#</b> 11360+54			
<b>Pic 11 Desc.</b> Section of RoW showing conditions and controls.		<b>Pic 12 Desc.</b> S-KL43.			

<b>AFE</b> 124300137	<b>Date/Time</b> 8/18/2022 7:02 AM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41147	
<b>Inspector</b> Chris Burns		<b>Date/Time</b> 8/18/2022 7:02 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11353+67
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	11471+56
<b>County</b> Giles	<b>Ground</b> Wet	<b>Temperature (°F)</b>	73.00
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/18/2022 7:02 AM	<b>Report #</b> 41147
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Level Spreader	Acceptable			
Other	Acceptable			







**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)

See photos for GPS coordinates.  
 Met with environmental staff.  
 Performed SWPPP inspection from MP 215.04 (11353+67) and MP 217.26 (11471+56).  
 Accompanied by fellow EI David Schoolcraft.  
 PPL crews conducting vegetative maintenance in this area.  
 Robert's Corrosion currently installing temporary anode beds at three locations, 11462+15, 11446+46 and 11410+00.  
 This section of RoW is partially restored.  
 All perimeter controls, ECDs and BMPs functional at time of inspection.  
 Vegetation or stabilization sufficient.  
 No impact to sensitive resources observed.  
 Section 6 - other (waterbars).

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 8/18/2022 7:02 AM		Report #	
Pictures					
					
<b>GPS Location</b> 1		<b>GPS Location</b> 2			
<b>Field Station#</b> 11469+00		<b>Field Station#</b> 11462+00			
<b>Pic 1 Desc.</b> Section of RoW showing conditions and controls.		<b>Pic 2 Desc.</b> Crews performing vegetative maintenance.			
					
<b>GPS Location</b> 3		<b>GPS Location</b> 4			
<b>Field Station#</b> 11451+87		<b>Field Station#</b> 11451+08			
<b>Pic 3 Desc.</b> S-0012.		<b>Pic 4 Desc.</b> S-0013			
					
<b>GPS Location</b> 5		<b>GPS Location</b> 6			
<b>Field Station#</b> 11448+93		<b>Field Station#</b> 11438+75			
<b>Pic 5 Desc.</b> S-0014/W-CD12.		<b>Pic 6 Desc.</b> Section of restored RoW showing conditions and controls.			

AFE 124300137		Date/Time 8/18/2022 7:02 AM		Report #	
Pictures					
					
<b>GPS Location</b> 7		<b>GPS Location</b> 8			
<b>Field Station#</b> 11431+00		<b>Field Station#</b> 11413+00			
<b>Pic 7 Desc.</b> Representative photo of permanent waterbar and level spreaders installed.		<b>Pic 8 Desc.</b> Section of restored RoW showing conditions and controls.			
					
<b>GPS Location</b> 9		<b>GPS Location</b> 10			
<b>Field Station#</b> 11397+00		<b>Field Station#</b> 11387+00			
<b>Pic 9 Desc.</b> Section of restored RoW showing conditions and controls.		<b>Pic 10 Desc.</b> Section of restored RoW showing conditions and controls.			
					
<b>GPS Location</b> 11		<b>GPS Location</b> 12			
<b>Field Station#</b> 11367+00		<b>Field Station#</b> 11360+54			
<b>Pic 11 Desc.</b> Section of RoW showing conditions and controls.		<b>Pic 12 Desc.</b> S-KL43.			

<b>AFE</b> 124300137	<b>Date/Time</b> 8/18/2022 7:02 AM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41144	
<b>Inspector</b> Eric Hanlon		<b>Date/Time</b> 8/18/2022 6:49 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11254+99
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b>	11353+67
<b>County</b> Giles	<b>Ground</b> Damp	<b>Temperature (°F)</b>	60.00
<b>Municipality</b> N/A	<b>Weather</b> Cloudy	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |



<b>AFE</b> 124300137	<b>Date/Time</b> 8/18/2022 6:49 AM	<b>Report #</b> 41144
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)

Completed a VA SWPPP inspection from ST# 11254+99 (MP 213.6) to ST# 11353+67 (MP 215.04).  
 No Compliance issues noted:  
 Observance:  
 Crew working on vegetative maintenance on access road 253.01.  
 ROW has been temporary stabilized.  
 No areas with open ditch.  
 All other ECDs and BMPs functional at time of inspection.  
 50' buffers in place at stream crossings S-MM18, S-NN12 and S-NN11.  
 AR-253.02, 256.02 & 256 road crossing RCEs are maintained in acceptable condition.  
 The ROW is damp and in stable condition.  
 No sensitive resources have been impacted.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/18/2022 6:49 AM	Report #
<b>Pictures</b>				
 <p>Date &amp; Time: Thu, Aug 18, 2022, 06:47:21 EDT Position: +38.202187° / -080.49797° (-14.27) Altitude: 2237 ft (-13.27) Datum: WGS-84 Azimuth/Bearing: 337° S43W 488mils True (-13°) Elevation Angle: -16.3° Horizon Angle: +01.2° Zoom: 1.0X 11285.00</p>	 <p>Date &amp; Time: Thu, Aug 18, 2022, 06:50:27 EDT Position: +38.202187° / -080.49797° (-14.27) Altitude: 2237 ft (-13.27) Datum: WGS-84 Azimuth/Bearing: 070° N20E 1244mils True (-13°) Elevation Angle: -13.9° Horizon Angle: +00.1° Zoom: 1.0X 11285.00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11337+00	<b>Field Station#</b>	11328+00	
<b>Pic 1 Desc.</b>	Temporary stabilization in place	<b>Pic 2 Desc.</b>	Resource buffers in place	
 <p>Date &amp; Time: Thu, Aug 18, 2022, 08:22:09 EDT Position: +37.22226° / -080.48173° (-14.14) Altitude: 2131 ft (-13.4th) Datum: WGS-84 Azimuth/Bearing: 078° N78E 1387mils True (-12°) Elevation Angle: -16.4° Horizon Angle: +03.4° Zoom: 1.0X 11293.00</p>	 <p>Date &amp; Time: Thu, Aug 18, 2022, 08:22:15 EDT Position: +37.225962° / -080.48383° (-14.15) Altitude: 2255 ft (-11.7th) Datum: WGS-84 Azimuth/Bearing: 075° N75E 1339mils True (-12°) Elevation Angle: -15.8° Horizon Angle: +03.6° Zoom: 1.0X 11285.00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11293+00	<b>Field Station#</b>	11285+00	
<b>Pic 3 Desc.</b>	Equipment bridge functional	<b>Pic 4 Desc.</b>	Picture showing condition of row	
 <p>Date &amp; Time: Thu, Aug 18, 2022, 08:19:35 EDT Position: +38.202187° / -080.49797° (-14.27) Altitude: 2237 ft (-13.27) Datum: WGS-84 Azimuth/Bearing: 137° S43E 2436mils True (-12°) Elevation Angle: -14.9° Horizon Angle: +02.5° Zoom: 1.0X 11271.00</p>	 <p>Date &amp; Time: Thu, Aug 18, 2022, 08:11:10 EDT Position: +38.202187° / -080.49797° (-14.27) Altitude: 2237 ft (-13.27) Datum: WGS-84 Azimuth/Bearing: 270° S43W 480mils True (-13°) Elevation Angle: -2.9° Horizon Angle: +03.3° Zoom: 1.0X 11255.00</p>			
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo	
<b>Field Station#</b>	11271+00	<b>Field Station#</b>	11256+00	
<b>Pic 5 Desc.</b>	Plunge pool in place	<b>Pic 6 Desc.</b>	Water bars and ET in place	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/18/2022 6:49 AM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**



Insert image here

<b>GPS Location</b>	See photo	<b>GPS Location</b>	
---------------------	-----------	---------------------	--

<b>Field Station#</b>	11353+67	<b>Field Station#</b>	
-----------------------	----------	-----------------------	--

<b>Pic 7 Desc.</b>	RCE functional	<b>Pic 8 Desc.</b>	
--------------------	----------------	--------------------	--

Insert image here

Insert image here

<b>GPS Location</b>		<b>GPS Location</b>	
---------------------	--	---------------------	--

<b>Field Station#</b>		<b>Field Station#</b>	
-----------------------	--	-----------------------	--

<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	
--------------------	--	---------------------	--

Insert image here

Insert image here

<b>GPS Location</b>		<b>GPS Location</b>	
---------------------	--	---------------------	--

<b>Field Station#</b>		<b>Field Station#</b>	
-----------------------	--	-----------------------	--

<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	
---------------------	--	---------------------	--

<b>AFE</b> 124300137	<b>Date/Time</b> 8/18/2022 6:49 AM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41172	
<b>Inspector</b> Jared Saunders		<b>Date/Time</b> 8/18/2022 2:26 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11471+56
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b>	11524+15
<b>County</b> Giles	<b>Ground</b> Dry	<b>Temperature (°F)</b>	83.00
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/18/2022 2:26 PM	<b>Report #</b> 41172
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from ST# 11471+56 (Steele Acres) to ST# 11524+16 (AR-258.02)  
 VA SWPPP inspection of MP 217.26 to MP 218.26  
 No deficiencies were located during inspection.  
 Environmental crew observed working in section of ROW inspected. Crew was conducting vegetative maintenance along LOD and topsoil spoil piles.  
 This section of ROW has undergone temporary stabilization. Topsoil stock piles and cleanwater diversion berms have been stabilized.  
 Slope drains with stone inlet protection, Perimeter controls, and waterbars with end treatments are in place.  
 Triple protection ECDs are in place at karst feature.  
 Sensitive resource buffers are in place at stream crossings S-PP3, and S-PP4.  
 AR-258.01, 258.02, and Stever's Gap road crossing RCEs are maintained in acceptable condition.  
 No sensitive resources have been impacted.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/18/2022 2:26 PM	Report #	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.		
<b>Field Station#</b>	11473+00	<b>Field Station#</b>	11480+00		
<b>Pic 1 Desc.</b>	Triple barrier ECDs in place along LOD where off ROW karst feature is located.	<b>Pic 2 Desc.</b>	Clean water drainage feature in place.		
					
<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.		
<b>Field Station#</b>	11503+00	<b>Field Station#</b>	11505+00		
<b>Pic 3 Desc.</b>	Rock line channel in place.	<b>Pic 4 Desc.</b>	Clean water diversion pipe and plunge pool in place.		
					
<b>GPS Location</b>	See photo for GPS location.	<b>GPS Location</b>	See photo for GPS location.		
<b>Field Station#</b>	11496+00	<b>Field Station#</b>	11519+00		
<b>Pic 5 Desc.</b>	Priority one silt fence in place along LOD.	<b>Pic 6 Desc.</b>	Sensitive resource buffer in place at stream S-PP4.		

<b>AFE</b> 124300137	<b>Date/Time</b> 8/18/2022 2:26 PM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	



<b>A/E</b>	124300137	<b>Date/Time</b>	8/18/2022 2:26 PM	<b>Report #</b>	
------------	-----------	------------------	-------------------	-----------------	--

<b>Pictures</b>					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41164	
<b>Inspector</b> Rob Robertson		<b>Date/Time</b> 8/18/2022 11:34 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 11524+16	
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b> 11600+01	
<b>County</b> Montgomery	<b>Ground</b> Damp	<b>Temperature (°F)</b> 68.00	
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b> 0.00	
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)	Communication	Repair livestock damaged P1		
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Rock Construction Entrance	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/18/2022 11:34 AM	<b>Report #</b> 41164
----------------------	-------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Level Spreader	Acceptable			

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)







Completed a regular scheduled VADEQ SWPPP inspection on private and JNF lands located between access road CR-259.02 and Craig Creek Road. The ROW remains in stable condition with no rilling, channeling or gulying of soils occurring. Temporary and permanent grasses are established in adequate amounts to hold the surface. ECDs are in place with only one maintenance need identified. Livestock damage occurred to P1 silt fencing at 11526+57. No impact resulted from the damage. Worn CFS will be replaced before any surface disturbance occurs. The contractor will be notified and appropriate repair completed. Slope breakers, sumps and end treatments are functioning properly. Resource buffers are well vegetated with ECDs in place. There has not been any impact to resources crossed or adjacent to the LOD. RCEs and access roads are in good condition. No environmental concerns were identified.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/18/2022 11:34 AM	Report #	
<b>Pictures</b>					
 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 11:34:01 EDT Position: +037.324099 / -080.413181 (+30.0m) Altitude: 82.9m (+24.0m) Datum: WGS-84 Azimuth/Bearing: 112.5385° 254mils Magnetic (+13°) Elevation Angle: -0.2° Horizon Angle: -0.0° Zoom: 1.0X 11526+57</small></p>		 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 09:49:21 EDT Position: +037.325530 / -080.416373 (+30.0m) Altitude: 79.9m (+22.0m) Datum: WGS-84 Azimuth/Bearing: 155° 534E 254mils Magnetic (+13°) Elevation Angle: -0.2° Horizon Angle: -0.2° Zoom: 1.0X 11537+50</small></p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11526+57	<b>Field Station#</b>	11537+50		
<b>Pic 1 Desc.</b>	COMMUNICATION; livestock damage to P1 silt fence. Contractor will be notified via punch list.	<b>Pic 2 Desc.</b>	Good vegetation. ECDs in place. No erosion taking place.		
 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 09:41:58 EDT Position: +037.323833 / -080.416843 (+30.0m) Altitude: 79.6m (+23.0m) Datum: WGS-84 Azimuth/Bearing: 164.536E 254mils Magnetic (+12°) Elevation Angle: -14.2° Horizon Angle: -00.1° Zoom: 1.0X 11545+00</small></p>		 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 09:12:42 EDT Position: +037.325530 / -080.416373 (+30.0m) Altitude: 82.9m (+24.0m) Datum: WGS-84 Azimuth/Bearing: 109.537E 254mils Magnetic (+12°) Elevation Angle: -15.3° Horizon Angle: -02.5° Zoom: 1.0X 11548+50</small></p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11545+00	<b>Field Station#</b>	11548+50		
<b>Pic 3 Desc.</b>	ROW stable with ECDs in place. No movement of sediment.	<b>Pic 4 Desc.</b>	ROW stable. Vegetation and erosion control blanket holding surface soils. ECDs in place.		
 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 10:00:33 EDT Position: +037.324099 / -080.413181 (+30.0m) Altitude: 82.9m (+24.0m) Datum: WGS-84 Azimuth/Bearing: 160.520E 284mils Magnetic (+12°) Elevation Angle: -28.4° Horizon Angle: -00.1° Zoom: 1.0X 11554+00</small></p>		 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 10:00:33 EDT Position: +037.324099 / -080.413181 (+30.0m) Altitude: 82.9m (+24.0m) Datum: WGS-84 Azimuth/Bearing: 038° N86E 0640mils Magnetic (+13°) Elevation Angle: -22.2° Horizon Angle: -00.2° Zoom: 1.0X 11555+00</small></p>			
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo		
<b>Field Station#</b>	11554+00	<b>Field Station#</b>	11555+00		
<b>Pic 5 Desc.</b>	Good vegetation on steep slope. No erosion. ECDs in place.	<b>Pic 6 Desc.</b>	Heavy vegetation. No erosion taking place. ECDs in place.		

<b>AFE</b>	124300137	<b>Date/Time</b>	8/18/2022 11:34 AM	<b>Report #</b>	
------------	-----------	------------------	--------------------	-----------------	--

## Pictures

 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 10:13:31 EDT Position: +433.41630 / -839.41310 (±5.0m) Altitude: 780m (±8.0m) Datum: WGS-84 Azimuth/Bearing: 029° N47E 834mils Magnetic (±12°) Elevation Angle: +5.2° Horizon Angle: +0.7° Zoom: 1.0X 11566+00</small></p>		 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 10:10:42 EDT Position: +433.41630 / -839.41310 (±5.0m) Altitude: 779m (±8.0m) Datum: WGS-84 Azimuth/Bearing: 221° S51W 319mils Magnetic (±12°) Elevation Angle: +25.7° Horizon Angle: +05.0° Zoom: 1.0X 11567+83 S-PP22</small></p>	
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo
<b>Field Station#</b>	11566+00	<b>Field Station#</b>	11568+22
<b>Pic 7 Desc.</b>	ROW stable. ECDs in place.	<b>Pic 8 Desc.</b>	The S-PP22 crossing is stable.
 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 10:33:04 EDT Position: +437.22460 / -880.41210 (±5.0m) Altitude: 753m (±8.0m) Datum: WGS-84 Azimuth/Bearing: 306° N54W 542mils Magnetic (±12°) Elevation Angle: +5.2° Horizon Angle: +03.7° Zoom: 1.0X 11573+50</small></p>		 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 10:31:57 EDT Position: +437.22460 / -880.41210 (±5.0m) Altitude: 625m (±8.0m) Datum: WGS-84 Azimuth/Bearing: 286° N74W 598mils Magnetic (±12°) Elevation Angle: +07.7° Horizon Angle: +00.2° Zoom: 1.0X S-PP21</small></p>	
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo
<b>Field Station#</b>	11573+50	<b>Field Station#</b>	11585+48
<b>Pic 9 Desc.</b>	ROW stable. Good vegetation coverage with ECDs in place.	<b>Pic 10 Desc.</b>	The S-PP21 crossing is stable with no impact.
 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 10:35:58 EDT Position: +437.21672 / -880.40971 (±5.0m) Altitude: 623m (±8.0m) Datum: WGS-84 Azimuth/Bearing: 177° S70E 514mils Magnetic (±12°) Elevation Angle: +02.2° Horizon Angle: +00.4° Zoom: 1.0X S-PP20</small></p>		 <p><small>Date &amp; Time: Thu, Aug 18, 2022, 10:37:19 EDT Position: +437.21672 / -880.40971 (±5.0m) Altitude: 623m (±8.0m) Datum: WGS-84 Azimuth/Bearing: 327° N54W 572mils Magnetic (±12°) Elevation Angle: +00.5° Horizon Angle: +00.5° Zoom: 1.0X 11595+00</small></p>	
<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo
<b>Field Station#</b>	11588+41	<b>Field Station#</b>	11595+00
<b>Pic 11 Desc.</b>	The S-PP20 crossing is stable.	<b>Pic 12 Desc.</b>	ROW stable with ECDs in place.

<b>A/E</b>	124300137	<b>Date/Time</b>	8/18/2022 11:34 AM	<b>Report #</b>	
------------	-----------	------------------	--------------------	-----------------	--

<b>Pictures</b>					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41190	
<b>Inspector</b> Eric Hanlon		<b>Date/Time</b> 8/19/2022 6:59 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b> 11899+89	
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b> 12005+00	
<b>County</b> Giles	<b>Ground</b> Damp	<b>Temperature (°F)</b> 65.00	
<b>Municipality</b> N/A	<b>Weather</b> Cloudy	<b>Rain Gauge (in)</b> 0.00	
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Housekeeping	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/19/2022 6:59 AM	<b>Report #</b> 41190
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Level Spreader	Acceptable			
Other	Acceptable			













**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)

Completed on a VA SWPPP inspection from ST# 11899+89 (MP 225.37) to ST# 12005+00 (MP 227.37).  
 No Compliance issues noted:  
 Observance:  
 Perimeter controls in place but are very aged.  
 Permanent water bars (other) and level spreader in place. Some are of an earlier design.  
 ROW has temporary and permanent stabilization.  
 No areas with open ditch.  
 All other ECDs and BMPs functional at time of inspection.  
 AR-266.03, 266 Catawba road crossing RCEs are maintained in acceptable condition.  
 The ROW is damp and in stable condition.  
 No sensitive resources have been impacted.


**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.



AFE	124300137	Date/Time	8/19/2022 6:59 AM	Report #	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11929+24	<b>Field Station#</b>	11985+00		
<b>Pic 1 Desc.</b>	Check dams and erosion control blanket in place	<b>Pic 2 Desc.</b>	Permanent stabilization in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11948+00	<b>Field Station#</b>	11944+00		
<b>Pic 3 Desc.</b>	Water bars in place	<b>Pic 4 Desc.</b>	Permanent stabilization in place		
					
<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo		
<b>Field Station#</b>	11917+00	<b>Field Station#</b>	11907+00		
<b>Pic 5 Desc.</b>	Perimeter controls in place	<b>Pic 6 Desc.</b>	Permanent water bars and level spreader in place		

<b>AFE</b>	124300137	<b>Date/Time</b>	8/19/2022 6:59 AM	<b>Report #</b>	
------------	-----------	------------------	-------------------	-----------------	--

**Pictures**



<b>GPS Location</b>	See photo	<b>GPS Location</b>	See photo
---------------------	-----------	---------------------	-----------

<b>Field Station#</b>	11995+00	<b>Field Station#</b>	11899+89
-----------------------	----------	-----------------------	----------

<b>Pic 7 Desc.</b>	Permanent stabilization in place	<b>Pic 8 Desc.</b>	Broad base dips functional
--------------------	----------------------------------	--------------------	----------------------------

Insert image here

Insert image here

<b>GPS Location</b>		<b>GPS Location</b>	
---------------------	--	---------------------	--

<b>Field Station#</b>		<b>Field Station#</b>	
-----------------------	--	-----------------------	--

<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	
--------------------	--	---------------------	--

Insert image here

Insert image here

<b>GPS Location</b>		<b>GPS Location</b>	
---------------------	--	---------------------	--

<b>Field Station#</b>		<b>Field Station#</b>	
-----------------------	--	-----------------------	--

<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	
---------------------	--	---------------------	--

<b>AFE</b> 124300137	<b>Date/Time</b> 8/19/2022 6:59 AM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41234	
<b>Inspector</b> David Schoolcraft		<b>Date/Time</b> 8/19/2022 7:48 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11670+00
<b>State</b> VA	<b>Inspection Area</b> Full	<b>Station End</b>	11788+52
<b>County</b> Montgomery	<b>Ground</b> Damp	<b>Temperature (°F)</b>	74.00
<b>Municipality</b> N/A	<b>Weather</b> Sunny	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/19/2022 7:48 PM	<b>Report #</b> 41234
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Met with environmental team  
 Performed Va SWPPP inspection from MP 221.02 (11670+00) to MP 223.27 (11788+52)  
 This section of ROW has no current construction.  
 No deficiencies found.  
 All perimeter controls, ECDs and BMPs functional at time of inspection. Stream buffers and controls in place at the time of inspection.  
 No sensitive resources have been impacted

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 8/19/2022 7:48 PM		Report #			
Pictures							
 <p>Date &amp; Time: Fri, Aug 19, 2022 7:48:03 EDT  Position: +037.2232297, -080.3452411  Altitude: 2268ft (691m)  Datum: WGS-84  Azimuth/Bearing: 184.532E 2631mils True (+12°)  Elevation Angle: -03.7°  Horizon Angle: -100.6°  Zoom: 0.5X  11671+00</p>		 <p>Date &amp; Time: Fri, Aug 19, 2022 7:53:18 EDT  Position: +037.2232297, -080.3452411  Altitude: 2268ft (691m)  Datum: WGS-84  Azimuth/Bearing: 148.532E 2631mils True (+12°)  Elevation Angle: -04.5°  Horizon Angle: -00.2°  Zoom: 0.5X  11687+02</p>		GPS Location See Photo		GPS Location See Photo	
Field Station# 11671+00		Field Station# 11687+42		Pic 1 Desc. Waterbars		Pic 2 Desc. Equipment bridge	
 <p>Date &amp; Time: Fri, Aug 19, 2022 7:47:10 EDT  Position: +037.223212, -080.3452411  Altitude: 2269ft (691m)  Datum: WGS-84  Azimuth/Bearing: 112.532E 2169mils True (+12°)  Elevation Angle: -04.5°  Horizon Angle: -083.1°  Zoom: 0.5X  11704+10 SMN22</p>		 <p>Date &amp; Time: Fri, Aug 19, 2022 7:50:46 EDT  Position: +037.2232297, -080.3452411  Altitude: 2218ft (676m)  Datum: WGS-84  Azimuth/Bearing: 676.532E 164mils True (+12°)  Elevation Angle: -07.0°  Horizon Angle: -01.2°  Zoom: 0.5X  11724+00</p>		GPS Location See Photo		GPS Location See Photo	
Field Station# 11704+10		Field Station# 11724+00		Pic 3 Desc. S-MN22		Pic 4 Desc. Perimeter controls	
 <p>Date &amp; Time: Fri, Aug 19, 2022 10:18:08 EDT  Position: +037.2232297, -080.3452411  Altitude: 2032ft (620m)  Datum: WGS-84  Azimuth/Bearing: 044.532E 1038mils True (+12°)  Elevation Angle: -05.9°  Horizon Angle: -01.9°  Zoom: 0.5X  11766+00</p>		 <p>Date &amp; Time: Fri, Aug 19, 2022 10:19:55 EDT  Position: +037.2232297, -080.3452411  Altitude: 2040ft (621m)  Datum: WGS-84  Azimuth/Bearing: 007E 0458mils True (+12°)  Elevation Angle: -01.9°  Horizon Angle: -011.4°  Zoom: 0.5X  11766+80</p>		GPS Location See Photo		GPS Location See Photo	
Field Station# 11766+00		Field Station# 11766+80		Pic 5 Desc. Section of row showing conditions and controls		Pic 6 Desc. RCE	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/19/2022 7:48 PM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/19/2022 7:48 PM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	





# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41243	
<b>Inspector</b> Jared Saunders		<b>Date/Time</b> 8/19/2022 3:06 PM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11788+52
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	11899+89
<b>County</b> Montgomery	<b>Ground</b> Damp	<b>Temperature (°F)</b>	75.00
<b>Municipality</b> N/A	<b>Weather</b> Cloudy	<b>Rain Gauge (in)</b>	0.00
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/19/2022 3:06 PM	<b>Report #</b> 41243
----------------------	------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)













<b>PCSM BMPs</b>	<b>Compliance Level</b>	<b>Corrective Action</b>	<b>Corrective Time Frame</b>	<b>Date Repaired</b>
Level Spreader	Acceptable			
Other	Acceptable			

**7. Identify all remedial measures that have been taken since the previous inspection was conducted.**

**Comments** (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from ST# 11788+52 (Mount Tabor Road) to ST# 11899+89 (AR 266.03) MP 223.27 to MP 225.37.  
 No compliance issues found.  
 No environmental crews observed working in area of ROW inspected.  
 Active construction site; additional deficiencies may be identified by other EIs.  
 This section of ROW has undergone permanent restoration. Permanent waterbars (section 6 other) with level spreaders in place where designated on E&S sheets. Perimeter controls have been removed due to final restoration vegetation growth. The only remaining ECDs exist around the Mount tabor RCE and along AR 266.03.  
 AR 266.03 and Mount Tabor road crossing RCEs are maintained in acceptable condition.  
 No sensitive resources have been impacted.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/19/2022 3:06 PM	Report #	
<b>Pictures</b>					
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11885+00		<b>Field Station#</b>	11864+00	
<b>Pic 1 Desc.</b>	ROW permanently restored.		<b>Pic 2 Desc.</b>	Sensitive resource P-KL2.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11855+00		<b>Field Station#</b>	11830+00	
<b>Pic 3 Desc.</b>	ROW permanently restored. waterbars with level spreaders in place.		<b>Pic 4 Desc.</b>	ROW permanently restored. waterbars with level spreaders in place.	
					
<b>GPS Location</b>	See photo for GPS location.		<b>GPS Location</b>	See photo for GPS location.	
<b>Field Station#</b>	11789+00		<b>Field Station#</b>	11788+75	
<b>Pic 5 Desc.</b>	Super silt fence in place along LOD.		<b>Pic 6 Desc.</b>	RCE in place at Mount Tabor Road.	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/19/2022 3:06 PM	<b>Report #</b>
----------------------	------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 7 Desc.</b>		<b>Pic 8 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 9 Desc.</b>		<b>Pic 10 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 11 Desc.</b>		<b>Pic 12 Desc.</b>	

<b>A/E</b>	124300137	<b>Date/Time</b>	8/19/2022 3:06 PM	<b>Report #</b>	
------------	-----------	------------------	-------------------	-----------------	--

<b>Pictures</b>					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here		Insert image here	
-------------------	--	-------------------	--

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	



# Visual Site Inspection Report

<b>Project Name</b> H-600 Pipeline Spread G		<b>AFE</b> 124300137	<b>Spread</b> H-600 Pipeline Spread G
<b>Contractor</b> Precision		<b>Report #</b> 41197	
<b>Inspector</b> Rob Robertson		<b>Date/Time</b> 8/19/2022 10:46 AM	
<b>Permit #</b> TBD	<b>Inspection Type</b> VA SWPP	<b>Station Begin</b>	11600+01
<b>State</b> VA	<b>Inspection Area</b> Partial	<b>Station End</b>	11670+00
<b>County</b> Montgomery	<b>Ground</b> Damp	<b>Temperature (°F)</b>	68.00
<b>Municipality</b> N/A	<b>Weather</b> Cloudy	<b>Rain Gauge (in)</b>	0.05
			<b>Rain Accumulation Time (days)</b> 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)	Communication	Replace worn P1		
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Rock Construction Entrance	Acceptable			

- 5. Site Conditions**
- |   |     |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No  |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?   | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?   | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form)  | No  |

<b>AFE</b> 124300137	<b>Date/Time</b> 8/19/2022 10:46 AM	<b>Report #</b> 41197
----------------------	-------------------------------------	-----------------------

**6. PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

**7.** Identify all remedial measures that have been taken since the previous inspection was conducted.

**Comments** (Reference above questions as appropriate.)

Completed a regular scheduled VADEQ SWPPP inspection on JNF and private property at Brush Mountain. The ROW remains stable with no forms of erosion occurring. Vegetation is heavy on JNF property while sparse on private tracts in this area. Straw mulch is currently adequate to prevent erosion on the private lands. Slope breakers continue to control runoff. Sumps and end treatments are in acceptable condition. Worn CFS located on JNF will be replaced before. Any disturbance occurs. There has not been any impact at resources crossed by the route. Stream buffers are heavily vegetated and ECDs are in place. He contractor has been notified of need to replace worn P1 silt fencing located at 11607+50. No impact has occurred at the site. RCEs are in good condition. No evidence of vandalism was discovered. No environmental concerns identified.

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

<b>AFE</b>	124300137	<b>Date/Time</b>	8/19/2022 10:46 AM	<b>Report #</b>	
------------	-----------	------------------	--------------------	-----------------	--

## Pictures



<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo
<b>Field Station#</b>	11664+00	<b>Field Station#</b>	11658+00
<b>Pic 1 Desc.</b>	ROW stable with ECDs in place.	<b>Pic 2 Desc.</b>	No sediment movement. Runoff being properly controlled.



<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo
<b>Field Station#</b>	11656+00	<b>Field Station#</b>	11646+00
<b>Pic 3 Desc.</b>	ROW stable. No movement of soils taking place.	<b>Pic 4 Desc.</b>	ROW stable. ECDs in place.



<b>GPS Location</b>	On photo	<b>GPS Location</b>	On photo
<b>Field Station#</b>	11627+50	<b>Field Station#</b>	11626+04
<b>Pic 5 Desc.</b>	No erosion occurring. ECDs in place.	<b>Pic 6 Desc.</b>	The S-HH18 crossing is stable.



<b>AFE</b>	124300137	<b>Date/Time</b>	8/19/2022 10:46 AM	<b>Report #</b>	
------------	-----------	------------------	--------------------	-----------------	--

## Pictures



<b>GPS Location</b>	On photo
<b>Field Station#</b>	11614+75
<b>Pic 7 Desc.</b>	Perimeter ECDs are functional.

<b>GPS Location</b>	On photo
<b>Field Station#</b>	11614+20
<b>Pic 8 Desc.</b>	The S-RR14 crossing is stable.



<b>GPS Location</b>	On photo
<b>Field Station#</b>	11607+81
<b>Pic 9 Desc.</b>	The S-006 crossing is stable.

<b>GPS Location</b>	On photo
<b>Field Station#</b>	11607+50
<b>Pic 10 Desc.</b>	COMMUNICATION. Replace worn P1 silt fence.



Insert image here

<b>GPS Location</b>	On photo
<b>Field Station#</b>	11601+50
<b>Pic 11 Desc.</b>	ROW stable. No issues caused by runoff.

<b>GPS Location</b>	
<b>Field Station#</b>	
<b>Pic 12 Desc.</b>	

<b>AFE</b> 124300137	<b>Date/Time</b> 8/19/2022 10:46 AM	<b>Report #</b>
----------------------	-------------------------------------	-----------------

**Pictures**

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 13 Desc.</b>		<b>Pic 14 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 15 Desc.</b>		<b>Pic 16 Desc.</b>	

Insert image here	Insert image here
-------------------	-------------------

<b>GPS Location</b>		<b>GPS Location</b>	
<b>Field Station#</b>		<b>Field Station#</b>	
<b>Pic 17 Desc.</b>		<b>Pic 18 Desc.</b>	