



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40724	
Inspector Joe Sweeden		Date/Time 8/8/2022 6:53 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11254+99	
State VA	Inspection Area Partial	Station End 11353+67	
County Giles	Ground Wet	Temperature (°F) 80.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.40	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/8/2022 6:53 AM	Report # 40724
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed Virginia SWPP inspection from station # 11254+99-11353+67 (MP 213.6-215.04) Rte 42 - Old Furnace, with EI, Eric Hanlon.
 No Deficiencies found today.

Observances:
 The ROW in this area received approximately .40" of precipitation over the last 24 hours.
 The ROW was wet.
 Multiple environmental crews were in the area cutting vegetation and repairing previous PL items
 The ROW has been temporarily stabilized.
 Karst areas have occurred in sumps at station 11348+00.areas are protected with ECDs. The water bars and compost sock are in good condition.
 Steep slopes have had erosion control fabric placed on them. Vegetation is sufficient. Slope drains are functioning as designed.
 ECs at streams are in compliance.
 No trash on the ROW.
 No sensitive resources were impacted.
 All perimeter controls, ECDs and BMPs were functional at time of inspection.
 Rock Road approaches are clean and free of loose rock.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.


AFE 124300137		Date/Time 8/8/2022 6:53 AM		Report #	
Pictures					
 <p>Date & Time: Mon, Aug 08, 2022, 10:07:25 EDT Position: -037.305695, -080.447149 (-16.4N) Altitude: 2008ft (-9.8ft) Datum: WGS-84 Azimuth/Bearing: 233° S53W 41.42mils Magnetic (+12°) Elevation Angle: -19.2° Horizon Angle: -03.1° Zoom: 110X 11353+00 Spread G</p>				 <p>Date & Time: Mon, Aug 08, 2022, 10:05:05 EDT Position: -037.305166, -080.447630 (-16.4N) Altitude: 2048ft (-9.8ft) Datum: WGS-84 Azimuth/Bearing: 319° N42W 56.64mils Magnetic (+12°) Elevation Angle: -18.9° Horizon Angle: -05.7° Zoom: 110X 11351+00 Spread G</p>	
GPS Location		See photo		GPS Location	
Field Station#		11353+00		Field Station#	
Pic 1 Desc.		Old furnace		Pic 2 Desc.	
				Karst environmental controls	
 <p>Date & Time: Mon, Aug 08, 2022, 10:01:27 EDT Position: -037.293959, -080.448389 (-16.4N) Altitude: 2155ft (-9.8ft) Datum: WGS-84 Azimuth/Bearing: 039° N39E 06.93mils Magnetic (+12°) Elevation Angle: -29.6° Horizon Angle: -00.0° Zoom: 110X 11342+00 Spread G</p>				 <p>Date & Time: Mon, Aug 08, 2022, 09:50:34 EDT Position: -037.304664, -080.447690 (-16.4N) Altitude: 2156ft (-9.8ft) Datum: WGS-84 Azimuth/Bearing: 244° S64W 43.88mils Magnetic (+12°) Elevation Angle: -17.5° Horizon Angle: -02.3° Zoom: 110X 11322+00 Spread G</p>	
GPS Location		see photo		GPS Location	
Field Station#		11342+00		Field Station#	
Pic 3 Desc.		Stabilized ROW		Pic 4 Desc.	
				S-NN 12	
 <p>Date & Time: Mon, Aug 08, 2022, 09:22:41 EDT Position: -037.296377, -080.448109 (-16.4N) Altitude: 2123ft (-9.8ft) Datum: WGS-84 Azimuth/Bearing: 243° S83W 46.76mils Magnetic (+12°) Elevation Angle: -21.3° Horizon Angle: -00.7° Zoom: 110X 11293+00 S-MM18 Spread G</p>				 <p>Date & Time: Mon, Aug 08, 2022, 09:12:49 EDT Position: -037.285913, -080.448927 (-16.4N) Altitude: 2301ft (-16.5ft) Datum: WGS-84 Azimuth/Bearing: 100° S80E 107.8mils Magnetic (+5.8°) Elevation Angle: -42.9° Horizon Angle: -01.1° Zoom: 110X 11286+00 Spread G</p>	
GPS Location		see photo		GPS Location	
Field Station#		11293+00		Field Station#	
Pic 5 Desc.		S-MM 18		Pic 6 Desc.	
				Environmental controls	

AFE 124300137	Date/Time 8/8/2022 6:53 AM	Report #
----------------------	-----------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	see photo
Field Station#	11278+00	Field Station#	11258+00
Pic 7 Desc.	Cut vegetation	Pic 8 Desc.	Sumps/water bars/end treatments



GPS Location	GPS Location
Field Station#	Field Station#
Pic 9 Desc.	Pic 10 Desc.



GPS Location	GPS Location
Field Station#	Field Station#
Pic 11 Desc.	Pic 12 Desc.

A/E	124300137	Date/Time	8/8/2022 6:53 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		GPS Location	
Field Station#		Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		GPS Location	
Field Station#		Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.		Pic 17 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		GPS Location	
Field Station#		Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.		Pic 19 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread H		AFE 124300138	Spread H-600 Pipeline Spread H
Contractor Precision		Report # 40745	
Inspector Jonathan Altizer		Date/Time 8/8/2022 3:16 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	12284+75
State VA	Inspection Area Partial	Station End	12443+75
County Montgomery	Ground Wet	Temperature (°F)	90.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	3.20
			Rain Accumulation Time (days) 2.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300138	Date/Time 8/8/2022 3:16 PM	Report # 40745
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.







Comments (Reference above questions as appropriate.)

The VADEQ SWPPP Inspection was performed on this date. An inspection was performed from Station 12284+75 to Station 12443+75. All ECDs observed appeared to be in compliance and well maintained. ROW that has been disturbed and is inactive has been stabilized with either ECB, straw mulch, or temporary or permanent vegetation. Stabilization observed appeared to be adequate. Stream Crossings included in the inspection were S-OO16, S-NN19 and S-NN16. There were no issues noted at stream crossings or their corresponding buffer areas. Access roads MN-276.03 and MN-277.02 were observed and no issues noted.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300138		Date/Time 8/8/2022 3:16 PM		Report #	
Pictures					
GPS Location		See photo		GPS Location	
Field Station#		12284+75		Field Station#	
Pic 1 Desc.		Current ROW conditions. ROW is stable and ECDs are functional.		Pic 2 Desc.	
Pic 2 Desc.		Current ROW conditions. ROW is stable and ECDs are functional.			
GPS Location		See photo		GPS Location	
Field Station#		12309+00		Field Station#	
Pic 3 Desc.		Sump and End Treatment are functional		Pic 4 Desc.	
Pic 4 Desc.		Current ROW conditions. ROW is stable and ECDs are functional.			
GPS Location		See photo		GPS Location	
Field Station#		12316+00		Field Station#	
Pic 5 Desc.		Current ROW conditions. ROW is stable and ECDs are functional.		Pic 6 Desc.	
Pic 6 Desc.		Waterbars are functional			

AFE 124300138		Date/Time 8/8/2022 3:16 PM	Report #
Pictures			
GPS Location	See photo	GPS Location	See photo
Field Station#	12330+00	Field Station#	12336+00
Pic 7 Desc.	Slope drain is functional	Pic 8 Desc.	Current ROW conditions. ROW is stable and ECDs are functional.
GPS Location	See photo	GPS Location	See photo
Field Station#	12362+00	Field Station#	12367+00
Pic 9 Desc.	Current ROW conditions. ROW is stable and ECDs are functional.	Pic 10 Desc.	Current ROW conditions. ROW is stable and ECDs are functional.
GPS Location	See photo	GPS Location	See photo
Field Station#	12374+16	Field Station#	12380+04
Pic 11 Desc.	Looking downstream at Stream S-0016	Pic 12 Desc.	Upstream of crossing at Stream S-NN19

AFE 124300138		Date/Time 8/8/2022 3:16 PM		Report #	
Pictures					
 <p>DIRECTION W (T) 37.24429°N 080.20704°W ACCURACY 4 m DATUM WGS84</p> <p>12380+04 S-NN19 8/8/22, 12:07:37 PM</p>		 <p>DIRECTION S (T) 37.24369°N 080.20642°W ACCURACY 8 m DATUM WGS84</p> <p>12382+00 Drainage feature 8/8/22, 12:10:02 PM</p>			
GPS Location	See photo		GPS Location	See photo	
Field Station#	12380+04		Field Station#	12382+00	
Pic 13 Desc.	Downstream of crossing at Stream S-NN19		Pic 14 Desc.	Drainage feature is functional	
 <p>DIRECTION NW (T) 37.24118°N 080.20186°W ACCURACY 4 m DATUM WGS84</p> <p>12398+00 ROW 8/8/22, 12:19:50 PM</p>		 <p>DIRECTION SE (T) 37.24032°N 080.20017°W ACCURACY 4 m DATUM WGS84</p> <p>12407+00 ROW 8/8/22, 12:22:17 PM</p>			
GPS Location	See photo		GPS Location	See photo	
Field Station#	12398+00		Field Station#	12407+00	
Pic 15 Desc.	Current ROW conditions. ROW is stable and ECDs are functional.		Pic 16 Desc.	Current ROW conditions. ROW is stable and ECDs are functional.	
 <p>DIRECTION SW (T) 37.23778°N 080.19924°W ACCURACY 4 m DATUM WGS84</p> <p>12417+00 ROW 8/8/22, 12:26:54 PM</p>		 <p>DIRECTION N (T) 37.23680°N 080.19953°W ACCURACY 4 m DATUM WGS84</p> <p>12420+00 ROW 8/8/22, 12:29:46 PM</p>			
GPS Location	See photo		GPS Location	See photo	
Field Station#	12417+00		Field Station#	12420+00	
Pic 17 Desc.	Current ROW conditions. ROW is stable and ECDs are functional.		Pic 18 Desc.	Current ROW conditions. ROW is stable and ECDs are functional.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40730	
Inspector Chris Burns		Date/Time 8/8/2022 7:43 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11353+67	
State VA	Inspection Area Partial	Station End 11471+56	
County Giles	Ground Wet	Temperature (°F) 81.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.40	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	See punch list	Addressed	8/8/2022
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/8/2022 7:43 AM	Report # 40730
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)













PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Level Spreader	Acceptable			
Other	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

See photos for GPS coordinates.
 Met with environmental staff.
 Performed SWPPP inspection from MP 215.04 (11353+67) and MP 217.26 (11471+56).
 This section of RoW is partially restored.
 One location of wildlife damage to controls was identified and added to the punch list, following proper notifications.
 Crews made repairs prior to the end of day.
 All other perimeter controls, ECDs and BMPs functional at time of inspection.
 Vegetation or stabilization sufficient.
 No impact to sensitive resources observed.
 Section 6 - other (waterbars).
 Discussed RoW conditions with LEI Brian Shields, Utility Inspector Chris Dollar and PPL Environmental Foreman Patty Wright.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/8/2022 7:43 AM	Report #	
Pictures					
				 	
GPS Location	1		GPS Location	2	
Field Station#	11469+00		Field Station#	11466+00	
Pic 1 Desc.	Section of RoW showing conditions and controls.		Pic 2 Desc.	Repair P-1.	
					
GPS Location	3		GPS Location	4	
Field Station#	11452+87		Field Station#	11451+28	
Pic 3 Desc.	S-0012.		Pic 4 Desc.	S-0013.	
					
GPS Location	5		GPS Location	6	
Field Station#	11448+93		Field Station#	11438+75	
Pic 5 Desc.	S-0014/W-CD12.		Pic 6 Desc.	Section of restored RoW showing conditions and controls.	

AFE	124300137	Date/Time	8/8/2022 7:43 AM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures



GPS Location	7	GPS Location	8
Field Station#	11436+00	Field Station#	11432+50
Pic 7 Desc.	Perimeter controls functional.	Pic 8 Desc.	Representative photo of permanent waterbar and level spreaders installed.



GPS Location	9	GPS Location	10
Field Station#	11409+00	Field Station#	11393+00
Pic 9 Desc.	Section of restored RoW showing conditions and controls.	Pic 10 Desc.	Section of restored RoW showing conditions and controls.




GPS Location	11	GPS Location	12
Field Station#	11385+50	Field Station#	11379+00
Pic 11 Desc.	Section of restored RoW showing conditions and controls.	Pic 12 Desc.	Section of restored RoW showing conditions and controls.

AFE 124300137	Date/Time 8/8/2022 7:43 AM	Report #
----------------------	-----------------------------------	-----------------


Pictures



GPS Location 13	GPS Location 14
Field Station# 11363+00	Field Station# 11360+54
Pic 13 Desc. Section of RoW showing conditions and controls.	Pic 14 Desc. S-KL43.



GPS Location 15	GPS Location
Field Station# 11356+00	Field Station#
Pic 15 Desc. Section of RoW showing conditions and controls.	Pic 16 Desc.



GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40758	
Inspector Jared Saunders		Date/Time 8/8/2022 4:01 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11471+56
State VA	Inspection Area Full	Station End	11524+16
County Giles	Ground Wet	Temperature (°F)	85.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	1.10
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	Punchlist		

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/8/2022 4:01 PM	Report # 40758
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from ST# 11471+56 (Steele Acres) to ST# 11524+16 (AR-258.02)
 VA SWPPP inspection of MP 217.26 to MP 218.26
 Deficiencies found at the following station numbers:
 11505+90 - hole in priority one damaged by livestock. Item communication to the contractor via text message and punchlist.
 Active construction site; additional deficiencies may be identified by other EIs.
 Observed no environmental maintenance crews actively working on this section of ROW at time of inspection.
 This section of ROW has undergone temporary stabilization. Topsoil stock piles and cleanwater diversion berms have been stabilized.
 Slope drains with stone inlet protection, Perimeter controls, and waterbars with end treatments are in place.
 Triple protection ECDs are in place at karst feature.
 Sensitive resource buffers are in place at stream crossings S-PP3, and S-PP4.
 AR-258.01, 258.02, and Stever's Gap road crossing RCEs are maintained in acceptable condition.
 No sensitive resources have been impacted.
 Checked rain gauges at Mount Tabor - 1.1 inches, Catawba Road - 0.6 inches, and Stevers Gap Road - 0.4 inches.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/8/2022 4:01 PM	Report #
Pictures				
 <p><small>Date & Time: Mon, Aug 08, 2022, 05:45:55 EDT Position: +037.324974 / -080.427270 Altitude: 2252ft (686.30) Datum: WGS-84 Azimuth/Bearing: 337° N23W 5991mils True (±15°) Elevation Angle: -17.3° Horizon Angle: -01.4° Zoom: 1.0X 11505+00</small></p>		 <p><small>Date & Time: Mon, Aug 08, 2022, 05:46:25 EDT Position: +037.324974 / -080.427270 Altitude: 2252ft (686.30) Datum: WGS-84 Azimuth/Bearing: 337° N23W 5991mils True (±15°) Elevation Angle: -17.3° Horizon Angle: -01.4° Zoom: 1.0X 11519+00 S-PP4</small></p>		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	11505+90	Field Station#	11519+00	
Pic 1 Desc.	Hole in priority one silt fence caused by livestock damage.		Pic 2 Desc.	Sensitive resource buffer in place at stream S-PP4.
 <p><small>Date & Time: Mon, Aug 08, 2022, 09:24:50 EDT Position: +037.324974 / -080.427270 Altitude: 2160ft (658.2ft) Datum: WGS-84 Azimuth/Bearing: 241° S61W 4284mils True (±14°) Elevation Angle: -22.0° Horizon Angle: -00.4° Zoom: 1.0X 11490+00</small></p>		 <p><small>Date & Time: Mon, Aug 08, 2022, 09:24:56 EDT Position: +037.324974 / -080.427270 Altitude: 2200ft (670.1ft) Datum: WGS-84 Azimuth/Bearing: 294° N66W 3027mils True (±14°) Elevation Angle: -41.4° Horizon Angle: -00.4° Zoom: 1.0X 11481+00</small></p>		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	11490+00	Field Station#	11481+00	
Pic 3 Desc.	RCE in place at Stevers Gap Road.		Pic 4 Desc.	Slope drain in place over fill slope.
 <p><small>Date & Time: Mon, Aug 08, 2022, 09:11:48 EDT Position: +037.324974 / -080.427270 Altitude: 2216ft (675.0ft) Datum: WGS-84 Azimuth/Bearing: 000° N00E 0000mils True (±14°) Elevation Angle: -25.3° Horizon Angle: -01.2° Zoom: 1.0X 11503+00</small></p>		 <p><small>Date & Time: Mon, Aug 08, 2022, 09:26:05 EDT Position: +037.324974 / -080.427270 Altitude: 2231ft (680.3ft) Datum: WGS-84 Azimuth/Bearing: 269° S26W 4427mils True (±15°) Elevation Angle: -43.3° Horizon Angle: -00.7° Zoom: 1.0X 11480+00</small></p>		
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.	
Field Station#	11503+00	Field Station#	11480+00	
Pic 5 Desc.	Rock lined channel in place.		Pic 6 Desc.	Clean water drainage feature in place.

AFE 124300137	Date/Time 8/8/2022 4:01 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE	124300137	Date/Time	8/8/2022 4:01 PM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40737	
Inspector Rob Robertson		Date/Time 8/8/2022 11:23 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11524+16
State VA	Inspection Area Partial	Station End	11600+01
County Montgomery	Ground Wet	Temperature (°F)	76.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.40
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Rock-lined Channel	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/8/2022 11:23 AM	Report # 40737
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Level Spreader	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Completed a regular scheduled VADEQ SWPPP inspection on JNF and private property at Sinking Creek Mountain between access road CR-258.02 and Craig Creek Road. The ROW received approximately 0.4" of rainfall in the past 24 hours. Restored and temporarily stabilized areas are well vegetated or have erosion control blanket in place that is preventing rilling or other forms of erosion. ECDs are in place and effective. There are no issues being created by runoff. Slope breakers are functioning properly. Sumps and end treatments are functional although some of the CFS is worn and must be replaced before any surface disturbance. Resource crossings are stable with no impact to streams crossed by the route or any adjacent resources. Access points are in good condition. No evidence of vandalism was discovered. No environmental concerns identified.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/8/2022 11:23 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	On photo	GPS Location	On photo
Field Station#	11526+57	Field Station#	11531+00
Pic 1 Desc.	ROW stable and ECDs in place. No erosion occurring.	Pic 2 Desc.	ROW stable with no erosion.



GPS Location	On photo	GPS Location	On photo
Field Station#	11545+00	Field Station#	11549+00
Pic 3 Desc.	ROW is stable. No erosion.	Pic 4 Desc.	ROW well vegetated with ECDs in place.



GPS Location	On photo	GPS Location	On photo
Field Station#	11563+25	Field Station#	11565+75
Pic 5 Desc.	No erosion occurring at sumps.	Pic 6 Desc.	Well vegetated ROW and ECDs in place.

AFE	124300137	Date/Time	8/8/2022 11:23 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures

GPS Location	On photo	GPS Location	On photo
Field Station#	11568+22	Field Station#	11573+00
Pic 7 Desc.	The S-PP22 crossing remains stable.	Pic 8 Desc.	ROW stable. ECDs are in place.
GPS Location	On photo	GPS Location	On photo
Field Station#	11583+00	Field Station#	11585+48
Pic 9 Desc.	The ROW is well vegetated and stable. No erosion occurring.	Pic 10 Desc.	The S-PP21 crossing is stable.
GPS Location	On photo	GPS Location	On photo
Field Station#	11588+41	Field Station#	11595+00
Pic 11 Desc.	The S-PP20 crossing is stable.	Pic 12 Desc.	Slope breakers, sumps and end treatments are effective at control of runoff.

AFE 124300137	Date/Time 8/8/2022 11:23 AM	Report #
----------------------	------------------------------------	-----------------

Pictures			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40786	
Inspector David Schoolcraft		Date/Time 8/9/2022 11:24 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	12005+00
State VA	Inspection Area Full	Station End	12005+00
County Giles	Ground Dry	Temperature (°F)	91.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Broad-Based Dip	Acceptable			
Secondary Containment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/9/2022 11:24 AM	Report # 40786
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.


Comments (Reference above questions as appropriate.)

Completed a VA SWPPP at LY 026.
 The perimeter controls CFS functioning properly.
 RCE was clean and functioning
 The yard was free of debris. Used oils were stored properly in secondary containment. The generator and air compressor were in secondary containment that was maintained properly.
 All other ECDs were clean of sediment and functioning properly.
 Trash bns clearly identified and in good condition
 Housekeeping was in good condition.
 Construction of a neighboring company ongoing
 Giles county is currently installing stormwater system and any damaged ECDs will be replaced upon completion off project.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/9/2022 11:24 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	See Photo	GPS Location	See Photo
Field Station#	12005+00	Field Station#	12005+00
Pic 1 Desc.	Fuel cell and secondary containment	Pic 2 Desc.	Trash containers and housekeeping



GPS Location	See Photo	GPS Location	See Photo
Field Station#	12005+00	Field Station#	12005+00
Pic 3 Desc.	Secondary Containment	Pic 4 Desc.	Secondary Containment



GPS Location	See Photo	GPS Location	See Photo
Field Station#	12005+00	Field Station#	12005+00
Pic 5 Desc.	RCE	Pic 6 Desc.	Perimeter controls

AFE 124300137	Date/Time 8/9/2022 11:24 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 8/9/2022 11:24 AM	Report #
----------------------	------------------------------------	-----------------

Pictures			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40807	
Inspector Daniel Fortune		Date/Time 8/9/2022 6:07 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	12005+00
State VA	Inspection Area Partial	Station End	12005+00
County Giles	Ground Dry	Temperature (°F)	82.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/9/2022 6:07 PM	Report # 40807
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Completed a SWPPP inspection for LY 028 (12005+00)
 No Deficiencies recorded for repairs today.
 Waste management control bin on site with no trash or debris in the yard. Perimeter controls in place and functional as intended. The yard area received approximately 0."of precipitation over the last 24 hours. This yard has porta- Jon's stored throughout. No Trash or debris around. The Transit busses remain parked with no leaks visible at the time of inspection. Entry to the yard has functional CFS installed. No Issues At this time.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/9/2022 6:07 PM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	12005+00	Field Station#	12005+00
-----------------------	----------	-----------------------	----------

Pic 1 Desc.	RCE to LY028. No Issues at this time.	Pic 2 Desc.	RCE and Truck storage area.
--------------------	---------------------------------------	--------------------	-----------------------------



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	12005+00	Field Station#	12005+00
-----------------------	----------	-----------------------	----------

Pic 3 Desc.	RCE and trash receptacle area. No Issues at this time.	Pic 4 Desc.	Logging trailers and float trailer storage area.
--------------------	--	--------------------	--



GPS Location	See photo	GPS Location	
---------------------	-----------	---------------------	--

Field Station#	12005+00	Field Station#	
-----------------------	----------	-----------------------	--

Pic 5 Desc.	Perimeter CFS controls found functional.	Pic 6 Desc.	
--------------------	--	--------------------	--

AFE 124300137	Date/Time 8/9/2022 6:07 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 8/9/2022 6:07 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40790	
Inspector Joe Sweeden		Date/Time 8/9/2022 11:49 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	12005+00
State VA	Inspection Area Full	Station End	12005+00
County Giles	Ground Damp	Temperature (°F)	81.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	0.00
Rain Accumulation Time (days)			1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waste Management	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

A/E	124300137	Date/Time	8/9/2022 11:49 AM	Report #	40790
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.


Comments (Reference above questions as appropriate.)

Performed VA SWPP at Yard 29.
 Observances:
 No activity in Yard.
 Vegetation around yard is sufficient.
 The Yard received no precipitation in the last 24 hours.
 Equipment in the yard was free of leaks.
 The perimeter compost sock was in place and functioning as designed.
 The rock road approach was clean, no mud or other debris on road.
 The yard was free of debris. No trash was seen.
 Trash receptacles in the Yard were clearly labeled.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/9/2022 11:49 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--


Pictures



GPS Location	See photo	GPS Location	see photo
Field Station#	12005+00	Field Station#	12005+00
Pic 1 Desc.	Yard 29	Pic 2 Desc.	Vegetation




GPS Location	see photo	GPS Location	see photo
Field Station#	12005+00	Field Station#	12005+00
Pic 3 Desc.	Equipment	Pic 4 Desc.	Waste management



GPS Location	see photo	GPS Location	see photo
Field Station#	12005+00	Field Station#	12005+00
Pic 5 Desc.	Compost sock	Pic 6 Desc.	Compost sock

AFE 124300137	Date/Time 8/9/2022 11:49 AM	Report #
----------------------	------------------------------------	-----------------

Pictures



Insert image here

GPS Location	See photo	GPS Location	
---------------------	-----------	---------------------	--

Field Station#	12005+00	Field Station#	
-----------------------	----------	-----------------------	--

Pic 7 Desc.	RCE	Pic 8 Desc.	
--------------------	-----	--------------------	--

Insert image here

Insert image here

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 9 Desc.		Pic 10 Desc.	
--------------------	--	---------------------	--

Insert image here

Insert image here

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 11 Desc.		Pic 12 Desc.	
---------------------	--	---------------------	--

AFE 124300137	Date/Time 8/9/2022 11:49 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40777	
Inspector Joe Sweeden		Date/Time 8/9/2022 6:51 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11899+89	
State VA	Inspection Area Partial	Station End 12005+00	
County Montgomery	Ground Wet	Temperature (°F) 80.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.30	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/9/2022 6:51 AM	Report # 40777
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Level Spreader	Acceptable			
Other	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed VA SWPPP inspection from ST# 11899+89-12005+00,(MP 225.37-227.37), AR 266.03 to Spread break, with EI. Eric Hanlon.
 No deficiencies found:
 Station numbers are approximate.
 ROW received 0.30" of precipitation over the last 24 hours.
 Observed;

The ROW is inundated with woody barbed shrubs, small trees and the invasive grass, Sericea Lespedeza. The vegetation is from chest high to over 7 ft tall.
 The pipe is in the ground through this section and the ROW has been restored. Water bars (other), are built to specifications and functioning as designed.
 The restored area is in good shape and the vegetation is sufficient. The environmental controls are aged, in some areas, but functional. Rock Road approaches were cleaned and functioning as designed.
 The highway at Catawba was clean and free of any loose rock. LOD ECDs were in place and functional.
 There is an area of ditch subsidence at station # 11932+00

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/9/2022 6:51 AM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures



GPS Location	See photo	GPS Location	see photo
---------------------	-----------	---------------------	-----------

Field Station#	11992+00	Field Station#	11970+00
-----------------------	----------	-----------------------	----------


Pic 1 Desc.	Restored ROW	Pic 2 Desc.	Water bars
--------------------	--------------	--------------------	------------



GPS Location	see photo	GPS Location	see photo
---------------------	-----------	---------------------	-----------

Field Station#	11950+00	Field Station#	11936+00
-----------------------	----------	-----------------------	----------

Pic 3 Desc.	Tall trees and brush	Pic 4 Desc.	Compost sock/super silt
--------------------	----------------------	--------------------	-------------------------



GPS Location	see photo	GPS Location	see photo
---------------------	-----------	---------------------	-----------

Field Station#	11929+00	Field Station#	11922+00
-----------------------	----------	-----------------------	----------

Pic 5 Desc.	Woody shrubs	Pic 6 Desc.	Level spreader/ water bar (other)
--------------------	--------------	--------------------	-----------------------------------

AFE 124300137	Date/Time 8/9/2022 6:51 AM	Report #
----------------------	-----------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	11902+00	Field Station#	11917+00
-----------------------	----------	-----------------------	----------


Pic 7 Desc.	Restored ROW	Pic 8 Desc.	Sericea Lespedeza
--------------------	--------------	--------------------	-------------------



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 9 Desc.		Pic 10 Desc.	
--------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 11 Desc.		Pic 12 Desc.	
---------------------	--	---------------------	--

AFE 124300137	Date/Time 8/9/2022 6:51 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40780	
Inspector Chris Burns		Date/Time 8/9/2022 7:13 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11670+00
State VA	Inspection Area Partial	Station End	11788+52
County Montgomery	Ground Wet	Temperature (°F)	84.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.30
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Sump Pit	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE 124300137	Date/Time 8/9/2022 7:13 AM	Report # 40780
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)


See photos for GPS coordinates.
 Met with environmental staff.
 Performed SWPPP inspection from MP 221.02 (11670+00) to MP 223.27 (11788+52).
 Accompanied by fellow EI David Schoolcraft.
 Discussed ECDs, BMPs and RoW conditions with fellow EI David Schoolcraft.
 All perimeter controls, ECDs and BMPs functional at time of inspection.
 No impact to sensitive resources observed.
 Vegetation or stabilization sufficient.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 8/9/2022 7:13 AM		Report #	
Pictures					
					
GPS Location 1		GPS Location 2			
Field Station# 11671+00		Field Station# 11679+00			
Pic 1 Desc. Section of RoW showing conditions and controls.		Pic 2 Desc. Section of RoW showing conditions and controls.			
					
GPS Location 3		GPS Location 4			
Field Station# 11687+42		Field Station# 11699+00			
Pic 3 Desc. Overview S-MN21.		Pic 4 Desc. Perimeter controls functional.			
					
GPS Location 5		GPS Location 6			
Field Station# 11704+10		Field Station# 11709+00			
Pic 5 Desc. S-MN22.		Pic 6 Desc. Section of RoW showing conditions and controls.			

AFE	124300137	Date/Time	8/9/2022 7:13 AM	Report #	
------------	-----------	------------------	------------------	-----------------	--


Pictures



GPS Location	7	GPS Location	8
Field Station#	11723+00	Field Station#	11740+55
Pic 7 Desc.	Section of RoW showing conditions and controls.	Pic 8 Desc.	Overview of S-EF65.



GPS Location	9	GPS Location	10
Field Station#	11743+97	Field Station#	11755+50
Pic 9 Desc.	Overview of S-EF62.	Pic 10 Desc.	Section of RoW showing conditions and controls.



GPS Location	11	GPS Location	12
Field Station#	11767+44	Field Station#	11774+00
Pic 11 Desc.	S-IJ52/W-IJ46.	Pic 12 Desc.	Section of RoW showing conditions and controls.

AFE 124300137	Date/Time 8/9/2022 7:13 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures



Insert image here

GPS Location	13	GPS Location	
---------------------	----	---------------------	--

Field Station#	11788+52	Field Station#	
-----------------------	----------	-----------------------	--

Pic 13 Desc.	RCE off Mt Tabor rd.	Pic 14 Desc.	
---------------------	----------------------	---------------------	--

Insert image here

Insert image here

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 15 Desc.		Pic 16 Desc.	
---------------------	--	---------------------	--

Insert image here

Insert image here

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 17 Desc.		Pic 18 Desc.	
---------------------	--	---------------------	--



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40804	
Inspector Jared Saunders		Date/Time 8/9/2022 4:29 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11899+89
State VA	Inspection Area Full	Station End	11788+52
County Montgomery	Ground Wet	Temperature (°F)	84.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.30
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Broad-Based Dip	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE 124300137	Date/Time 8/9/2022 4:29 PM	Report # 40804
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)


PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Level Spreader	Acceptable			
Other	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from ST# 11788+52 (Mount Tabor Road) to ST# 11899+89 (AR 266.03) MP 223.27 to MP 225.37.
 No compliance issues found.
 Active construction site; additional deficiencies may be identified by other EIs.
 Observed no environmental maintenance crews actively working on this section of ROW at time of inspection.
 This section of ROW has undergone permanent restoration. Permanent waterbars (section 6 other) with level spreaders in place where designated on E&S sheets. Perimeter controls have been removed due to final restoration vegetation growth. The only remaining ECDs exist around the Mount tabor RCE and along AR 266.03.
 AR 266.03 and Mount Tabor road crossing RCEs are maintained in acceptable condition.
 No sensitive resources have been impacted.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/9/2022 4:29 PM	Report #	
Pictures					
					
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.		
Field Station#	11789+00	Field Station#	11789+50		
Pic 1 Desc.	RCE in place at Mount Tabor Road.	Pic 2 Desc.	Super silt fence in place along LOD.		
					
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.		
Field Station#	11855+00	Field Station#	11874+00		
Pic 3 Desc.	Level spreader in place.	Pic 4 Desc.	Permanent waterbar and level spreader in place.		
					
GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.		
Field Station#	11879+00	Field Station#	11790+00		
Pic 5 Desc.	ROW permanently restored.	Pic 6 Desc.	Rain gauge at Mount Tabor Road reads 0.3 inches.		

AFE 124300137	Date/Time 8/9/2022 4:29 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 8/9/2022 4:29 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40795	
Inspector Rob Robertson		Date/Time 8/9/2022 12:42 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11600+01
State VA	Inspection Area Partial	Station End	11670+00
County Montgomery	Ground Damp	Temperature (°F)	77.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/9/2022 12:42 PM	Report # 40795
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Completed a regular scheduled VADEQ SWPPP inspection on JNF and private property at Brush Mountain today. The ROW remains stable with no erosion taking place. Slope breakers, sumps and end treatments are controlling runoff properly. Resource buffers are well vegetated. Resource crossings are stable with no impact occurring at streams. ECDs are in place as needed and required. One maintenance need was identified today. The contractor will be notified of need to replace 50' of worn P1 silt fence from 11662+00 - 11662+50. No other ECDs replacement or repairs needed at this time. It is not practical to replace worn CFS located on the JNF lands at this time. Replacement will be completed prior to any soil disturbance activity. Access points are in good condition. No evidence of vandalism was discovered.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/9/2022 12:42 PM	Report #	
Pictures					
	 <p><small>Date & Time: Tue, Aug 09, 2022, 10:01:11 EDT Position: +037.394267° / +80.394629° (±5.0m) Altitude: 810m (±6.0m) Datum: WGS 84 Azimuth/Bearing: 132.548E 3347mils Magnetic (±10°) Elevation Angle: -01.2 Horizon Angle: -02.2 Zoom: 1.0x 11669+00</small></p>			 <p><small>Date & Time: Tue, Aug 09, 2022, 10:05:40 EDT Position: +037.394267° / +80.394629° (±5.0m) Altitude: 823m (±6.0m) Datum: WGS 84 Azimuth/Bearing: 137.558E 3347mils Magnetic (±10°) Elevation Angle: -00.8 Horizon Angle: -03.1 Zoom: 1.0x 11664+00</small></p>	
GPS Location	On photo		GPS Location	On photo	
Field Station#	11669+00		Field Station#	11664+00	
Pic 1 Desc.	Top of Brush Mountain is stable.		Pic 2 Desc.	ECDs along perimeter in acceptable condition.	
	 <p><small>Date & Time: Tue, Aug 09, 2022, 10:11:32 EDT Position: +037.394697° / +80.394174° (±5.0m) Altitude: 810m (±6.0m) Datum: WGS 84 Azimuth/Bearing: 202.551E 10142mils Magnetic (±10°) Elevation Angle: -21.1 Horizon Angle: -03.4 Zoom: 1.0x 11662+00</small></p>			 <p><small>Date & Time: Tue, Aug 09, 2022, 10:16:17 EDT Position: +037.395247° / +80.394709° (±5.0m) Altitude: 786m (±6.0m) Datum: WGS 84 Azimuth/Bearing: 10° N200.604mils Magnetic (±10°) Elevation Angle: -21.1 Horizon Angle: +03.4 Zoom: 1.0x 11660+00</small></p>	
GPS Location	On photo		GPS Location	On photo	
Field Station#	11662+00		Field Station#	11660+00	
Pic 3 Desc.	COMMUNICATION; p1 silt fence in need of replacement from 11662+00 - 11662+50. The wooden stakes are broken or rotten.		Pic 4 Desc.	ROW stable. No issues from runoff. ECDs in place.	
	 <p><small>Date & Time: Tue, Aug 09, 2022, 10:31:32 EDT Position: +037.398172° / +80.397512° (±5.0m) Altitude: 810m (±6.0m) Datum: WGS 84 Azimuth/Bearing: 003° N03E 0053mils Magnetic (±12°) Elevation Angle: -23.1 Horizon Angle: -00.7 Zoom: 1.0x 11647+00</small></p>			 <p><small>Date & Time: Tue, Aug 09, 2022, 10:31:32 EDT Position: +037.398172° / +80.397512° (±5.0m) Altitude: 814m (±6.0m) Datum: WGS 84 Azimuth/Bearing: -405° N55W 5422mils Magnetic (±12°) Elevation Angle: -14.2 Horizon Angle: -00.7 Zoom: 1.0x 11630+00</small></p>	
GPS Location	On photo		GPS Location	On photo	
Field Station#	11647+00		Field Station#	11630+00	
Pic 5 Desc.	Vegetation coverage very good. ECDs in place.		Pic 6 Desc.	ROW stable. Slope breakers functional. ECDs are in place.	

AFE 124300137	Date/Time 8/9/2022 12:42 PM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	On photo	GPS Location	On photo
Field Station#	11628+00	Field Station#	11626+04
Pic 7 Desc.	ECDs functional.	Pic 8 Desc.	The S-HH18 crossing is currently stable. No impact occurring.



GPS Location	On photo	GPS Location	On photo
Field Station#	11614+20	Field Station#	11607+81
Pic 9 Desc.	The S-RR14 crossing is stable. No impact occurring.	Pic 10 Desc.	The S-006 crossing remains stable with no impact.



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 8/9/2022 12:42 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40834	
Inspector Daniel Fortune		Date/Time 8/10/2022 10:40 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	10655+00
State VA	Inspection Area Partial	Station End	10749+92
County Giles	Ground Damp	Temperature (°F)	78.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	0.20
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/10/2022 10:40 AM	Report # 40834
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired






7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Completed a VA SWPPP inspection from ST# 10655+00 to ST# 10749+92 (MP 201.6 to MP 203.6). Drainage features, waterbodies, equipment crossings, perimeter controls, sump pits, and end treatments have been inspected today. A few sump pits have water standing but no issues at this time. Will continue to monitor receding water levels. Upon arrival to the row, the row conditions were damp from early morning dew but no issues at this time. The temporary water bars remain stable and functional. The perimeter ECDs remain without displacement and are functional according to design. There were a few resources (W-Z11 wetland near 10732+50, S-G33 10712+73, and S-G32 10698+15, that remain functional without impacts at this time. There is visible new vegetation emerging from fresh areas of temporary stabilization throughout the areas of inspection aforementioned above. The drainage features do have abundant vegetation without erosion issues.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 8/10/2022 10:40 AM		Report #			
Pictures							
 <p>Date & Time: Wed, Aug 10, 2022, 08:46:24 EDT Position: +037.345145° / -080.535765° (-12,21) Altitude: 2390ft (-13.1ft) Datum: WGS-84 Azimuth/Bearing: 228° 54W 405mils True (-15°) Elevation Grade: -076° Horizon Grade: +003° Zoom: 0.5X 10748+04</p>		 <p>Date & Time: Wed, Aug 10, 2022, 08:46:11 EDT Position: +037.345145° / -080.535765° (-12,21) Altitude: 2390ft (-13.1ft) Datum: WGS-84 Azimuth/Bearing: 130° 53W 300mils True (-13°) Elevation Grade: -076° Horizon Grade: +003° Zoom: 0.5X 10748+04</p>		<p>GPS Location See photo</p> <p>Field Station# 10748+04</p> <p>Pic 1 Desc. Stone inlet protection conditions.</p>		<p>GPS Location See photo</p> <p>Field Station# 10742+00</p> <p>Pic 2 Desc. Drainage feature and adequate vegetation conditions.</p>	
 <p>Date & Time: Wed, Aug 10, 2022, 09:26:43 EDT Position: +037.345377° / -080.541391° (-12,21) Altitude: 2350ft (-7.3ft) Datum: WGS-84 Azimuth/Bearing: 058° N35E 1049mils True (-15°) Elevation Grade: -012° Horizon Grade: -001° Zoom: 0.5X 10732+32 W-211</p>		 <p>Date & Time: Wed, Aug 10, 2022, 09:16:25 EDT Position: +037.345452° / -080.545929° (-12,21) Altitude: 2358ft (-7.8ft) Datum: WGS-84 Azimuth/Bearing: 239° N31W 800mils True (-15°) Elevation Grade: -017° Horizon Grade: +004° Zoom: 0.5X 10712+02</p>		<p>GPS Location See photo</p> <p>Field Station# 10732+32</p> <p>Pic 3 Desc. W-Z11 wetland. Equipment bridge found functional</p>		<p>GPS Location See photo</p> <p>Field Station# 10712+46</p> <p>Pic 4 Desc. S-G33 and vegetated buffer zones.</p>	
 <p>Date & Time: Wed, Aug 10, 2022, 09:29:02 EDT Position: +037.345382° / -080.541707° (-12,21) Altitude: 2370ft (-9.9ft) Datum: WGS-84 Azimuth/Bearing: 330° 53W 401mils True (-15°) Elevation Grade: -002° Horizon Grade: +002° Zoom: 0.5X 10709+44</p>		 <p>Date & Time: Wed, Aug 10, 2022, 09:29:02 EDT Position: +037.345382° / -080.541707° (-12,21) Altitude: 2370ft (-9.9ft) Datum: WGS-84 Azimuth/Bearing: 330° 53W 401mils True (-15°) Elevation Grade: -002° Horizon Grade: +002° Zoom: 0.5X 10704+02</p>		<p>GPS Location See photo</p> <p>Field Station# 10709+44</p> <p>Pic 5 Desc. Temporary stabilization of row</p>		<p>GPS Location See photo</p> <p>Field Station# 10704+02</p> <p>Pic 6 Desc. Steep slope stabilization and temporary vegetation growth.</p>	

AFE	124300137	Date/Time	8/10/2022 10:40 AM	Report #	
Pictures					
 <p><small>Date & Time: Wed, Aug 10, 2022, 09:55:39 EDT Position: +037.348947° N, -080.681678° W (-381.51) Altitude: 2028ft (-616.61m) Datum: WGS-84 Azimuth Bearing: 317° N43W 53.6mils True (-12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 0.5X 10699-00</small></p>		 <p><small>Date & Time: Wed, Aug 10, 2022, 09:56:09 EDT Position: +037.349222° N, -080.681910° W (-381.51) Altitude: 2084ft (-635.24m) Datum: WGS-84 Azimuth Bearing: 313° N42W 56.6mils True (-12°) Elevation Grade: +00% Horizon Grade: +00% Zoom: 0.5X 10698-39</small></p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10699+00	Field Station#	10698+39		
Pic 7 Desc.	TLS conditions. No issues at time of inspection.		Pic 8 Desc.	S-G32 Stream resource area conditions. No issues at this time.	
 <p><small>Date & Time: Wed, Aug 10, 2022, 10:15:22 EDT Position: +037.349295° N, -080.682913° W (-381.51) Altitude: 2028ft (-616.61m) Datum: WGS-84 Azimuth Bearing: 309° N51W 54.9mils True (-12°) Elevation Grade: +01% Horizon Grade: +00% Zoom: 0.5X 10694-00</small></p>		 <p><small>Date & Time: Wed, Aug 10, 2022, 10:07:01 EDT Position: +037.353321° N, -080.688812° W (-381.51) Altitude: 2070ft (-630.40m) Datum: WGS-84 Azimuth Bearing: 085° N85E 1511mils True (-12°) Elevation Grade: +02% Horizon Grade: +00% Zoom: 1.0X 10678-33</small></p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10694+00	Field Station#	10678+33		
Pic 9 Desc.	AR at Buffalo anklets access and vegetated drainage features.		Pic 10 Desc.	S-G30 Stream resource conditions. Temporary stabilization of row also in view.	
 <p><small>Date & Time: Wed, Aug 10, 2022, 10:05:35 EDT Position: +037.347412° N, -080.655238° W (-371.28) Altitude: 2017ft (-614.61m) Datum: WGS-84 Azimuth Bearing: 200° N20W 80.0mils True (-12°) Elevation Grade: +1% Horizon Grade: +00% Zoom: 0.5X 10675-10</small></p>		 <p><small>Date & Time: Wed, Aug 10, 2022, 09:55:49 EDT Position: +037.351311° N, -080.683312° W (-381.51) Altitude: 2228ft (-678.21m) Datum: WGS-84 Azimuth Bearing: 210° S20W 102.7mils True (-12°) Elevation Grade: +01% Horizon Grade: +00% Zoom: 0.5X 10669-70</small></p>			
GPS Location	See photo	GPS Location	See photo		
Field Station#	10675+10	Field Station#	10669+70		
Pic 11 Desc.	Big Stoney Rd conditions at row crossing.		Pic 12 Desc.	AR (GI 240) conditions.	

AFE 124300137	Date/Time 8/10/2022 10:40 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	10683+80	Field Station#	10660+00
-----------------------	----------	-----------------------	----------

Pic 13 Desc.	Stone inlet protection and TLS conditions. No issues at this time.	Pic 14 Desc.	Temporary stabilization of row.
---------------------	--	---------------------	---------------------------------

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 15 Desc.		Pic 16 Desc.	
---------------------	--	---------------------	--

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 17 Desc.		Pic 18 Desc.	
---------------------	--	---------------------	--



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40824	
Inspector Joe Sweeden		Date/Time 8/10/2022 6:50 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 10859+46	
State VA	Inspection Area Partial	Station End 10929+80	
County Giles	Ground Wet	Temperature (°F) 78.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/10/2022 6:50 AM	Report # 40824
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed Virginia SWPP inspection from station # 10859+46-10929+80.(MP 205.67-207.00) Kow Camp gravel to Doe Creek, with El Eric Hanlon.
 No Deficiencies found today.
 Observances:
 ROW was dry in spots and damp in spots.
 The ROW is temporarily stabilized and stabilization is sufficient.
 Environmental controls at water bodies are in place and functioning as designed.
 Soil piles are stabilized.
 No trash on the ROW.
 No sensitive resources were impacted.
 All perimeter controls, ECDs and BMPs were functional at time of inspection.
 Rock Road approaches are clean and free of loose rock

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/10/2022 6:50 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	See photo	GPS Location	see photo
Field Station#	10929+00	Field Station#	10928+00
Pic 1 Desc.	Doe creek RCE, S-Y 2	Pic 2 Desc.	S-Y 3



GPS Location	see photo	GPS Location	see photo
Field Station#	10923+00	Field Station#	10911+00
Pic 3 Desc.	Stabilized ROW	Pic 4 Desc.	P1, water bars




GPS Location	see photo	GPS Location	see photo
Field Station#	11902+00	Field Station#	11885+00
Pic 5 Desc.	P 1, perimeter controls, water bars	Pic 6 Desc.	Water bars, sumps

AFE 124300137	Date/Time 8/10/2022 6:50 AM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	see photo
Field Station#	110882+50	Field Station#	10863+00
Pic 7 Desc.	Kow Camp, S-A 32	Pic 8 Desc.	Clean water diversion pipe



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 8/10/2022 6:50 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40828	
Inspector Chris Burns		Date/Time 8/10/2022 7:36 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	10798+92
State VA	Inspection Area Partial	Station End	10859+46
County Giles	Ground Damp	Temperature (°F)	77.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/10/2022 7:36 AM	Report # 40828
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

See photos for GPS coordinates.
 Met with environmental staff.
 Discussed RoW/ECD conditions, within this section, with fellow EI David Schoolcraft.
 Performed SWPPP inspection from MP 204.53 (10798+92) and MP 205.67 (10859+46).
 Accompanied by fellow EI David Schoolcraft.
 All perimeter controls, ECDs and BMPs functional at time of inspection.
 Vegetation or stabilization sufficient.
 No impact to sensitive resources observed.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 8/10/2022 7:36 AM		Report #			
Pictures							
 <p>Date & Time: Wed, Aug 10, 2022, 08:42:10 EDT Position: 2015923.792 E / 2531845.224 N (s1084.110) Altitude: 1899ft (s78.7ft) Datum: WGS-84 Azimuth/Bearing: 102.578E (0.31mile True (s12)) Elevation Angle: -05.5 Horizon Angle: -01.8 Zoom: 0.5X 10799-00 S-Z10/W-Z3</p>		 <p>Date & Time: Wed, Aug 10, 2022, 08:45:48 EDT Position: 2016882.372 E / 2530938.288 N (s1084.110) Altitude: 1941ft (s74.1ft) Datum: WGS-84 Azimuth/Bearing: 316.288W (0.84mile True (s12)) Elevation Angle: -04.6 Horizon Angle: -01.6 Zoom: 0.5X 10801-54 S-Z11/S-Z12/S-Z13</p>		 <p>Date & Time: Wed, Aug 10, 2022, 09:19:19 EDT Position: 2003369.359 E / 2530261.888 N (s1084.110) Altitude: 2339ft (s71.1ft) Datum: WGS-84 Azimuth/Bearing: 300° N60W (0.88mile True (s12)) Elevation Angle: -09.3 Horizon Angle: +08.1 Zoom: 0.5X 10859-25</p>		 <p>Date & Time: Wed, Aug 10, 2022, 09:15:02 EDT Position: 2001242.494 E / 2530266.681 N (s1084.110) Altitude: 2274ft (s67.1ft) Datum: WGS-84 Azimuth/Bearing: 020° N20E (0.36mile True (s12)) Elevation Angle: -00.8 Horizon Angle: +00.9 Zoom: 0.5X 10856-04 S-A33</p>	
GPS Location 1		GPS Location 2		GPS Location 3			
Field Station# 10799+00		Field Station# 10801+52		Field Station# 10859+25			
Pic 1 Desc. S-Z10/W-Z3.		Pic 2 Desc. S-Z11/S-Z12/S-Z13.		Pic 3 Desc. Section of RoW showing conditions and controls.			
 <p>Date & Time: Wed, Aug 10, 2022, 09:19:19 EDT Position: 2003369.359 E / 2530261.888 N (s1084.110) Altitude: 2339ft (s71.1ft) Datum: WGS-84 Azimuth/Bearing: 300° N60E (0.88mile True (s12)) Elevation Angle: -10.2 Horizon Angle: -33.2 Zoom: 0.5X 10854-70 S-A34</p>		 <p>Date & Time: Wed, Aug 10, 2022, 09:04:51 EDT Position: 2017676.681 E / 2530194.078 N (s1084.110) Altitude: 2418ft (s72.9ft) Datum: WGS-84 Azimuth/Bearing: 213.839W (0.89mile True (s12)) Elevation Angle: -05 Horizon Angle: -00.8 Zoom: 0.5X 10846-75</p>		GPS Location 4			
Field Station# 10854+70		Field Station# 10846+75		Field Station# 10856+04			
Pic 5 Desc. S-A34.		Pic 6 Desc. CWDP outlet protection functional.		Pic 4 Desc. S-A33.			

AFE 124300137		Date/Time 8/10/2022 7:36 AM		Report #	
Pictures					
					
GPS Location 7		GPS Location 8			
Field Station# 10840+00		Field Station# 10835+50			
Pic 7 Desc. Section of RoW showing conditions and controls.		Pic 8 Desc. Section of RoW showing conditions and controls.			
					
GPS Location 9		GPS Location 10			
Field Station# 10818+00		Field Station# 10809+04			
Pic 9 Desc. Section of RoW showing conditions and controls.		Pic 10 Desc. S-Z14.			
			Insert image here		
GPS Location 11		GPS Location			
Field Station# 10804+00		Field Station#			
Pic 11 Desc. Section of RoW showing conditions and controls.		Pic 12 Desc.			

A/E	124300137	Date/Time	8/10/2022 7:36 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40852	
Inspector Jared Saunders		Date/Time 8/10/2022 4:10 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	10747+92
State VA	Inspection Area Full	Station End	10797+92
County Giles	Ground Damp	Temperature (°F)	83.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.20
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Culvert	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/10/2022 4:10 PM	Report # 40852
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Completed VA SWPPP inspection from ST# 10749+92 (Hendrickson) to ST# 10798+92 (Cascade)
 VA SWPPP inspection of MP 203.6 to MP 204.53.
 No deficiencies were located during inspection.
 Active construction site; additional deficiencies may be identified by other EIs.
 Observed no environmental maintenance crews actively working on this section of ROW at time of inspection.
 This section of ROW is temporarily stabilized with seed and mulch. Vegetation growth is present throughout section.
 Clean water diversion berms, pipes and level spreaders are in place. ECDs in place per E&S sheets.
 Sensitive resource buffers are in place at stream crossings S-G35, S-SS4, S-Z9, S-Z7 braid 1, and S-Z7 braid 2.
 Hendrickson Road, Big Branch Hollow Road, and Cascade Road crossing RCEs are maintained in acceptable condition.
 No sensitive resources have been impacted.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/10/2022 4:10 PM	Report #	
Pictures					
<p>Date & Time: Wed, Aug 10, 2022, 08:33:30 EDT Position: -037.342422 / -080.621377 (-227.911) Altitude: 1914ft (-643.0m) Datum: WGS-84 Azimuth/Bearing: 098 S82E-1742mils True (+13) Elevation Angle: -07.6° Horizon Angle: -01.3° Zoom: 1.0x 10797+00</p>			<p>Date & Time: Wed, Aug 10, 2022, 08:31:35 EDT Position: -037.342939 / -080.632018 (-15.4m) Altitude: 1338ft (-411.0m) Datum: WGS-84 Azimuth/Bearing: 038 N38E-0676mils True (+14) Elevation Angle: -03.7° Horizon Angle: 00.8° Zoom: 1.0x 10791+00</p>		
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10797+00		Field Station#	10791+00	
Pic 1 Desc.	RCE in place at Cascade Road crossing.		Pic 2 Desc.	Clean water diversion berm and clean water diversion pipe inlet in place.	
<p>Date & Time: Wed, Aug 10, 2022, 08:26:31 EDT Position: -037.344193 / -080.626354 (-15.7m) Altitude: 2107ft (-648.0m) Datum: WGS-84 Azimuth/Bearing: 049 N49E-0871mils True (+14) Elevation Angle: -08.2° Horizon Angle: -00.5° Zoom: 1.0x 10780+00</p>			<p>Date & Time: Wed, Aug 10, 2022, 08:18:21 EDT Position: -037.345002 / -080.632018 (-15.6m) Altitude: 2151ft (-655.0m) Datum: WGS-84 Azimuth/Bearing: 175 S05E-3111mils True (+17) Elevation Angle: 23.0° Horizon Angle: -09.9° Zoom: 1.0x 10762+00</p>		
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10780+00		Field Station#	10762+00	
Pic 3 Desc.	Sensitive resource buffer in place S-Z7.		Pic 4 Desc.	Rock inlet in place at slope drain pipe inlet.	
<p>Date & Time: Wed, Aug 10, 2022, 08:15:57 EDT Position: -037.344743 / -080.633797 (-15.6m) Altitude: 2055ft (-626.0m) Datum: WGS-84 Azimuth/Bearing: 025 N65E-1173mils True (+17) Elevation Angle: -11.6° Horizon Angle: -02.2° Zoom: 1.0x 10758+00 S-G35</p>			<p>Date & Time: Wed, Aug 10, 2022, 08:11:41 EDT Position: -037.342928 / -080.617472 (-15.0m) Altitude: 2287ft (-696.0m) Datum: WGS-84 Azimuth/Bearing: 071 N71E-1262mils True (+9) Elevation Angle: -24.2° Horizon Angle: -00.9° Zoom: 1.0x 10753+00</p>		
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10758+00		Field Station#	10753+00	
Pic 5 Desc.	Sensitive resource buffer in place at stream S-G35.		Pic 6 Desc.	Waterbars in place over steep slope.	

AFE 124300137	Date/Time 8/10/2022 4:10 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300137	Date/Time	8/10/2022 4:10 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40899	
Inspector Daniel Fortune		Date/Time 8/11/2022 1:34 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11884+85	
State VA	Inspection Area Partial	Station End 11254+99	
County Giles	Ground Dry	Temperature (°F) 76.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Waterbar	Acceptable			
Rock-lined Channel	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE 124300137	Date/Time 8/11/2022 1:34 PM	Report # 40899
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)



PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Level Spreader	Acceptable			
Other	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Completed VA SWPPP inspection from ST# 11184+85 to ST# 11254+99 (MP 211.83 to MP 213.6)
 The Row received 0.0" precipitation in the last 24 hours and light rain is expected periodically throughout the day. No erosion or sediment migration has been observed today. This section of row has been final stabilized from 11184+85 to near station 11222+43. Permanent water bars, level spreaders, and perimeter ECDs remain installed and functioning to design. There is good vegetation throughout. There are some spots with sparse vegetation but will continue to grow. Final restoration did not start until early fall 2021. A full growing season has not been established. There is temporary stabilization between 11222+43 to 11253+50. This section of row has been temporarily stabilized with no issues observed during todays inspection. There are temporary water bars and temporary ECDs throughout this area that appear to function as intended. Temporary vegetation remains visible with sparse areas of little to poor, to no growth between Stations 11226+00 to near 11251+00. Prior to the fall of this year, additional vegetation will need to be established. This has been previously reported by other EIs. No sensitive resources have been impacted. No activity observed in the area.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 8/11/2022 1:34 PM		Report #			
Pictures							
 <p>Date & Time: Thu, Aug 11, 2022, 08:25:51 EDT Position: +037.307427 / -080.511652 (+11.81) Altitude: 1963ft (+13.1ft) Datum: WGS-84 Azimuth/Bearing: 123.5576 2187mils True (+12.1) Elevation Grade: -005% Horizon Grade: -007% Zoom: 0.5X 11184+85</p>		 <p>Date & Time: Thu, Aug 11, 2022, 08:35:20 EDT Position: +037.305497 / -080.507863 (+12.87) Altitude: 1959ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 070 N70E 1244mils True (+12.1) Elevation Grade: -025% Horizon Grade: -008% Zoom: 0.5X 11191+40</p>		<p>GPS Location See photo</p> <p>Field Station# 11184+85</p> <p>Pic 1 Desc. Final restoration area.</p>		<p>GPS Location See photo</p> <p>Field Station# 11191+40</p> <p>Pic 2 Desc. Vegetative drainage feature in the final restoration area. No issues at this time.</p>	
 <p>Date & Time: Thu, Aug 11, 2022, 08:41:06 EDT Position: +037.305672 / -080.507693 (+14.03) Altitude: 1988ft (+15.23) Datum: WGS-84 Azimuth/Bearing: 152.5385 2702mils True (+12.1) Elevation Grade: -026% Horizon Grade: -016% Zoom: 0.5X 11199+45</p>		 <p>Date & Time: Thu, Aug 11, 2022, 08:44:47 EDT Position: +037.305242 / -080.507099 (+15.71) Altitude: 2057ft (+19.7ft) Datum: WGS-84 Azimuth/Bearing: 136.546E 2382mils True (+12.1) Elevation Grade: -045% Horizon Grade: -018% Zoom: 0.5X 11205+55</p>		<p>GPS Location See photo</p> <p>Field Station# 11199+45</p> <p>Pic 3 Desc. Vegetative cover in the final restoration area.</p>		<p>GPS Location See photo</p> <p>Field Station# 11205+55</p> <p>Pic 4 Desc. Permanent level spreader and vegetation conditions.</p>	
 <p>Date & Time: Thu, Aug 11, 2022, 08:49:20 EDT Position: +037.304691 / -080.505592 (+13.10) Altitude: 1984ft (+11.8ft) Datum: WGS-84 Azimuth/Bearing: 169.511E 3004mils True (+12.1) Elevation Grade: -035% Horizon Grade: -001% Zoom: 0.5X 11206+80</p>		 <p>Date & Time: Thu, Aug 11, 2022, 08:51:20 EDT Position: +037.303899 / -080.504429 (+11.11) Altitude: 2000ft (+15.7ft) Datum: WGS-84 Azimuth/Bearing: 026 N26E 022mils True (+12.1) Elevation Grade: -015% Horizon Grade: -001% Zoom: 1.0X 11209+50</p>		<p>GPS Location See photo</p> <p>Field Station# 11206+80</p> <p>Pic 5 Desc. Sparse area section in final restoration area.</p>		<p>GPS Location See photo</p> <p>Field Station# 11209+50</p> <p>Pic 6 Desc. Vegetated soil pile along the LOD.</p>	

AFE	124300137	Date/Time	8/11/2022 1:34 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	See photo	GPS Location	See photo
Field Station#	11219+70	Field Station#	11224+25
Pic 7 Desc.	Another sparse area in the final restoration.	Pic 8 Desc.	Stone inlet protection. Temporary stabilized area.



GPS Location	See photo	GPS Location	See photo
Field Station#	11231+00	Field Station#	11234+00
Pic 9 Desc.	Perimeter P1 silt fencing conditions. No Issues at this time.	Pic 10 Desc.	Slope drain pipe conditions along with the sump pit and water bar end treatment. No Issues at this time.



GPS Location	See photo	GPS Location	
Field Station#	11252+16	Field Station#	
Pic 11 Desc.	Steep slope and died off vegetation conditions. No erosion issues at this time.	Pic 12 Desc.	

AFE 124300137	Date/Time 8/11/2022 1:34 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 13 Desc.	Pic 14 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 15 Desc.	Pic 16 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40872	
Inspector Joe Sweeden		Date/Time 8/11/2022 7:20 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11023+80	
State VA	Inspection Area Partial	Station End 11098+47	
County Giles	Ground Damp	Temperature (°F) 80.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/11/2022 7:20 AM	Report # 40872
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed VA SWPPP inspection from ST# 11023+80 - 11098+47 (MP 208.78-210.2). AR 244 - 245.02. With EI Eric Hanlon. No deficiency found:

Station numbers are approximate.

Observances:

The ROW in that area received no precipitation overnight. The ROW was dry.

The ROW from AR 244 to AR 245.01 has been temporarily stabilized. Stabilization is sufficient.

The ROW from 245.01 to 245.02 has been restored.

The restored area is in good shape and the vegetation is sufficient. Annual grasses have gone to seed and perineal grasses are well established.

The water bars (other), in the restored area are in place and functioning as designed.

The environmental controls are to specifications and and functioning as designed.

No construction being performed in the area.

One area of open ditch in the area. RCE's are clean.

The EC's at the WB's in this area are in place and functioning as designed.

LOD ECDs were in place and functional.

Water bars have been installed to specifications.

ECDS at the sensitive resources see in place and the resources have not been impacted

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/11/2022 7:20 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	See photo	GPS Location	see photo
Field Station#	11026+00	Field Station#	11030+00
Pic 1 Desc.	S-IJ 18	Pic 2 Desc.	Slope drain/end treatments/sumps



GPS Location	see photo	GPS Location	see photo
Field Station#	11050+00	Field Station#	11055+00
Pic 3 Desc.	S-IJ 16B	Pic 4 Desc.	Stabilized ROW




GPS Location	see photo	GPS Location	see photo
Field Station#	11065+00	Field Station#	11072+00
Pic 5 Desc.	Drainage feature @ 245.01	Pic 6 Desc.	Stabilized/restored ROW

AFE 124300137	Date/Time 8/11/2022 7:20 AM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	see photo
Field Station#	11088+00	Field Station#	11098+00
Pic 7 Desc.	Water bars (other), permanent vegetation	Pic 8 Desc.	245.02



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300137	Date/Time	8/11/2022 7:20 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40874	
Inspector Chris Burns		Date/Time 8/11/2022 7:32 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11098+47
State VA	Inspection Area Partial	Station End	11184+85
County Giles	Ground Damp	Temperature (°F)	77.00
Municipality N/A	Weather Light Rain	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/11/2022 7:32 AM	Report # 40874
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)









PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Level Spreader	Acceptable			
Other	Acceptable			





7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

See photos for GPS coordinates.
 Met with environmental staff.
 Discussed RoW/ECD conditions, within this section, with fellow EI David Schoolcraft.
 Performed SWPPP inspection from MP 210.2 (11098+47) and MP 211.83 (11184+85).
 Inspection performed, partially, during rain event.
 Accompanied by fellow EI David Schoolcraft.
 This section of RoW is partially restored.
 All perimeter controls, ECDs and BMPs functional at time of inspection.
 Vegetation or stabilization sufficient.
 No impact to sensitive resources observed.
 Section 6 - other (waterbars)
 Assessed AR 245.02, AR 249.02 and AR 249.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300137		Date/Time 8/11/2022 7:32 AM		Report #			
Pictures							
 <p>Date & Time Thu, Aug 11, 2022, 08:28:57 EDT Position: 2048135.629 E / 2921028.222 N (±15.3M) Altitude: 1723ft (±26.2ft) Datum: WGS-84 Azimuth/Bearing: 08° N85E 0516mils True (±12°) Elevation Angle: +93.4° Horizon Angle: +00.0° Zoom: 0.5X 11182+00</p>		 <p>Date & Time Thu, Aug 11, 2022, 08:35:49 EDT Position: 2038171.449 E / 2921041.378 N (±30.65M) Altitude: 1829ft (±29.0ft) Datum: WGS-84 Azimuth/Bearing: 818° N27W 5824mils True (±12°) Elevation Angle: +64.4° Horizon Angle: +01.2° Zoom: 0.5X 11167+25</p>		 <p>Date & Time Thu, Aug 11, 2022, 08:55:11 EDT Position: 2027038.618 E / 2923031.699 N (±16.8M) Altitude: 1894ft (±11.8ft) Datum: WGS-84 Azimuth/Bearing: 138° S88E 2108mils True (±12°) Elevation Angle: +69.4° Horizon Angle: +03.5° Zoom: 0.5X 11158-68 S-NN17</p>		 <p>Date & Time Thu, Aug 11, 2022, 09:03:26 EDT Position: 2022233.638 E / 2923337.217 N (±31.0M) Altitude: 2074ft (±37.4ft) Datum: WGS-84 Azimuth/Bearing: 028° N64E 1108mils True (±12°) Elevation Angle: +16.4° Horizon Angle: +03.6° Zoom: 0.5X 11105+00</p>	
GPS Location 1		GPS Location 2					
Field Station# 11182+00		Field Station# 11167+25					
Pic 1 Desc. Representative photo of permanent waterbar and level spreaders installed.		Pic 2 Desc. CWDP outlet protection functional.					
 <p>Date & Time Thu, Aug 11, 2022, 09:16:18 EDT Position: 2026833.218 E / 2923031.141 N (±11.6M) Altitude: 2143ft (±3.8ft) Datum: WGS-84 Azimuth/Bearing: 93° S91W 4364mils True (±12°) Elevation Angle: +64.0° Horizon Angle: +07.0° Zoom: 0.5X 11114+50</p>		 <p>Date & Time Thu, Aug 11, 2022, 09:20:09 EDT Position: 2026754.034 E / 2923345.218 N (±24.0M) Altitude: 1920ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 202° N16W 4180mils True (±12°) Elevation Angle: +14.0° Horizon Angle: +02.0° Zoom: 0.5X 11121+50</p>					
GPS Location 3		GPS Location 4					
Field Station# 11158+68		Field Station# 11105+00					
Pic 3 Desc. S-NN17.		Pic 4 Desc. Section of restored RoW showing conditions and controls.					
 <p>Date & Time Thu, Aug 11, 2022, 09:16:18 EDT Position: 2026833.218 E / 2923031.141 N (±11.6M) Altitude: 2143ft (±3.8ft) Datum: WGS-84 Azimuth/Bearing: 93° S91W 4364mils True (±12°) Elevation Angle: +64.0° Horizon Angle: +07.0° Zoom: 0.5X 11114+50</p>		 <p>Date & Time Thu, Aug 11, 2022, 09:20:09 EDT Position: 2026754.034 E / 2923345.218 N (±24.0M) Altitude: 1920ft (±39.4ft) Datum: WGS-84 Azimuth/Bearing: 202° N16W 4180mils True (±12°) Elevation Angle: +14.0° Horizon Angle: +02.0° Zoom: 0.5X 11121+50</p>					
GPS Location 5		GPS Location 6					
Field Station# 11114+50		Field Station# 11121+50					
Pic 5 Desc. Section of restored RoW showing conditions and controls.		Pic 6 Desc. Section of restored RoW showing conditions and controls.					

AFE 124300137		Date/Time 8/11/2022 7:32 AM		Report #	
Pictures					
					
GPS Location 7		GPS Location 8			
Field Station# 11131+00		Field Station# 11138+25			
Pic 7 Desc. Section of restored RoW showing conditions and controls.		Pic 8 Desc. Section of restored RoW showing conditions and controls.			
					
GPS Location 9		GPS Location 10			
Field Station# 11151+50		Field Station# 11098+47			
Pic 9 Desc. Section of RoW showing conditions and controls.		Pic 10 Desc. AR 245.02 conditions and controls.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300137	Date/Time	8/11/2022 7:32 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40894	
Inspector Jared Saunders		Date/Time 8/11/2022 12:34 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	10929+80
State VA	Inspection Area Full	Station End	11023+80
County Giles	Ground Damp	Temperature (°F)	74.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300137	Date/Time	8/11/2022 12:34 PM	Report #	40894
------------	-----------	------------------	--------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Completed VA SWPPP inspection from ST# 10929+80 (Doe Creek Road) to ST# 11023+80 (Access Road 244)
 VA SWPPP inspection of MP 207 to MP 208.78.
 No compliance issues found.
 Active construction site; additional deficiencies may be identified by other EIs.
 Observed no environmental maintenance crews actively working on this section of ROW at time of inspection.
 ST#s 10929+80 to 10940+25 and 10961+75 to 11023+80 have undergone temporary stabilization with seed and mulch. Minor vegetation growth is present throughout section. Clean water diversion berms, pipes and level spreaders are in place. ECDs in place per E&S sheets.
 The ROW is permanently stabilized from ST# 10940+25 to ST# 10961+75. Area is stabilized with seed and mulch. Vegetation growth is present. CFS in place to minimize rilling and maintain sheet flow.
 Sensitive resource buffers are in place at streams S-PA07, S-RR5, S-E24, and S-E25.
 Triple barrier protection around karst feature located at station number 10966+00.
 RCEs in place and maintained at Doe Creek Road crossing, Access Road 244, and Access Road 241.02.
 The ROW is wet and in stable condition. No sensitive resources have been impacted.
 Checked rain gauges at Catawba Road - 0.0 inches, AR 244 - 0.0 inches, and Mount Tabor Road - 0.0.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/11/2022 12:34 PM	Report #	
Pictures					
 <p><small>Date & Time: Thu, Aug 11, 2022, 12:16:29 EDT Position: +037.3233007, -080.5263111 (+59.870) Altitude: 2642ft (+80.24m) Datum: WGS-84 Azimuth Bearing: 289° N71W 5188mils True (+13.1°) Elevation Angle: -01.0° Horizon Angle: +00.8° Zoom: 1.0X 11015+75 S-PA07 & S-RR5</small></p>		 <p><small>Date & Time: Thu, Aug 11, 2022, 08:21:30 EDT Position: +037.3232447, -080.5263663 (+59.870) Altitude: 2658ft (+80.95m) Datum: WGS-84 Azimuth Bearing: 330° N30W 5078mils True (+13.1°) Elevation Angle: -01.0° Horizon Angle: +00.8° Zoom: 1.0X 11011+40</small></p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11015+75		Field Station#	11011+40	
Pic 1 Desc.	Sensitive resource buffer in place at streams S-PA07 and S-RR5.		Pic 2 Desc.	Clean water diversion pipe inlet and clean water diversion berm in place.	
 <p><small>Date & Time: Thu, Aug 11, 2022, 08:25:33 EDT Position: +037.3242711, -080.5593955 (+15.4ft) Altitude: 2642ft (+80.24m) Datum: WGS-84 Azimuth Bearing: 310° S30W 3733mils True (+13.1°) Elevation Angle: -2.5° Horizon Angle: +06.6° Zoom: 1.0X 11004+00</small></p>		 <p><small>Date & Time: Thu, Aug 11, 2022, 08:29:38 EDT Position: +037.3243207, -080.5593857 (+17.55ft) Altitude: 2658ft (+80.95m) Datum: WGS-84 Azimuth Bearing: 316° N66W 5382mils True (+13.1°) Elevation Angle: -31.4° Horizon Angle: +09.6° Zoom: 1.0X 10995+00</small></p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	11004+00		Field Station#	10995+00	
Pic 3 Desc.	Clean water diversion pipe and level spreader in place.		Pic 4 Desc.	Priority one silt fence in place along LOD.	
 <p><small>Date & Time: Thu, Aug 11, 2022, 08:43:08 EDT Position: +037.3266827, -080.5263927 (+16.00ft) Altitude: 2670ft (+81.41m) Datum: WGS-84 Azimuth Bearing: 35° N63W 5816mils True (+14.1°) Elevation Angle: -01.0° Horizon Angle: +03.7° Zoom: 1.0X 10947+00</small></p>		 <p><small>Date & Time: Thu, Aug 11, 2022, 08:57:38 EDT Position: +037.3269227, -080.5322137 (+15.4ft) Altitude: 2132ft (+65.21m) Datum: WGS-84 Azimuth Bearing: 042° N42E 0747mils True (+14.1°) Elevation Angle: -16.4° Horizon Angle: +03.2° Zoom: 1.0X 10930+00</small></p>			
GPS Location	See photo for GPS location.		GPS Location	See photo for GPS location.	
Field Station#	10947+00		Field Station#	10930+00	
Pic 5 Desc.	ROW permanently restored.		Pic 6 Desc.	RCE in place at Doe Creek Road.	

AFE 124300137	Date/Time 8/11/2022 12:34 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 8/11/2022 12:34 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40945	
Inspector Daniel Fortune		Date/Time 8/12/2022 11:17 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11524+16
State VA	Inspection Area Partial	Station End	11600+01
County Montgomery	Ground Dry	Temperature (°F)	73.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Waterbar	Acceptable			
Stone Inlet Protection	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/12/2022 11:17 AM	Report # 40945
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Level Spreader	Acceptable			
Other	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Completed a VA SWPP inspection from ST# 11524+16 to ST# 11600+01 (MP 218.26 to MP 219.70) The Row received 0.0" of precipitation in the last 24 hours. This section of row has been final stabilized from 11524+16 to near station 11551+88. Permanent water bars, (other) and level spreaders remain installed and are functioning to design. Final restoration did not start between the stations mentioned above until late summer 2021. There is good vegetation throughout. There is temporary stabilization between 11551+88 to 11600+01. There is heavy temporary vegetation growth throughout the area aforementioned.

This section is in the JNF and permits have not been released for construction continuation. There are temporary water bars and perimeter ECDs throughout this area. There are ECDs that have been in place for a while. The established vegetation is functioning as a well erosion control BMP. The ECDs appear to be functioning according to design. Until permits are released for the JNF, no equipment is to be allowed in this area.

No deficiencies found during todays inspection.

Observances: Environmental crew (1710) on site near 11595+00 installing additional P1 silt fencing behind sump pit.

There are three stream resources in the areas of inspection. Conditions are as follows:

S-PP 22 - near 11567+42 - Equipment bridge weathered and in tact. NOT suitable for heavy equipment at this time. Well vegetated buffer zones remain undisturbed. ECD's protecting resource functioning with no maintenance required.

S-PP 21- near 11585+48 - Equipment bridge weathered and in tact. NOT suitable for heavy equipment at this time. Well vegetated buffer zones remain undisturbed. ECD's protecting resource functioning with no maintenance required.

S-PP20 - near 11588+41 - Equipment bridge weathered and in tact. NOT suitable for heavy equipment at this time. Well vegetated buffer zones remain undisturbed. ECD's protecting resource functioning with no maintenance required.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/12/2022 11:17 AM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures

GPS Location	See photo	GPS Location	See photo
Field Station#	11595+75	Field Station#	11588+75
Pic 1 Desc.	P1 Silt fencing added to perimeter LOD.	Pic 2 Desc.	Stone inlet protection conditions.
GPS Location	See photo	GPS Location	See photo
Field Station#	11587+92	Field Station#	11587+92
Pic 3 Desc.	S-PP20 cobble filled stream bed conditions. Vegetated buffers zones adequately protected with ECDs.	Pic 4 Desc.	S-PP20 Equipment bridge condition.
GPS Location	See photo	GPS Location	See photo
Field Station#	11585+35	Field Station#	11585+35
Pic 5 Desc.	S-PP21 Stream bed and vegetated buffer zone conditions.	Pic 6 Desc.	S-PP21 Equipment bridge condition.

AFE	124300137	Date/Time	8/12/2022 11:17 AM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures



GPS Location	See photo
Field Station#	11584+00
Pic 7 Desc.	Perimeter P1 silt fencing condition. Temporary stabilization of row condition.



GPS Location	See photo
Field Station#	11584+37
Pic 8 Desc.	P1 silt fencing condition.




GPS Location	See photo
Field Station#	11584+02
Pic 9 Desc.	(Reinforced) Super silt fence condition.




GPS Location	See photo
Field Station#	11567+93
Pic 10 Desc.	S-PP22 Stream bed flow path. Vegetated buffer zones adequately protected with functional ECDs.



GPS Location	See photo
Field Station#	11534+00
Pic 11 Desc.	Perimeter CFS and P1 silt fencing found functional.



GPS Location	See photo
Field Station#	11533+45
Pic 12 Desc.	Small subsidence area below permanent level spreader over ditch line. Approximate area 3'x3'x1'.

AFE 124300137		Date/Time 8/12/2022 11:17 AM	Report #
Pictures			
 <p><small>Date & Time: Fri, Aug 12, 2022, 11:33:11 EDT Position: +037.329705° / -080.418844° (-11531+00) Altitude: 2348ft (+11.0ft) Datum: WGS-84 Azimuth/Bearing: 238° S55W 4178mils True (+12°) Elevation Grade: +06% Horizon Grade: +00% Zoom: 0.5X 11531+00</small></p>		 <p><small>Date & Time: Fri, Aug 12, 2022, 11:34:05 EDT Position: +037.329950° / -080.419194° (-11529+00) Altitude: 2337ft (+13.3ft) Datum: WGS-84 Azimuth/Bearing: 247° S67W 4391mils True (+16°) Elevation Grade: +02% Horizon Grade: -01% Zoom: 0.5X 11529+00</small></p>	
GPS Location	See photo	GPS Location	See photo
Field Station#	11531+00	Field Station#	11529+00
Pic 13 Desc.	Final restoration area and well vegetated permanent water bar.	Pic 14 Desc.	Final restoration area and level spreader. Adequate vegetation coverage visible.
 <p><small>Date & Time: Fri, Aug 12, 2022, 11:35:30 EDT Position: +037.329834° / -080.420104° (-11526+45) Altitude: 2330ft (+13.4ft) Datum: WGS-84 Azimuth/Bearing: 249° S57W 3916mils True (+14°) Elevation Grade: +7% Horizon Grade: +00% Zoom: 0.5X 11526+45</small></p>		 <p><small>Date & Time: Fri, Aug 12, 2022, 11:35:52 EDT Position: +037.329834° / -080.420104° (-11525+00) Altitude: 2358ft (+9.9ft) Datum: WGS-84 Azimuth/Bearing: 220° S40W 3911mils True (+14°) Elevation Grade: -01% Horizon Grade: -01% Zoom: 0.5X 11525+00</small></p>	
GPS Location	See photo	GPS Location	See photo
Field Station#	11526+45	Field Station#	11525+00
Pic 15 Desc.	Vegetated drainage feature area. No Issues at this time.	Pic 16 Desc.	AR 258.02 conditions.
 <p><small>Date & Time: Fri, Aug 12, 2022, 11:42:08 EDT Position: +037.329377° / -080.423355° (-11525+00 AR 258.02 S-QQ2) Altitude: 2338ft (+13.2ft) Datum: WGS-84 Azimuth/Bearing: 177° S41E 3116mils True (+27°) Elevation Grade: +0% Horizon Grade: +00% Zoom: 0.5X 11525+00 AR 258.02 S-QQ2</small></p>		Insert image here	
GPS Location	See photo	GPS Location	
Field Station#	11525+00	Field Station#	
Pic 17 Desc.	AR 258.02 - S-QQ2 equipment bridge crossing condition. No Issues at this time.	Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40928	
Inspector Joe Sweeden		Date/Time 8/12/2022 6:45 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11254+99	
State VA	Inspection Area Partial	Station End 11353+67	
County Giles	Ground Dry	Temperature (°F) 75.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Slope Drain Pipe	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/12/2022 6:45 AM	Report # 40928
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed Virginia SWPP inspection from station # 11254+99-11353+67 (MP 213.6-215.04) Rte 42 - Old Furnace, with EI, Eric Hanlon.
 No Deficiencies found today.
 Observances:
 The ROW in this area received approximately .40" of precipitation over the last 24 hours.
 The ROW was wet.
 Multiple environmental crews were in the area cutting vegetation and repairing previous PL items
 The ROW has been temporarily stabilized.
 Karst areas have occurred in sumps at station 11348+00.areas are protected with ECDs. The water bars and compost sock are in good condition.
 Steep slopes have had erosion control fabric placed on them. Vegetation is sufficient. Slope drains are functioning as designed.
 ECs at streams are in compliance.
 No trash on the ROW.
 No sensitive resources were impacted.
 All perimeter controls, ECDs and BMPs were functional at time of inspection.
 Rock Road approaches are clean and free of loose rock.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/12/2022 6:45 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	See photo	GPS Location	see photo
Field Station#	11353+00	Field Station#	11346+00
Pic 1 Desc.	S-NN 11	Pic 2 Desc.	Stabilized ROW



GPS Location	see photo	GPS Location	see photo
Field Station#	11323+00	Field Station#	11306+00
Pic 3 Desc.	S-NN12	Pic 4 Desc.	Stabilized ROW



GPS Location	see photo	GPS Location	See photo
Field Station#	11294+09	Field Station#	11287+00
Pic 5 Desc.	S-MM 18	Pic 6 Desc.	Slope drain/sump

AFE 124300137	Date/Time 8/12/2022 6:45 AM	Report #
----------------------	------------------------------------	-----------------

Pictures



GPS Location	See photo	GPS Location	see photo
---------------------	-----------	---------------------	-----------

Field Station#	11271+00	Field Station#	11257+00
-----------------------	----------	-----------------------	----------

Pic 7 Desc.	Maintained vegetation	Pic 8 Desc.	End treatments/perimeter controls
--------------------	-----------------------	--------------------	-----------------------------------

Insert image here

Insert image here

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 9 Desc.		Pic 10 Desc.	
--------------------	--	---------------------	--

Insert image here

Insert image here

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 11 Desc.		Pic 12 Desc.	
---------------------	--	---------------------	--

AFE 124300137	Date/Time 8/12/2022 6:45 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40927	
Inspector Chris Burns		Date/Time 8/12/2022 6:29 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	11353+67
State VA	Inspection Area Partial	Station End	11471+56
County Giles	Ground Damp	Temperature (°F)	72.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/12/2022 6:29 AM	Report # 40927
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)










PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Level Spreader	Acceptable			
Other	Acceptable			

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)







See photos for GPS coordinates.
 Met with environmental staff.
 Performed SWPPP inspection from MP 215.04 (11353+67) and MP 217.26 (11471+56).
 Accompanied by fellow EI David Schoolcraft.
 This section of RoW is partially restored.
 All perimeter controls, ECDs and BMPs functional at time of inspection.
 Vegetation or stabilization sufficient.
 No impact to sensitive resources observed.
 Section 6 - other (waterbars).

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/12/2022 6:29 AM	Report #	
Pictures					
					
GPS Location	1		GPS Location	2	
Field Station#	11469+00		Field Station#	11451+87	
Pic 1 Desc.	Section of RoW showing conditions and controls.		Pic 2 Desc.	S-0012.	
					
GPS Location	3		GPS Location	4	
Field Station#	11451+18		Field Station#	11448+93	
Pic 3 Desc.	S-0013.		Pic 4 Desc.	S-0014/W-CD12.	
					
GPS Location	5		GPS Location	6	
Field Station#	11438+75		Field Station#	11430+00	
Pic 5 Desc.	Section of restored RoW showing conditions and controls.		Pic 6 Desc.	Representative photo of permanent waterbar and level spreaders installed.	

AFE	124300137	Date/Time	8/12/2022 6:29 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures

 <p><small>Date & Time: Fri, Aug 12, 2022, 08:32:27 EDT Position: 2068372.7 E / 7872233.67 N (e15.1M) Altitude: 2280ft (e11.2M) Datum: WGS-84 Azimuth (Bearing): 235° 58W (4.78mils True (e12°)) Elevation Angle: -05.4° Horizon Angle: -01.6° Zoom: 0.5X 11423+00</small></p>		 <p><small>Date & Time: Fri, Aug 12, 2022, 08:07:38 EDT Position: 2065792.988 E / 7872770.200 N (e15.1M) Altitude: 2280ft (e11.2M) Datum: WGS-84 Azimuth (Bearing): 215° 53W (3822mils True (e12°)) Elevation Angle: -02.5° Horizon Angle: -02.1° Zoom: 0.5X 11413+00</small></p>	
GPS Location	7	GPS Location	8
Field Station#	11423+00	Field Station#	11413+00
Pic 7 Desc.	Section of restored RoW showing conditions and controls.	Pic 8 Desc.	Section of restored RoW showing conditions and controls.
 <p><small>Date & Time: Fri, Aug 12, 2022, 09:21:41 EDT Position: 2062783.045 E / 7872714.637 N (e15.1M) Altitude: 2280ft (e11.2M) Datum: WGS-84 Azimuth (Bearing): 230° N=4W (562mils True (e12°)) Elevation Angle: -08.3° Horizon Angle: -08.2° Zoom: 0.5X 11397+00</small></p>		 <p><small>Date & Time: Fri, Aug 12, 2022, 08:42:17 EDT Position: 2062787.130 E / 7872652.883 N (e15.1M) Altitude: 2280ft (e11.2M) Datum: WGS-84 Azimuth (Bearing): 229° 53W (4920mils True (e12°)) Elevation Angle: -07.4° Horizon Angle: -02.1° Zoom: 0.5X 11377+00</small></p>	
GPS Location	9	GPS Location	10
Field Station#	11397+00	Field Station#	11377+00
Pic 9 Desc.	Section of restored RoW showing conditions and controls.	Pic 10 Desc.	Section of restored RoW showing conditions and controls.
 <p><small>Date & Time: Fri, Aug 12, 2022, 08:58:31 EDT Position: 2061972.015 E / 7872707.935 N (e15.1M) Altitude: 2014ft (e61.6M) Datum: WGS-84 Azimuth (Bearing): 241° S=1W (428mils True (e12°)) Elevation Angle: -03.7° Horizon Angle: -03.9° Zoom: 0.5X 11362+00</small></p>		 <p><small>Date & Time: Fri, Aug 12, 2022, 08:41:45 EDT Position: 2061462.130 E / 7872771.634 N (e15.1M) Altitude: 1988ft (e60.4M) Datum: WGS-84 Azimuth (Bearing): 145° S=2E (2530mils True (e12°)) Elevation Angle: -06.5° Horizon Angle: -01.1° Zoom: 0.5X 11360+54.5_KL43</small></p>	
GPS Location	11	GPS Location	12
Field Station#	11362+00	Field Station#	11360+54
Pic 11 Desc.	Section of RoW showing conditions and controls.	Pic 12 Desc.	S-KL43.

A/E	124300137	Date/Time	8/12/2022 6:29 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread G		AFE 124300137	Spread H-600 Pipeline Spread G
Contractor Precision		Report # 40961	
Inspector Jared Saunders		Date/Time 8/12/2022 5:14 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 11471+56	
State VA	Inspection Area Full	Station End 11524+16	
County Craig	Ground Dry	Temperature (°F) 75.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300137	Date/Time 8/12/2022 5:14 PM	Report # 40961
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted VA SWPPP inspection from ST# 11471+56 (Steele Acres) to ST# 11524+16 (AR-258.02)
 VA SWPPP inspection of MP 217.26 to MP 218.26
 No deficiencies were located during inspection.
 Observed no environmental maintenance crews actively working on this section of ROW at time of inspection.
 This section of ROW has undergone temporary stabilization. Topsoil stock piles and cleanwater diversion berms have been stabilized.
 Slope drains with stone inlet protection, Perimeter controls, and waterbars with end treatments are in place.
 Triple protection ECDs are in place at karst feature.
 Sensitive resource buffers are in place at stream crossings S-PP3, and S-PP4.
 AR-258.01, 258.02, and Stever's Gap road crossing RCEs are maintained in acceptable condition.
 No sensitive resources have been impacted.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300137	Date/Time	8/12/2022 5:14 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.
Field Station#	11473+00	Field Station#	11477+00
Pic 1 Desc.	Triple barrier ECDs in place at off ROW karst feature.	Pic 2 Desc.	Rock inlet protection at slope drain inlet.



GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.
Field Station#	11490+00	Field Station#	11495+00
Pic 3 Desc.	RCE in place at Stevers Gap Road.	Pic 4 Desc.	Priority one silt fence in place along LOD.



GPS Location	See photo for GPS location.	GPS Location	See photo for GPS location.
Field Station#	11503+00	Field Station#	11519+00
Pic 5 Desc.	Rock lined channel in place.	Pic 6 Desc.	Sensitive resource buffer in place at stream S-PP4.

A/E	124300137	Date/Time	8/12/2022 5:14 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300137	Date/Time 8/12/2022 5:14 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	