



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40496	
Inspector Ben Farmer		Date/Time 8/1/2022 12:54 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13853+45	
State VA	Inspection Area Partial	Station End 13958+31	
County Franklin	Ground Wet	Temperature (°F) 72.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 1.50	
Rain Accumulation Time (days)			0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	P1 has been damaged and needs to		
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
3rd Party Damages	Communication	ROW has been damaged by 3rd party		

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/1/2022 12:54 PM	Report # 40496
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in good		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP Inspection (Cloudy, 72F)
 Rain Gauge= 1.5"
 13853+45-13958+31


- Resource buffers remain well vegetated at all stream and wetland crossings.
- CWDs are in good condition and functioning as intended
- Equipment bridge ECDs are in good condition and functioning.
- CFS is in good condition throughout this section.
- Steep slope at 13889+00 remains stabilized.
- RCEs are in good condition at all road crossings.
- P1 has been damaged and needs to be replaced at 13916+30.
- Topsoil berms remain stabilized.
- Sediment trap at 13897+00 is in good condition with no evidence of discharge.
- Waterbars/end treatments are in good condition.
- ROW has been damaged by 3rd party and needs to be re-stabilized at 13947+00.
- Slope drain is functioning at 13955+00.
- Stream S-CD6 and S-II2 are turbid entering ROW. This turbidity is a result of upstream disturbance NOT related to MVP construction.

*Issues identified in the field have been added to the punch list to be addressed by the contractor

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/1/2022 12:54 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	13863+00	Field Station#	13875+73
-----------------------	----------	-----------------------	----------


Pic 1 Desc.	Resource buffers remain well vegetated	Pic 2 Desc.	Equipment bridge ECDs are in good condition
--------------------	--	--------------------	---



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	13875+73	Field Station#	13888+00
-----------------------	----------	-----------------------	----------







Pic 3 Desc.	Stream S-CD6 is turbid entering ROW. This turbidity is a result of upstream disturbance NOT related to MVP construction	Pic 4 Desc.	Slope drain is in good condition and functioning
--------------------	---	--------------------	--



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	13892+45	Field Station#	13897+00
-----------------------	----------	-----------------------	----------

Pic 5 Desc.	RCEs are in good condition at all road crossings.	Pic 6 Desc.	Topsoil pile remains stabilized
--------------------	---	--------------------	---------------------------------

AFE 124300139		Date/Time 8/1/2022 12:54 PM	Report #
Pictures			
			
GPS Location	See photo	GPS Location	See photo
Field Station#	13897+00	Field Station#	13915+12
Pic 7 Desc.	Sediment trap is functioning as intended. No evidence of discharge.	Pic 8 Desc.	Stream S-II2 is turbid entering ROW. This turbidity is a result of upstream disturbance NOT related to MVP construction
			
GPS Location	See photo	GPS Location	See photo
Field Station#	13916+30	Field Station#	13925+00
Pic 9 Desc.	P1 has been damaged and needs to be replaced	Pic 10 Desc.	CFS is in good condition throughout this section
			
GPS Location	See photo	GPS Location	See photo
Field Station#	13939+50	Field Station#	13942+00
Pic 11 Desc.	SSF is in good condition	Pic 12 Desc.	CWDs are functioning as intended

AFE 124300139	Date/Time 8/1/2022 12:54 PM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	13947+00	Field Station#	13953+00
-----------------------	----------	-----------------------	----------


Pic 13 Desc.	ROW has been damaged by 3rd party. Area needs to be re-stabilized.	Pic 14 Desc.	Slope drain outlet is in good condition and functioning
---------------------	--	---------------------	---



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 15 Desc.		Pic 16 Desc.	
---------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 17 Desc.		Pic 18 Desc.	
---------------------	--	---------------------	--



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40489	
Inspector Justin Burch		Date/Time 8/1/2022 12:06 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15142+66
State VA	Inspection Area Full	Station End	15260+00
County Pittsylvania	Ground Wet	Temperature (°F)	86.00
Municipality Chatham	Weather Cloudy	Rain Gauge (in)	1.10
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/1/2022 12:06 PM	Report # 40489
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		






7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15142+66 to 15260+00 (Rock Creek Road to the Pigg River HDD Exit). Four punch list items were submitted for the punch list including one location where CFS was deteriorated and three locations where CFS was damaged by wildlife. Other inspected ECDs were observed as in compliance at the time of inspection.
- The EI did not observe that any contractor activity has occurred in the area since the last SWPPP inspection.
- Since the last SWPPP inspection the inspection area has received three rainfall events with a total of 1.10" at Snowberry Road.
- The ROW ground condition is wet.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion
- At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15145+00 to 15153+00 and from 15173+00 to 15260+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/1/2022 12:06 PM		Report #	
Pictures					
GPS Location		0		GPS Location	
Field Station#		15228+00		Field Station#	
Pic 1 Desc.		12" CFS is deteriorated		Pic 2 Desc.	
				18" triple stack CFS was damaged by wildlife from 15255+00 to 15255+80	
GPS Location		0		GPS Location	
Field Station#		15255+00		Field Station#	
Pic 3 Desc.		18" CFS was damaged by wildlife from 15255+00 to 15255+65		Pic 4 Desc.	
				18" triple stack CFS was damaged by wildlife	
GPS Location		0		GPS Location	
Field Station#		15222+00		Field Station#	
Pic 5 Desc.		Waterbar in acceptable condition		Pic 6 Desc.	
				Waterbar end treatment in acceptable condition	

AFE 124300139		Date/Time 8/1/2022 12:06 PM		Report #	
Pictures					
267°W (T) 17 N 627055 4085502 ±26929ft ▲ 815ft  15182+00 08-01-2022, 10:34:20				267°W (T) 17 N 627055 4085502 ±26929ft ▲ 815ft  15182+00 08-01-2022, 10:34:20	
GPS Location 0		GPS Location 0		GPS Location 0	
Field Station# 15182+00		Field Station# 15182+00		Field Station# 15182+00	
Pic 7 Desc. Permanent vegetative stabilization in acceptable condition		Pic 8 Desc. Permanent vegetative stabilization in acceptable condition		Pic 8 Desc. Permanent vegetative stabilization in acceptable condition	
314°NW (T) 17 N 627326 4089528 ±13ft ▲ 812ft  15172+00 08-01-2022, 10:36:32				308°NW (T) 17 N 623236 4082773 ±26699ft ▲ 724ft  15167+00 08-01-2022, 11:42:29	
GPS Location 0		GPS Location 0		GPS Location 0	
Field Station# 15172+00		Field Station# 15167+00		Field Station# 15167+00	
Pic 9 Desc. Temporary vegetative stabilization in acceptable condition		Pic 10 Desc. Temporary vegetative stabilization in acceptable condition		Pic 10 Desc. Temporary vegetative stabilization in acceptable condition	
62°NE (T) 17 N 626885 4089794 ±13ft ▲ 799ft  15157+00 08-01-2022, 11:56:46				47°NE (T) 17 N 626893 4089799 ±39ft ▲ 800ft  15157+00 08-01-2022, 11:56:32	
GPS Location 0		GPS Location 0		GPS Location 0	
Field Station# 15157+00		Field Station# 15157+00		Field Station# 15157+00	
Pic 11 Desc. Waterbar in acceptable condition		Pic 12 Desc. Waterbar end treatment in acceptable condition		Pic 12 Desc. Waterbar end treatment in acceptable condition	

Pictures			
-----------------	--	--	--

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40445	
Inspector Ben Davenport		Date/Time 8/1/2022 11:20 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14311+57	
State VA	Inspection Area Partial	Station End 14454+22	
County Franklin	Ground Muddy	Temperature (°F) 85.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 4.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance		
Equipment Bridge	Communication	Routine maintenance		
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance		
Compost Filter Sock	Communication	Routine maintenance		
Equipment Bridge	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/1/2022 11:20 AM	Report # 40445
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

-Available for work
 -Received instruction from Lead EI for daily tasks
 -Checked rain gauges in covered area
 -Cloudy with muddy ground conditions during inspection
 -Performed SWPPP inspection on portion of MVP Spread I section
 -Covered territory between station# 14311+57 — 14454+22 (Farm View Rd to Webster Rd)
 -Walked ROW making note of condition of ROW and environmental controls
 -Verified the completion and accuracy of punch list items in covered area from previous inspections
 -Perimeter controls and ECD's were inspected; 2 issues identified
 -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; 2 issues identified
 -Inspection observed condition of RCEs and culverts in section; no issues identified
 -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
 -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
 -Continue to monitor ROW for signs of erosion
 -4 items added to environmental punch list

-Rain Gauge Totals:
 +Farm View: 2.40 inches recorded
 +Timber Ridge: 4.00 inches recorded

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/1/2022 11:20 AM	Report #	
Pictures					
					
<small>37°2'10" N 79°47'56" W 337°NW COURSE 89° GPS Glade Hill, VA 24092, United States</small>			<small>37°1'51" N 79°46'43" W 163°S COURSE 102° GPS Glade Hill, VA 24092, United States</small>		
<small>08.01.2022 11:18:51 Accur +/-11.8 Ft ALT 1076 Ft</small>			<small>08.01.2022 12:01:26 Accur +/-22.3 Ft ALT 1023 Ft</small>		
GPS Location	1		GPS Location	2	
Field Station#	14354+00		Field Station#	14420+21	
Pic 1 Desc.	Routine maintenance. Perimeter P1 silt fence undermining in resource buffer.		Pic 2 Desc.	Routine maintenance. Tree down on equipment bridge.	
					
<small>37°1'44" N 79°46'30" W 58°NE COURSE -1° GPS Glade Hill, VA 24092, United States</small>			<small>37°1'44" N 79°46'29" W 65°NE COURSE -1° GPS Glade Hill, VA 24092, United States</small>		
<small>08.01.2022 12:07:42 Accur +/-15.1 Ft ALT 1035 Ft</small>			<small>08.01.2022 12:07:52 Accur +/-15.1 Ft ALT 1040 Ft</small>		
GPS Location	3		GPS Location	4	
Field Station#	14433+00		Field Station#	14433+25	
Pic 3 Desc.	Routine maintenance. Replace row of P1 silt fence beyond effective lifespan behind end treatment.		Pic 4 Desc.	Routine maintenance. Tree down on perimeter CFS; repair/replace damaged CFS.	
					
<small>37°2'16" N 79°48'14" W 350°N COURSE -1° GPS 1862 Golden View Rd, Glade Hill, VA 24092, United States</small>			<small>37°1'53" N 79°47'17" W 349°N COURSE 280° GPS Glade Hill, VA 24092, United States</small>		
<small>08.01.2022 11:10:26 Accur +/-14.0 Ft ALT 1141 Ft</small>			<small>08.01.2022 11:46:42 Accur +/-79.7 Ft ALT 1032 Ft</small>		
GPS Location	5		GPS Location	6	
Field Station#	14338+56		Field Station#	14391+59	
Pic 5 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.		Pic 6 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	

AFE 124300139	Date/Time 8/1/2022 11:20 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300139	Date/Time	8/1/2022 11:20 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40503	
Inspector Charles Head		Date/Time 8/1/2022 2:40 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	14694+77
State VA	Inspection Area Full	Station End	14802+19
County Franklin	Ground Wet	Temperature (°F)	82.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	1.10
			Rain Accumulation Time (days) 2.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/1/2022 2:40 PM	Report #	40503
------------	-----------	------------------	------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/1/2022 2:40 PM	Report #
Pictures			
GPS Location	0	GPS Location	0
Field Station#	14694+77	Field Station#	14729+19
Pic 1 Desc.	Approximately 14694+77. Overview of road crossing and RCE.	Pic 2 Desc.	Approximately 14729+19. Overview of stream crossing, equipment bridge and ECDs at stream S-A20.
GPS Location	0	GPS Location	0
Field Station#	14743+00	Field Station#	14794+00
Pic 3 Desc.	Approximately 14743+00. Overview of ROW.	Pic 4 Desc.	Approximately 14794+00. Overview of stream crossing, equipment bridge and ECDs at stream S-H24.
GPS Location	0	GPS Location	0
Field Station#	14706+00	Field Station#	14716+40
Pic 5 Desc.	Approximately 14706+00. Overview of ROW.	Pic 6 Desc.	Approximately 14716+40. Overview of LOD at wetland W-H11. Sediment and debris have entered wetland W-H11 due to lack of/non functioning third party ECDs.

AFE 124300139	Date/Time 8/1/2022 2:40 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/1/2022 2:40 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40487	
Inspector John White		Date/Time 8/1/2022 10:46 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15584+23
State VA	Inspection Area Full	Station End	15647+03
County Pittsylvania	Ground Wet	Temperature (°F)	82.00
Municipality Chatham	Weather Cloudy	Rain Gauge (in)	1.00
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication	Perform maintenance		
Silt Fence (Filter Fabric Fence)	Communication	Contractor performed maintenance		8/1/2022
Waterbar	Communication	Stabilize		
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/1/2022 10:46 AM	Report # 40487
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Checked rain gauges, Anderson Mill #2=.6", Mill Creek =.5", Transco =.6". Other than that there were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/1/2022 10:46 AM		Report #	
Pictures					
GPS Location O		GPS Location O			
Field Station# 15589+00		Field Station# 15590+00			
Pic 1 Desc. Observing temporary stabilization and water bars		Pic 2 Desc. Observing water bar that needs to be stabilized			
GPS Location O		GPS Location O			
Field Station# 15595+60		Field Station# 15601+00			
Pic 3 Desc. Observing temporary stabilization,buffer, equipment crossing and ECD's		Pic 4 Desc. Observing water bar that needs to be stabilized			
GPS Location O		GPS Location O			
Field Station# 15603+00		Field Station# 15619+48			
Pic 5 Desc. Observing tree that needs to be removed from CFS and maintenance performed as needed		Pic 6 Desc. Observing road crossing and RCE's			

AFE 124300139		Date/Time 8/1/2022 10:46 AM		Report #	
Pictures					
GPS Location O		GPS Location O			
Field Station# 15624+00		Field Station# 15611+00			
Pic 7 Desc. Observing temporary stabilization and water bars		Pic 8 Desc. Observing water bar that needs to be stabilized			
GPS Location O		GPS Location O			
Field Station# 15632+00		Field Station# 15636+45			
Pic 9 Desc. Observing temporary stabilization, CWD outlet and ECD's		Pic 10 Desc. Observing temporary stabilization, buffer, equipment crossing and ECD's			
GPS Location O		GPS Location O			
Field Station# 15639+00		Field Station# 15639+00			
Pic 11 Desc. Observing P1 that required maintenance		Pic 12 Desc. Observing the Contractor performing maintenance			

A/E	124300139	Date/Time	8/1/2022 10:46 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40552	
Inspector Ben Farmer		Date/Time 8/2/2022 12:55 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13958+31	
State VA	Inspection Area Partial	Station End 14062+17	
County Franklin	Ground Damp	Temperature (°F) 75.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/2/2022 12:55 PM	Report # 40552
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		






7. Identify all remedial measures that have been taken since the previous inspection was conducted.













Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 75F)
 Rain Gauge= 0.0"
 13958+31-14062+17

- This section remains stabilized.
- CWD/CWD inlets are in good condition and functioning as intended
- Equipment bridge ECDs are in good condition
- MVP-ATWS-1446 remains stabilized with controls in place.
- P1 is in good condition at all stream and wetland buffers.
- No evidence of 3rd party pond discharging onto ROW at 14000+00
- Resource buffers remain well vegetated.
- Slope on the CIS of Highway 220 remains stabilized with controls in place.
- Waterbars/end treatments are functioning as intended.
- CFS is in good condition
- Slope drain is functioning as intended at 14058+00
- Rock check dams are functioning at 14059+00.
- Vegetation continues to fill in throughout this section


Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/2/2022 12:55 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13960+00		Field Station#	13997+50	
Pic 1 Desc.	CWDs are functioning as intended		Pic 2 Desc.	P1 is in good condition at all stream and wetland buffers	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14000+00		Field Station#	14009+11	
Pic 3 Desc.	No evidence of 3rd party pond discharging onto ROW		Pic 4 Desc.	SSF is in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14018+47		Field Station#	14027+00	
Pic 5 Desc.	RCEs are in good condition at all road crossings		Pic 6 Desc.	CFS is in good condition throughout this section	

AFE 124300139		Date/Time 8/2/2022 12:55 PM	Report #
Pictures			
 		 	
GPS Location	See photo	GPS Location	See photo
Field Station#	14033+00	Field Station#	14033+00
Pic 7 Desc.	Waterbars are in good condition	Pic 8 Desc.	End treatments are functioning as intended
 		 	
GPS Location	See photo	GPS Location	See photo
Field Station#	14035+00	Field Station#	14050+00
Pic 9 Desc.	Resource buffers remain well vegetated	Pic 10 Desc.	Slope remains stabilized with controls in place
 		 	
GPS Location	See photo	GPS Location	See photo
Field Station#	14051+00	Field Station#	14057+00
Pic 11 Desc.	Equipment bridge ECDs are in good condition	Pic 12 Desc.	Slope drain outlet is in good condition and functioning

AFE 124300139	Date/Time 8/2/2022 12:55 PM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	
---------------------	-----------	---------------------	--

Field Station#	14060+00	Field Station#	
-----------------------	----------	-----------------------	--


Pic 13 Desc.	RCEs are in good condition and functioning	Pic 14 Desc.	
---------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 15 Desc.		Pic 16 Desc.	
---------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 17 Desc.		Pic 18 Desc.	
---------------------	--	---------------------	--



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40538	
Inspector Justin Burch		Date/Time 8/2/2022 9:08 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15260+00
State VA	Inspection Area Full	Station End	15370+62
County Pittsylvania	Ground Wet	Temperature (°F)	91.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.80
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Reinforce Filter Fence)	Communication			
Compost Filter Sock	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Rock Construction Entrance	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/2/2022 9:08 AM	Report # 40538
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		





7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15260+00 to 15370+62 (Pigg River HDD Exit to Snowberry Road). Two issues were submitted for the punch list, both of which consisted of P1 silt fence which was damaged by livestock. Other inspected ECDs were observed as in compliance at the time of inspection.
- The EI did not observe that the contractor has worked in the area since the last SWPPP inspection.
- Since the last SWPPP inspection the inspection area has received two rainfall events with a total of 0.80" at Snowberry Road.
- The ROW ground condition is wet.
- At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15355+00 to 15370+00.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/2/2022 9:08 AM		Report #			
Pictures							
							
GPS Location		0		GPS Location		0	
Field Station#		15313+00		Field Station#		15311+00	
Pic 1 Desc.		P1 silt fence damaged by livestock (3 panels)		Pic 2 Desc.		P1 silt fence damaged by livestock (4 panels)	
							
GPS Location		0		GPS Location		0	
Field Station#		15353+00		Field Station#		15337+00	
Pic 3 Desc.		Perimeter CFS in acceptable condition		Pic 4 Desc.		Temporary vegetative stabilization in acceptable condition	
							
GPS Location		0		GPS Location		0	
Field Station#		15335+00		Field Station#		15316+00	
Pic 5 Desc.		Sump pit in acceptable condition		Pic 6 Desc.		Waterbar in acceptable condition	

AFE 124300139		Date/Time 8/2/2022 9:08 AM		Report #	
Pictures					
<small>☺ 294°NW (T) ● 17 N 631301 4088102 ±13ft ▲ 684ft</small> 		<small>☺ 154°SE (T) ● 17 N 623554 4083085 ±26699ft ▲ 669ft</small> 			
<small>15315+00 08-02-2022 09:25:34</small>		<small>15314+29 08-02-2022 09:28:42</small>			
GPS Location	0		GPS Location	0	
Field Station#	15315+00		Field Station#	15314+29	
Pic 7 Desc.	Waterbar end treatment in acceptable condition		Pic 8 Desc.	Equipment bridge in acceptable condition	
<small>☺ 299°NW (T) ● 17 N 631190 4088102 ±561ft ▲ 671ft</small> 		<small>☺ 225°SW (T) ● 17 N 631121 4088159 ±32ft ▲ 733ft</small> 			
<small>15311+00 08-02-2022 09:32:10</small>		<small>15310+00 08-02-2022 09:37:09</small>			
GPS Location	0		GPS Location	0	
Field Station#	15311+00		Field Station#	15310+00	
Pic 9 Desc.	Temporary vegetative stabilization in acceptable condition		Pic 10 Desc.	Waterbar in acceptable condition	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		

AFE 124300139	Date/Time 8/2/2022 9:08 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 13 Desc.	Pic 14 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 15 Desc.	Pic 16 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40498	
Inspector Ben Davenport		Date/Time 8/2/2022 11:32 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14454+22	
State VA	Inspection Area Partial	Station End 14546+75	
County Franklin	Ground Muddy	Temperature (°F) 88.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)	Communication	Ineffective ESC measure		
Compost Filter Sock	Communication	Routine maintenance		
Equipment Bridge	Communication	Routine maintenance		
Equipment Bridge	Communication	Routine maintenance		
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance		
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Sensitive Resource Buffer	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/2/2022 11:32 AM	Report # 40498
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- Available for work
- Received instruction from Lead EI for daily tasks
- Sunny with muddy ground conditions during inspection
- Performed SWPPP inspection on portion of MVP Spread I section
- Covered territory between station# 14454+22 — 14546+75 (Webster Rd to Tobacco Rd)
- Roberts Corrosion at Timber Ridge Road performing maintenance during inspection
- Precision environmental crew in section during inspection
- Walked ROW making note of condition of ROW and environmental controls
- Verified the completion and accuracy of punch list items in covered area from previous inspections
- Perimeter controls and ECDs were inspected; multiple issues identified
- Inspection observed condition of equipment bridges and surrounding ECDs around stream crossings and resource buffers; multiple issues identified
- Inspection observed condition of RCEs and culverts in section; no issues identified
- Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
- Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
- Continue to monitor ROW for signs of erosion
- 5 items added to environmental punch list in section

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/2/2022 11:32 AM		Report #	
Pictures					
					
37°11'11" N 79°45'44" W 357' N COURSE 158' GPS Glade Hill, VA 24092, United States 08.02.2022 09:43:06 Accur +/-43.4 Ft ALT 917 Ft		37°12' N 79°45'35" W 19' N COURSE 322' GPS 1142 SR-703, Glade Hill, VA 24092, United States 08.02.2022 09:27:22 Accur +/-11.6 Ft ALT 880 Ft			
GPS Location	1	GPS Location	2		
Field Station#	14485+00	Field Station#	14496+00		
Pic 1 Desc.	Ineffective ESC measure. Perimeter P1 silt fence undermined. Replace row of P1 silt fence and repair/ stabilize erosion channel.	Pic 2 Desc.	Routine maintenance. Perimeter CFS in resource buffer shifted due to water flow. Needs reset and restaked.		
					
37°12' N 79°45'35" W 165' S COURSE -1' GPS 1142 SR-703, Glade Hill, VA 24092, United States 08.02.2022 09:26:37 Accur +/-13.4 Ft ALT 886 Ft		37°0'33" N 79°45'15" W 119' SE COURSE -1' GPS Glade Hill, VA 24092, United States 08.02.2022 10:14:41 Accur +/-15.5 Ft ALT 1011 Ft			
GPS Location	3	GPS Location	4		
Field Station#	14496+58	Field Station#	14531+58		
Pic 3 Desc.	Routine maintenance. Bridge maintenance required at S-G20.	Pic 4 Desc.	Routine maintenance. Bridge maintenance required at S-G18.		
					
37°0'33" N 79°45'15" W 134' SE COURSE 238' GPS Glade Hill, VA 24092, United States 08.02.2022 10:17:03 Accur +/-13.0 Ft ALT 999 Ft		37°0'53" N 79°45'29" W 72' E COURSE 311' GPS 1979 SR-674, Glade Hill, VA 24092, United States 08.02.2022 09:17:57 Accur +/-12.7 Ft ALT 967 Ft			
GPS Location	5	GPS Location	6		
Field Station#	14532+00	Field Station#	14507+00		
Pic 5 Desc.	Routine maintenance. P1 silt fence in resource buffer undermining and needs repaired.	Pic 6 Desc.	ROW stabilized and vegetated in temporary area; perimeter SSF in place and functional.		

AFE 124300139	Date/Time 8/2/2022 11:32 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/2/2022 11:32 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40550	
Inspector Charles Head		Date/Time 8/2/2022 11:48 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14802+19	
State VA	Inspection Area Full	Station End 14928+52	
County Franklin	Ground Damp	Temperature (°F) 88.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
3rd Party Damages	Communication	Repair livestock damage to CFS and		
Compost Filter Sock	Communication	Remove soil from CFS from livestock		
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	Repair livestock damage		
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/2/2022 11:48 AM	Report # 40550
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/2/2022 11:48 AM	Report #	
Pictures					
					
GPS Location 0		GPS Location 0			
Field Station# 14809+00		Field Station# 14845+68			
Pic 1 Desc. Approximately 14809+00. Overview of ROW. Permanent vegetation.		Pic 2 Desc. Approximately 14845+68. Overview of road crossing and RCEs.			
					
GPS Location 0		GPS Location 0			
Field Station# 14870+00		Field Station# 14907+60			
Pic 3 Desc. Approximately 14870+00. Overview of stream crossing, equipment bridge and ECDs at stream S-SS8.		Pic 4 Desc. Approximately 14907+60. Overview of stream crossing, equipment bridge and ECDs at stream S-DD3.			
					
GPS Location 0		GPS Location 0			
Field Station# 14923+00		Field Station# 14823+40			
Pic 5 Desc. Approximately 14923+00. P-1 along drainage feature requires maintenance. Damaged by livestock.		Pic 6 Desc. Approximately 14823+40. CFS requires maintenance. Livestock damage. Remove soil buildup from CFS.			

AFE 124300139	Date/Time 8/2/2022 11:48 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300139	Date/Time	8/2/2022 11:48 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40546	
Inspector John White		Date/Time 8/2/2022 10:41 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15647+03
State VA	Inspection Area Full	Station End	15772+27
County Pittsylvania	Ground Damp	Temperature (°F)	85.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.90
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar	Communication	Stabilize		
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Communication	Gap fill and check placement		
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			

- 5. Site Conditions**
- Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. No
 - Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? Yes
 - Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? Yes
 - Has a new slip/slide been observed? (If yes, complete Slide Report Form) No

AFE	124300139	Date/Time	8/2/2022 10:41 AM	Report #	40546
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. Checked rain gauges, Anderson Mill #2=0, Mill Creek =0, Transco =.2". Other than that there were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/2/2022 10:41 AM	Report #
Pictures			
GPS Location	O	GPS Location	O
Field Station#	15740+00	Field Station#	15730+00
Pic 1 Desc.	Observing temporary stabilization, sump and end treatment	Pic 2 Desc.	Observing end of water bar that needs to be stabilized
GPS Location	O	GPS Location	O
Field Station#	15720+00	Field Station#	15713+52
Pic 3 Desc.	Observing temporary stabilization, CWD outlet and ECD's	Pic 4 Desc.	Observing temporary stabilization, water bar, signage, buffer, equipment crossing and ECD's
GPS Location	O	GPS Location	O
Field Station#	15710+00	Field Station#	15709+00
Pic 5 Desc.	Observing end of water bar that needs to be stabilized	Pic 6 Desc.	Observing end of water bar that needs to be stabilized

AFE	124300139	Date/Time	8/2/2022 10:41 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--


Pictures



GPS Location	O	GPS Location	O
Field Station#	15690+00	Field Station#	15671+93
Pic 7 Desc.	Observing temporary stabilization and water bars	Pic 8 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's



GPS Location	O	GPS Location	O
Field Station#	15658+43	Field Station#	15693+89
Pic 9 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's	Pic 10 Desc.	Observing road crossing and RCE's



GPS Location	O	GPS Location	O
Field Station#	15755+00	Field Station#	15752+00
Pic 11 Desc.	Observing temporary stabilization, sump, end treatment and ECD's	Pic 12 Desc.	Observing temporary stabilization and water bars

A/E	124300139	Date/Time	8/2/2022 10:41 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40598	
Inspector Ben Farmer		Date/Time 8/3/2022 1:21 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14062+17	
State VA	Inspection Area Partial	Station End 14171+36	
County Franklin	Ground Dry	Temperature (°F) 75.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Communication	RCE needs additional stone.		
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/3/2022 1:21 PM	Report # 40598
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.







Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 75F)
 Rain Gauge= 0.0"
 14062+17-14171+36

- P1 is in good condition at all stream and wetland buffers
- Equipment bridge ECDs are in good condition and functioning.
- CWDs are functioning as intended.
- MVP-FR-309.05 is in good condition with controls in place.
- Resource buffers remain well vegetated.
- CFS is in good condition throughout this section
- Waterbars/end treatments are in good condition and functioning
- RCE needs additional stone at 14131+00.
- Slope drain is functioning as intended at 14157+00.
- Vegetation continues to fill in throughout this section







*Issues identified in the field have been added to the punch list to be addressed by the contractor.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/3/2022 1:21 PM		Report #	
Pictures					
					
GPS Location See photo		GPS Location See photo			
Field Station# 14066+00		Field Station# 14070+00			
Pic 1 Desc. Equipment bridge ECDs are in good condition and functioning		Pic 2 Desc. CWDs are functioning as intended			
					
GPS Location See photo		GPS Location See photo			
Field Station# 14081+53		Field Station# 14090+00			
Pic 3 Desc. MVP-FR-309.05 is in good condition with controls in place		Pic 4 Desc. Topsoil berms remain stabilized			
					
GPS Location See photo		GPS Location See photo			
Field Station# 14105+20		Field Station# 14109+00			
Pic 5 Desc. Resource buffers remain well vegetated		Pic 6 Desc. End treatments are functioning as intended			

AFE 124300139	Date/Time 8/3/2022 1:21 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

			
GPS Location	See photo	GPS Location	See photo
Field Station#	14109+00	Field Station#	14120+00
Pic 7 Desc.	Waterbars are in good condition	Pic 8 Desc.	CFS is in good condition throughout this section
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14131+00	Field Station#	14141+00
Pic 9 Desc.	RCE needs additional stone.	Pic 10 Desc.	P1 is in good condition at all stream and wetland buffers
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14156+00	Field Station#	14171+36
Pic 11 Desc.	Slope drain is in good condition and functioning	Pic 12 Desc.	SSF is in good condition.

AFE	124300139	Date/Time	8/3/2022 1:21 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Pic 13 Desc.		Pic 14 Desc.		Pic 14 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Pic 15 Desc.		Pic 16 Desc.		Pic 16 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Pic 17 Desc.		Pic 18 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40621	
Inspector Frank Craycroft		Date/Time 8/3/2022 2:24 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	13670+00
State VA	Inspection Area Full	Station End	13748+30
County Franklin	Ground Dry	Temperature (°F)	90.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Equipment Bridge	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/3/2022 2:24 PM	Report # 40621
----------------------	-----------------------------------	-----------------------

6. **PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation established fr		













7. Identify all remedial measures that have been taken since the previous inspection was conducted.







Comments (Reference above questions as appropriate.)

Conducted SWPPP inspection of ROW from Spread H/I break to Green Level Rd. Vegetation was generally good to excellent with permanent grasses established from app. SN 13710+00 to Green Level Rd. No signs of erosion or washing were observed. All perimeter ECDs inspected were functional and in good condition. Resource buffers in area are intact and stable with no signs of sedimentation entering resource. Rock construction entrances were free of mud and dirt accumulation.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/3/2022 2:24 PM		Report #	
Pictures					
GPS Location 0		GPS Location 0			
Field Station# 13678+50		Field Station# 13678+00			
Pic 1 Desc. CIS S-E29 Banks		Pic 2 Desc. CIS S-E29 Buffer zone silt fence			
GPS Location 0		GPS Location 0			
Field Station# 13685+00		Field Station# 13737+00			
Pic 3 Desc. Perimeter CFS		Pic 4 Desc. Perimeter CFS			
GPS Location 0		GPS Location 0			
Field Station# 13727+50		Field Station# 13716+00			
Pic 5 Desc. CIS S-EF4 Travel lane and buffer zone		Pic 6 Desc. Sideslope vegetation			

AFE 124300139		Date/Time 8/3/2022 2:24 PM		Report #	
Pictures					
 		 		ert image here	
GPS Location 0		GPS Location 00			
Field Station# 13715+00		Field Station# 13707+00			
Pic 7 Desc. Perimeter CFS		Pic 8 Desc. Sump and J-Hook			
 		 		ert image here	
GPS Location 0		GPS Location 0			
Field Station# 13706+00		Field Station# 13705+00			
Pic 9 Desc. GAS S-E28 Buffer zone ECDs		Pic 10 Desc. S-E28 Equipment bridge			
 		 			
GPS Location 0		GPS Location 0			
Field Station# 13701+00		Field Station# 13695+00			
Pic 11 Desc. Fill slope vegetation and perimeter Super Silt Fence		Pic 12 Desc. CIS W-E7 Silt fence			

AFE 124300139		Date/Time 8/3/2022 2:24 PM		Report #	
Pictures					
					
GPS Location 0		GPS Location 0			
Field Station# 13692+70		Field Station# 13720+00			
Pic 13 Desc. S-E28 Channel		Pic 14 Desc. Sideslope vegetation			
					
GPS Location 0		GPS Location			
Field Station# 13740+00		Field Station#			
Pic 15 Desc. Perimeter CFS		Pic 16 Desc.			
					
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40595	
Inspector Justin Burch		Date/Time 8/3/2022 11:29 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15370+62
State VA	Inspection Area Full	Station End	15480+67
County Pittsylvania	Ground Wet	Temperature (°F)	92.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.50
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Communication			
Compost Filter Sock	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Equipment Bridge	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/3/2022 11:29 AM	Report # 40595
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		





7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15370+62 to 15480+67 (Snowberry Road to Toshes Road). Three items were submitted for the punch list all of which were due to third party damaged to temporary vegetative stabilization. Other inspected ECDs were observed as in compliance at the time of inspection.
- The EI did not observe that the contractor has worked in the area since the last SWPPP inspection.
- The EI observed that the solar farm perimeter ECDs on the CIS of Toshes Road appeared to be in acceptable condition.
- Since the last SWPPP inspection the inspection area has received one rain event with a total of 0.50" at Snowberry Road.
- The ROW ground condition is damp.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion.
- At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15438+00 to 15445+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/3/2022 11:29 AM		Report #	
Pictures					
					
GPS Location 0		GPS Location P			
Field Station# 15458+00		Field Station# 15463+00			
Pic 1 Desc. Third party damage to temporary vegetative stabilization from 15458+00 to 15458+50		Pic 2 Desc. Third party damage to temporary vegetative stabilization from 15462+00 to 15465+00			
					
GPS Location 0		GPS Location 0			
Field Station# 15468+00		Field Station# 15472+00			
Pic 3 Desc. Third party damage to temporary vegetative stabilization from 15468+00 to 15470+00		Pic 4 Desc. Perimeter CFS and temporary vegetative stabilization in acceptable conditions			
					
GPS Location 0		GPS Location 0			
Field Station# 15394+00		Field Station# 15396+00			
Pic 5 Desc. P1 silt fence in acceptable condition		Pic 6 Desc. Temporary vegetative stabilization in acceptable condition			

AFE 124300139		Date/Time 8/3/2022 11:29 AM		Report #	
Pictures					
 <p>4°N (T) 17 N 632798 4087241 ±167ft ▲ 784ft 15376+00 08-03-2022, 09:13:24</p>		 <p>352°N (T) 17 N 632800 4087268 ±597ft ▲ 780ft 15376+00 08-03-2022, 09:13:50</p>			
GPS Location	0	GPS Location	0		
Field Station#	15376+00	Field Station#	15376+00		
Pic 7 Desc.	Waterbar in acceptable condition		Pic 8 Desc.	Waterbar end treatment in acceptable condition	
 <p>308°NW (T) 17 N 633940 4086811 ±456ft ▲ 786ft 15415+00 08-03-2022, 10:03:09</p>		 <p>149°SE (T) 17 N 634073 4086786 ±255ft ▲ 817ft 15419+00 08-03-2022, 10:07:25</p>			
GPS Location	0	GPS Location	0		
Field Station#	15415+00	Field Station#	15419+00		
Pic 9 Desc.	P1 silt fence and sensitive resource buffer in acceptable conditions		Pic 10 Desc.	Waterbar end treatment and perimeter CFS in acceptable conditions	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	8/3/2022 11:29 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40548	
Inspector Ben Davenport		Date/Time 8/3/2022 1:37 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14546+75	
State VA	Inspection Area Partial	Station End 14649+67	
County Franklin	Ground Muddy	Temperature (°F) 88.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
Rain Accumulation Time (days)			0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication	Routine maintenance		
Waterbar	Communication	Routine maintenance		
Vegetative Stabilization (Temporary)	Acceptable			
Temporary Diversion Berm	Acceptable			
Plunge Pool	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Sediment Filter Log	Acceptable			

- 5. Site Conditions**
- Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. No
 - Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? Yes
 - Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? Yes
 - Has a new slip/slide been observed? (If yes, complete Slide Report Form) No

AFE 124300139	Date/Time 8/3/2022 1:37 PM	Report # 40548
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- Available for work
- Received instruction from Lead EI for daily tasks
- Sunny with muddy ground conditions during inspection
- Performed SWPPP inspection on portion of MVP Spread I section
- Covered territory between station# 14546+75 — 14649+67 (Tobacco Rd to Hwy 40 crossing)
- Walked ROW making note of condition of ROW and environmental controls
- Verified the completion and accuracy of punch list items in covered area from previous inspections
- Perimeter controls and ECDs were inspected; 2 issues identified
- Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified
- Inspection observed condition of RCEs and culverts in section; no issues identified
- Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
- Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
- Continue to monitor ROW for signs of erosion
- 2 items added to environmental punch list in covered area

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/3/2022 1:37 PM		Report #	
Pictures					
					
<small>37°0'11" N 79°44'33" W 91°E COURSE 253' GPS Glade Hill, VA 24092, United States</small>		<small>08.03.2022 10:15:24 Accur +/-15.5 Ft ALT 854 Ft</small>		<small>36°59'54" N 79°44'21" W 259°W COURSE 169' GPS 753 Simmons Creek Rd, Union Hall, VA 24176, United States</small>	
<small>08.03.2022 10:26:50 Accur +/-11.6 Ft ALT 948 Ft</small>					
GPS Location	1	GPS Location	2	GPS Location	3
Field Station#	14583+25	Field Station#	14595+00	Field Station#	14553+00
Pic 1 Desc.	Routine maintenance. CFS in resource buffer needs reset and restaked.	Pic 2 Desc.	Routine maintenance. Denuded area in throat of water bar needs seeded and stabilized.	Pic 3 Desc.	ROW stabilized and vegetated in temporary area.
					
<small>37°0'12" N 79°45'4" W 192°S COURSE -1' GPS 594 Tobacco Rd, Glade Hill, VA 24092, United States</small>		<small>08.03.2022 09:57:17 Accur +/-15.1 Ft ALT 937 Ft</small>		<small>37°0'3" N 79°44'50" W 10°N COURSE 263' GPS 594 Tobacco Rd, Glade Hill, VA 24092, United States</small>	
<small>08.03.2022 10:05:09 Accur +/-17.3 Ft ALT 862 Ft</small>					
GPS Location	3	GPS Location	4	GPS Location	5
Field Station#	14553+00	Field Station#	14568+10	Field Station#	14606+00
Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer; signage visible and intact.	Pic 5 Desc.	Plunge pool performing intended function.	Pic 6 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.
					
<small>36°59'46" N 79°44'10" W 165°S COURSE -1' GPS 753 Simmons Creek Rd, Union Hall, VA 24176, United States</small>		<small>08.03.2022 10:32:18 Accur +/-15.1 Ft ALT 897 Ft</small>		<small>36°59'44" N 79°44'7" W 118°SE COURSE 79' GPS Sorry no results found</small>	
<small>08.03.2022 10:34:55 Accur +/-34.7 Ft ALT 892 Ft</small>					
GPS Location	5	GPS Location	6	GPS Location	
Field Station#	14606+00	Field Station#	14611+38	Field Station#	

AFE 124300139	Date/Time 8/3/2022 1:37 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/3/2022 1:37 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40591	
Inspector Charles Head		Date/Time 8/3/2022 9:59 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14928+52	
State VA	Inspection Area Full	Station End 15063+85	
County Franklin/Pittsylvania	Ground Damp	Temperature (°F) 77.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/3/2022 9:59 AM	Report # 40591
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.


Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/3/2022 9:59 AM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures



GPS Location	0	GPS Location	0
Field Station#	14950+47	Field Station#	14969+00
Pic 1 Desc.	Approximately 14950+47. Overview of stream crossing, equipment bridge and ECDs at stream S-G13.	Pic 2 Desc.	Approximately 14969+00. Overview of ROW. Permanent vegetation.



GPS Location	0	GPS Location	0
Field Station#	14981+00	Field Station#	14991+62
Pic 3 Desc.	Approximately 14981+00. Overview of ROW, road crossing and RCEs.	Pic 4 Desc.	Approximately 14991+62. Overview of stream crossing, equipment bridge and ECDs at stream S-D7.



GPS Location	0	GPS Location	0
Field Station#	15016+00	Field Station#	15026+00
Pic 5 Desc.	Approximately 15016+00. Overview of ROW.	Pic 6 Desc.	Approximately 15026+00. Overview of stream crossing, equipment bridge and ECDs at stream S-D3.

AFE 124300139	Date/Time 8/3/2022 9:59 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/3/2022 9:59 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40589	
Inspector John White		Date/Time 8/3/2022 9:37 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15772+27	
State VA	Inspection Area Full	Station End 15947+64	
County Pittsylvania	Ground Damp	Temperature (°F) 84.00	
Municipality Chatham	Weather Sunny	Rain Gauge (in) 0.50	
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar	Communication	Stabilize		
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Sump Pit	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

A/E	124300139	Date/Time	8/3/2022 9:37 AM	Report #	40589
------------	-----------	------------------	------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.


AFE 124300139		Date/Time 8/3/2022 9:37 AM		Report #	
Pictures					
GPS Location O		GPS Location O			
Field Station# 15809+00		Field Station# 15807+00			
Pic 1 Desc. Observing temporary stabilization, sump and end treatment		Pic 2 Desc. Observing temporary stabilization, equipment crossing and ECD's			
GPS Location O		GPS Location O			
Field Station# 15794+77		Field Station# 15781+22			
Pic 3 Desc. Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		Pic 4 Desc. Observing temporary stabilization, equipment crossing and ECD's			
GPS Location O		GPS Location O			
Field Station# 15790+00		Field Station# 15825+00			
Pic 5 Desc. Observing temporary stabilization, CWD outlet and ECD's		Pic 6 Desc. Observing temporary stabilization, plunge pool and ECD's			

AFE 124300139	Date/Time 8/3/2022 9:37 AM	Report #
----------------------	-----------------------------------	-----------------


Pictures



GPS Location	O	GPS Location	O
Field Station#	15803+00	Field Station#	15850+00
Pic 7 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 8 Desc.	Observing end of water bar that needs to be stabilized



GPS Location	O	GPS Location	O
Field Station#	15925+00	Field Station#	15863+00
Pic 9 Desc.	Observing end of water bar that needs to be stabilized	Pic 10 Desc.	Observing end of water bar that needs to be stabilized



GPS Location	O	GPS Location	O
Field Station#	15875+00	Field Station#	15935+00
Pic 11 Desc.	Observing end of water bar that needs to be stabilized	Pic 12 Desc.	Observing end of water bar that needs to be stabilized

AFE 124300139	Date/Time 8/3/2022 9:37 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40640	
Inspector Glenn Mike Renfro		Date/Time 8/4/2022 1:38 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	0000+00
State VA	Inspection Area Full	Station End	0000+00
County Franklin	Ground Dry	Temperature (°F)	88.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	1.50
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Other - Explain in Comments	Acceptable	Inlet protection for catch basins		
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | N/A |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | N/A |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/4/2022 1:38 PM	Report #	40640
------------	-----------	------------------	------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va.
- The locations have received 1.5" of rainfall since the last inspection and site conditions were dry.
- All perimeter ECD's were inspected and no issues were observed.
- The inlet protection for the catch basins at LY-046 were found to be in acceptable condition.
- All secondary containment structures were inspected and no issues were identified at the time of inspection.
- The RCE at LY-045 was in good condition.
- All equipment at both locations were inspected and no leaks were observed the during inspection.
- The General Construction permits and contact information are posted at the entrance of LY-046 as required.
- There ware no problems identified during today's inspection.


Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139	Date/Time 8/4/2022 1:38 PM	Report #
----------------------	-----------------------------------	-----------------


Pictures



GPS Location	See picture	GPS Location	See picture
Field Station#	0000+00	Field Station#	0000+00
Pic 1 Desc.	RCE at LY-045 in good condition.	Pic 2 Desc.	Equipment at LY-045 inspected and no leaks observed at the time of inspection



GPS Location	See picture	GPS Location	See picture
Field Station#	0000+00	Field Station#	0000+00
Pic 3 Desc.	Secondary containment structure on south end of tent at LY-045 in acceptable condition.	Pic 4 Desc.	Perimeter ECD's on west side of LY-045 in good condition.



GPS Location	See picture	GPS Location	See picture
Field Station#	0000+00	Field Station#	0000+00
Pic 5 Desc.	Perimeter ECD's and inlet protection near storage building at LY-046 in good condition.	Pic 6 Desc.	Secondary containment structure for fuel cell at LY-046 in good condition.

AFE 124300139	Date/Time 8/4/2022 1:38 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures



GPS Location	See picture
---------------------	-------------

Field Station#	0000+00
-----------------------	---------

Pic 7 Desc.	Perimeter ECD's on north end of LY-046 in good condition.
--------------------	---

Insert image here	Insert image here
-------------------	-------------------

GPS Location	
---------------------	--

Field Station#	
-----------------------	--

Pic 9 Desc.	Pic 10 Desc.
--------------------	---------------------

Insert image here	Insert image here
-------------------	-------------------

GPS Location	
---------------------	--

Field Station#	
-----------------------	--

Pic 11 Desc.	Pic 12 Desc.
---------------------	---------------------

AFE 124300139	Date/Time 8/4/2022 1:38 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40639	
Inspector Ben Farmer		Date/Time 8/4/2022 1:13 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14171+36	
State VA	Inspection Area Partial	Station End 14311+57	
County Franklin	Ground Dry	Temperature (°F) 75.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/4/2022 1:13 PM	Report # 40639
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.







Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 75F)
 Rain Gauge= 0.0"
 14171+36-14311+57

- RCEs are in good condition at all road crossings.
- Equipment bridge ECDs are in good condition and functioning
- CWDs are functioning as intended.
- SSF is in good condition
- P1 is in good condition at all stream and wetland buffers
- Waterbars are in good condition throughout this section.
- Slope drain is in good condition and functioning at 14232+00
- Resource buffers remain well vegetated.
- CFS is in good condition throughout this section
- Topsoil berms remain stabilized

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/4/2022 1:13 PM		Report #	
Pictures					
					
GPS Location		See photo		GPS Location	
Field Station#		14171+36		Field Station#	
Pic 1 Desc.		RCEs are in good condition at all road crossings		Pic 2 Desc.	
				SSF is in good condition	
					
GPS Location		See photo		GPS Location	
Field Station#		14190+00		Field Station#	
Pic 3 Desc.		P1 is in good condition at all stream and wetland buffers		Pic 4 Desc.	
				CWDs are functioning as intended	
					
GPS Location		See photo		GPS Location	
Field Station#		14209+00		Field Station#	
Pic 5 Desc.		Equipment bridge ECDs are in good condition and functioning		Pic 6 Desc.	
				MVP-FR-311 remains in good condition with controls in place	

AFE	124300139	Date/Time	8/4/2022 1:13 PM	Report #
Pictures				
				
GPS Location	See photo		GPS Location	See photo
Field Station#	14232+00		Field Station#	14274+00
Pic 7 Desc.	Slope drain is in good condition and functioning		Pic 8 Desc.	CFS is in good condition throughout this section
				
GPS Location	See photo		GPS Location	See photo
Field Station#	14277+00		Field Station#	14277+00
Pic 9 Desc.	Waterbars are in good condition		Pic 10 Desc.	End treatments are functioning as intended
				
GPS Location	See photo		GPS Location	See photo
Field Station#	14278+93		Field Station#	14305+00
Pic 11 Desc.	Resource buffers remain well vegetated		Pic 12 Desc.	CWDs are functioning as intended.

AFE	124300139	Date/Time	8/4/2022 1:13 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40667	
Inspector Frank Craycroft		Date/Time 8/4/2022 2:48 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	0+00
State VA	Inspection Area Full	Station End	0+00
County Franklin	Ground Dry	Temperature (°F)	95.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Timber Mat	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waste Management	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	N/A
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE 124300139	Date/Time 8/4/2022 2:48 PM	Report # 40667
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)


Conducted SWPPP inspection of LY-032, -033, -048, and ANC-006. All portable equipment and hazardous materials were maintained within secondary containment. All stormwater drain inlets had proper perimeter protection and were free of debris and vegetation. All rock entrances were free of dirt and mud buildup. All loose materials and trash were maintained within bulk dumpsters on-site. All perimeter ECDs were functional and in good condition.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.


AFE	124300139	Date/Time	8/4/2022 2:48 PM	Report #	
Pictures					
					
GPS Location			0		
Field Station#			0+00		
Pic 1 Desc.			LY-033 Stormwater drain inlet protection		
					
GPS Location			0		
Field Station#			0+00		
Pic 3 Desc.			LY-033 Rock construction entrance		
					
GPS Location			0		
Field Station#			0+00		
Pic 5 Desc.			ANC-006 Southeast perimeter CFS		
Pic 6 Desc.			LY-048 West perimeter CFS		

AFE 124300139	Date/Time 8/4/2022 2:48 PM	Report #
----------------------	-----------------------------------	-----------------


Pictures



GPS Location	0	GPS Location	0
Field Station#	0+00	Field Station#	0+00
Pic 7 Desc.	LY-048 Southwest perimeter CFS	Pic 8 Desc.	LY-032 Secondary containment



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/4/2022 2:48 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40669	
Inspector Frank Craycroft		Date/Time 8/4/2022 3:09 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13748+30	
State VA	Inspection Area Full	Station End 13853+45	
County Franklin	Ground Dry	Temperature (°F) 95.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/4/2022 3:09 PM	Report #	40669
------------	-----------	------------------	------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)













PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired







7. Identify all remedial measures that have been taken since the previous inspection was conducted.





Comments (Reference above questions as appropriate.)

Conducted SWPPP inspection of ROW from Green Level Rd to MVP-FR-303.01. All perimeter ECDs observed were functional and in good condition. All resource buffers in area were intact and showed no signs of sedimentation reaching resource from ROW. All equipment bridges were clean and free of sediment or mud. Vegetation was generally good to excellent with some areas of the travel lane and road approaches having less productive growth. All waterbars and sumps are functioning well and have adequate additional storage capacity.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/4/2022 3:09 PM	Report #	
Pictures					
				GPS Location	0
Field Station#	13783+00	Field Station#	13781+00	Pic 1 Desc.	Sump
Pic 2 Desc.		Pic 3 Desc.	CIS S-RR15 Buffer zone and ECDs	GPS Location	0
				GPS Location	0
Field Station#	13770+00	Field Station#	13760+00	Pic 3 Desc.	CIS S-MM42 Buffer zone
Pic 4 Desc.		Pic 5 Desc.	Perimeter silt fence	GPS Location	0
				GPS Location	0
Field Station#	13757+00	Field Station#	13755+50	Pic 5 Desc.	GAS S-EF12 Buffer zone vegetation and Silt fence
Pic 6 Desc.		Pic 6 Desc.	S-EF12 Channel and banks		

AFE 124300139		Date/Time 8/4/2022 3:09 PM		Report #	
Pictures					
				<p>ert image here</p>	
GPS Location 0		GPS Location 0			
Field Station# 13783+00		Field Station# 13790+50			
Pic 7 Desc. Waterbar relay		Pic 8 Desc. S-D23 Channel and banks			
					
GPS Location 0		GPS Location 0			
Field Station# 13795+00		Field Station# 13806+50			
Pic 9 Desc. GAS S-D22 Buffer zone and silt fence		Pic 10 Desc. GAS S-D18 ECDs			
					
GPS Location 0		GPS Location 0			
Field Station# 13809+00		Field Station# 13815+00			
Pic 11 Desc. COS Brick Church Rd Vegetation		Pic 12 Desc. CFS Triple stack			

AFE 124300139		Date/Time 8/4/2022 3:09 PM		Report #	
Pictures					
 <p>GPS photo showing a grassy slope with trees. GPS coordinates: 331°NW (T) • 37.068099, -79.922386 ±12ft ▲ 1027ft</p>				 <p>GPS photo showing a stream crossing with a wooden structure and orange silt fence. GPS coordinates: 332°NW (T) • 37.063719, -79.921909 ±12ft ▲ 959ft</p>	
GPS Location 0		GPS Location 0			
Field Station# 13820+00		Field Station# 13835+50			
Pic 13 Desc. Sideslope vegetation		Pic 14 Desc. GAS S-C14 Buffer zone ECDs			
 <p>GPS photo showing a super silt fence perimeter. GPS coordinates: 26°N (T) • 37.063203, -79.921575 ±12ft ▲ 936ft</p>				 <p>GPS photo showing a GAS S-C16 Buffer zone with CFS. GPS coordinates: 316°NW (T) • 37.060425, -79.921112 ±12ft ▲ 947ft</p>	
GPS Location 0		GPS Location 0			
Field Station# 13840+00		Field Station# 13848+00			
Pic 15 Desc. Super silt fence perimeter of ROW		Pic 16 Desc. GAS S-C16 Buffer zone and CFS			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name H-603 Pipeline Spread I		AFE 124300139	Spread H-603 Pipeline Spread I
Contractor Precision		Report # 40630	
Inspector John White		Date/Time 8/4/2022 10:12 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	00+00
State VA	Inspection Area Full	Station End	24+53
County Pittsylvania	Ground Dry	Temperature (°F)	85.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.80
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/4/2022 10:12 AM	Report #	40630
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/4/2022 10:12 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--


Pictures



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	14+00	Field Station#	22+00
-----------------------	-------	-----------------------	-------

Pic 1 Desc.	Observing temporary stabilization and buffer	Pic 2 Desc.	Observing temporary stabilization and buffer
--------------------	--	--------------------	--



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	12+00	Field Station#	6+00
-----------------------	-------	-----------------------	------

Pic 3 Desc.	Observing temporary stabilization, sump and end treatment	Pic 4 Desc.	Observing temporary stabilization, sump and end treatment
--------------------	---	--------------------	---

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 5 Desc.		Pic 6 Desc.	
--------------------	--	--------------------	--

AFE	124300139	Date/Time	8/4/2022 10:12 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 7 Desc.	
Pic 7 Desc.		Pic 8 Desc.		Pic 8 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 9 Desc.	
Pic 9 Desc.		Pic 10 Desc.		Pic 10 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 11 Desc.	
Pic 11 Desc.		Pic 12 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/4/2022 10:12 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-602 Pipeline Spread I		AFE 124300139	Spread H-602 Pipeline Spread I
Contractor Precision		Report # 40632	
Inspector John White		Date/Time 8/4/2022 10:26 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	00+00
State VA	Inspection Area Full	Station End	19+25
County Pittsylvania	Ground Dry	Temperature (°F)	85.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.80
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/4/2022 10:26 AM	Report #	40632
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139	Date/Time 8/4/2022 10:26 AM	Report #
----------------------	------------------------------------	-----------------

Pictures



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	6+00	Field Station#	12+65
-----------------------	------	-----------------------	-------

Pic 1 Desc.	Observing temporary stabilization and access road	Pic 2 Desc.	Observing temporary stabilization,buffer equipment crossing and ECD's
--------------------	---	--------------------	---



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	15+00	Field Station#	13+50
-----------------------	-------	-----------------------	-------

Pic 3 Desc.	Observing temporary stabilization	Pic 4 Desc.	Observing temporary stabilization,water bar, sump and end treatment
--------------------	-----------------------------------	--------------------	---

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 5 Desc.		Pic 6 Desc.	
--------------------	--	--------------------	--

AFE 124300139	Date/Time 8/4/2022 10:26 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/4/2022 10:26 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40634	
Inspector Justin Burch		Date/Time 8/4/2022 11:19 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15480+67	
State VA	Inspection Area Full	Station End 15584+23	
County Pittsylvania	Ground Damp	Temperature (°F) 92.00	
Municipality Chatham	Weather Sunny	Rain Gauge (in) 0.50	
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Slope Drain Pipe	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/4/2022 11:19 AM	Report # 40634
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		





7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15480+67 to 15584+23 (Toshes Road to Anderson Mill Road 1). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection.
- The EI observed that the solar farm ECDs adjacent to the ROW on both sides of Climax Road appeared to be in acceptable condition and that solar farm grading is continuing between Toshes Road and Climax Road.
- The EI did not observe that the contractor has worked in the area since the last SWPPP inspection.
- Since the last SWPPP inspection the inspection area has received one rain event with a total of 0.50" at Snowberry Road.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion.
- At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15482+00 to 15495+00.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/4/2022 11:19 AM		Report #	
Pictures					
					
GPS Location		0		GPS Location	
Field Station#		15519+00		Field Station#	
Pic 1 Desc.		Waterbar in acceptable condition		Pic 2 Desc.	
				Waterbar end treatment in acceptable condition	
					
GPS Location		0		GPS Location	
Field Station#		15537+00		Field Station#	
Pic 3 Desc.		Clean water diversion berm and temporary vegetative stabilization in acceptable conditions		Pic 4 Desc.	
				P1 silt fence and sensitive resource buffer in acceptable conditions	
					
GPS Location		0		GPS Location	
Field Station#		15568+00		Field Station#	
Pic 5 Desc.		Temporary vegetative stabilization in acceptable condition		Pic 6 Desc.	
				Waterbar in acceptable condition	

AFE 124300139		Date/Time 8/4/2022 11:19 AM		Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15572+00	Field Station#	15573+00		
Pic 7 Desc.	Waterbar end treatment in acceptable condition		Pic 8 Desc.	Super silt fence in acceptable condition	
					
GPS Location	0	GPS Location	0		
Field Station#	15577+00	Field Station#	15498+00		
Pic 9 Desc.	Sump pit and slope drain pipe in acceptable conditions		Pic 10 Desc.	Solar farm perimeter ECDs appear to be in acceptable conditions	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

AFE 124300139	Date/Time 8/4/2022 11:19 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40628	
Inspector Ben Davenport		Date/Time 8/4/2022 11:07 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14649+67	
State VA	Inspection Area Partial	Station End 14694+77	
County Franklin	Ground Damp	Temperature (°F) 90.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Temporary Diversion Berm	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Erosion Control Blanket	Acceptable			
Compost Filter Sock	Acceptable			
Waterbar	Acceptable			
Sump Pit	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/4/2022 11:07 AM	Report # 40628
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- Available for work
- Received instruction from Lead EI for daily tasks
- Sunny with damp ground conditions during inspection
- Performed SWPPP inspection on portion of MVP Spread I section
- Covered territory between station# 14649+67 — 14694+77 (Hwy 40 crossing to Jacks Creek Rd)
- Walked ROW making note of condition of ROW and environmental controls
- Verified the completion and accuracy of punch list items in covered area from previous inspections
- Perimeter controls and ECDs were inspected; no issues identified
- Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified
- Inspection observed condition of RCEs and culverts in section; no issues identified
- Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
- Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
- Continue to monitor ROW for signs of erosion
- No items added to environmental punch list in section

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/4/2022 11:07 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	1	GPS Location	2
Field Station#	14650+50	Field Station#	14656+37
Pic 1 Desc.	Spoil pile stabilized and vegetated.	Pic 2 Desc.	Perimeter P1 silt fence in resource buffer in place and functional.



GPS Location	3	GPS Location	4
Field Station#	14658+60	Field Station#	14671+00
Pic 3 Desc.	Contractor installed erosion control blanket per punch list item.	Pic 4 Desc.	Water bar performing intended function; ROW stabilized and vegetated in temporary area.



GPS Location	5	GPS Location	6
Field Station#	14673+10	Field Station#	14678+00
Pic 5 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	Pic 6 Desc.	Sump pit and CFS end treatment performing intended functions.

AFE 124300139	Date/Time 8/4/2022 11:07 AM	Report #
----------------------	------------------------------------	-----------------

Pictures			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/4/2022 11:07 AM	Report #
----------------------	------------------------------------	-----------------

Pictures			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40637	
Inspector Charles Head		Date/Time 8/4/2022 12:56 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15063+85	
State VA	Inspection Area Full	Station End 15142+66	
County Pittsylvania	Ground Dry	Temperature (°F) 91.00	
Municipality Chatham	Weather Cloudy	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/4/2022 12:56 PM	Report # 40637
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/4/2022 12:56 PM	Report #
Pictures			
GPS Location	0	GPS Location	0
Field Station#	15086+00	Field Station#	15092+95
Pic 1 Desc.	Approximately 15086+00. Overview of ROW.	Pic 2 Desc.	Approximately 15092+95. Overview of stream crossing, equipment bridge and ECDs at stream S-G9.
GPS Location	0	GPS Location	0
Field Station#	15100+00	Field Station#	15103+45
Pic 3 Desc.	Approximately 15100+00. Overview of ROW. Permanent vegetation. Landowner allowing livestock to graze area.	Pic 4 Desc.	Approximately 15103+45. Overview of stream crossing, equipment bridge and ECDs at stream S-G8.
GPS Location	0	GPS Location	0
Field Station#	15110+00	Field Station#	15126+40
Pic 5 Desc.	Approximately 15110+00. Overview of ROW.	Pic 6 Desc.	Approximately 15126+40. Overview of stream crossing, equipment bridge and ECDs at stream S-A6.

AFE 124300139	Date/Time 8/4/2022 12:56 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/4/2022 12:56 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40633	
Inspector John White		Date/Time 8/4/2022 10:33 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15947+64	
State VA	Inspection Area Full	Station End 16027+46	
County Pittsylvania	Ground Dry	Temperature (°F) 85.00	
Municipality Chatham	Weather Sunny	Rain Gauge (in) 0.80	
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Waterbar	Communication	Stabilize		

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/4/2022 10:33 AM	Report #	40633
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/4/2022 10:33 AM		Report #	
Pictures					
<p>Your Watermark 04 Aug 2022, 08:23:11</p>			<p>Your Watermark 04 Aug 2022, 08:24:08</p>		
<p>GPS Location O</p>			<p>GPS Location O</p>		
<p>Field Station# 15970+00</p>			<p>Field Station# 15965+50</p>		
<p>Pic 1 Desc. Observing temporary stabilization and CWD berm</p>			<p>Pic 2 Desc. Observing end of water bar that needs to be stabilized</p>		
<p>Your Watermark 04 Aug 2022, 08:26:32</p>			<p>Your Watermark 04 Aug 2022, 08:29:54</p>		
<p>GPS Location O</p>			<p>GPS Location O</p>		
<p>Field Station# 15972+00</p>			<p>Field Station# 15977+35</p>		
<p>Pic 3 Desc. Observing temporary stabilization, CWD outlet and ECD's</p>			<p>Pic 4 Desc. Observing temporary stabilization, water bar, buffer, equipment crossing and ECD's</p>		
<p>Your Watermark 04 Aug 2022, 08:32:08</p>			<p>Your Watermark 04 Aug 2022, 08:32:10</p>		
<p>GPS Location O</p>			<p>GPS Location O</p>		
<p>Field Station# 15988+00</p>			<p>Field Station# 15988+00</p>		
<p>Pic 5 Desc. Observing end of water bar that needs to be stabilized</p>			<p>Pic 6 Desc. Observing end of water bar that needs to be stabilized</p>		

AFE	124300139	Date/Time	8/4/2022 10:33 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures

GPS Location	O	GPS Location	O
Field Station#	15986+50	Field Station#	15999+80
Pic 7 Desc.	Observing end of water bar that needs to be stabilized	Pic 8 Desc.	Observing temporary stabilization,water bar and buffer
GPS Location	O	GPS Location	O
Field Station#	16020+00	Field Station#	16020+00
Pic 9 Desc.	Observing location that needs to be stabilized	Pic 10 Desc.	Observing end of water bar that needs to be stabilized
GPS Location	O	GPS Location	O
Field Station#	16016+36	Field Station#	16004+00
Pic 11 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's	Pic 12 Desc.	Observing temporary stabilization,water bar,signage and buffer

AFE 124300139	Date/Time 8/4/2022 10:33 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40687	
Inspector Ben Farmer		Date/Time 8/5/2022 1:50 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13853+45	
State VA	Inspection Area Partial	Station End 13958+31	
County Franklin	Ground Dry	Temperature (°F) 75.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/5/2022 1:50 PM	Report # 40687
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 75F)
 Rain Gauge= 0.0"
 13853+45-13958+31


- Resource buffers remain well vegetated at all stream and wetland crossings.
- CWDs are in good condition and functioning as intended
- Equipment bridge ECDs are in good condition and functioning.
- CFS is in good condition throughout this section.
- Steep slope at 13889+00 remains stabilized.
- RCEs are in good condition at all road crossings.
- P1 is in good condition at all stream and wetland buffers.
- Topsoil berms remain stabilized.
- Sediment trap at 13897+00 is in good condition with no evidence of discharge.
- Waterbars/end treatments are in good condition.
- ROW has been damaged by 3rd party and needs to be re-stabilized at 13947+00.
- Slope drain is functioning at 13955+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.


AFE 124300139		Date/Time 8/5/2022 1:50 PM		Report #	
Pictures					
GPS Location See photo		GPS Location See photo			
Field Station# 13863+00		Field Station# 13875+73			
Pic 1 Desc. Resource buffers remain well vegetated		Pic 2 Desc. Equipment bridge ECDs are in good condition and functioning			
GPS Location See photo		GPS Location See photo			
Field Station# 13876+00		Field Station# 13888+00			
Pic 3 Desc. P1 is in good condition at all stream and wetland buffers		Pic 4 Desc. Slope drain is in good condition and functioning			
GPS Location See photo		GPS Location See photo			
Field Station# 13892+45		Field Station# 13897+00			
Pic 5 Desc. RCEs are in good condition at all stream and wetland buffers		Pic 6 Desc. Topsoil pile remains stabilized			

AFE	124300139	Date/Time	8/5/2022 1:50 PM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures



GPS Location	See photo	GPS Location	See photo
Field Station#	13897+00	Field Station#	13925+00
Pic 7 Desc.	Sediment trap is functioning as intended	Pic 8 Desc.	CFS is in good condition throughout this section



GPS Location	See photo	GPS Location	See photo
Field Station#	13939+50	Field Station#	13942+00
Pic 9 Desc.	SSF is in good condition	Pic 10 Desc.	CWDs are functioning as intended



GPS Location	See photo	GPS Location	See photo
Field Station#	13953+00	Field Station#	13955+00
Pic 11 Desc.	Slope drain outlet is in good condition and functioning	Pic 12 Desc.	Waterbars are in good condition

AFE 124300139	Date/Time 8/5/2022 1:50 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 13 Desc.	Pic 14 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 15 Desc.	Pic 16 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40679	
Inspector Justin Burch		Date/Time 8/5/2022 11:35 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15142+66
State VA	Inspection Area Full	Station End	15260+00
County Pittsylvania	Ground Dry	Temperature (°F)	92.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Compost Filter Sock	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Slope Drain Pipe	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/5/2022 11:35 AM	Report # 40679
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15142+66 to 15260+00 (Rock Creek Road to the Pigg River HDD Exit). No punch list items were submitted due to the inspected ECDs being in acceptable conditions at the time of inspection.
- The EI observed that the contractor has worked in the area since the last SWPPP inspection and addressed punch list items.
- Since the last SWPPP inspection the inspection area has not received any rainfall.
- The ROW ground condition is dry
- At the time of inspection temporary vegetative stabilization was sufficiently established to inhibit erosion.
- At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15145+00 to 15153+00 and from 15173+00 to 15260+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/5/2022 11:35 AM		Report #	
Pictures					
<small>☉ 346°N (T) ● 17 N 626594 4090040 ±13ft ▲ 907ft</small> 		<small>☉ 76°E (T) ● 17 N 626564 4090022 ±29ft ▲ 898ft</small> 			
15143+00 08-05-2022, 09:14:42		15143+00 08-05-2022, 09:15:19			
GPS Location 0		GPS Location 0			
Field Station# 15143+00		Field Station# 15143+00			
Pic 1 Desc. Waterbar in acceptable condition		Pic 2 Desc. Waterbar end treatment and perimeter CFS in acceptable conditionS			
<small>☉ 12°N (T) ● 17 N 626682 4089929 ±111ft ▲ 898ft</small> 		<small>☉ 103°E (T) ● 17 N 626772 4089854 ±101ft ▲ 850ft</small> 			
15149+00 08-05-2022, 09:25:06		15153+00 08-05-2022, 09:35:04			
GPS Location 0		GPS Location 0			
Field Station# 15149+00		Field Station# 15153+00			
Pic 3 Desc. Permanent vegetative stabilization in acceptable condition		Pic 4 Desc. Temporary vegetative stabilization in acceptable condition			
<small>☉ 230°SW (T) ● 17 N 627204 4089593 ±187ft ▲ 730ft</small> 		<small>☉ 265°W (T) ● 17 N 628327 4089178 ±26ft ▲ 836ft</small> 			
15169+00 08-05-2022, 10:00:01		15210+00 08-05-2022, 10:38:32			
GPS Location 0		GPS Location 0			
Field Station# 15169+00		Field Station# 15210+00			
Pic 5 Desc. Super silt fence in acceptable condition		Pic 6 Desc. Permanent vegetative stabilization in acceptable condition			

AFE 124300139		Date/Time 8/5/2022 11:35 AM		Report #	
Pictures					
204°SW (T) 17 N 628435 4089165 ±265ft ▲ 832ft 			78°E (T) 17 N 628407 4089139 ±13ft ▲ 848ft 		
GPS Location		0		GPS Location	
Field Station#		15213+00		Field Station#	
Pic 7 Desc.		Waterbar in acceptable condition		Pic 8 Desc.	
				Waterbar end treatment in acceptable condition	
117°SE (T) 17 N 628454 4089152 ±13ft ▲ 846ft 			307°NW (T) 17 N 629618 4088620 ±13ft ▲ 795ft 		
GPS Location		0		GPS Location	
Field Station#		15215+00		Field Station#	
Pic 9 Desc.		Permanent vegetative stabilization in acceptable condition		Pic 10 Desc.	
				Permanent vegetative stabilization in acceptable condition	
Insert image here			Insert image here		
GPS Location				GPS Location	
Field Station#				Field Station#	
Pic 11 Desc.				Pic 12 Desc.	

AFE 124300139	Date/Time 8/5/2022 11:35 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 13 Desc.	Pic 14 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 15 Desc.	Pic 16 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40645	
Inspector Ben Davenport		Date/Time 8/5/2022 1:30 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14311+57	
State VA	Inspection Area Partial	Station End 14454+22	
County Franklin	Ground Dry	Temperature (°F) 87.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Sump Pit	Acceptable			
Compost Filter Sock	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Plunge Pool	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Rock Construction Entrance	Acceptable			
Temporary Diversion Berm	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/5/2022 1:30 PM	Report # 40645
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

-Available for work
 -Received instruction from Lead EI for daily tasks
 -Sunny with dry ground conditions during inspection
 -Performed SWPPP inspection on portion of MVP Spread I section
 -Covered territory between station# 14311+57 — 14454+22 (Farm View Rd to Webster Rd)
 -Walked ROW making note of condition of ROW and environmental controls
 -Verified the completion and accuracy of punch list items in covered area from previous inspections
 -Perimeter controls and ECD's were inspected; no issues identified
 -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified
 -Inspection observed condition of RCEs and culverts in section; no issues identified
 -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
 -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
 -Continue to monitor ROW for signs of erosion
 -No items added to environmental punch list

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/5/2022 1:30 PM		Report #	
Pictures					
					
<small>37°29' N 79°47'43" W 129°SE COURSE 347' GPS 08.05.2022 12:37:38 Glade Hill, VA 24092, United States Accur +/-15.5 Ft ALT 1139 Ft</small>			<small>37°2'8" N 79°47'47" W 341°N COURSE 134' GPS 08.05.2022 12:36:11 Glade Hill, VA 24092, United States Accur +/-15.4 Ft ALT 1127 Ft</small>		
GPS Location	1		GPS Location	2	
Field Station#	14346+50		Field Station#	14362+00	
Pic 1 Desc.	Sump pit and CFS end treatment performing intended functions.		Pic 2 Desc.	Plunge pool performing intended function.	
					
<small>37°2'5" N 79°47'37" W 158°SE COURSE 125' GPS 08.05.2022 12:40:03 Glade Hill, VA 24092, United States Accur +/-15.5 Ft ALT 1120 Ft</small>			<small>37°1'44" N 79°46'29" W 125°SE COURSE 47' GPS 08.05.2022 11:02:05 Glade Hill, VA 24092, United States Accur +/-15.4 Ft ALT 1052 Ft</small>		
GPS Location	3		GPS Location	4	
Field Station#	14371+00		Field Station#	14433+00	
Pic 3 Desc.	ROW stabilized and vegetated in temporary area.		Pic 4 Desc.	Contractor replaced P1 silt fence per punch list item.	
					
<small>37°1'40" N 79°46'14" W 269°W COURSE -1' GPS 08.05.2022 10:55:59 201-483 Old Carriage Rd, Glade Hill, VA 24092, United States Accur +/-21.7 Ft ALT 1108 Ft</small>			<small>37°1'36" N 79°46'6" W 305°NW COURSE 0' GPS 08.05.2022 10:52:29 2750 Webster Rd, Glade Hill, VA 24092, United States Accur +/-31.3 Ft ALT 0 Ft</small>		
GPS Location	5		GPS Location	6	
Field Station#	14444+00		Field Station#	14454+22	
Pic 5 Desc.	Water bar performing intended function; ROW stabilized and vegetated in temporary area.		Pic 6 Desc.	RCE at Webster Rd in good condition.	

AFE 124300139	Date/Time 8/5/2022 1:30 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300139	Date/Time	8/5/2022 1:30 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 13 Desc.		Pic 14 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40688	
Inspector Charles Head		Date/Time 8/5/2022 2:01 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14694+77	
State VA	Inspection Area Full	Station End 14802+19	
County Franklin	Ground Dry	Temperature (°F) 93.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/5/2022 2:01 PM	Report # 40688
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.


Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/5/2022 2:01 PM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures



GPS Location	0	GPS Location	0
Field Station#	14748+00	Field Station#	14758+50
Pic 1 Desc.	Approximately 14748+00. Overview of ROW.	Pic 2 Desc.	Approximately 14758+50. Overview of road crossing and RCEs.



GPS Location	0	GPS Location	0
Field Station#	14716+92	Field Station#	14700+00
Pic 3 Desc.	Approximately 14716+92. Overview of stream crossing, equipment bridge and ECDs at stream S-H30.	Pic 4 Desc.	Approximately 14700+00. Overview of ROW.



GPS Location	0	GPS Location	0
Field Station#	14769+52	Field Station#	14785+00
Pic 5 Desc.	Approximately 14769+52. Overview of stream crossing, equipment bridge and ECDs at stream S-MM45.	Pic 6 Desc.	Approximately 14785+00. Overview of ROW.

AFE 124300139	Date/Time 8/5/2022 2:01 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/5/2022 2:01 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40696	
Inspector John White		Date/Time 8/5/2022 10:52 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15584+23	
State VA	Inspection Area Full	Station End 15647+03	
County Pittsylvania	Ground Dry	Temperature (°F) 85.00	
Municipality Chatham	Weather Sunny	Rain Gauge (in) 0.60	
Rain Accumulation Time (days)			4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			

- 5. Site Conditions**
- Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. No
 - Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? Yes
 - Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? Yes
 - Has a new slip/slide been observed? (If yes, complete Slide Report Form) No

AFE	124300139	Date/Time	8/5/2022 10:52 AM	Report #	40696
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/5/2022 10:52 AM	Report #
Pictures			
GPS Location	O	GPS Location	O
Field Station#	15617+00	Field Station#	15614+94
Pic 1 Desc.	Observing temporary stabilization, water bar, sump and end treatment	Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's
GPS Location	O	GPS Location	O
Field Station#	15610+00	Field Station#	15623+00
Pic 3 Desc.	Observing temporary stabilization	Pic 4 Desc.	Observing temporary stabilization, CWD berm and water bars
GPS Location	O	GPS Location	O
Field Station#	15625+00	Field Station#	15647+03
Pic 5 Desc.	Observing temporary stabilization, CWD outlet and ECD's	Pic 6 Desc.	Observing road crossing and RCE's

AFE 124300139	Date/Time 8/5/2022 10:52 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/5/2022 10:52 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name Transco Interconnect Station		AFE 124300113	Spread Transco Interconnect Sta
Contractor Kanahwa		Report # 40631	
Inspector John White		Date/Time 8/4/2022 10:22 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	00+00
State VA	Inspection Area Full	Station End	00+00
County Pittsylvania	Ground Dry	Temperature (°F)	85.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.80
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Housekeeping	Acceptable			
Rock-lined Channel	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Basin	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300113	Date/Time	8/4/2022 10:22 AM	Report #	40631
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)













PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300113		Date/Time 8/4/2022 10:22 AM		Report #	
Pictures					
 		 			
GPS Location O		GPS Location O			
Field Station# 00+00		Field Station# 00+00			
Pic 1 Desc. Observing RCE		Pic 2 Desc. Observing lay down yard			
 		 			
GPS Location O		GPS Location O			
Field Station# 00+00		Field Station# 00+00			
Pic 3 Desc. Observing temporary stabilization and sediment basin		Pic 4 Desc. Observing temporary stabilization and rock drain			
 		 			
GPS Location O		GPS Location O			
Field Station# 00+00		Field Station# 00+00			
Pic 5 Desc. Observing temporary stabilization and sediment basin		Pic 6 Desc. Observing temporary stabilization and storm water pond			

AFE 124300113	Date/Time 8/4/2022 10:22 AM	Report #
----------------------	------------------------------------	-----------------

Pictures			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300113	Date/Time	8/4/2022 10:22 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	