



Visual Site Inspection Report

Project Name H-602 Pipeline Spread I		AFE 124300139	Spread H-602 Pipeline Spread I
Contractor Precision		Report # 41263	
Inspector John White		Date/Time 8/22/2022 10:18 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	00+00
State VA	Inspection Area Full	Station End	19+25
County Pittsylvania	Ground Wet	Temperature (°F)	74.00
Municipality Chatham	Weather Cloudy	Rain Gauge (in)	0.60
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication	Perform maintenance		
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/22/2022 10:18 AM	Report # 41263
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this line. There was one issue identified and added to the punch list. Other than that there were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139	Date/Time 8/22/2022 10:18 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures



GPS Location O	GPS Location O
-----------------------	-----------------------

Field Station# 6+00	Field Station# 12+00
----------------------------	-----------------------------

Pic 1 Desc. Observing temporary stabilization	Pic 2 Desc. Observing temporary stabilization, sump and end treatment
--	--



GPS Location O	GPS Location O
-----------------------	-----------------------

Field Station# 12+65	Field Station# 12+75
-----------------------------	-----------------------------

Pic 3 Desc. Observing temporary stabilization, buffer, equipment crossing and ECD's	Pic 4 Desc. Observing CFS that requires maintenance
--	--

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
---------------------	---------------------

Field Station#	Field Station#
-----------------------	-----------------------

Pic 5 Desc.	Pic 6 Desc.
--------------------	--------------------

AFE 124300139	Date/Time 8/22/2022 10:18 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/22/2022 10:18 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 13 Desc.	Pic 14 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 15 Desc.	Pic 16 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name H-603 Pipeline Spread I		AFE 124300139	Spread H-603 Pipeline Spread I
Contractor Precision		Report # 41260	
Inspector John White		Date/Time 8/22/2022 9:46 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	00+00
State VA	Inspection Area Full	Station End	24+53
County Pittsylvania	Ground Wet	Temperature (°F)	74.00
Municipality Chatham	Weather Cloudy	Rain Gauge (in)	0.60
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/22/2022 9:46 AM	Report #	41260
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139	Date/Time 8/22/2022 9:46 AM	Report #
----------------------	------------------------------------	-----------------

Pictures



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	14+00	Field Station#	22+00
-----------------------	-------	-----------------------	-------

Pic 1 Desc.	Observing temporary stabilization and ECD's	Pic 2 Desc.	Observing temporary stabilization and buffer
--------------------	---	--------------------	--



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	12+00	Field Station#	5+00
-----------------------	-------	-----------------------	------

Pic 3 Desc.	Observing temporary stabilization, sump, end treatment and ECD's	Pic 4 Desc.	Observing temporary stabilization
--------------------	--	--------------------	-----------------------------------

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 5 Desc.		Pic 6 Desc.	
--------------------	--	--------------------	--

AFE	124300139	Date/Time	8/22/2022 9:46 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/22/2022 9:46 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41273	
Inspector Justin Burch		Date/Time 8/22/2022 11:18 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15480+67	
State VA	Inspection Area Full	Station End 15584+23	
County Pittsylvania	Ground Wet	Temperature (°F) 83.00	
Municipality Chatham	Weather Cloudy	Rain Gauge (in) 0.80	
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Sump Pit	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE 124300139	Date/Time 8/22/2022 11:18 AM	Report # 41273
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15480+67 to 15584+23 (Toshes Road to Anderson Mill Road 1). No items were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection.
- The did not observe that the contractor has worked in the area since the last SWPPP inspection.
- The EI observed that streams S-MM8 at 15521+00 and S-CC5 at 15542+19 were running clear. These streams have been impacted in the past by upstream activities not related to MVP.
- The EI observed that the solar farm ECDs adjacent to the ROW on GAS of Climax Road appeared to be in acceptable condition and that the super silt fence on the CIS of climax Road was down in multiple locations where the solar farm fencing crew has recently worked.
- Since the last SWPPP inspection the inspection area has received one rain event with a total of 0.80" at Snowberry Road.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion.
- At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15482+00 to 15495+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/22/2022 11:18 AM	Report #
Pictures			
			
GPS Location	0	GPS Location	0
Field Station#	15497+00	Field Station#	15502+00
Pic 1 Desc.	P1 silt fence in acceptable condition	Pic 2 Desc.	Waterbar in acceptable condition
			
GPS Location	0	GPS Location	0
Field Station#	15502+00	Field Station#	15503+00
Pic 3 Desc.	Waterbar end treatment in acceptable condition	Pic 4 Desc.	Solar farm perimeter ECDs and grading operation
			
GPS Location	0	GPS Location	0
Field Station#	15573+00	Field Station#	15530+00
Pic 5 Desc.	Super silt fence in acceptable condition	Pic 6 Desc.	Temporary vegetative stabilization in acceptable condition

AFE 124300139		Date/Time 8/22/2022 11:18 AM	Report #
Pictures			
			
GPS Location	0	GPS Location	0
Field Station#	15538+00	Field Station#	15564+00
Pic 7 Desc.	Clean water diversion pipe and CFS in acceptable conditions	Pic 8 Desc.	Waterbar in acceptable condition
			
GPS Location	0	GPS Location	0
Field Station#	15564+00	Field Station#	15486+00
Pic 9 Desc.	Waterbar end treatment in acceptable condition	Pic 10 Desc.	Solar farm perimeter super silt fence is down
			
GPS Location	0	GPS Location	0
Field Station#	15490+00	Field Station#	15582+50
Pic 11 Desc.	Permanent vegetative stabilization in acceptable condition	Pic 12 Desc.	Sump pit and CFS in acceptable conditions

AFE 124300139	Date/Time 8/22/2022 11:18 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41279	
Inspector Ben Farmer		Date/Time 8/22/2022 1:43 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14171+36	
State VA	Inspection Area Partial	Station End 14311+57	
County Franklin	Ground Damp	Temperature (°F) 67.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 1.90	
Rain Accumulation Time (days)			0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	P1 has been damaged and needs to		
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/22/2022 1:43 PM	Report # 41279
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 67F)
 Rain Gauge= 1.9"
 14171+36-14311+57

- RCEs are in good condition at all road crossings.
- CWDs are functioning as intended.
- SSF is in good condition
- Equipment bridge ECDs are in good condition and functioning.
- Waterbars/end treatments are in good condition throughout this section.
- P1 has been damaged and needs to be replaced at 14224+00/14230+00.
- Slope drain is in good condition and functioning at 14232+00
- Resource buffers remain well vegetated.
- CFS checks have been damaged by 3rd party mowing at 14273+00.
 - >Per LEI, checks are to be removed (these are temporary checks installed within permanently vegetated area)
 - >Perimeter CFS remains in good condition.
 - >Vegetation along this drainage remains uniform, mature enough to survive and inhibiting erosion.
- Topsoil berms remain stabilized







*Issues identified in the field have been added to the punch list to be addressed by the contractor.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/22/2022 1:43 PM		Report #	
Pictures					
					
GPS Location See photo		GPS Location See photo			
Field Station# 14180+00		Field Station# 14182+00			
Pic 1 Desc. CWDs are functioning as intended		Pic 2 Desc. SSF is in good condition			
					
GPS Location See photo		GPS Location See photo			
Field Station# 14186+00		Field Station# 14186+00			
Pic 3 Desc. Waterbars are functioning as intended		Pic 4 Desc. End treatments are functioning as intended			
					
GPS Location See photo		GPS Location See photo			
Field Station# 14190+00		Field Station# 14208+69			
Pic 5 Desc. P1 is in good condition at all stream and wetland buffers		Pic 6 Desc. Equipment bridge ECDs are in good condition and functioning			

AFE 124300139	Date/Time 8/22/2022 1:43 PM	Report #
----------------------	------------------------------------	-----------------

Pictures


			
GPS Location	See photo	GPS Location	See photo
Field Station#	14216+00	Field Station#	14223+41
Pic 7 Desc.	Perimeter CFS is in good condition throughout this section	Pic 8 Desc.	MVP-FR-311 is in good condition with controls in place
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14224+00	Field Station#	14230+00
Pic 9 Desc.	Perimeter P1 has been damaged and needs to be replaced	Pic 10 Desc.	Perimeter P1 has been damaged and needs to be replaced
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14232+00	Field Station#	14273+00
Pic 11 Desc.	Slope drain is in good condition and functioning	Pic 12 Desc.	CFS checks to be removed after being damaged by 3rd party mowing

AFE 124300139	Date/Time 8/22/2022 1:43 PM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	See photo
Field Station#	14278+93	Field Station#	14311+57
Pic 13 Desc.	Resource buffers remain well vegetated	Pic 14 Desc.	RCEs are in good condition at all road crossings.



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41284	
Inspector Glenn Mike Renfro		Date/Time 8/22/2022 2:21 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	0000+00
State VA	Inspection Area Full	Station End	0000+00
County Franklin	Ground Wet	Temperature (°F)	83.00
Municipality N/A	Weather Light Rain	Rain Gauge (in)	1.90
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Other - Explain in Comments	Acceptable	Inlet protection for catch basins.		
Secondary Containment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | N/A |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | N/A |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/22/2022 2:21 PM	Report # 41284
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va.
- The locations have received 1.9" of rainfall since the last inspection and site conditions were wet.
- All perimeter ECD's were inspected and no issues were observed.
- The inlet protection for the catch basins at LY-046 were found to be in acceptable condition.
- All secondary containment structures were inspected and no issues were found during the inspections.
- The RCE at LY-045 was in good condition.
- All equipment at both locations were inspected and no leaks were observed the during inspection.
- The General Construction permits and contact information are posted at the entrance of LY-046 as required.
- There were no issues identified during todays inspections.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/22/2022 2:21 PM		Report #	
Pictures					
GPS Location	See picture	GPS Location	See picture		
Field Station#	0000+00	Field Station#	0000+00		
Pic 1 Desc.	RCE at LY-045 in good condition.	Pic 2 Desc.	Perimeter ECD's on south end of LY-045 in good condition.		
GPS Location	See picture	GPS Location	See picture		
Field Station#	0000+00	Field Station#	0000+00		
Pic 3 Desc.	Secondary containment structure on south end of tent at LY-045 in good condition	Pic 4 Desc.	Perimeter ECD's and secondary containment structure on north end of LY-045 in good condition.		
GPS Location	See picture	GPS Location	See picture		
Field Station#	0000+00	Field Station#	0000+00		
Pic 5 Desc.	Secondary containment structure for fuel cell at LY-046 in good condition.	Pic 6 Desc.	Perimeter ECD's on northwest corner of LY-046 in good condition.		

AFE 124300139	Date/Time 8/22/2022 2:21 PM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	See picture	GPS Location	See picture
---------------------	-------------	---------------------	-------------

Field Station#	000+00	Field Station#	0000+00
-----------------------	--------	-----------------------	---------


Pic 7 Desc.	Perimeter ECD's and secondary containment structure for light plant at south end of LY-046 in good condition.	Pic 8 Desc.	General construction permits and contact info posted at entrance of LY-046 as required.
--------------------	---	--------------------	---



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 9 Desc.		Pic 10 Desc.	
--------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 11 Desc.		Pic 12 Desc.	
---------------------	--	---------------------	--

AFE 124300139	Date/Time 8/22/2022 2:21 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41287	
Inspector Frank Craycroft		Date/Time 8/22/2022 2:34 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	0+00
State VA	Inspection Area Full	Station End	0+00
County Franklin	Ground Muddy	Temperature (°F)	80.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	1.50
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Timber Mat	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waste Management	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | N/A |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/22/2022 2:34 PM	Report # 41287
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted SWPPP inspection of LY-032, -033, -048, and ANC-006. All portable equipment and hazardous materials were maintained within secondary containment. All perimeter ECDs were functional and in good condition. All rock construction entrances were free of mud and dirt buildup. All sites were free of loose debris and trash and dumpsters had adequate additional storage capacity. Stormwater drain inlets had proper perimeter protection and were free of loose debris and vegetation. No issues were observed.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/22/2022 2:34 PM		Report #	
Pictures					
					
GPS Location 0		GPS Location 0			
Field Station# 0+00		Field Station# 0+00			
Pic 1 Desc. LY-033 Secondary containment		Pic 2 Desc. LY-032 Secondary containment			
					
GPS Location 0		GPS Location 0			
Field Station# 0+00		Field Station# 0+00			
Pic 3 Desc. LY-032 Rock construction entrance		Pic 4 Desc. LY-033 Timber mat staging area			
					
GPS Location 0		GPS Location 0			
Field Station# 0+00		Field Station# 0+00			
Pic 5 Desc. ANC-006 Stormwater drain inlet protection		Pic 6 Desc. ANC-006 Secondary containment			

AFE	124300139	Date/Time	8/22/2022 2:34 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 7 Desc.	LY-048 West perimeter CFS	Pic 8 Desc.	LY-048 Temporary vegetation		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

AFE 124300139	Date/Time 8/22/2022 2:34 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41285	
Inspector Frank Craycroft		Date/Time 8/22/2022 2:30 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13748+30	
State VA	Inspection Area Full	Station End 13853+45	
County Franklin	Ground Muddy	Temperature (°F) 80.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 1.50	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/22/2022 2:30 PM	Report # 41285
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired





7. Identify all remedial measures that have been taken since the previous inspection was conducted.



Comments (Reference above questions as appropriate.)

Conducted SWPPP inspection of ROW from Green Level Rd to MVP-FR-303.01. All ECDs along perimeter of ROW and at resource buffers in area were functional and in good condition. Buffer zones were intact and showed no signs of erosion or sedimentation of resources. Equipment bridges across resources were clean and showed no signs of sediment deposits. All waterbars and sumps observed were functioning properly and have adequate storage capacity. No signs of erosion or washing were observed.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/22/2022 2:30 PM		Report #	
Pictures					
					
GPS Location 0		GPS Location 0			
Field Station# 13835+50		Field Station# 13834+50			
Pic 1 Desc. GAS S-C14 Buffer zone silt fence		Pic 2 Desc. S-C14 Channel upstream of ROW and banks			
					
GPS Location 0		GPS Location 0			
Field Station# 13842+00		Field Station# 13830+00			
Pic 3 Desc. Plunge pool		Pic 4 Desc. Sump and J-hook			
					
GPS Location 0		GPS Location 0			
Field Station# 13825+00		Field Station# 13794+50			
Pic 5 Desc. Perimeter CFS Triple stack		Pic 6 Desc. S-D22 Channel and buffer zones			

AFE 124300139		Date/Time 8/22/2022 2:30 PM		Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	13790+00	Field Station#	13786+00		
Pic 7 Desc.	CIS S-D23 Buffer zone and CFS	Pic 8 Desc.	Perimeter CFS		
					
GPS Location	0	GPS Location	0		
Field Station#	13781+00	Field Station#	13783+00		
Pic 9 Desc.	CIS S-RR15 Buffer zone and CFS	Pic 10 Desc.	Perimeter silt fence		
				rt image here	
GPS Location	0	GPS Location	0		
Field Station#	13784+00	Field Station#	13755+00		
Pic 11 Desc.	Sump and J-hook	Pic 12 Desc.	CIS S-EF12 Buffer zone silt fence		

AFE	124300139	Date/Time	8/22/2022 2:30 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	13752+00	Field Station#	13748+50		
Pic 13 Desc.	Plunge pool	Pic 14 Desc.	S-EF7 Silt fence		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 15 Desc.		Pic 16 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41269	
Inspector Charles Head		Date/Time 8/22/2022 10:59 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15063+85	
State VA	Inspection Area Full	Station End 15142+66	
County Pittsylvania	Ground Damp	Temperature (°F) 81.00	
Municipality Chatham	Weather Cloudy	Rain Gauge (in) 0.50	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
3rd Party Damages	Communication	Repair ruts, seed and stabilize		
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/22/2022 10:59 AM	Report # 41269
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/22/2022 10:59 AM	Report #
Pictures			
GPS Location	0	GPS Location	0
Field Station#	15069+00	Field Station#	15072+86
Pic 1 Desc.	Approximately 15069+00. Overview of ROW.	Pic 2 Desc.	Approximately 15072+86. Overview of stream crossing, equipment bridge and ECDs at stream S-G11.
GPS Location	0	GPS Location	0
Field Station#	15084+00	Field Station#	15113+00
Pic 3 Desc.	Approximately 15084+00. Overview of ROW.	Pic 4 Desc.	Approximately 15113+00. Overview of road crossing and RCEs.
GPS Location	0	GPS Location	0
Field Station#	15137+00	Field Station#	15111+50
Pic 5 Desc.	Approximately 15137+00. Overview of ROW.	Pic 6 Desc.	Approximately 15111+50. Third party damage. Repair ruts, seed and stabilize.

AFE 124300139	Date/Time 8/22/2022 10:59 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/22/2022 10:59 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41215	
Inspector Ben Davenport		Date/Time 8/22/2022 10:35 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14649+67	
State VA	Inspection Area Partial	Station End 14694+77	
County Franklin	Ground Muddy	Temperature (°F) 81.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 1.20	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication	Routine maintenance; missing perim		
Vegetative Stabilization (Temporary)	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Erosion Control Blanket	Acceptable			
Waterbar	Acceptable			
Sediment Filter Log	Acceptable			
Temporary Diversion Berm	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/22/2022 10:35 AM	Report # 41215
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

-Available for work
 -Received instruction from Lead EI for daily tasks
 -Checked rain gauges in covered area
 -Sunny with muddy ground conditions during inspection
 -Performed SWPPP inspection on portion of MVP Spread I section
 -Covered territory between station# 14649+67 — 14694+77 (Hwy 40 crossing to Jacks Creek Rd)
 -Walked ROW making note of condition of ROW and environmental controls
 -Verified the completion and accuracy of punch list items in covered area from previous inspections
 -Perimeter controls and ECDs were inspected; 1 issue identified
 -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified
 -Inspection observed condition of RCEs and culverts in section; no issues identified
 -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
 -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
 -Continue to monitor ROW for signs of erosion
 -1 item added to environmental punch list in section

-Rain Gauge Totals:
 +Farm View: 1.20 inches recorded
 +Timber Ridge: 0.90 inches recorded

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/22/2022 10:35 AM	Report #
Pictures			
GPS Location	1	GPS Location	2
Field Station#	14694+50	Field Station#	14656+87
Pic 1 Desc.	Routine maintenance. Install perimeter ECD where landowner has cut gap.	Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.
GPS Location	3	GPS Location	4
Field Station#	14657+50	Field Station#	14670+82
Pic 3 Desc.	Perimeter erosion control blanket and CFS in place and functional.	Pic 4 Desc.	Water bar performing intended function; ROW stabilized and vegetated in temporary area.
GPS Location	5	GPS Location	6
Field Station#	14673+10	Field Station#	14689+36
Pic 5 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	Pic 6 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.

AFE 124300139	Date/Time 8/22/2022 10:35 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300139	Date/Time	8/22/2022 10:35 AM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41264	
Inspector John White		Date/Time 8/22/2022 10:26 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15947+64	
State VA	Inspection Area Full	Station End 16027+46	
County Pittsylvania	Ground Wet	Temperature (°F) 74.00	
Municipality Chatham	Weather Cloudy	Rain Gauge (in) 0.60	
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Filter Outlet	Acceptable			
Sediment Filter Log	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

A/E	124300139	Date/Time	8/22/2022 10:26 AM	Report #	41264
------------	-----------	------------------	--------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/22/2022 10:26 AM		Report #	
Pictures					
GPS Location O		GPS Location O			
Field Station# 15970+00		Field Station# 15972+00			
Pic 1 Desc. Observing temporary stabilization and CWD berm		Pic 2 Desc. Observing temporary stabilization, CWD outlet and ECD's			
GPS Location O		GPS Location O			
Field Station# 15975+00		Field Station# 15977+35			
Pic 3 Desc. Observing temporary stabilization		Pic 4 Desc. Observing temporary stabilization, water bar, buffer, equipment crossing and ECD's			
GPS Location O		GPS Location O			
Field Station# 15961+37		Field Station# 16022+00			
Pic 5 Desc. Observing temporary stabilization and wetlands		Pic 6 Desc. Observing temporary stabilization, water bars and CFS checks			

AFE 124300139	Date/Time 8/22/2022 10:26 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/22/2022 10:26 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 13 Desc.	Pic 14 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 15 Desc.	Pic 16 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41332	
Inspector Justin Burch		Date/Time 8/23/2022 12:28 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15142+66
State VA	Inspection Area Full	Station End	15260+00
County Pittsylvania	Ground Damp	Temperature (°F)	85.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.90
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Slope Drain Pipe	Acceptable			
Sump Pit	Acceptable			
Rock Construction Entrance	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/23/2022 12:28 PM	Report # 41332
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15142+66 to 15260+00 (Rock Creek Road to the Pigg River HDD Exit). No items were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection.
- The EI observed that the contractor has worked in the area since the last SWPPP inspection to address punch list items.
- Since the last SWPPP inspection the inspection area has received two rain events with a total of 0.90" at Snowberry Road.
- The ROW ground condition is damp.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion
- At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15145+00 to 15153+00 and from 15173+00 to 15260+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/23/2022 12:28 PM	Report #
Pictures			
			
GPS Location	0	GPS Location	0
Field Station#	15143+00	Field Station#	15143+00
Pic 1 Desc.	Waterbar end treatment in acceptable condition	Pic 2 Desc.	Waterbar in acceptable condition
			
GPS Location	0	GPS Location	0
Field Station#	15145+00	Field Station#	15163+00
Pic 3 Desc.	Permanent vegetative stabilization and perimeter CFS in acceptable conditions	Pic 4 Desc.	P1 silt fence in acceptable condition
			
GPS Location	0	GPS Location	0
Field Station#	15170+00	Field Station#	15183+00
Pic 5 Desc.	Temporary vegetative stabilization in acceptable condition	Pic 6 Desc.	Waterbar and permanent vegetative stabilization in acceptable conditions

AFE 124300139	Date/Time 8/23/2022 12:28 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300139	Date/Time	8/23/2022 12:28 PM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41334	
Inspector Ben Farmer		Date/Time 8/23/2022 1:52 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13853+45	
State VA	Inspection Area Partial	Station End 13958+31	
County Franklin	Ground Damp	Temperature (°F) 65.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
3rd Party Damages	Communication	CFS and P1 have been damaged by		
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	P1 has been damaged and needs to		
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/23/2022 1:52 PM	Report # 41334
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.







Comments (Reference above questions as appropriate.)







SWPPP Inspection (Sunny, 65F)
 Rain Gauge= 0.0"
 13853+45-13958+31

- Resource buffers remain well vegetated at all stream and wetland crossings.
- CWDs are in good condition and functioning as intended
- Equipment bridge ECDs are in good condition and functioning.
- P1 has been damaged at 13955+00/13889+50/13889+00 and needs to be replaced.
- P1 has been damaged by 3rd party and needs to be replaced at 13900+00/13888+00.
- CFS has been damaged by 3rd party at 13907+00/13905+00
- Steep slope at 13889+00 remains stabilized.
- RCEs are in good condition at all road crossings.
- Topsoil berms remain stabilized.
- Sediment trap at 13897+00 is in good condition with no evidence of discharge.
- SSF is in good condition
- Waterbars/end treatments are in good condition.
- Slope drain is functioning at 13955+00.

*Issues identified in the field have been added to the punch list to be addressed by the contractor







Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/23/2022 1:52 PM		Report #	
Pictures					
					
GPS Location See photo		GPS Location See photo			
Field Station# 13955+00		Field Station# 13954+00			
Pic 1 Desc. P1 has been damaged and needs to be replaced		Pic 2 Desc. Slope drain outlet is in good condition and functioning			
					
GPS Location See photo		GPS Location See photo			
Field Station# 13949+00		Field Station# 13943+00			
Pic 3 Desc. SSF is in good condition throughout this section		Pic 4 Desc. Topsoil berms remain stabilized			
					
GPS Location See photo		GPS Location See photo			
Field Station# 13942+00		Field Station# 13907+00			
Pic 5 Desc. CWDs are functioning as intended		Pic 6 Desc. CFS has been damaged by 3rd party and needs to be repaired			

AFE 124300139		Date/Time 8/23/2022 1:52 PM	Report #
Pictures			
 <p>279°W (T) LAT: 37.051459 LON: -79.910519 ±13ft ▲ 1044ft</p>		 <p>73°E (T) LAT: 37.052512 LON: -79.909931 ±13ft ▲ 1084ft</p>	
GPS Location	See photo	GPS Location	See photo
Field Station#	13905+00	Field Station#	13900+00
Pic 7 Desc.	CFS has been damaged by 3rd party and needs to be repaired	Pic 8 Desc.	P1 has been damaged by 3rd party and needs to be replaced
 <p>42°NE (T) LAT: 37.053543 LON: -79.909508 ±9ft ▲ 1124ft</p>		 <p>247°SW (T) LAT: 37.053577 LON: -79.909501 ±9ft ▲ 1123ft</p>	
GPS Location	See photo	GPS Location	See photo
Field Station#	13897+00	Field Station#	13897+00
Pic 9 Desc.	Topsoil pile remains stabilized	Pic 10 Desc.	Sediment trap is functioning as intended
 <p>355°N (T) LAT: 37.054103 LON: -79.910173 ±88ft ▲ 1142ft</p>		 <p>280°W (T) LAT: 37.054985 LON: -79.910399 ±9ft ▲ 1086ft</p>	
GPS Location	See photo	GPS Location	See photo
Field Station#	13892+45	Field Station#	13890+00
Pic 11 Desc.	RCEs are in good condition at all road crossings	Pic 12 Desc.	Waterbars are functioning as intended

AFE	124300139	Date/Time	8/23/2022 1:52 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures

			
GPS Location	See photo	GPS Location	See photo
Field Station#	13889+50	Field Station#	13889+00
Pic 13 Desc.	P1 has been damaged and needs to be replaced	Pic 14 Desc.	P1 has been damaged and needs to be replaced
			
GPS Location	See photo	GPS Location	See photo
Field Station#	13888+50	Field Station#	13888+00
Pic 15 Desc.	Slope drain is functioning as intended	Pic 16 Desc.	P1 has been damaged by 3rd party and needs to be replaced
			
GPS Location	See photo	GPS Location	See photo
Field Station#	13875+73	Field Station#	13863+00
Pic 17 Desc.	Equipment bridge ECDs are in good condition and functioning	Pic 18 Desc.	Resource buffers remain well vegetated



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41325	
Inspector Charles Head		Date/Time 8/23/2022 10:34 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	14694+77
State VA	Inspection Area Full	Station End	14802+19
County Franklin	Ground Wet	Temperature (°F)	77.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.30
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/23/2022 10:34 AM	Report # 41325
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/23/2022 10:34 AM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures



GPS Location	0	GPS Location	0
---------------------	---	---------------------	---

Field Station#	14758+00	Field Station#	14799+00
-----------------------	----------	-----------------------	----------

Pic 1 Desc.	Approximately 14758+00. Overview of road crossing and RCEs.	Pic 2 Desc.	Approximately 14799+00. Overview of ROW.
--------------------	---	--------------------	--



GPS Location	0	GPS Location	0
---------------------	---	---------------------	---

Field Station#	14729+19	Field Station#	14743+00
-----------------------	----------	-----------------------	----------

Pic 3 Desc.	Approximately 14729+19. Overview of stream crossing, equipment bridge and ECDs at stream S-A20.	Pic 4 Desc.	Approximately 14743+00. Overview of ROW.
--------------------	---	--------------------	--



GPS Location	0	GPS Location	0
---------------------	---	---------------------	---

Field Station#	14782+25	Field Station#	14760+00
-----------------------	----------	-----------------------	----------

Pic 5 Desc.	Approximately 14782+25. Overview of stream crossing, equipment bridge and ECDs at stream S-MM48.	Pic 6 Desc.	Approximately 14760+00. Overview of ROW.
--------------------	--	--------------------	--

AFE 124300139	Date/Time 8/23/2022 10:34 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/23/2022 10:34 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41289	
Inspector Ben Davenport		Date/Time 8/23/2022 10:23 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14311+57	
State VA	Inspection Area Partial	Station End 14454+22	
County Franklin	Ground Damp	Temperature (°F) 82.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.10	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Equipment Bridge	Acceptable			
Sediment Filter Log	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Temporary Diversion Berm	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/23/2022 10:23 AM	Report # 41289
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

-Available for work
 -Attended inspection meeting in office
 -Received instruction from Lead EI for daily tasks
 -Checked rain gauges in covered area
 -Sunny with damp ground conditions during inspection
 -Performed SWPPP inspection on portion of MVP Spread I section
 -Covered territory between station# 14311+57 — 14454+22 (Farm View Rd to Webster Rd)
 -Walked ROW making note of condition of ROW and environmental controls
 -Verified the completion and accuracy of punch list items in covered area from previous inspections
 -Perimeter controls and ECD's were inspected; no issues identified
 -Inspection observed condition of equipment bridges and surrounding ECDs around stream crossings and resource buffers; no issues identified
 -Inspection observed condition of RCEs and culverts in section; no issues identified
 -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
 -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
 -Continue to monitor ROW for signs of erosion
 -No items added to environmental punch list

-Rain Gauge Totals:
 +Farm View: no rain measured
 +Timber: 0.10 inches recorded

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/23/2022 10:23 AM	Report #
Pictures			
			
GPS Location	1	GPS Location	2
Field Station#	14314+79	Field Station#	14322+85
Pic 1 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	Pic 2 Desc.	ROW stabilized and vegetated in temporary area; perimeter controls in good condition.
			
GPS Location	3	GPS Location	4
Field Station#	14347+00	Field Station#	14354+03
Pic 3 Desc.	Water bar performing intended function; ROW stabilized and vegetated in temporary area.	Pic 4 Desc.	Perimeter P1 silt fence repaired per punch list item.
			
GPS Location	5	GPS Location	6
Field Station#	14399+00	Field Station#	14420+70
Pic 5 Desc.	Rock end treatment performing intended function.	Pic 6 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.

AFE 124300139	Date/Time 8/23/2022 10:23 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/23/2022 10:23 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41330	
Inspector John White		Date/Time 8/23/2022 12:13 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15584+23	
State VA	Inspection Area Full	Station End 15647+03	
County Pittsylvania	Ground Dry	Temperature (°F) 82.00	
Municipality Chatham	Weather Sunny	Rain Gauge (in) 0.80	
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter Outlet	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/23/2022 12:13 PM	Report #	41330
------------	-----------	------------------	--------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/23/2022 12:13 PM	Report #
Pictures			
GPS Location	O	GPS Location	O
Field Station#	15588+00	Field Station#	15584+23
Pic 1 Desc.	Observing temporary stabilization	Pic 2 Desc.	Observing road crossing and RCE's
GPS Location	O	GPS Location	O
Field Station#	15593+00	Field Station#	15610+00
Pic 3 Desc.	Observing temporary stabilization, sump and end treatment	Pic 4 Desc.	Observing temporary stabilization
GPS Location	O	GPS Location	O
Field Station#	15630+00	Field Station#	15636+45
Pic 5 Desc.	Observing temporary stabilization, CWD outlet and ECD's	Pic 6 Desc.	Observing temporary stabilization, water bar, buffer, equipment crossing and ECD's

AFE 124300139	Date/Time 8/23/2022 12:13 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/23/2022 12:13 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41382	
Inspector Justin Burch		Date/Time 8/24/2022 10:43 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15260+00
State VA	Inspection Area Full	Station End	15370+62
County Pittsylvania	Ground Wet	Temperature (°F)	85.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.90
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Equipment Bridge	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/24/2022 10:43 AM	Report # 41382
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		





7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15260+00 to 15370+62 (Pigg River HDD Exit to Snowberry Road). No punch list items were submitted by the EI due to the inspected ECDs being in compliance at the time of inspection.
- The EI observed that the contractor has been in the area since the last SWPPP inspection performing routine maintenance.
- Since the last SWPPP inspection the inspection area has received two rain events with a total of 0.90" at Snowberry Road.
- The ROW ground condition is wet.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion and permanent vegetative stabilization was adequately established to inhibit erosion from 15355+00 to 15370+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/24/2022 10:43 AM	Report #
Pictures			
			
GPS Location	0	GPS Location	0
Field Station#	15360+00	Field Station#	15345+00
Pic 1 Desc.	CFS in acceptable condition	Pic 2 Desc.	Waterbar in acceptable condition
			
GPS Location	0	GPS Location	0
Field Station#	15345+00	Field Station#	15338+00
Pic 3 Desc.	Waterbar end treatment in acceptable condition	Pic 4 Desc.	Sump pit in acceptable condition
			
GPS Location	0	GPS Location	0
Field Station#	15332+00	Field Station#	15314+18
Pic 5 Desc.	Temporary vegetative stabilization in acceptable condition	Pic 6 Desc.	Equipment bridge in acceptable condition

AFE 124300139		Date/Time 8/24/2022 10:43 AM		Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	15345+00	Field Station#	15313+00		
Pic 7 Desc.	Super silt fence in acceptable condition		Pic 8 Desc.	P1 silt fence and temporary vegetative stabilization in acceptable conditions	
					
GPS Location	0	GPS Location	0		
Field Station#	15298+00	Field Station#	15311+00		
Pic 9 Desc.	Temporary vegetative stabilization in acceptable condition		Pic 10 Desc.	P1 silt fence in acceptable condition	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

AFE 124300139	Date/Time 8/24/2022 10:43 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41387	
Inspector Ben Farmer		Date/Time 8/24/2022 1:09 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13958+31	
State VA	Inspection Area Partial	Station End 14062+17	
County Franklin	Ground Dry	Temperature (°F) 66.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Communication	Equipment bridge fabric needs to be		
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	P1 checks need to be replaced		
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			
Rock Check Dam	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

A/E	124300139	Date/Time	8/24/2022 1:09 PM	Report #	41387
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.




Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 66F)
 Rain Gauge= 0.0"
 13958+31-14062+17

- This section remains stabilized.
- CWD/CWD inlets are in good condition and functioning as intended
- MVP-ATWS-1446 remains stabilized with controls in place.
- P1 is in good condition at all stream and wetland buffers.
- No evidence of 3rd party pond discharging onto ROW at 14000+00
- Resource buffers remain well vegetated.
- Slope on the CIS of Highway 220 remains stabilized with controls in place.
- Waterbars/end treatments are functioning as intended.
- P1 checks have been damaged and need to be replaced at 14035+00.
- CFS is in good condition throughout this section
- Equipment bridge fabric needs to be reattached at 14050+28.
- Slope drain is functioning as intended at 14058+00
- Rock check dams are functioning at 14060+00
- Vegetation continues to fill in throughout this section

*Issues identified in the field have been added to the punch list to be addressed by the contractor

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/24/2022 1:09 PM		Report #	
Pictures					
					
GPS Location		See photo		GPS Location	
Field Station#		13958+31		Field Station#	
Pic 1 Desc.		RCEs are in good condition at all road crossings		Pic 2 Desc.	
				CWDs are functioning as intended	
					
GPS Location		See photo		GPS Location	
Field Station#		13970+00		Field Station#	
Pic 3 Desc.		Area remains stabilized		Pic 4 Desc.	
				P1 is in good condition at all stream and wetland buffers	
					
GPS Location		See photo		GPS Location	
Field Station#		14000+00		Field Station#	
Pic 5 Desc.		No evidence of 3rd party pond discharging onto ROW		Pic 6 Desc.	
				CFS is in good condition throughout this section	

AFE 124300139		Date/Time 8/24/2022 1:09 PM	Report #
Pictures			
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14033+00	Field Station#	14033+00
Pic 7 Desc.	Waterbars are in good condition	Pic 8 Desc.	End treatments are functioning as intended
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14035+00	Field Station#	14035+00
Pic 9 Desc.	Resource buffers remain well vegetated	Pic 10 Desc.	P1 checks need to be replaced
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14050+00	Field Station#	14050+28
Pic 11 Desc.	Slope remains stabilized	Pic 12 Desc.	Equipment bridge fabric needs to be reattached

AFE 124300139	Date/Time 8/24/2022 1:09 PM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	14057+00	Field Station#	14060+00
-----------------------	----------	-----------------------	----------


Pic 13 Desc.	Slope drain is in good condition and functioning	Pic 14 Desc.	Rock check dams are functioning as intended
---------------------	--	---------------------	---



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 15 Desc.		Pic 16 Desc.	
---------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 17 Desc.		Pic 18 Desc.	
---------------------	--	---------------------	--



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41390	
Inspector Charles Head		Date/Time 8/24/2022 2:30 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14802+19	
State VA	Inspection Area Full	Station End 14928+52	
County Franklin	Ground Dry	Temperature (°F) 86.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/24/2022 2:30 PM	Report # 41390
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/24/2022 2:30 PM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14900+00	Field Station#	14812+00		
Pic 1 Desc.	Approximately 14900+00. Overview of ROW.	Pic 2 Desc.	Approximately 14812+00. Overview of ROW. Permanent vegetation.		
GPS Location	0	GPS Location	0		
Field Station#	14881+54	Field Station#	14907+60		
Pic 3 Desc.	Approximately 14881+54. Overview of stream crossing, equipment bridge and ECDs at stream S-CD8.	Pic 4 Desc.	Approximately 14907+60. Overview of stream crossing, equipment bridge and ECDs at stream S-DD3.		
GPS Location	0	GPS Location	0		
Field Station#	14915+10	Field Station#	14806+00		
Pic 5 Desc.	Approximately 14915+10. Overview of stream crossing, equipment bridge and ECDs at stream S-G16.	Pic 6 Desc.	Approximately 14806+00. Overview of ROW.		

AFE 124300139	Date/Time 8/24/2022 2:30 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300139	Date/Time	8/24/2022 2:30 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41327	
Inspector Ben Davenport		Date/Time 8/24/2022 11:32 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14454+22	
State VA	Inspection Area Partial	Station End 14546+75	
County Franklin	Ground Damp	Temperature (°F) 84.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Temporary Diversion Berm	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Compost Filter Sock	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Sump Pit	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/24/2022 11:32 AM	Report # 41327
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- Available for work
- Received instruction from Lead EI for daily tasks
- Sunny with damp ground conditions during inspection
- Performed SWPPP inspection on portion of MVP Spread I section
- Covered territory between station# 14454+22 — 14546+75 (Webster Rd to Tobacco Rd)
- Precision environmental crew in section during inspection
- Walked ROW making note of condition of ROW and environmental controls
- Verified the completion and accuracy of punch list items in covered area from previous inspections
- Perimeter controls and ECDs were inspected; no issues identified
- Inspection observed condition of equipment bridges and surrounding ECDs around stream crossings and resource buffers; no issues identified
- Inspection observed condition of RCEs and culverts in section; no issues identified
- Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
- Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
- Continue to monitor ROW for signs of erosion
- No items added to environmental punch list in section

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/24/2022 11:32 AM	Report #
Pictures			
			
<small>37°125' N 79°4554' W 128° SE COURSE 162° GPS 2832 Webster Rd, Glade Hill, VA 24092, United States 08-24-2022 09:53:53 Accur +/-56.3 Ft ALT 1069 Ft</small>		<small>37°112' N 79°4544' W 239° SW COURSE -1° GPS Glade Hill, VA 24092, United States 08-24-2022 10:01:24 Accur +/-15.1 Ft ALT 944 Ft</small>	
GPS Location	1	GPS Location	2
Field Station#	14468+00	Field Station#	14483+00
Pic 1 Desc.	Temporary diversion berm stabilized and vegetated.	Pic 2 Desc.	Perimeter P1 silt fence in good condition.
			
<small>37°111' N 79°4543' W 231° SW COURSE 144° GPS Glade Hill, VA 24092, United States 08-24-2022 10:01:58 Accur +/-15.5 Ft ALT 926 Ft</small>		<small>37°041' N 79°4517' W 44° NE COURSE 359° GPS 1705 SR-674, Glade Hill, VA 24092, United States 08-24-2022 10:32:44 Accur +/-15.4 Ft ALT 1004 Ft</small>	
GPS Location	3	GPS Location	4
Field Station#	14486+56	Field Station#	14522+00
Pic 3 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	Pic 4 Desc.	Water bar performing intended function; ROW stabilized and vegetated in temporary area.
			
<small>37°040' N 79°4519' W 206° SW COURSE -1° GPS 1705 SR-674, Glade Hill, VA 24092, United States 08-24-2022 10:32:07 Accur +/-15.4 Ft ALT 1076 Ft</small>		<small>37°038' N 79°4516' W 294° NW COURSE -1° GPS 1700 SR-674, Glade Hill, VA 24092, United States 08-24-2022 10:30:49 Accur +/-15.1 Ft ALT 1050 Ft</small>	
GPS Location	5	GPS Location	6
Field Station#	14524+76	Field Station#	14529+00
Pic 5 Desc.	RCE at Timber Ridge in good condition.	Pic 6 Desc.	Sump pit and CFS end treatment performing intended functions.

AFE 124300139	Date/Time 8/24/2022 11:32 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/24/2022 11:32 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 13 Desc.	Pic 14 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 15 Desc.	Pic 16 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41378	
Inspector John White		Date/Time 8/24/2022 8:53 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15647+03	
State VA	Inspection Area Full	Station End 15772+27	
County Pittsylvania	Ground Dry	Temperature (°F) 74.00	
Municipality Chatham	Weather Sunny	Rain Gauge (in) 0.80	
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter Outlet	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/24/2022 8:53 AM	Report #	41378
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/24/2022 8:53 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15658+43	Field Station#	15665+50		
Pic 1 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's	Pic 2 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15680+00	Field Station#	15693+89		
Pic 3 Desc.	Observing temporary stabilization CWD berm and water bars	Pic 4 Desc.	Observing road crossing and RCE's		
					
GPS Location	O	GPS Location	O		
Field Station#	15710+00	Field Station#	15735+00		
Pic 5 Desc.	Observing temporary stabilization, sump and end treatment	Pic 6 Desc.	Observing temporary stabilization, CWD outlet and ECD's		

AFE 124300139	Date/Time 8/24/2022 8:53 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/24/2022 8:53 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41420	
Inspector Justin Burch		Date/Time 8/25/2022 11:53 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15370+62
State VA	Inspection Area Full	Station End	15480+67
County Pittsylvania	Ground Damp	Temperature (°F)	85.00
Municipality Chatham	Weather Cloudy	Rain Gauge (in)	0.90
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Communication			
Equipment Bridge	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sump Pit	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/25/2022 11:53 AM	Report # 41420
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		





7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15370+62 to 15480+67 (Snowberry Road to Toshes Road). One punch list item was submitted which consisted of a location where temporary stabilization was damaged by a third party. Other inspected ECDs were observed as being in compliance at the time of inspection.
- The EI did not observe that the contractor has worked in the area since the last SWPPP inspection.
- The EI observed that stream S-G4 (15426+54) was running clear. This stream has been impacted in the past by upstream activities not related to MVP.
- The EI observed that the solar farm perimeter ECDs on the CIS of Toshes Road appeared to be in acceptable condition.
- Since the last SWPPP inspection the inspection area has received two rain events with a total of 0.90" at Snowberry Road.
- The ROW ground condition is damp .
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion and permanent vegetative stabilization was adequately established to inhibit erosion from 15438+00 to 15445+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/25/2022 11:53 AM	Report #
Pictures			
			
GPS Location	0	GPS Location	0
Field Station#	15425+50	Field Station#	15384+74
Pic 1 Desc.	Temporary vegetative stabilization damaged by third party from 15425+50 to 15426+00	Pic 2 Desc.	Equipment bridge in acceptable condition
			
GPS Location	0	GPS Location	0
Field Station#	15402+00	Field Station#	15404+00
Pic 3 Desc.	Temporary vegetative stabilization in acceptable condition	Pic 4 Desc.	Clean water diversion pipe in acceptable condition
			
GPS Location	0	GPS Location	0
Field Station#	15416+00	Field Station#	15416+00
Pic 5 Desc.	Waterbar in acceptable condition	Pic 6 Desc.	Waterbar end treatment in acceptable condition

AFE 124300139		Date/Time 8/25/2022 11:53 AM		Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	15426+54		Field Station#	15427+00	
Pic 7 Desc.	Stream S-G4 is running clear		Pic 8 Desc.	P1 silt fence and sensitive resource buffer in acceptable conditions	
					
GPS Location	0		GPS Location	0	
Field Station#	15465+00		Field Station#	15472+00	
Pic 9 Desc.	Sump pit in acceptable condition		Pic 10 Desc.	Solar farm perimeter ECDs appear to be in acceptable conditions	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 11 Desc.			Pic 12 Desc.		

AFE 124300139	Date/Time 8/25/2022 11:53 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 13 Desc.	Pic 14 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 15 Desc.	Pic 16 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41424	
Inspector Ben Farmer		Date/Time 8/25/2022 12:37 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14062+17	
State VA	Inspection Area Partial	Station End 14171+36	
County Franklin	Ground Dry	Temperature (°F) 65.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/25/2022 12:37 PM	Report # 41424
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.






Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 65F)
 Rain Gauge= 0.0"
 14062+17-14171+36

- RCE are in good condition at all road crossings.
- Equipment bridge ECDs are in good condition and functioning.
- CWDs are functioning as intended.
- Topsoil berm remains stabilized
- MVP-FR-309.05 is in good condition with controls in place.
- P1 is in good condition throughout this section.
- Resource buffers remain well vegetated.
- CFS is in good condition throughout this section
- Waterbars/end treatments are in good condition and functioning
- Slope drain is functioning as intended at 14157+00.
- SSF is in good condition.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/25/2022 12:37 PM	Report #
Pictures			
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14062+17	Field Station#	14066+77
Pic 1 Desc.	RCEs are in good condition at all road crossings	Pic 2 Desc.	Equipment bridge ECDs are functioning as intended
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14070+00	Field Station#	14085+00
Pic 3 Desc.	CWDs are functioning as intended	Pic 4 Desc.	Topsoil berms remain stabilized
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14105+20	Field Station#	14110+00
Pic 5 Desc.	Resource buffers remain well vegetated	Pic 6 Desc.	Waterbars are in good condition

AFE 124300139		Date/Time 8/25/2022 12:37 PM		Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14110+00		Field Station#	14120+00	
Pic 7 Desc.	End treatments are functioning as intended		Pic 8 Desc.	CFS is in good condition throughout this section	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14132+00		Field Station#	14141+00	
Pic 9 Desc.	CWD is functioning as intended		Pic 10 Desc.	P1 is in good condition at all stream and wetland buffers.	
		Insert image here			
GPS Location	See photo		GPS Location		
Field Station#	14171+36		Field Station#		
Pic 11 Desc.	SSF is in good condition		Pic 12 Desc.		

AFE 124300139	Date/Time 8/25/2022 12:37 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41430	
Inspector Frank Craycroft		Date/Time 8/25/2022 3:33 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13670+00	
State VA	Inspection Area Full	Station End 13748+30	
County Franklin	Ground Dry	Temperature (°F) 85.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/25/2022 3:33 PM	Report # 41430
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted SWPPP inspection of ROW from Spread H/I break to Green Level Rd. Vegetation is generally excellent to full and no signs of erosion or washing was observed. All perimeter ECDs observed were functional and in good condition. All buffer zones were intact and show no signs of erosion or sedimentation from ROW. Equipment bridges were clean and free of sediment and mud buildup. Waterbars and sumps in area were still functional and show no signs of sediment buildup.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/25/2022 3:33 PM		Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	13679+50	Field Station#	13690+80		
Pic 1 Desc.	GAS S-E29 Vegetation	Pic 2 Desc.	CIS Grassy Hill Rd Perimeter Silt fence		
					
GPS Location	0	GPS Location	0		
Field Station#	13690+00	Field Station#	13692+70		
Pic 3 Desc.	CIS Grassy Hill Rd Perimeter CFS	Pic 4 Desc.	S-E28 Channel and banks		
					
GPS Location	0	GPS Location	0		
Field Station#	13700+00	Field Station#	13693+00		
Pic 5 Desc.	Travel lane vegetation	Pic 6 Desc.	Perimeter silt fence		

AFE 124300139		Date/Time 8/25/2022 3:33 PM		Report #	
Pictures					
GPS Location 0		GPS Location 0			
Field Station# 13695+50		Field Station# 13705+00			
Pic 7 Desc. W-E7 and perimeter silt fence		Pic 8 Desc. S-E28 Channel and banks			
				ert image here	
GPS Location 0		GPS Location 0			
Field Station# 13707+00		Field Station# 13733+00			
Pic 9 Desc. Sump and J-hook		Pic 10 Desc. Temporary vegetation			
				ert image here	
GPS Location 0		GPS Location 0			
Field Station# 13738+00		Field Station# 13743+00			
Pic 11 Desc. Perimeter CFS		Pic 12 Desc. Perimeter CFS			

AFE 124300139	Date/Time 8/25/2022 3:33 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41418	
Inspector Charles Head		Date/Time 8/25/2022 10:57 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14928+52	
State VA	Inspection Area Full	Station End 15063+85	
County Franklin/Pittsylvania	Ground Dry	Temperature (°F) 79.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Communication	Reattach fabric to chain link		

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/25/2022 10:57 AM	Report #
Pictures			
GPS Location	0	GPS Location	0
Field Station#	14972+00	Field Station#	14981+00
Pic 1 Desc.	Approximately 14972+00. Overview of ROW. Permanent vegetation.	Pic 2 Desc.	Approximately 14981+00. Overview of road crossing and RCEs.
GPS Location	0	GPS Location	0
Field Station#	14944+00	Field Station#	15026+00
Pic 3 Desc.	Approximately 14944+00. Overview of ROW.	Pic 4 Desc.	Approximately 15026+00. Overview of stream crossing, equipment bridge and ECDs at stream S-D3.
GPS Location	0	GPS Location	0
Field Station#	15011+00	Field Station#	14951+50
Pic 5 Desc.	Approximately 15011+00. Overview of ROW.	Pic 6 Desc.	Approximately 14951+50. SSF requires maintenance. Reattach fabric to chain link.

AFE 124300139	Date/Time 8/25/2022 10:57 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300139	Date/Time	8/25/2022 10:57 AM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41395	
Inspector Ben Davenport		Date/Time 8/25/2022 10:12 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14546+75	
State VA	Inspection Area Partial	Station End 14649+67	
County Franklin	Ground Dry	Temperature (°F) 83.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)	Communication	Routine maintenance; cattle damage		
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Temporary Diversion Berm	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE 124300139	Date/Time 8/25/2022 10:12 AM	Report # 41395
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

-Available for work
 -Received instruction from Lead EI for daily tasks
 -Sunny with dry ground conditions during inspection
 -Performed SWPPP inspection on portion of MVP Spread I section
 -Covered territory between station# 14546+75 — 14649+67 (Tobacco Rd to Hwy 40 crossing)
 -Walked ROW making note of condition of ROW and environmental controls
 -Verified the completion and accuracy of punch list items in covered area from previous inspections
 -Perimeter controls and ECDs were inspected; 1 issue identified
 -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified
 -Inspection observed condition of RCEs and culverts in section; no issues identified
 -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
 -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
 -Continue to monitor ROW for signs of erosion
 -1 item added to environmental punch list

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/25/2022 10:12 AM		Report #	
Pictures					
					
<small>37°02' N 79°44'40" W 1" N COURSE 79° GPS 08.25.2022 10:29:33 Glade Hill, VA 24092, United States Accur +/-15.5 Ft ALT 873 Ft</small>			<small>37°10' N 79°45'2" W 257"W COURSE -1° GPS 08.25.2022 10:18:46 Accur +/-15.1 Ft ALT 922 Ft</small>		
GPS Location	1		GPS Location	2	
Field Station#	14575+00		Field Station#	14556+00	
Pic 1 Desc.	Routine maintenance. Replace damaged panels of P1 silt fence from cattle damage.		Pic 2 Desc.	Erosion control blanket and CFS in place and functional on perimeter.	
					
<small>37°07' N 79°44'58" W 155°SE COURSE 83° GPS 08.25.2022 10:20:49 Sorry no results found Accur +/-11.6 Ft ALT 913 Ft</small>			<small>37°03' N 79°44'50" W 268°W COURSE 156° GPS 08.25.2022 10:24:43 Sorry no results found Accur +/-22.4 Ft ALT 891 Ft</small>		
GPS Location	3		GPS Location	4	
Field Station#	14560+00		Field Station#	14568+10	
Pic 3 Desc.	Equipment bridge over natural drainage area performing intended function.		Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer; signage visible and intact.	
					
<small>37°02' N 79°44'37" W 145°SE COURSE 136° GPS 08.25.2022 10:31:13 Glade Hill, VA 24092, United States Accur +/-11.8 Ft ALT 866 Ft</small>			<small>37°01' N 79°44'34" W 144°SE COURSE 86° GPS 08.25.2022 10:32:54 Glade Hill, VA 24092, United States Accur +/-15.5 Ft ALT 850 Ft</small>		
GPS Location	5		GPS Location	6	
Field Station#	14570+00		Field Station#	14582+85	
Pic 5 Desc.	Water bar performing intended function.		Pic 6 Desc.	Downstream view of S-E17 at ROW crossing.	

AFE 124300139	Date/Time 8/25/2022 10:12 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/25/2022 10:12 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41416	
Inspector John White		Date/Time 8/25/2022 10:28 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15772+27	
State VA	Inspection Area Full	Station End 15947+64	
County Pittsylvania	Ground Dry	Temperature (°F) 75.00	
Municipality Chatham	Weather Cloudy	Rain Gauge (in) 0.80	
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication	Perform maintenance		
Silt Fence (Filter Fabric Fence)	Communication	Perform maintenance		
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Plunge Pool	Acceptable			
Rock Filter Outlet	Acceptable			
Sediment Filter Log	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/25/2022 10:28 AM	Report #	41416
------------	-----------	------------------	--------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/25/2022 10:28 AM	Report #
Pictures			
GPS Location	O	GPS Location	O
Field Station#	15934+00	Field Station#	15923+49
Pic 1 Desc.	Observing temporary stabilization,CWD outlet and ECD's	Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's
GPS Location	O	GPS Location	O
Field Station#	15878+08	Field Station#	15850+00
Pic 3 Desc.	Observing temporary stabilization,water bars, buffer, equipment crossing and ECD's	Pic 4 Desc.	Observing temporary stabilization,sump and end treatment
GPS Location	O	GPS Location	O
Field Station#	15825+00	Field Station#	15782+00
Pic 5 Desc.	Observing temporary stabilization,plunge pool and ECD's	Pic 6 Desc.	Observing P1 that requires maintenance

AFE	124300139	Date/Time	8/25/2022 10:28 AM	Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15776+00	Field Station#	15794+77		
Pic 7 Desc.	Observing CFS that requires maintenance	Pic 8 Desc.	Observing temporary stabilization, water bar, buffer, equipment crossing and ECD's		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 9 Desc.		Pic 10 Desc.			
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

AFE 124300139	Date/Time 8/25/2022 10:28 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-602 Pipeline Spread I		AFE 124300139	Spread H-602 Pipeline Spread I
Contractor Precision		Report # 41454	
Inspector John White		Date/Time 8/26/2022 8:03 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	00+00
State VA	Inspection Area Full	Station End	19+25
County Pittsylvania	Ground Dry	Temperature (°F)	69.00
Municipality Chatham	Weather Cloudy	Rain Gauge (in)	0.60
			Rain Accumulation Time (days) 4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

A/E	124300139	Date/Time	8/26/2022 8:03 AM	Report #	41454
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139	Date/Time 8/26/2022 8:03 AM	Report #
----------------------	------------------------------------	-----------------

Pictures



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	6+00	Field Station#	12+65
-----------------------	------	-----------------------	-------

Pic 1 Desc.	Observing temporary stabilization	Pic 2 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's
--------------------	-----------------------------------	--------------------	--



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	13+50	Field Station#	15+00
-----------------------	-------	-----------------------	-------

Pic 3 Desc.	Observing temporary stabilization, sump and end treatment	Pic 4 Desc.	Observing temporary stabilization
--------------------	---	--------------------	-----------------------------------

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 5 Desc.		Pic 6 Desc.	
--------------------	--	--------------------	--

AFE 124300139	Date/Time 8/26/2022 8:03 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE	124300139	Date/Time	8/26/2022 8:03 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-603 Pipeline Spread I		AFE 124300139	Spread H-603 Pipeline Spread I
Contractor Precision		Report # 41452	
Inspector John White		Date/Time 8/26/2022 7:53 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	00+00
State VA	Inspection Area Full	Station End	24+53
County Pittsylvania	Ground Dry	Temperature (°F)	69.00
Municipality Chatham	Weather Cloudy	Rain Gauge (in)	0.60
			Rain Accumulation Time (days) 4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/26/2022 7:53 AM	Report #	41452
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139	Date/Time 8/26/2022 7:53 AM	Report #
----------------------	------------------------------------	-----------------

Pictures



GPS Location ○	GPS Location ○
-----------------------	-----------------------

Field Station# 14+00	Field Station# 22+00
-----------------------------	-----------------------------

Pic 1 Desc. Observing temporary stabilization and RCE	Pic 2 Desc. Observing temporary stabilization and buffer
--	---



GPS Location ○	GPS Location ○
-----------------------	-----------------------

Field Station# 12+00	Field Station# 6+00
-----------------------------	----------------------------

Pic 3 Desc. Observing temporary stabilization, sump, end treatment and ECD's	Pic 4 Desc. Observing temporary stabilization and water bar
---	--

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
---------------------	---------------------

Field Station#	Field Station#
-----------------------	-----------------------

Pic 5 Desc.	Pic 6 Desc.
--------------------	--------------------

AFE 124300139	Date/Time 8/26/2022 7:53 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/26/2022 7:53 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 13 Desc.	Pic 14 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 15 Desc.	Pic 16 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41461	
Inspector Justin Burch		Date/Time 8/26/2022 10:18 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15480+67	
State VA	Inspection Area Full	Station End 15584+23	
County Pittsylvania	Ground Damp	Temperature (°F) 89.00	
Municipality Chatham	Weather Sunny	Rain Gauge (in) 0.10	
Rain Accumulation Time (days)			4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Sump Pit	Acceptable			
Equipment Bridge	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/26/2022 10:18 AM	Report # 41461
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15480+67 to 15584+23 (Toshes Road to Anderson Mill Road 1). No punch list items were submitted due to the inspected ECDs being in compliance at the time of inspection.
- The EI observed that the contractor has worked in the area since the last SWPPP inspection and addressed punch list items.
- The EI observed that streams S-MM8 at 15521+00 and S-CC5 at 15542+11 were running without elevated turbidity. These streams have been impacted in the past by upstream activities not related to MVP.
- The EI observed that a land clearing operation has continued from approximate 15548+00 to 15560+00 on the south side of the ROW on the CIS of Anderson Mill Road 1. No perimeter ECDs were observed by the EI and no impacts were observed to streams S-CC5, S-CC9 or S-CC10.
- The EI observed that the solar farm ECDs adjacent to the ROW on GAS of Climax Road appeared to be in acceptable condition and that their super silt fence on the CIS of climax Road was down in multiple locations where the solar farm fencing crew has recently worked. The EI also observed that a grading operation was in progress from approximately 15498+00 to 15506+00 on the north side of the ROW on the GAS of Climax Road.
- The EI inspected the MVP ROW at 15483+00 where the solar farm had a dewatering operation draining across MVP ROW yesterday and observed that no sedimentation had occurred.
- Since the last SWPPP inspection the inspection area has received one rain event with a total of 0.10" at Snowberry Road.
- The ROW ground condition is damp.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion and permanent vegetative stabilization was adequately established to inhibit erosion from 15482+00 to 15495+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/26/2022 10:18 AM		Report #	
Pictures					
					
GPS Location		0		GPS Location	
Field Station#		15508+00		Field Station#	
Pic 1 Desc.		P1 silt fence and sensitive resource buffer in acceptable conditions		Pic 2 Desc.	
					
GPS Location		0		GPS Location	
Field Station#		15514+00		Field Station#	
Pic 3 Desc.		Waterbar end treatment in acceptable condition		Pic 4 Desc.	
					
GPS Location		0		GPS Location	
Field Station#		15538+00		Field Station#	
Pic 5 Desc.		Clean water diversion pipe in acceptable condition		Pic 6 Desc.	

AFE 124300139		Date/Time 8/26/2022 10:18 AM	Report #
Pictures			
			
GPS Location	0	GPS Location	0
Field Station#	15549+00	Field Station#	15548+00
Pic 7 Desc.	Clean water diversion berm and temporary vegetative stabilization in acceptable conditions	Pic 8 Desc.	A field that recently had stumps and rocks cleared upslope from streams S-CC5, S-CC9 and S-CC10
			
GPS Location	0	GPS Location	0
Field Station#	15555+00	Field Station#	15505+00
Pic 9 Desc.	A field that recently had stumps and rocks cleared upslope from streams S-CC5, S-CC9 and S-CC10	Pic 10 Desc.	Solar farm perimeter ECDs and grading operation on the GAS of Climax Road
			
GPS Location	0	GPS Location	0
Field Station#	15483+00	Field Station#	15573+00
Pic 11 Desc.	No sediment was observed on MVP ROW from yesterday's solar farm dewatering operation	Pic 12 Desc.	Sump pit in acceptable condition

AFE 124300139	Date/Time 8/26/2022 10:18 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41470	
Inspector Ben Farmer		Date/Time 8/26/2022 12:46 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14171+36	
State VA	Inspection Area Partial	Station End 14311+57	
County Franklin	Ground Dry	Temperature (°F) 67.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Communication			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/26/2022 12:46 PM	Report # 41470
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in good		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)







SWPPP Inspection (Sunny, 67F)
 Rain Gauge= 0.0"
 14171+36-14311+57

- RCEs are in good condition at all road crossings.
- CWDs are functioning as intended.
- Equipment bridge ECDs are in good condition and functioning.
- Waterbars/end treatments are in good condition throughout this section.
- P1 is in good condition at all stream and wetland buffers.
- SSF fabric needs to be reattached at 14196+90.
- Slope drain is in good condition and functioning at 14232+00
- Resource buffers remain well vegetated.
- CFS is in good condition throughout this section.
- Topsoil berms remain stabilized

*Issues identified in the field have been added to the punch list to be addressed by the contractor.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/26/2022 12:46 PM		Report #	
Pictures					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14171+36		Field Station#	14180+00	
Pic 1 Desc.	RCEs are in good condition at all road crossings		Pic 2 Desc.	CWDs are functioning as intended	
GPS Location	See photo		GPS Location	See photo	
Field Station#	14185+00		Field Station#	14185+00	
Pic 3 Desc.	Waterbars are in good condition		Pic 4 Desc.	End treatments are functioning as intended	
GPS Location	See photo		GPS Location	See photo	
Field Station#	14191+00		Field Station#	14196+90	
Pic 5 Desc.	P1 is in good condition at all stream and wetland buffers		Pic 6 Desc.	SSF fabric needs to be reattached	

AFE 124300139		Date/Time 8/26/2022 12:46 PM	Report #
Pictures			
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14209+00	Field Station#	14213+75
Pic 7 Desc.	Equipment bridge ECDs are functioning as intended	Pic 8 Desc.	Resource buffers remain well vegetated
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14216+00	Field Station#	14223+41
Pic 9 Desc.	CFS is in good condition	Pic 10 Desc.	MVP-FR-311 remains in good condition with controls in place
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14232+00	Field Station#	14300+00
Pic 11 Desc.	Slope drain is functioning as intended	Pic 12 Desc.	Topsoil berms remain stabilized

AFE 124300139	Date/Time 8/26/2022 12:46 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41469	
Inspector Glenn Mike Renfro		Date/Time 8/26/2022 12:40 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	0000+00
State VA	Inspection Area Full	Station End	0000+00
County Franklin	Ground Dry	Temperature (°F)	84.00
Municipality N/A	Weather Cloudy	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Other - Explain in Comments	Acceptable	Inlet protection for catch basins		
Secondary Containment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | N/A |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | N/A |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/26/2022 12:40 PM	Report #	41469
------------	-----------	------------------	--------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va.
- The locations have not received any rainfall since the last inspection and site conditions were dry.
- All perimeter ECD's were inspected and no issues were observed.
- The inlet protection for the catch basins at LY-046 were found to be in acceptable condition.
- All secondary containment structures were inspected and no issues were found during the inspections.
- The RCE at LY-045 was in good condition.
- All equipment at both locations were inspected and no leaks were observed the during inspection.
- The General Construction permits and contact information are posted at the entrance of LY-046 as required.
- There were no issues identified during todays inspections.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139	Date/Time 8/26/2022 12:40 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures



GPS Location	See picture	GPS Location	See picture
Field Station#	0000+00	Field Station#	0000+00
Pic 1 Desc.	RCE at LY-045 in good condition.	Pic 2 Desc.	Secondary containment structure and perimeter ECD's on north end of LY-045 in good condition.



GPS Location	See picture	GPS Location	See picture
Field Station#	0000+00	Field Station#	0000+00
Pic 3 Desc.	Perimeter ECD's on west side of LY-045 in good condition.	Pic 4 Desc.	Secondary containment structure for pressure washer at LY-045 in good condition.



GPS Location	See picture	GPS Location	See picture
Field Station#	0000+00	Field Station#	0000+00
Pic 5 Desc.	Perimeter ECD's on northwest corner of LY-046 in good condition.	Pic 6 Desc.	Perimeter ECD's and inlet protection for catch basin on southwest corner of LY-046 in good condition.

AFE 124300139	Date/Time 8/26/2022 12:40 PM	Report #
----------------------	-------------------------------------	-----------------


Pictures



GPS Location	See picture	GPS Location	See picture
---------------------	-------------	---------------------	-------------

Field Station#	00000+00	Field Station#	0000+00
-----------------------	----------	-----------------------	---------


Pic 7 Desc.	Perimeter ECD's on south end of LY-046 in good condition.	Pic 8 Desc.	Secondary containment structure for fuel cell at LY-046 in good condition.
--------------------	---	--------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 9 Desc.		Pic 10 Desc.	
--------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 11 Desc.		Pic 12 Desc.	
---------------------	--	---------------------	--

AFE 124300139	Date/Time 8/26/2022 12:40 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41471	
Inspector Frank Craycroft		Date/Time 8/26/2022 12:51 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13748+30	
State VA	Inspection Area Full	Station End 13853+45	
County Franklin	Ground Dry	Temperature (°F) 85.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/26/2022 12:51 PM	Report # 41471
----------------------	-------------------------------------	-----------------------

6. **PCSM BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired




7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted SWPPP inspection of ROW from Green Level Rd to MVP-FR-303.01. Vegetation was generally good to excellent with annual grains. Waterbars and sumps were functioning and showed no signs of sedimentation. All ECDs along perimeter of ROW and buffer zones in area were functional and in good condition. Buffer zones were intact and showed no signs of erosion or sedimentation from ROW. Equipment bridges were clean and free of sediment deposits. No signs of erosion or washing were observed.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/26/2022 12:51 PM		Report #	
Pictures					
					
GPS Location 0		GPS Location 0			
Field Station# 13830+00		Field Station# 13847+00			
Pic 1 Desc. Sump and J-hook		Pic 2 Desc. S-C16 Buffer zones			
					
GPS Location 0		GPS Location 0			
Field Station# 13824+00		Field Station# 13839+00			
Pic 3 Desc. Temporary vegetation		Pic 4 Desc. Perimeter Super silt fence			
					
GPS Location 0		GPS Location 0			
Field Station# 13818+00		Field Station# 13815+00			
Pic 5 Desc. Sideslope vegetation		Pic 6 Desc. Plunge pool			

AFE 124300139		Date/Time 8/26/2022 12:51 PM		Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	13811+75	Field Station#	13806+50		
Pic 7 Desc.	CIS Brick Church Rd CFS	Pic 8 Desc.	GAS S-D20 Buffer zone and silt fence		
		Insert image here			
GPS Location	0	GPS Location			
Field Station#	13805+70	Field Station#			
Pic 9 Desc.	S-D20 Channel and banks	Pic 10 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

AFE 124300139	Date/Time 8/26/2022 12:51 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 13 Desc.	Pic 14 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 15 Desc.	Pic 16 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41473	
Inspector Frank Craycroft		Date/Time 8/26/2022 12:58 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	0+00
State VA	Inspection Area Full	Station End	0+00
County Franklin	Ground Dry	Temperature (°F)	85.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Timber Mat	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waste Management	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | N/A |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/26/2022 12:58 PM	Report # 41473
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted SWPPP inspection of LY-032, -033, and ANC-006. All perimeter ECDs observed were functional and in good condition. All entrances were free of mud and dirt buildup. All portable equipment and hazardous materials were maintained within secondary containment. All trash and loose debris was maintained within bulk dumpsters on-site. Stormwater drain inlets had proper perimeter protection and were free of trash and loose vegetation.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/26/2022 12:58 PM	Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 1 Desc.	LY-032 Staging area	Pic 2 Desc.	ANC-006 Stormwater drain inlet protection		
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 3 Desc.	ANC-006 Perimeter CFS	Pic 4 Desc.	LY-032 Secondary containment		
					
GPS Location	0	GPS Location	0		
Field Station#	0+00	Field Station#	0+00		
Pic 5 Desc.	LY-033 Stormwater drain inlet protection	Pic 6 Desc.	LY-033 Secondary containment		

AFE 124300139	Date/Time 8/26/2022 12:58 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/26/2022 12:58 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41460	
Inspector Charles Head		Date/Time 8/26/2022 9:47 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15063+85	
State VA	Inspection Area Full	Station End 15142+66	
County Pittsylvania	Ground Damp	Temperature (°F) 73.00	
Municipality Chatham	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/26/2022 9:47 AM	Report # 41460
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation.		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/26/2022 9:47 AM	Report #
Pictures			
GPS Location	0	GPS Location	0
Field Station#	15113+00	Field Station#	15137+00
Pic 1 Desc.	Approximately 15113+00. Overview of road crossing and RCEs.	Pic 2 Desc.	Approximately 15137+00. Overview of ROW.
GPS Location	0	GPS Location	0
Field Station#	15126+40	Field Station#	15133+00
Pic 3 Desc.	Approximately 15126+40. Overview of stream crossing, equipment bridge and ECDs at stream S-A6.	Pic 4 Desc.	Approximately 15133+00. Overview of ROW.
GPS Location	0	GPS Location	0
Field Station#	15101+00	Field Station#	15068+00
Pic 5 Desc.	Approximately 15101+00. Overview of ROW. Permanent vegetation. Livestock graze area.	Pic 6 Desc.	Approximately 15068+00. Overview of ROW.

AFE 124300139	Date/Time 8/26/2022 9:47 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/26/2022 9:47 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41429	
Inspector Ben Davenport		Date/Time 8/26/2022 11:40 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14649+67	
State VA	Inspection Area Partial	Station End 14694+77	
County Franklin	Ground Dry	Temperature (°F) 82.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Sediment Filter Log	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/26/2022 11:40 AM	Report # 41429
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

-Available for work
 -Received instruction from Lead EI for daily tasks
 -Sunny with dry ground conditions during inspection
 -Performed SWPPP inspection on portion of MVP Spread I section
 -Covered territory between station# 14649+67 — 14694+77 (Hwy 40 crossing to Jacks Creek Rd)
 -Walked ROW making note of condition of ROW and environmental controls
 -Verified the completion and accuracy of punch list items in covered area from previous inspections
 -Perimeter controls and ECDs were inspected; no issues identified
 -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified
 -Inspection observed condition of RCEs and culverts in section; no issues identified
 -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
 -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
 -Continue to monitor ROW for signs of erosion
 -No items added to environmental punch list in section

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/26/2022 11:40 AM		Report #	
Pictures					
					
<small>36°59'16" N 79°42'37" W 215°SW COURSE 0° GPS 08.26.2022 09:41:23 Sorry no results found Accur +/-13.5 Ft ALT 0 Ft</small>			<small>36°59'22" N 79°43'27" W 55°NE COURSE -1° GPS 08.26.2022 10:01:07 Union Hall, VA 24176, United States Accur +/-14.1 Ft ALT 944 Ft</small>		
GPS Location	1		GPS Location	2	
Field Station#	14694+50		Field Station#	14651+00	
Pic 1 Desc.	Contractor installed missing perimeter ECD per punch list item.e		Pic 2 Desc.	ROW stabilized and vegetated in final cleanup area.	
					
<small>36°59'22" N 79°43'21" W 87°E COURSE 117° GPS 08.26.2022 10:01:33 Union Hall, VA 24176, United States Accur +/-15.4 Ft ALT 939 Ft</small>			<small>36°59'16" N 79°42'52" W 259°W COURSE -1° GPS 08.26.2022 09:48:39 Sorry no results found Accur +/-15.1 Ft ALT 917 Ft</small>		
GPS Location	3		GPS Location	4	
Field Station#	14656+37		Field Station#	14680+29	
Pic 3 Desc.	Perimeter P1 silt fence in resource buffer in good condition.		Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	
					
<small>36°59'16" N 79°42'52" W 201°S COURSE -1° GPS 08.26.2022 09:48:45 Sorry no results found Accur +/-15.1 Ft ALT 918 Ft</small>			<small>36°59'16" N 79°42'43" W 275°W COURSE -1° GPS 08.26.2022 09:44:42 Sorry no results found Accur +/-37.7 Ft ALT 953 Ft</small>		
GPS Location	5		GPS Location	6	
Field Station#	14681+25		Field Station#	14688+86	
Pic 5 Desc.	Perimeter SSF in place and functional.		Pic 6 Desc.	Perimeter CFS triple stack in good condition.	

AFE 124300139	Date/Time 8/26/2022 11:40 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/26/2022 11:40 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41456	
Inspector John White		Date/Time 8/26/2022 8:47 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15947+64	
State VA	Inspection Area Full	Station End 16027+46	
County Pittsylvania	Ground Dry	Temperature (°F) 69.00	
Municipality Chatham	Weather Cloudy	Rain Gauge (in) 0.60	
Rain Accumulation Time (days)			4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication			
Vegetative Stabilization (Temporary)	Communication	Third party damage. Repair rutting		

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/26/2022 8:47 AM	Report #	41456
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.

PPL has identified issues and items will be added to the punchlist.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/26/2022 8:47 AM		Report #	
Pictures					
GPS Location		O		GPS Location	
Field Station#		16022+00		Field Station#	
Pic 1 Desc.		Observing temporary stabilization and water bar		Pic 2 Desc.	
GPS Location		O		GPS Location	
Field Station#		15977+35		Field Station#	
Pic 3 Desc.		Observing temporary stabilization, water bar, buffer, equipment crossing and ECD's		Pic 4 Desc.	
GPS Location		O		GPS Location	
Field Station#		15997+00		Field Station#	
Pic 5 Desc.		Observing temporary stabilization, water bar and erosion control blanket		Pic 6 Desc.	
				Observing temporary stabilization, signage, buffer and ECD's	

AFE 124300139	Date/Time 8/26/2022 8:47 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/26/2022 8:47 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41459	
Inspector John White		Date/Time 8/26/2022 9:15 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	00+00
State VA	Inspection Area Full	Station End	00+00
County Pittsylvania	Ground Dry	Temperature (°F)	73.00
Municipality Chatham	Weather Cloudy	Rain Gauge (in)	0.60
			Rain Accumulation Time (days) 4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/26/2022 9:15 AM	Report #	41459
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on the Blairs yard. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/26/2022 9:15 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--


Pictures



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	00+00	Field Station#	00+00
-----------------------	-------	-----------------------	-------

Pic 1 Desc.	Observing temporary stabilization	Pic 2 Desc.	Observing temporary stabilization and ECD's
--------------------	-----------------------------------	--------------------	---



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	00+00	Field Station#	00+00
-----------------------	-------	-----------------------	-------

Pic 3 Desc.	Observing temporary stabilization and ECD's	Pic 4 Desc.	Observing temporary stabilization and ECD's
--------------------	---	--------------------	---

<p>Insert image here</p>	<p>Insert image here</p>
--------------------------	--------------------------

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 5 Desc.		Pic 6 Desc.	
--------------------	--	--------------------	--

AFE 124300139	Date/Time 8/26/2022 9:15 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/26/2022 9:15 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 13 Desc.	Pic 14 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 15 Desc.	Pic 16 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name Transco Interconnect Station		AFE 124300113	Spread Transco Interconnect Sta
Contractor Kanahwa		Report # 41262	
Inspector John White		Date/Time 8/22/2022 10:12 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	00+00
State VA	Inspection Area Full	Station End	00+00
County Pittsylvania	Ground Wet	Temperature (°F)	74.00
Municipality Chatham	Weather Cloudy	Rain Gauge (in)	0.60
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Check Dam	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sediment Basin	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300113	Date/Time	8/22/2022 10:12 AM	Report #	41262
------------	-----------	------------------	--------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300113		Date/Time 8/22/2022 10:12 AM	Report #
Pictures			
			
GPS Location	O	GPS Location	O
Field Station#	00+00	Field Station#	00+00
Pic 1 Desc.	Observing RCE	Pic 2 Desc.	Observing temporary stabilization, rock check dam and ECD's
			
GPS Location	O	GPS Location	O
Field Station#	00+00	Field Station#	00+00
Pic 3 Desc.	Observing lay down yard	Pic 4 Desc.	Observing temporary stabilization, rock drain and CFS check
			
GPS Location	O	GPS Location	O
Field Station#	00+00	Field Station#	00+00
Pic 5 Desc.	Observing temporary stabilization and sediment basin	Pic 6 Desc.	Observing temporary stabilization, storm water pond and ECD's

AFE 124300113	Date/Time 8/22/2022 10:12 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300113	Date/Time 8/22/2022 10:12 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name Transco Interconnect Station		AFE 124300113	Spread Transco Interconnect Sta
Contractor Kanahwa		Report # 41453	
Inspector John White		Date/Time 8/26/2022 7:59 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	00+00
State VA	Inspection Area Full	Station End	00+00
County Pittsylvania	Ground Dry	Temperature (°F)	69.00
Municipality Chatham	Weather Cloudy	Rain Gauge (in)	0.60
			Rain Accumulation Time (days) 4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Check Dam	Acceptable			
Rock-lined Channel	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Sediment Basin	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300113	Date/Time	8/26/2022 7:59 AM	Report #	41453
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300113		Date/Time 8/26/2022 7:59 AM		Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 1 Desc.	Observing RCE	Pic 2 Desc.	Observing temporary stabilization, rock check dam and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 3 Desc.	Observing lay down yard	Pic 4 Desc.	Observing temporary stabilization, rock drain and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	00+00	Field Station#	00+00		
Pic 5 Desc.	Observing temporary stabilization and rock drain	Pic 6 Desc.	Observing temporary stabilization and sediment basin		

AFE 124300113	Date/Time 8/26/2022 7:59 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300113	Date/Time	8/26/2022 7:59 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	