



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41511	
Inspector Justin Burch		Date/Time 8/29/2022 12:12 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15142+66
State VA	Inspection Area Full	Station End	15260+00
County Pittsylvania	Ground Dry	Temperature (°F)	90.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.00
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			
Sump Pit	Acceptable			
Slope Drain Pipe	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Equipment Bridge	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/29/2022 12:12 PM	Report # 41511
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		





7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15142+66 to 15260+00 (Rock Creek Road to the Pigg River HDD Exit). No punch list items were submitted due to the inspected ECDs being in compliance at the time of inspection.
- The EI did not observe that the contractor has worked in the area since the last SWPPP inspection.
- Since the last SWPPP inspection the inspection area has not received any rainfall.
- The ROW ground condition is dry.
- At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15145+00 to 15153+00 and from 15173+00 to 15260+00.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/29/2022 12:12 PM	Report #
Pictures			
<p>43°NE (T) 36.948204°, -79.578313° ±65ft ▲ 889ft</p>  <p>15143+00 08-29-2022 09:11:06</p>		<p>167°S (T) 36.948106°, -79.578332° ±36ft ▲ 887ft</p>  <p>15144+00 08-29-2022 09:11:39</p>	
GPS Location	0	GPS Location	0
Field Station#	15143+00	Field Station#	15144+00
Pic 1 Desc.	Perimeter CFS in acceptable condition	Pic 2 Desc.	Permanent vegetative stabilization in acceptable condition
<p>239°SW (T) 36.945832°, -79.575629° ±13ft ▲ 823ft</p>  <p>15155+00 08-29-2022 09:24:48</p>		<p>87°E (T) 36.940357°, -79.562310° ±13ft ▲ 787ft</p>  <p>15200+00 08-29-2022 10:53:05</p>	
GPS Location	0	GPS Location	0
Field Station#	15155+00	Field Station#	15200+00
Pic 3 Desc.	Waterbar end treatment in acceptable condition	Pic 4 Desc.	Permanent vegetative stabilization in acceptable condition
<p>220°SW (T) 36.943923°, -79.571599° ±4169ft ▲ 722ft</p>  <p>15170+00 08-29-2022 09:36:58</p>		<p>242°SW (T) 36.943664°, -79.571302° ±13ft ▲ 742ft</p>  <p>15170+00 08-29-2022 09:37:48</p>	
GPS Location	0	GPS Location	0
Field Station#	15170+00	Field Station#	15170+00
Pic 5 Desc.	Waterbar in acceptable condition	Pic 6 Desc.	Sump pit and slope drain pipe in acceptable conditions

AFE 124300139		Date/Time 8/29/2022 12:12 PM		Report #	
Pictures					
					
GPS Location	0	GPS Location	0	GPS Location	0
Field Station#	15163+00	Field Station#	15162+00	Field Station#	15162+00
Pic 7 Desc.	P1 silt fence in acceptable condition		Pic 8 Desc.	Temporary vegetative stabilization in acceptable condition	
					
GPS Location	0	GPS Location	0	GPS Location	0
Field Station#	15174+00	Field Station#	15218+00	Field Station#	15218+00
Pic 9 Desc.	Permanent vegetative stabilization in acceptable condition		Pic 10 Desc.	Permanent vegetative stabilization in acceptable condition	
Insert image here			Insert image here		
GPS Location		GPS Location		GPS Location	
Field Station#		Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/29/2022 12:12 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41512	
Inspector Ben Farmer		Date/Time 8/29/2022 12:29 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13853+45	
State VA	Inspection Area Partial	Station End 13958+31	
County Franklin	Ground Damp	Temperature (°F) 68.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.10	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
3rd Party Damages	Communication	CFS has been damaged by 3rd part		
Equipment Bridge	Communication	Equipment bridge sideboard and fat		
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/29/2022 12:29 PM	Report # 41512
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in good		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 68F)
 Rain Gauge= 0.1"
 13853+45-13958+31

- Resource buffers remain well vegetated at all stream and wetland crossings.
- CWDs are in good condition and functioning as intended
- CFS has been damaged by 3rd party and needs to be replaced at 13950+50.
- Equipment bridge sideboard and fabric needs to be reattached at 13949+70.
- P1 is in good condition at all stream and wetland buffers
- Steep slope at 13889+00 remains stabilized.
- RCEs are in good condition at all road crossings.
- Topsoil berms remain stabilized.
- Sediment trap at 13897+00 is in good condition with no evidence of discharge.
- SSF is in good condition
- Waterbars/end treatments are in good condition.
- Slope drain is functioning at 13955+00.

*Issues identified in the field have been added to the punch list to be addressed by the contractor

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/29/2022 12:29 PM	Report #
Pictures			
GPS Location	See photo	GPS Location	See photo
Field Station#	13954+00	Field Station#	13950+50
Pic 1 Desc.	Slope drain outlet is in good condition and functioning	Pic 2 Desc.	CFS has been damaged by 3rd party and needs to be replaced
GPS Location	See photo	GPS Location	See photo
Field Station#	13949+70	Field Station#	13949+00
Pic 3 Desc.	Equipment bridge sideboard and fabric needs to be reattached	Pic 4 Desc.	SSF is in good condition
GPS Location	See photo	GPS Location	See photo
Field Station#	13942+00	Field Station#	13897+00
Pic 5 Desc.	CWDs are functioning as intended	Pic 6 Desc.	Sediment trap is functioning as intended

AFE 124300139		Date/Time 8/29/2022 12:29 PM	Report #
Pictures			
GPS Location	See photo	GPS Location	See photo
Field Station#	13897+00	Field Station#	13892+45
Pic 7 Desc.	Topsoil pile remains stabilized	Pic 8 Desc.	RCEs are in good condition at all road crossings.
GPS Location	See photo	GPS Location	See photo
Field Station#	13888+50	Field Station#	13875+00
Pic 9 Desc.	Slope drain is functioning as intended	Pic 10 Desc.	P1 is in good condition at all stream and wetland buffers
GPS Location	See photo	GPS Location	See photo
Field Station#	13863+00	Field Station#	13860+00
Pic 11 Desc.	Resource buffers remain well vegetated	Pic 12 Desc.	Waterbars are functioning as intended

A/E	124300139	Date/Time	8/29/2022 12:29 PM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41525	
Inspector Charles Head		Date/Time 8/29/2022 2:50 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14694+77	
State VA	Inspection Area Full	Station End 14802+19	
County Franklin	Ground Dry	Temperature (°F) 88.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/29/2022 2:50 PM	Report # 41525
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Observed at approximately 14739+25 third party timber harvesting activities occurring along the south side of the ROW, third party is also crossing the ROW to access timber tract and skid timber north of ROW to be loaded out. Will continue to monitor situation. LEI has been notified. Timber harvesting activities are ongoing.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/29/2022 2:50 PM	Report #
Pictures			
			
GPS Location	0	GPS Location	0
Field Station#	14799+00	Field Station#	14788+77
Pic 1 Desc.	Approximately 14799+00. Overview of ROW.	Pic 2 Desc.	Approximately 14788+77. Overview of stream crossing, equipment bridge and ECDs at stream S-H25.
			
GPS Location	0	GPS Location	0
Field Station#	14758+16	Field Station#	14743+00
Pic 3 Desc.	Approximately 14758+16. Overview of road crossing and RCEs.	Pic 4 Desc.	Approximately 14743+00. Overview of ROW.
			
GPS Location	0	GPS Location	0
Field Station#	14729+19	Field Station#	14708+00
Pic 5 Desc.	Approximately 14729+19. Overview of stream crossing, equipment bridge and ECDs at stream S-A20.	Pic 6 Desc.	Approximately 14708+00. Overview of ROW.

AFE 124300139	Date/Time 8/29/2022 2:50 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

		Insert image here
--	--	-------------------

GPS Location 0	GPS Location
-----------------------	---------------------

Field Station# 14739+25	Field Station#
--------------------------------	-----------------------

Pic 7 Desc. Approximately 14739+25. Third party timber harvesting activities as described above in comment section.	Pic 8 Desc.
--	--------------------

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
---------------------	---------------------

Field Station#	Field Station#
-----------------------	-----------------------

Pic 9 Desc.	Pic 10 Desc.
--------------------	---------------------

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
---------------------	---------------------

Field Station#	Field Station#
-----------------------	-----------------------

Pic 11 Desc.	Pic 12 Desc.
---------------------	---------------------

A/E	124300139	Date/Time	8/29/2022 2:50 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41465	
Inspector Ben Davenport		Date/Time 8/29/2022 11:48 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14311+57	
State VA	Inspection Area Partial	Station End 14454+22	
County Franklin	Ground Dry	Temperature (°F) 87.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
Rain Accumulation Time (days)			0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Acceptable			
Temporary Diversion Berm	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Waterbar	Acceptable			
Sump Pit	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/29/2022 11:48 AM	Report # 41465
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

-Available for work
 -Received instruction from Lead EI for daily tasks
 -Sunny with dry ground conditions during inspection
 -Performed SWPPP inspection on portion of MVP Spread I section
 -Covered territory between station# 14311+57 — 14454+22 (Farm View Rd to Webster Rd)
 -Walked ROW making note of condition of ROW and environmental controls
 -Verified the completion and accuracy of punch list items in covered area from previous inspections
 -Perimeter controls and ECD's were inspected; no issues identified
 -Inspection observed condition of equipment bridges and surrounding ECDs around stream crossings and resource buffers; no issues identified
 -Inspection observed condition of RCEs and culverts in section; no issues identified
 -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
 -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
 -Continue to monitor ROW for signs of erosion
 -No items added to environmental punch list

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/29/2022 11:48 AM	Report #
Pictures			
			
<p>37°2'33" N 79°48'33" W 287°W COURSE 266° GPS 54 Farm View Rd, Glade Hill, VA 24092, United States Accur +/-15.4 Ft ALT 1044 Ft</p>		<p>37°2'34" N 79°48'33" W 151°SE COURSE 101° GPS 54 Farm View Rd, Glade Hill, VA 24092, United States Accur +/-15.5 Ft ALT 1042 Ft</p>	
GPS Location	1	GPS Location	2
Field Station#	14312+00	Field Station#	14314+79
Pic 1 Desc.	Spoil pile stabilized and vegetated.	Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.
			
<p>37°2'12" N 79°48'2" W 143°SE COURSE -1° GPS Glade Hill, VA 24092, United States Accur +/-15.1 Ft ALT 1107 Ft</p>		<p>37°2'10" N 79°47'59" W 164°S COURSE 140° GPS Glade Hill, VA 24092, United States Accur +/-15.5 Ft ALT 1074 Ft</p>	
GPS Location	3	GPS Location	4
Field Station#	14349+00	Field Station#	14353+53
Pic 3 Desc.	Perimeter P1 silt fence in place and functional.	Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.
			
<p>37°2'12" N 79°48'2" W 116°SE COURSE 66° GPS Glade Hill, VA 24092, United States Accur +/-11.6 Ft ALT 1107 Ft</p>		<p>37°1'36" N 79°46'8" W 18°N COURSE 85° GPS 2753-2799 Webster Rd, Glade Hill, VA 24092, United States Accur +/-20.9 Ft ALT 0 Ft</p>	
GPS Location	5	GPS Location	6
Field Station#	14386+00	Field Station#	14452+00
Pic 5 Desc.	Sump pit and CFS end treatment performing intended functions.	Pic 6 Desc.	ROW stabilized and vegetated in temporary area.

AFE 124300139	Date/Time 8/29/2022 11:48 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/29/2022 11:48 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41501	
Inspector John White		Date/Time 8/29/2022 9:47 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15584+23
State VA	Inspection Area Full	Station End	15647+03
County Pittsylvania	Ground Dry	Temperature (°F)	82.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter Outlet	Acceptable			
Sediment Filter Log	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/29/2022 9:47 AM	Report #	41501
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.

PPL has identified an issue and will be added to the punchlist for correction.


Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/29/2022 9:47 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--


Pictures



GPS Location	O	GPS Location	O
Field Station#	15590+00	Field Station#	15595+00
Pic 1 Desc.	Observing temporary stabilization	Pic 2 Desc.	Observing temporary stabilization, CWD outlet and ECD's



GPS Location	O	GPS Location	O
Field Station#	15595+60	Field Station#	15600+12
Pic 3 Desc.	Observing temporary stabilization, buffer, equipment crossing and ECD's	Pic 4 Desc.	Observing temporary stabilization, buffer, equipment crossing and ECD's



GPS Location	O	GPS Location	O
Field Station#	15619+48	Field Station#	15636+45
Pic 5 Desc.	Observing road crossing and RCE's	Pic 6 Desc.	Observing temporary stabilization, water bar, buffer, equipment crossing and ECD's

AFE 124300139	Date/Time 8/29/2022 9:47 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/29/2022 9:47 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41558	
Inspector Justin Burch		Date/Time 8/30/2022 10:18 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15260+00
State VA	Inspection Area Full	Station End	15370+62
County Pittsylvania	Ground Dry	Temperature (°F)	89.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.00
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Permanent)	Communication			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Equipment Bridge	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/30/2022 10:18 AM	Report #	41558
------------	-----------	------------------	--------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15260+00 to 15370+62 (Pigg River HDD Exit to Snowberry Road). No punch list items were submitted due to the inspected ECDs being in compliance at the time of inspection.
- The EI did not observe that the contractor has worked in the area since the last SWPPP inspection.
- The inspection area has not received any rainfall since the last SWPPP inspection.
- The ROW ground condition is dry.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion and permanent vegetative stabilization was adequately established to inhibit erosion from 15355+00 to 15370+00.

PPL has identified issues and items will be added to the punchlist for repair.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/30/2022 10:18 AM		Report #			
Pictures							
☉ 63°NE (T) ● 36.909319°, -79.527232° ±22185ft ▲ 774ft 			☉ 221°SW (T) ● 36.922666°, -79.512488° ±16ft ▲ 760ft 				
GPS Location		0		GPS Location		0	
Field Station#		15366+00		Field Station#		15366+00	
Pic 1 Desc.		Waterbar in acceptable condition		Pic 2 Desc.		Waterbar end treatment and CFS in acceptable conditions	
☉ 341°N (T) ● 36.909687°, -79.528325° ±22185ft ▲ 750ft 			☉ 140°SE (T) ● 36.925203°, -79.517559° ±177ft ▲ 701ft 				
GPS Location		0		GPS Location		0	
Field Station#		15362+00		Field Station#		15346+00	
Pic 3 Desc.		Permanent vegetative stabilization in acceptable condition		Pic 4 Desc.		P1 silt fence and sensitive resource buffer in acceptable conditions	
☉ 225°SW (T) ● 36.926821°, -79.519605° ±16ft ▲ 769ft 			☉ 226°SW (T) ● 36.926690°, -79.519750° ±19ft ▲ 765ft 				
GPS Location		0		GPS Location		0	
Field Station#		15337+00		Field Station#		15337+00	
Pic 5 Desc.		Waterbar in acceptable condition		Pic 6 Desc.		Waterbar end treatment in acceptable condition	

AFE 124300139		Date/Time 8/30/2022 10:18 AM		Report #	
Pictures					
GPS Location		0		GPS Location	
Field Station#		15335+00		Field Station#	
Pic 7 Desc.		Temporary vegetative stabilization in acceptable condition		Pic 8 Desc.	
				CFS in acceptable condition	
GPS Location		0		GPS Location	
Field Station#		15312+00		Field Station#	
Pic 9 Desc.		Super silt fence in acceptable condition		Pic 10 Desc.	
				P1 silt fence and temporary vegetative stabilization in acceptable conditions	
<p style="text-align: center;">Insert image here</p>			<p style="text-align: center;">Insert image here</p>		
GPS Location				GPS Location	
Field Station#				Field Station#	
Pic 11 Desc.				Pic 12 Desc.	

AFE 124300139	Date/Time 8/30/2022 10:18 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41572	
Inspector Ben Farmer		Date/Time 8/30/2022 12:54 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13958+31	
State VA	Inspection Area Partial	Station End 14062+17	
County Franklin	Ground Dry	Temperature (°F) 70.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/30/2022 12:54 PM	Report # 41572
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 70F)
 Rain Gauge= 0.0"
 13958+31-14062+17

- This section remains stabilized.
- CWD/CWD inlets are in good condition and functioning as intended
- MVP-ATWS-1446 remains stabilized with controls in place.
- P1 is in good condition at all stream and wetland buffers.
- No evidence of 3rd party pond discharging onto ROW at 14000+00
- Resource buffers remain well vegetated.
- Slope on the CIS of Highway 220 remains stabilized with controls in place.
- Waterbars/end treatments are functioning as intended.
- CFS is in good condition throughout this section
- Equipment bridge fabric needs to be reattached at 14050+28.
- Slope drain is functioning as intended at 14058+00
- Rock check dams are functioning at 14060+00
- Vegetation continues to fill in throughout this section

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/30/2022 12:54 PM		Report #	
Pictures					
GPS Location		See photo		GPS Location	
Field Station#		13960+00		Field Station#	
Pic 1 Desc.		Slope drain is in good condition and functioning		Pic 2 Desc.	
				Vegetation continues to fill in throughout this section	
GPS Location		See photo		GPS Location	
Field Station#		13997+50		Field Station#	
Pic 3 Desc.		P1 is in good condition at all stream and wetland buffers		Pic 4 Desc.	
				Equipment bridge ECDs are functioning as intended	
GPS Location		See photo		GPS Location	
Field Station#		14000+00		Field Station#	
Pic 5 Desc.		No evidence of 3rd party pond discharging onto ROW.		Pic 6 Desc.	
				RCEs are in good condition at all road crossings.	

AFE	124300139	Date/Time	8/30/2022 12:54 PM	Report #	
------------	-----------	------------------	--------------------	-----------------	--


Pictures



GPS Location	See photo	GPS Location	See photo
Field Station#	14027+00	Field Station#	14033+00
Pic 7 Desc.	CFS is in good condition throughout this section.	Pic 8 Desc.	Waterbars are functioning as intended




GPS Location	See photo	GPS Location	See photo
Field Station#	14033+00	Field Station#	14035+00
Pic 9 Desc.	End treatments are functioning as intended	Pic 10 Desc.	Resource buffers remain well vegetated



GPS Location	See photo	GPS Location	See photo
Field Station#	14050+00	Field Station#	14057+00
Pic 11 Desc.	Slope remains stabilized with controls in place	Pic 12 Desc.	Slope drain is functioning as intended

AFE 124300139	Date/Time 8/30/2022 12:54 PM	Report #
----------------------	-------------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	14060+00	Field Station#	
-----------------------	----------	-----------------------	--


Pic 13 Desc.	Rock check dams are functioning as intended.	Pic 14 Desc.	
---------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 15 Desc.		Pic 16 Desc.	
---------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 17 Desc.		Pic 18 Desc.	
---------------------	--	---------------------	--



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41557	
Inspector Charles Head		Date/Time 8/30/2022 10:07 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14802+19	
State VA	Inspection Area Full	Station End 14928+52	
County Franklin	Ground Damp	Temperature (°F) 80.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/30/2022 10:07 AM	Report # 41557
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/30/2022 10:07 AM	Report #
Pictures			
GPS Location	0	GPS Location	0
Field Station#	14916+00	Field Station#	14895+00
Pic 1 Desc.	Approximately 14916+00. Overview of stream crossing, equipment bridge and ECDs at stream S-G16.	Pic 2 Desc.	Approximately 14895+00. Overview of ROW.
GPS Location	0	GPS Location	0
Field Station#	14870+43	Field Station#	14845+68
Pic 3 Desc.	Approximately 14870+43. Overview of stream crossing, equipment bridge and ECDs at stream S-SS8.	Pic 4 Desc.	Approximately 14845+68. Overview of road crossing and RCEs.
GPS Location	0	GPS Location	0
Field Station#	14832+80	Field Station#	14812+00
Pic 5 Desc.	Approximately 14832+80. Overview of stream crossing, equipment bridge and ECDs at stream S-80.	Pic 6 Desc.	Approximately 14812+00. Overview of ROW. Permanent vegetation.

AFE 124300139	Date/Time 8/30/2022 10:07 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/30/2022 10:07 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41513	
Inspector Ben Davenport		Date/Time 8/30/2022 10:54 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14454+22	
State VA	Inspection Area Partial	Station End 14546+75	
County Franklin	Ground Wet	Temperature (°F) 86.00	
Municipality N/A	Weather Thunderstorms	Rain Gauge (in) 0.00	
Rain Accumulation Time (days)			0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Compost Filter Sock	Acceptable			
Sump Pit	Acceptable			
Waterbar End Treatment	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/30/2022 10:54 AM	Report # 41513
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.


Comments (Reference above questions as appropriate.)

- Available for work
- Received instruction from Lead EI for daily tasks
- Sunny followed by afternoon thunderstorms with dry and then wet ground conditions during inspection
- Performed SWPPP inspection on portion of MVP Spread I section
- Covered territory between station# 14454+22 — 14546+75 (Webster Rd to Tobacco Rd)
- Walked ROW making note of condition of ROW and environmental controls
- Verified the completion and accuracy of punch list items in covered area from previous inspections
- Perimeter controls and ECDs were inspected; no issues identified
- Inspection observed condition of equipment bridges and surrounding ECDs around stream crossings and resource buffers; no issues identified
- Inspection observed condition of RCEs and culverts in section; no issues identified
- Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
- Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
- Continue to monitor ROW for signs of erosion
- No items added to environmental punch list in section

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/30/2022 10:54 AM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures



GPS Location	1	GPS Location	2
Field Station#	14454+22	Field Station#	14461+00
Pic 1 Desc.	RCE in good condition; portajon properly contained in secondary containment at road crossing.	Pic 2 Desc.	Perimeter SSF and CFS in good condition.



GPS Location	3	GPS Location	4
Field Station#	14479+00	Field Station#	14532+50
Pic 3 Desc.	Sump pit and CFS end treatment performing intended functions.	Pic 4 Desc.	Plunge pool performing intended function.



GPS Location	5	GPS Location	6
Field Station#	14542+00	Field Station#	14546+33
Pic 5 Desc.	ROW stabilized and vegetated in temporary area.	Pic 6 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.

AFE 124300139	Date/Time 8/30/2022 10:54 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/30/2022 10:54 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41551	
Inspector John White		Date/Time 8/30/2022 7:36 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15647+03
State VA	Inspection Area Full	Station End	15772+27
County Pittsylvania	Ground Dry	Temperature (°F)	70.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Filter Outlet	Acceptable			
Sediment Filter Log	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/30/2022 7:36 AM	Report #	41551
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)


Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/30/2022 7:36 AM	Report #	
Pictures					
 		 			
GPS Location O		GPS Location O			
Field Station# 15652+00		Field Station# 15658+43			
Pic 1 Desc. Observing temporary stabilization.		Pic 2 Desc. Observing temporary stabilization, buffer, equipment crossing and ECD's			
 		 			
GPS Location O		GPS Location O			
Field Station# 15665+50		Field Station# 15677+00			
Pic 3 Desc. Observing temporary stabilization, buffer, equipment crossing and ECD's		Pic 4 Desc. Observing temporary stabilization, CWD outlet and ECD's			
 		 			
GPS Location O		GPS Location O			
Field Station# 15680+00		Field Station# 15695+00			
Pic 5 Desc. Observing temporary stabilization and water bars		Pic 6 Desc. Observing temporary stabilization, water bars and CFS checks			

AFE 124300139	Date/Time 8/30/2022 7:36 AM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	15740+00	Field Station#	15713+52
-----------------------	----------	-----------------------	----------


Pic 7 Desc.	Observing temporary stabilization, sump and end treatment	Pic 8 Desc.	Observing temporary stabilization, water bar, buffer, equipment crossing and ECD's
--------------------	---	--------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 9 Desc.		Pic 10 Desc.	
--------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 11 Desc.		Pic 12 Desc.	
---------------------	--	---------------------	--

AFE 124300139	Date/Time 8/30/2022 7:36 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41620	
Inspector Justin Burch		Date/Time 8/31/2022 10:44 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15370+62
State VA	Inspection Area Full	Station End	15480+67
County Pittsylvania	Ground Wet	Temperature (°F)	84.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.40
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar End Treatment	Acceptable			
Compost Filter Sock	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Plunge Pool	Acceptable			
Equipment Bridge	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/31/2022 10:44 AM	Report # 41620
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable			


7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15370+62 to 15480+67 (Snowberry Road to Toshes Road). No punch list items were submitted due to the inspected ECDs being in compliance at the time of inspection.
- The EI observed that the contractor has worked in the area since the last SWPPP inspection and addressed items on the punch list.
- The EI observed that stream water at S-G4 (15426+54) was running clear. This stream has been impacted in the past by upstream activities not related to MVP.
- The EI observed that the solar farm perimeter ECDs on the CIS of Toshes Road appeared to be in acceptable condition.
- Since the last SWPPP inspection the inspection area has received one rainfall with a total of 0.40" at Snowberry Road.
- The ROW ground condition is wet.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion and permanent vegetative stabilization was adequately established to inhibit erosion from 15438+00 to 15445+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/31/2022 10:44 AM		Report #			
Pictures							
							
GPS Location		0		GPS Location		0	
Field Station#		15376+00		Field Station#		15381+00	
Pic 1 Desc.		Waterbar end treatment in acceptable condition		Pic 2 Desc.		CFS in acceptable condition	
							
GPS Location		0		GPS Location		0	
Field Station#		15386+00		Field Station#		15394+00	
Pic 3 Desc.		CFS and sensitive resource buffer in acceptable conditions		Pic 4 Desc.		P1 silt fence in acceptable condition	
							
GPS Location		0		GPS Location		0	
Field Station#		15404+00		Field Station#		15414+13	
Pic 5 Desc.		Plunge pool in acceptable condition		Pic 6 Desc.		Equipment bridge in acceptable condition	

AFE 124300139		Date/Time 8/31/2022 10:44 AM		Report #	
Pictures					
108°E (T) 36.916595°, -79.493927° ±173ft ▲ 827ft  <p style="text-align: right;">15423+00 08-31-2022, 09:10:53</p>				357°N (T) 36.916686°, -79.492690° ±131ft ▲ 764ft  <p style="text-align: right;">15426+54 08-31-2022, 09:21:57</p>	
GPS Location 0		GPS Location 0			
Field Station# 15423+00		Field Station# 15426+54			
Pic 7 Desc. Clean water diversion berm in acceptable condition		Pic 8 Desc. Stream S-G4 running without elevated turbidity			
21°N (T) 36.915446°, -79.489686° ±29ft ▲ 804ft  <p style="text-align: right;">15435+00 08-31-2022, 09:34:37</p>				327°NW (T) 36.929725°, -79.526295° ±16420ft ▲ 795ft  <p style="text-align: right;">15435+00 08-31-2022, 09:34:02</p>	
GPS Location 0		GPS Location 0			
Field Station# 15435+00		Field Station# 15435+00			
Pic 9 Desc. Waterbar in acceptable condition		Pic 10 Desc. Waterbar end treatment in acceptable condition			
346°N (T) 36.914572°, -79.488369° ±26ft ▲ 842ft  <p style="text-align: right;">15442+00 08-31-2022, 09:38:31</p>				254°W (T) 36.911295°, -79.480119° ±1532ft ▲ 894ft  <p style="text-align: right;">15472+00 08-31-2022, 10:19:05</p>	
GPS Location 0		GPS Location 0			
Field Station# 15442+00		Field Station# 15472+00			
Pic 11 Desc. Permanent vegetative stabilization in acceptable condition		Pic 12 Desc. Solar farm perimeter ECDs appear to be in acceptable conditions			

Pictures			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41629	
Inspector Ben Farmer		Date/Time 8/31/2022 12:36 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14062+17	
State VA	Inspection Area Partial	Station End 14171+36	
County Franklin	Ground Damp	Temperature (°F) 70.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 1.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/31/2022 12:36 PM	Report # 41629
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 70F)
 Rain Gauge= 1.0"
 14062+17-14171+36

- RCE are in good condition at all road crossings.
- Equipment bridge ECDs are in good condition and functioning.
- CWDs are functioning as intended.
- Topsoil berm remains stabilized
- MVP-FR-309.05 is in good condition with controls in place.
- P1 is in good condition throughout this section.
- Resource buffers remain well vegetated.
- CFS is in good condition throughout this section
- Waterbars/end treatments are in good condition and functioning
- Slope drain is functioning as intended at 14157+00.
- SSF is in good condition.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.


AFE 124300139		Date/Time 8/31/2022 12:36 PM	Report #
Pictures			
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14062+17	Field Station#	14066+77
Pic 1 Desc.	RCEs are in good condition at all road crossings	Pic 2 Desc.	Equipment bridge ECDs are functioning as intended
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14070+00	Field Station#	14085+00
Pic 3 Desc.	CWDs are functioning as intended	Pic 4 Desc.	Topsoil berms remain stabilized
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14105+20	Field Station#	14110+00
Pic 5 Desc.	Resource buffers remain well vegetated	Pic 6 Desc.	Waterbars are in good condition

AFE	124300139	Date/Time	8/31/2022 12:36 PM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures



GPS Location	See photo	GPS Location	See photo
Field Station#	14110+00	Field Station#	14120+00
Pic 7 Desc.	End treatments are functioning as intended	Pic 8 Desc.	CFS is in good condition throughout this section



GPS Location	See photo	GPS Location	See photo
Field Station#	14132+00	Field Station#	14141+00
Pic 9 Desc.	CWD is functioning as intended	Pic 10 Desc.	P1 is in good condition at all stream and wetland buffers



GPS Location	See photo	GPS Location	
Field Station#	14156+00	Field Station#	
Pic 11 Desc.	Slope drain is in good condition and functioning	Pic 12 Desc.	

A/E	124300139	Date/Time	8/31/2022 12:36 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Pic 13 Desc.		Pic 14 Desc.		Pic 14 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Pic 15 Desc.		Pic 16 Desc.		Pic 16 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Pic 17 Desc.		Pic 18 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41643	
Inspector Frank Craycroft		Date/Time 8/31/2022 3:27 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13670+00	
State VA	Inspection Area Full	Station End 13748+30	
County Franklin	Ground Dry	Temperature (°F) 85.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Rock Construction Entrance	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

A/E	124300139	Date/Time	8/31/2022 3:27 PM	Report #	41643
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted SWPPP inspection of ROW from Spread H/I break to Green Level Rd. Vegetation was generally excellent to full and no signs of erosion or washing were observed. Equipment bridges in area were clean and free of sediment and mud deposits. All resource buffers in area were intact and showed no signs of erosion or sedimentation from ROW. All perimeter ECDs observed were functional and in good condition. Waterbars and sumps in area were functioning properly and showed no signs of scouring in channel or sediment accumulation.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/31/2022 3:27 PM		Report #	
Pictures					
					
GPS Location 0		GPS Location 0			
Field Station# 13678+71		Field Station# 13672+00			
Pic 1 Desc. S-E29 Channel and banks		Pic 2 Desc. Perimeter CFS			
					
GPS Location 0		GPS Location 0			
Field Station# 13688+00		Field Station# 13692+75			
Pic 3 Desc. Perimeter CFS		Pic 4 Desc. GAS S-E28 Banks			
					
GPS Location 0		GPS Location 0			
Field Station# 13697+00		Field Station# 13699+00			
Pic 5 Desc. GAS W-E7 Buffer zone and silt fence		Pic 6 Desc. Sideslope vegetation			


AFE 124300139		Date/Time 8/31/2022 3:27 PM		Report #	
Pictures					
				<p>ert image here</p>	
GPS Location 0		GPS Location 0			
Field Station# 13705+50		Field Station# 13706+50			
Pic 7 Desc. GAS S-E28 Equipment bridge and banks		Pic 8 Desc. GAS S-E28 Buffer zone CFS Triple stack			
				<p>ert image here</p>	
GPS Location 0		GPS Location 0			
Field Station# 13710+00		Field Station# 13720+00			
Pic 9 Desc. Perimeter CFS		Pic 10 Desc. Vegetation			
				<p>ert image here</p>	
GPS Location 0		GPS Location 0			
Field Station# 13728+20		Field Station# 13738+00			
Pic 11 Desc. S-EF4 Channel and banks		Pic 12 Desc. Perimeter CFS			

AFE 124300139	Date/Time 8/31/2022 3:27 PM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	0	GPS Location	0
Field Station#	13747+50	Field Station#	13730+00
Pic 13 Desc.	CIS Green Level Rd Travel lane and ECDs	Pic 14 Desc.	Sump and J-hook



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41621	
Inspector Charles Head		Date/Time 8/31/2022 11:13 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14928+52	
State VA	Inspection Area Full	Station End 15063+85	
County Franklin/Pittsylvania	Ground Damp	Temperature (°F) 77.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.25	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/31/2022 11:13 AM	Report # 41621
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.

PPL crews identified issues. Items will be added to punchlist for repairs.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/31/2022 11:13 AM	Report #
Pictures			
GPS Location	0	GPS Location	0
Field Station#	15045+00	Field Station#	15054+00
Pic 1 Desc.	Approximately 15045+00. Overview of stream crossing, equipment bridge and ECDs at stream S-D2.	Pic 2 Desc.	Approximately 15054+00. Overview of ROW.
GPS Location	0	GPS Location	0
Field Station#	15026+00	Field Station#	15000+00
Pic 3 Desc.	Approximately 15026+00. Overview of stream crossing, equipment bridge and ECDs at stream S-D3.	Pic 4 Desc.	Approximately 15000+00. Overview of ROW.
GPS Location	0	GPS Location	0
Field Station#	14981+55	Field Station#	14993+50
Pic 5 Desc.	Approximately 14981+55. Overview of road crossing and RCEs.	Pic 6 Desc.	Approximately 14993+50. Overview of ROW. Permanent vegetation.

AFE 124300139	Date/Time 8/31/2022 11:13 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/31/2022 11:13 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41577	
Inspector Ben Davenport		Date/Time 8/31/2022 10:10 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14546+75	
State VA	Inspection Area Partial	Station End 14649+67	
County Franklin	Ground Muddy	Temperature (°F) 82.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 1.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication	Routine maintenance; landowner da		
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Sediment Filter Log	Acceptable			
Plunge Pool	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Temporary Diversion Berm	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/31/2022 10:10 AM	Report # 41577
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

-Available for work
 -Received instruction from Lead EI for daily tasks
 -Checked rain gauges in covered area
 -Sunny with muddy ground conditions during inspection
 -Performed SWPPP inspection on portion of MVP Spread I section
 -Covered territory between station# 14546+75 — 14649+67 (Tobacco Rd to Hwy 40 crossing)
 -Walked ROW making note of condition of ROW and environmental controls
 -Verified the completion and accuracy of punch list items in covered area from previous inspections
 -Perimeter controls and ECDs were inspected; no issues identified
 -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; 1 issue identified
 -Inspection observed condition of RCEs and culverts in section; no issues identified
 -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
 -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
 -Continue to monitor ROW for signs of erosion
 -1 item added to environmental punch list

-Rain Gauge Totals:
 +Farm View: 0.70 inches recorded
 +Timber Ridge: 1.00 inches recorded

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/31/2022 10:10 AM	Report #
Pictures			
			
<small>37°07' N 79°44'57" W 171°S COURSE 357° GPS 08.31.2022 10:17:37 Sorry no results found Accur +/-11.6 Ft ALT 903 Ft</small>		<small>37°0'10" N 79°45'2" W 182°S COURSE 196° GPS 08.31.2022 10:14:13 Sorry no results found Accur +/-15.4 Ft ALT 910 Ft</small>	
GPS Location	1	GPS Location	2
Field Station#	14565+00	Field Station#	14558+00
Pic 1 Desc.	Routine maintenance. Repair damaged CFS in natural drainage area from landowner or animal damage.	Pic 2 Desc.	CFS check dams performing intended function.
			
<small>37°04' N 79°44'52" W 74°E COURSE -1° GPS 08.31.2022 10:19:52 Sorry no results found Accur +/-15.1 Ft ALT 882 Ft</small>		<small>36°59'49" N 79°44'16" W 193°S COURSE -1° GPS 08.31.2022 10:34:03 Sorry no results found Accur +/-15.1 Ft ALT 910 Ft</small>	
GPS Location	3	GPS Location	4
Field Station#	14568+10	Field Station#	14605+00
Pic 3 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	Pic 4 Desc.	Plunge pool performing intended function.
			
<small>36°59'44" N 79°44'5" W 334°NW COURSE -1° GPS 08.31.2022 10:39:04 Union Hall, VA 24176, United States Accur +/-155.4 Ft ALT 931 Ft</small>		<small>36°59'44" N 79°44'6" W 150°SE COURSE 79° GPS 08.31.2022 10:42:16 Union Hall, VA 24176, United States Accur +/-173.4 Ft ALT 855 Ft</small>	
GPS Location	5	GPS Location	6
Field Station#	14611+17	Field Station#	14614+50
Pic 5 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	Pic 6 Desc.	ROW stabilized and vegetated in temporary area.

AFE 124300139	Date/Time 8/31/2022 10:10 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300139	Date/Time	8/31/2022 10:10 AM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41606	
Inspector John White		Date/Time 8/31/2022 7:45 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15772+27
State VA	Inspection Area Full	Station End	15947+64
County Pittsylvania	Ground Damp	Temperature (°F)	70.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.10
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Communication	Contractor performed maintenance		8/31/2022
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter Outlet	Acceptable			
Sediment Filter Log	Acceptable			
Plunge Pool	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/31/2022 7:45 AM	Report #	41606
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There were issues identified and repaired by the Contractor. Checked rain gauges, Anderson Mill #2=.3", Mill Creek =.10", Transco =.10". Other than that there were no issues to report at the time of Inspection.

PPL crews identified issues. Items will be added to punchlist for repairs.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/31/2022 7:45 AM	Report #	
Pictures					
 		 			
GPS Location	O	GPS Location	O		
Field Station#	15776+00	Field Station#	15781+22		
Pic 1 Desc.	Observing temporary stabilization and water bars		Pic 2 Desc.	Observing temporary stabilization, buffer, equipment crossing and ECD's	
 		 			
GPS Location	O	GPS Location	O		
Field Station#	15784+50	Field Station#	15784+50		
Pic 3 Desc.	Observing safety fence that required maintenance		Pic 4 Desc.	Observing safety fence that the Contractor repaired	
 		 			
GPS Location	O	GPS Location	O		
Field Station#	15794+77	Field Station#	15810+00		
Pic 5 Desc.	Observing temporary stabilization, buffer, equipment crossing and ECD's		Pic 6 Desc.	Observing geo tech that required maintenance	

AFE 124300139	Date/Time 8/31/2022 7:45 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

--	--

GPS Location O	GPS Location O
Field Station# 15810+00	Field Station# 15825+00
Pic 7 Desc. Observing geo tech that was repaired by the Contractor	Pic 8 Desc. Observing temporary stabilization,plunge pool and ECD's

--	--

GPS Location O	GPS Location O
Field Station# 15826+77	Field Station# 15866+00
Pic 9 Desc. Observing road crossing and RCE's	Pic 10 Desc. Observing temporary stabilization,CWD outlet and ECD's

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 11 Desc.	Pic 12 Desc.

A/E	124300139	Date/Time	8/31/2022 7:45 AM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 13 Desc.	
Pic 13 Desc.		Pic 14 Desc.		Pic 14 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 15 Desc.	
Pic 15 Desc.		Pic 16 Desc.		Pic 16 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Pic 17 Desc.		Pic 18 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-602 Pipeline Spread I		AFE 124300139	Spread H-602 Pipeline Spread I
Contractor Precision		Report # 41674	
Inspector John White		Date/Time 9/1/2022 9:21 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	00+00
State VA	Inspection Area Full	Station End	19+25
County Pittsylvania	Ground Dry	Temperature (°F)	70.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.10
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	9/1/2022 9:21 AM	Report #	41674
------------	-----------	------------------	------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139	Date/Time 9/1/2022 9:21 AM	Report #
----------------------	-----------------------------------	-----------------


Pictures



GPS Location	<input type="radio"/>	GPS Location	<input type="radio"/>
---------------------	-----------------------	---------------------	-----------------------

Field Station#	6+00	Field Station#	12+65
-----------------------	------	-----------------------	-------

Pic 1 Desc.	Observing temporary stabilization	Pic 2 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's
--------------------	-----------------------------------	--------------------	--



GPS Location	<input type="radio"/>	GPS Location	<input type="radio"/>
---------------------	-----------------------	---------------------	-----------------------

Field Station#	12+00	Field Station#	15+00
-----------------------	-------	-----------------------	-------

Pic 3 Desc.	Observing temporary stabilization, sump and end treatment	Pic 4 Desc.	Observing temporary stabilization
--------------------	---	--------------------	-----------------------------------

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 5 Desc.		Pic 6 Desc.	
--------------------	--	--------------------	--

AFE 124300139	Date/Time 9/1/2022 9:21 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 9/1/2022 9:21 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-603 Pipeline Spread I		AFE 124300139	Spread H-603 Pipeline Spread I
Contractor Precision		Report # 41673	
Inspector John White		Date/Time 9/1/2022 9:15 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	00+00
State VA	Inspection Area Full	Station End	24+53
County Pittsylvania	Ground Dry	Temperature (°F)	70.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.10
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	9/1/2022 9:15 AM	Report #	41673
------------	-----------	------------------	------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	9/1/2022 9:15 AM	Report #	
Pictures					
GPS Location	O		GPS Location	O	
Field Station#	14+00		Field Station#	22+00	
Pic 1 Desc.	Observing temporary stabilization and RCE		Pic 2 Desc.	Observing temporary stabilization and buffer	
GPS Location	O		GPS Location	O	
Field Station#	12+00		Field Station#	6+00	
Pic 3 Desc.	Observing temporary stabilization, sump, end treatment and ECD's		Pic 4 Desc.	Observing temporary stabilization and water bar	
Insert image here			Insert image here		
GPS Location			GPS Location		
Field Station#			Field Station#		
Pic 5 Desc.			Pic 6 Desc.		

AFE 124300139	Date/Time 9/1/2022 9:15 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE	124300139	Date/Time	9/1/2022 9:15 AM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41680	
Inspector Justin Burch		Date/Time 9/1/2022 10:43 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15480+67	
State VA	Inspection Area Full	Station End 15584+23	
County Pittsylvania	Ground Damp	Temperature (°F) 83.00	
Municipality Chatham	Weather Sunny	Rain Gauge (in) 0.40	
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Compost Filter Sock	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Equipment Bridge	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 9/1/2022 10:43 AM	Report # 41680
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15480+67 to 15584+23 (Toshes Road to Anderson Mill Road 1). No punch list items were submitted due to the inspected ECDs being in compliance at the time of inspection.
- The EI observed that the contractor has worked in the area since the last SWPPP inspection and addressed punch list items.
- The EI observed that streams S-MM8 at 15521+00 and S-CC5 at 15542+11 were running without elevated turbidity. These streams have been impacted in the past by upstream activities not related to MVP.
- The EI observed that stump and rock clearing has been performed recently from approximate 15548+00 to 15560+00 on the south side of the ROW on the CIS of Anderson Mill Road 1. No vegetated stabilization or perimeter ECDs were observed by the EI and also no impacts were observed to streams S-CC5, S-CC9 or S-CC10.
- The EI observed that the solar farm ECDs adjacent to the ROW on GAS of Climax Road appeared to be in acceptable condition and that their super silt fence on the CIS of climax Road was down in multiple locations where the solar farm fencing crew has recently worked. The EI also observed that a solar farm grading operation was in progress from approximately 15498+00 to 15506+00 on the north side of the ROW on the GAS of Climax Road.
- Since the last SWPPP inspection the inspection area has received one rain event with a total of 0.40" at Snowberry Road.
- The ROW ground condition is damp.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion and permanent vegetative stabilization was adequately established to inhibit erosion from 15482+00 to 15495+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 9/1/2022 10:43 AM	Report #
Pictures			
			
GPS Location	0	GPS Location	0
Field Station#	15496+00	Field Station#	15510+00
Pic 1 Desc.	Rock construction entrance in acceptable condition	Pic 2 Desc.	Temporary vegetative stabilization in acceptable condition
			
GPS Location	0	GPS Location	0
Field Station#	15520+00	Field Station#	15521+50
Pic 3 Desc.	P1 silt fence and sensitive resource buffer in acceptable conditions	Pic 4 Desc.	Perimeter CFS and sensitive resource buffer in acceptable conditions
			
GPS Location	0	GPS Location	0
Field Station#	15526+00	Field Station#	15526+00
Pic 5 Desc.	Waterbar in acceptable condition	Pic 6 Desc.	Waterbar end treatment in acceptable condition

AFE 124300139		Date/Time 9/1/2022 10:43 AM		Report #	
Pictures					
					
GPS Location 0		GPS Location 0			
Field Station# 15552+00		Field Station# 15556+83			
Pic 7 Desc. Clean water diversion pipe in acceptable condition		Pic 8 Desc. Equipment bridge in acceptable condition			
					
GPS Location 0		GPS Location 0			
Field Station# 15554+00		Field Station# 15505+00			
Pic 9 Desc. Land that was recently cleared of stumps and rocks with no stabilization		Pic 10 Desc. Solar farm grading operation			
					
GPS Location 0		GPS Location 0			
Field Station# 15521+00		Field Station# 15582+00			
Pic 11 Desc. Stream S-MM8 is running clear		Pic 12 Desc. Temporary vegetative stabilization in acceptable condition			

A/E	124300139	Date/Time	9/1/2022 10:43 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41688	
Inspector Ben Farmer		Date/Time 9/1/2022 12:32 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14171+36	
State VA	Inspection Area Partial	Station End 14311+57	
County Franklin	Ground Dry	Temperature (°F) 60.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Communication	CFS has been damaged by livestock		
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar End Treatment	Communication	End treatment CFS has been damaged		

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 9/1/2022 12:32 PM	Report # 41688
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in good		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.







Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 60F)
 Rain Gauge= 0.0"
 14171+36-14311+57

- RCEs are in good condition at all road crossings.
- CWDs are functioning as intended.
- Equipment bridge ECDs are in good condition and functioning.
- Waterbars are in good condition throughout this section.
- End treatment CFS has been damaged and needs to be replaced at 14205+00-14207+00.
- P1 is in good condition at all stream and wetland buffers.
- SSF is in good condition.
- Slope drain is in good condition and functioning at 14232+00
- Perimeter CFS has been damaged by livestock and needs to be repaired at 14260+00/14263+00.
- Resource buffers remain well vegetated.
- Topsoil berms remain stabilized

*Issues identified in the field have been added to the punch list to be addressed by the contractor.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 9/1/2022 12:32 PM	Report #
Pictures			
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14171+36	Field Station#	14180+00
Pic 1 Desc.	RCEs are in good condition at all road crossings	Pic 2 Desc.	CWDs are functioning as intended
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14182+00	Field Station#	14200+00
Pic 3 Desc.	SSF is in good condition	Pic 4 Desc.	CWD is functioning as intended
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14205+00	Field Station#	14208+69
Pic 5 Desc.	CFS end treatments have been damaged by livestock and needs to be replaced 14205+00-14207+00	Pic 6 Desc.	Equipment bridge ECDs are in good condition and functioning

AFE 124300139	Date/Time 9/1/2022 12:32 PM	Report #
----------------------	------------------------------------	-----------------

Pictures






GPS Location	See photo	GPS Location	See photo
Field Station#	14223+41	Field Station#	14232+00
Pic 7 Desc.	MVP-FR-311 is in good condition with controls in place.	Pic 8 Desc.	Slope drain is in good condition and functioning



GPS Location	See photo	GPS Location	See photo
Field Station#	14252+00	Field Station#	14260+00
Pic 9 Desc.	Slope remains stabilized with controls in place	Pic 10 Desc.	Perimeter CFS has been damaged by livestock and needs to be replaced



GPS Location	See photo	GPS Location	See photo
Field Station#	14263+00	Field Station#	14277+00
Pic 11 Desc.	Perimeter CFS has been damaged by livestock and needs to be replaced	Pic 12 Desc.	Waterbars are in good condition

AFE	124300139	Date/Time	9/1/2022 12:32 PM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14278+93	Field Station#	14294+00		
Pic 13 Desc.	Resource buffers remain well vegetated	Pic 14 Desc.	P1 is in good condition at all stream and wetland buffers		
		Insert image here			
GPS Location	See photo	GPS Location			
Field Station#	14300+00	Field Station#			
Pic 15 Desc.	Topsoil berms remain stabilized	Pic 16 Desc.			
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 17 Desc.		Pic 18 Desc.			



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41677	
Inspector Glenn Mike Renfro		Date/Time 9/1/2022 10:13 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	0000+00
State VA	Inspection Area Full	Station End	0000+00
County Franklin	Ground Dry	Temperature (°F)	71.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	1.00
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Other - Explain in Comments	Acceptable	Inlet protection for catch basins		
Secondary Containment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | N/A |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | N/A |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 9/1/2022 10:13 AM	Report # 41677
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)


- Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va.
- The locations have received 1" of rainfall since the last inspection and site conditions were dry.
- All perimeter ECD's were inspected and no issues were observed.
- The inlet protection for the catch basins at LY-046 were found to be in acceptable condition.
- All secondary containment structures were inspected and no issues were found during the inspections.
- The RCE at LY-045 was in good condition.
- All equipment at both locations were inspected and no leaks were observed the during inspection.
- The General Construction permits and contact information are posted at the entrance of LY-046 as required.
- There were no issues identified during todays inspections.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 9/1/2022 10:13 AM		Report #			
Pictures							
<p style="text-align: center;">West Elevation</p> <p style="text-align: center;">📍 111°E (T) ● 36°58'12"N, 79°52'5"W ±13ft ▲ 1203ft</p>  <p style="text-align: right; font-size: small;">01 Sep 2022, 08:00:56</p>			<p style="text-align: center;">West Elevation</p> <p style="text-align: center;">📍 111°E (T) ● 36°58'12"N, 79°52'7"W ±13ft ▲ 1200ft</p>  <p style="text-align: right; font-size: small;">01 Sep 2022, 07:59:57</p>				
GPS Location		See picture		GPS Location		See picture	
Field Station#		0000+00		Field Station#		0000+00	
Pic 1 Desc.		RCE at LY-045 in good condition.		Pic 2 Desc.		Secondary containment structure on south end of tent at LY-045 in good condition.	
<p style="text-align: center;">South East Elevation</p> <p style="text-align: center;">📍 328°NW (T) ● 36°58'13"N, 79°52'9"W ±13ft ▲ 1196ft</p>  <p style="text-align: right; font-size: small;">01 Sep 2022, 07:58:41</p>			<p style="text-align: center;">North East Elevation</p> <p style="text-align: center;">📍 209°SW (T) ● 36°58'15"N, 79°52'9"W ±13ft ▲ 1199ft</p>  <p style="text-align: right; font-size: small;">01 Sep 2022, 07:56:56</p>				
GPS Location		See picture		GPS Location		See picture	
Field Station#		0000+00		Field Station#		0000+00	
Pic 3 Desc.		Equipment inspected at LY-045 no leaks observed during inspections.		Pic 4 Desc.		Perimeter ECD's on north end of LY-045 in good condition.	
<p style="text-align: center;">North East Elevation</p> <p style="text-align: center;">📍 226°SW (T) ● 36°58'16"N, 79°52'9"W ±13ft ▲ 1194ft</p>  <p style="text-align: right; font-size: small;">01 Sep 2022, 07:56:31</p>			<p style="text-align: center;">North West Elevation</p> <p style="text-align: center;">📍 137°SE (T) ● 36°58'15"N, 79°52'14"W ±13ft ▲ 1183ft</p>  <p style="text-align: right; font-size: small;">01 Sep 2022, 07:54:40</p>				
GPS Location		See picture		GPS Location		See picture	
Field Station#		0000+00		Field Station#		0000+00	
Pic 5 Desc.		Perimeter ECD's and secondary containment structure for light plant on south end of LY-046 in good condition.		Pic 6 Desc.		Inlet protection and perimeter ECD's on south end of LY-046 in good condition.	

AFE 124300139	Date/Time 9/1/2022 10:13 AM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location See picture	GPS Location See picture
---------------------------------	---------------------------------

Field Station# 0000+00	Field Station# 0000+00
-------------------------------	-------------------------------


Pic 7 Desc. Secondary containment structure for fuel cell at LY-046 in good condition.	Pic 8 Desc. Perimeter ECD's on west side of LY-046 in good condition.
---	--



GPS Location	GPS Location
---------------------	---------------------

Field Station#	Field Station#
-----------------------	-----------------------

Pic 9 Desc.	Pic 10 Desc.
--------------------	---------------------



GPS Location	GPS Location
---------------------	---------------------

Field Station#	Field Station#
-----------------------	-----------------------

Pic 11 Desc.	Pic 12 Desc.
---------------------	---------------------

A/E	124300139	Date/Time	9/1/2022 10:13 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41699	
Inspector Frank Craycroft		Date/Time 9/1/2022 5:13 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	0+00
State VA	Inspection Area Full	Station End	0+00
County Franklin	Ground Dry	Temperature (°F)	85.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Timber Mat	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waste Management	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | N/A |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 9/1/2022 5:13 PM	Report # 41699
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted SWPPP inspection of LY-032, -033, -048, and ANC-006. All perimeter ECDs were functional and in good condition. All portable equipment and hazardous materials were maintained within secondary containment. All entrances were free of dirt accumulation. Sites were free of loose trash and debris, and bulk dumpsters on-site had adequate additional storage capacity.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.


AFE 124300139		Date/Time 9/1/2022 5:13 PM		Report #	
Pictures					
					
GPS Location 0		GPS Location 0			
Field Station# 0+00		Field Station# 0+00			
Pic 1 Desc. LY-033 Rock construction entrance		Pic 2 Desc. LY-032 Staging area			
					
GPS Location 0		GPS Location 0			
Field Station# 0+00		Field Station# 0+00			
Pic 3 Desc. LY-032 Secondary equipment		Pic 4 Desc. LY-033 Stormwater drain inlet protection			
					
GPS Location 0		GPS Location 0			
Field Station# 0+00		Field Station# 0+00			
Pic 5 Desc. ANC-006 Stormwater drain inlet protection		Pic 6 Desc. ANC-006 Waste management container			

AFE 124300139	Date/Time 9/1/2022 5:13 PM	Report #
----------------------	-----------------------------------	-----------------


Pictures



GPS Location	0	GPS Location	0
Field Station#	0+00	Field Station#	0+00
Pic 7 Desc.	LY-048 South perimeter CFS	Pic 8 Desc.	LY-048 West perimeter CFS



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 9/1/2022 5:13 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41700	
Inspector Frank Craycroft		Date/Time 9/1/2022 5:15 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13748+30	
State VA	Inspection Area Full	Station End 13853+45	
County Franklin	Ground Dry	Temperature (°F) 85.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Communication	Stabilize access road MVP-FR-300		
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 9/1/2022 5:15 PM	Report # 41700
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired













7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted SWPPP inspection of ROW from Green Level Rd to MVP-FR-303.01. Vegetation was generally good to excellent with annual grains. All perimeter ECDs observed were functional and in good condition. No signs of erosion or washing were observed. Buffer zones at resources in area were intact and showed no signs of erosion or sedimentation from ROW. All waterbars and sumps in area were functioning properly and showed no signs of sediment buildup. Equipment bridges in area were clean and free of dirt and mud buildup. Access road MVP-FR-300 required stabilization as mulch had been largely washed away and areas of minor erosion channels were developing. Ruts from unknown party's UTV near SN 13756+50 - 13757+00 will need to be monitored. This area is in low bottom with minimal drainage opportunities and soils tend to remain saturated.


Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 9/1/2022 5:15 PM		Report #	
Pictures					
					
GPS Location	0	GPS Location	0		
Field Station#	13755+60	Field Station#	13757+00		
Pic 1 Desc.	S-EF12 Channel and banks	Pic 2 Desc.	Third party rutting in ROW		
					
GPS Location	0	GPS Location	0		
Field Station#	13772+00	Field Station#	13776+00		
Pic 3 Desc.	GAS S-MM42 Buffer zone and silt fence	Pic 4 Desc.	Sump and J-hook		
					
GPS Location	0	GPS Location	0		
Field Station#	13781+00	Field Station#	13782+50		
Pic 5 Desc.	CIS S-RR15 Buffer zone and ECDs	Pic 6 Desc.	GAS S-RR15 ECDs		

AFE 124300139		Date/Time 9/1/2022 5:15 PM		Report #	
Pictures					
 		 		<p>ert image here</p>	
GPS Location	0	GPS Location	0		
Field Station#	13756+50	Field Station#	13784+00		
Pic 7 Desc.	GAS S-EF12 Silt fence		Pic 8 Desc.	Waterbar relay sump	
 		 		<p>ert image here</p>	
GPS Location	0	GPS Location	0		
Field Station#	13784+35	Field Station#	13784+35		
Pic 9 Desc.	MVP-FR-300 Stabilize access road from RCE to ROW		Pic 10 Desc.	MVP-FR-300 Stabilize access road from RCE to ROW	
 		 		<p>ert image here</p>	
GPS Location	0	GPS Location	0		
Field Station#	13784+35	Field Station#	13815+00		
Pic 11 Desc.	MVP-FR-300 Perimeter CFS near Brick Church Rd		Pic 12 Desc.	Plunge pool	

AFE 124300139	Date/Time 9/1/2022 5:15 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

	ert image here	Insert image here	
---	----------------	-------------------	--

GPS Location	0	GPS Location	
---------------------	---	---------------------	--

Field Station#	13832+00	Field Station#	
-----------------------	----------	-----------------------	--

Pic 13 Desc.	CIS S-C14 Temporary vegetation	Pic 14 Desc.	
---------------------	--------------------------------	---------------------	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 15 Desc.		Pic 16 Desc.	
---------------------	--	---------------------	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 17 Desc.		Pic 18 Desc.	
---------------------	--	---------------------	--



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41686	
Inspector Charles Head		Date/Time 9/1/2022 11:32 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15063+85
State VA	Inspection Area Full	Station End	15142+66
County Pittsylvania	Ground Dry	Temperature (°F)	77.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 9/1/2022 11:32 AM	Report # 41686
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 9/1/2022 11:32 AM	Report #
Pictures			
			
GPS Location	0	GPS Location	0
Field Station#	15113+00	Field Station#	15132+00
Pic 1 Desc.	Approximately 15113+00. Overview of road crossing and RCEs.	Pic 2 Desc.	Approximately 15132+00. Overview of ROW.
			
GPS Location	0	GPS Location	0
Field Station#	15126+40	Field Station#	15092+95
Pic 3 Desc.	Approximately 15126+40. Overview of stream crossing, equipment bridge and ECDs at stream S-A6.	Pic 4 Desc.	Approximately 15092+95. Overview of stream crossing, equipment bridge and ECDs at stream S-G9.
			
GPS Location	0	GPS Location	0
Field Station#	15102+00	Field Station#	15068+00
Pic 5 Desc.	Approximately 15102+00. Overview of ROW. Permanent vegetation. Grazed by livestock.	Pic 6 Desc.	Approximately 15068+00. Overview of ROW.

AFE 124300139	Date/Time 9/1/2022 11:32 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 9/1/2022 11:32 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41687	
Inspector Ben Davenport		Date/Time 9/1/2022 11:45 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	14649+67
State VA	Inspection Area Partial	Station End	14694+77
County Franklin	Ground Muddy	Temperature (°F)	81.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Rock Construction Entrance	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Compost Filter Sock	Acceptable			
Erosion Control Blanket	Acceptable			
Temporary Diversion Berm	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

5. Site Conditions	
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE 124300139	Date/Time 9/1/2022 11:45 AM	Report # 41687
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

-Available for work
 -Received instruction from Lead EI for daily tasks
 -Sunny with muddy ground conditions during inspection
 -Performed SWPPP inspection on portion of MVP Spread I section
 -Covered territory between station# 14649+67 — 14694+77 (Hwy 40 crossing to Jacks Creek Rd)
 -Walked ROW making note of condition of ROW and environmental controls
 -Verified the completion and accuracy of punch list items in covered area from previous inspections
 -Perimeter controls and ECDs were inspected; no issues identified
 -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified
 -Inspection observed condition of RCEs and culverts in section; no issues identified
 -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
 -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
 -Continue to monitor ROW for signs of erosion
 -No items added to environmental punch list in section

PPL crews identified issues. Items will be added to punchlist for repairs.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	9/1/2022 11:45 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	1	GPS Location	2
Field Station#	14649+67	Field Station#	14651+25
Pic 1 Desc.	RCE at Hwy 40 crossing in good condition.	Pic 2 Desc.	ROW stabilized and vegetated in final cleanup area.



GPS Location	3	GPS Location	4
Field Station#	14657+75	Field Station#	14680+37
Pic 3 Desc.	Erosion control blanket and perimeter CFS performing intended functions.	Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.



GPS Location	5	GPS Location	6
Field Station#	14686+00	Field Station#	14689+36
Pic 5 Desc.	Temporary diversion berm stabilized and vegetated.	Pic 6 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.

AFE 124300139	Date/Time 9/1/2022 11:45 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 9/1/2022 11:45 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41676	
Inspector John White		Date/Time 9/1/2022 9:32 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15947+64
State VA	Inspection Area Full	Station End	16027+46
County Pittsylvania	Ground Dry	Temperature (°F)	70.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.10
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	Perform maintenance		

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

A/E	124300139	Date/Time	9/1/2022 9:32 AM	Report #	41676
------------	-----------	------------------	------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)


Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of inspection.
PPL crews identified issues. Items will be added to punchlist for repairs.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.


AFE	124300139	Date/Time	9/1/2022 9:32 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15962+32	Field Station#	15963+50		
Pic 1 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's	Pic 2 Desc.	Observing p1 that requires maintenance		
					
GPS Location	O	GPS Location	O		
Field Station#	15970+00	Field Station#	15982+00		
Pic 3 Desc.	Observing temporary stabilization and CWD berm	Pic 4 Desc.	Observing temporary stabilization,CWD outlet and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15987+31	Field Station#	15999+00		
Pic 5 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's	Pic 6 Desc.	Observing temporary stabilization, signage, buffer and ECD's		

AFE 124300139	Date/Time 9/1/2022 9:32 AM	Report #
----------------------	-----------------------------------	-----------------


Pictures



GPS Location	O	GPS Location	
Field Station#	15998+00	Field Station#	
Pic 7 Desc.	Observing temporary stabilization, sump and end treatment	Pic 8 Desc.	



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 9/1/2022 9:32 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41721	
Inspector Justin Burch		Date/Time 9/2/2022 10:30 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15142+66	
State VA	Inspection Area Full	Station End 15260+00	
County Pittsylvania	Ground Damp	Temperature (°F) 86.00	
Municipality Chatham	Weather Sunny	Rain Gauge (in) 0.40	
Rain Accumulation Time (days)			4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar End Treatment	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Equipment Bridge	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Rock Construction Entrance	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 9/2/2022 10:30 AM	Report # 41721
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15142+66 to 15260+00 (Rock Creek Road to the Pigg River HDD Exit). No punch list items were submitted due to the inspected ECDs being in compliance at the time of inspection.
- The EI did not observe any contractor activity in the inspection area since the last SWPPP inspection.
- Since the last SWPPP inspection the inspection area has received one rainfall with a total of 0.40" at Snowberry Road.
- The ROW ground condition is damp.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion and permanent vegetative stabilization was adequately established to inhibit erosion from 15145+00 to 15153+00 and from 15173+00 to 15260+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE		124300139		Date/Time		9/2/2022 10:30 AM		Report #	
Pictures									
 <p>109°E (T) ● 36.937805°, -79.555504° ±5954ft ▲ 833ft 15227+00 09-02-2022, 08:26:13</p>					 <p>121°SE (T) ● 36.935707°, -79.548627° ±4353ft ▲ 778ft 15244+00 09-02-2022, 08:34:30</p>				
GPS Location 0					GPS Location 0				
Field Station# 15227+00					Field Station# 15244+00				
Pic 1 Desc. Perimeter CFS in acceptable condition					Pic 2 Desc. Permanent vegetative stabilization in acceptable condition				
 <p>276°W (T) ● 36.934492°, -79.542953° ±32ft ▲ 741ft 15259+50 09-02-2022, 08:41:45</p>					 <p>261°W (T) ● 36.939480°, -79.556482° ±19ft ▲ 831ft 15215+00 09-02-2022, 09:11:09</p>				
GPS Location 0					GPS Location 0				
Field Station# 15259+50					Field Station# 15215+00				
Pic 3 Desc. Perimeter CFS in acceptable condition					Pic 4 Desc. Permanent vegetative stabilization in acceptable condition				
 <p>47°NE (T) ● 36.939446°, -79.556472° ±19ft ▲ 829ft 15216+00 09-02-2022, 09:11:45</p>					 <p>59°NE (T) ● 36.939301°, -79.556730° ±13ft ▲ 829ft 15216+00 09-02-2022, 09:12:16</p>				
GPS Location 0					GPS Location 0				
Field Station# 15216+00					Field Station# 15216+00				
Pic 5 Desc. Waterbar end treatment in acceptable condition					Pic 6 Desc. Waterbar in acceptable condition				

AFE 124300139		Date/Time 9/2/2022 10:30 AM		Report #	
Pictures					
74°E (T) 36.946282°, -79.576202° ±13ft ▲ 847ft  <p style="text-align: right;">15154+00 09-02-2022, 10:03:28</p>				159°S (T) 36.945185°, -79.573849° ±32ft ▲ 788ft  <p style="text-align: right;">15162+00 09-02-2022, 10:10:29</p>	
GPS Location 0		GPS Location 0			
Field Station# 15154+00		Field Station# 15162+00			
Pic 7 Desc. Temporary vegetative stabilization in acceptable condition		Pic 8 Desc. Waterbar in acceptable condition			
171°S (T) 36.945129°, -79.573799° ±26ft ▲ 786ft  <p style="text-align: right;">15162+00 09-02-2022, 10:10:48</p>				83°E (T) 36.944054°, -79.571780° ±13ft ▲ 725ft  <p style="text-align: right;">15168+59 09-02-2022, 10:16:16</p>	
GPS Location 0		GPS Location 0			
Field Station# 15162+00		Field Station# 15168+59			
Pic 9 Desc. Waterbar end treatment in acceptable condition		Pic 10 Desc. Equipment bridge in acceptable condition			
150°SE (T) 36.943787°, -79.571291° ±13ft ▲ 727ft  <p style="text-align: right;">15170+00 09-02-2022, 10:20:13</p>				158°SE (T) 36.948185°, -79.578529° ±206ft ▲ 880ft  <p style="text-align: right;">15143+00 09-02-2022, 10:55:19</p>	
GPS Location 0		GPS Location 0			
Field Station# 15170+00		Field Station# 15143+00			
Pic 11 Desc. Temporary vegetative stabilization in acceptable condition		Pic 12 Desc. Rock construction entrance in acceptable condition			

A/E	124300139	Date/Time	9/2/2022 10:30 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41729	
Inspector Ben Farmer		Date/Time 9/2/2022 1:04 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13853+45	
State VA	Inspection Area Partial	Station End 13958+31	
County Franklin	Ground Dry	Temperature (°F) 60.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 9/2/2022 1:04 PM	Report # 41729
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 60F)
 Rain Gauge= 0.0"
 13853+45-13958+31

- Resource buffers remain well vegetated at all stream and wetland crossings.
- CWDs are in good condition and functioning as intended
- Equipment bridge ECDs are in good condition and functioning
- P1 is in good condition at all stream and wetland buffers
- Steep slope at 13889+00 remains stabilized.
- RCEs are in good condition at all road crossings.
- Topsoil berms remain stabilized.
- Sediment trap at 13897+00 is in good condition with no evidence of discharge.
- SSF is in good condition
- Waterbars/end treatments are in good condition.
- Slope drain is functioning at 13955+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.


AFE 124300139		Date/Time 9/2/2022 1:04 PM		Report #	
Pictures					
					
GPS Location See photo		GPS Location See photo			
Field Station# 13857+00		Field Station# 13857+00			
Pic 1 Desc. Waterbars are in good condition		Pic 2 Desc. End treatments are functioning as intended			
					
GPS Location See photo		GPS Location See photo			
Field Station# 13863+00		Field Station# 13875+50			
Pic 3 Desc. Resource buffers remain well vegetated		Pic 4 Desc. Equipment bridge ECDs are in good condition and functioning			
					
GPS Location See photo		GPS Location See photo			
Field Station# 13875+00		Field Station# 13888+50			
Pic 5 Desc. P1 is in good condition at all stream and wetland buffers		Pic 6 Desc. Slope drain is in good condition and functioning			

AFE 124300139	Date/Time 9/2/2022 1:04 PM	Report #
----------------------	-----------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	See photo
Field Station#	13892+45	Field Station#	13897+00
Pic 7 Desc.	RCEs are in good condition at all road crossings	Pic 8 Desc.	Sediment trap is functioning as intended



GPS Location	See photo	GPS Location	See photo
Field Station#	13897+00	Field Station#	13942+00
Pic 9 Desc.	Topsoil pile remains stabilized	Pic 10 Desc.	CWDs are functioning as intended throughout this section



GPS Location	See photo	GPS Location	See photo
Field Station#	13949+00	Field Station#	13954+00
Pic 11 Desc.	SSF is in good condition	Pic 12 Desc.	Slope drain outlet is in good condition

AFE 124300139	Date/Time 9/2/2022 1:04 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41739	
Inspector Charles Head		Date/Time 9/2/2022 3:06 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	14694+77
State VA	Inspection Area Full	Station End	14802+19
County Franklin	Ground Dry	Temperature (°F)	81.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sensitive Resource Signage	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 9/2/2022 3:06 PM	Report # 41739
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 9/2/2022 3:06 PM		Report #	
Pictures					
					
GPS Location 0		GPS Location 0			
Field Station# 14765+00		Field Station# 14794+00			
Pic 1 Desc. Approximately 13765+00. Overview of ROW.		Pic 2 Desc. Approximately 14794+00. Overview of stream crossing, equipment bridge and ECDs at stream S-H24.			
					
GPS Location 0		GPS Location 0			
Field Station# 14758+16		Field Station# 14751+50			
Pic 3 Desc. Approximately 14758+16. Overview of road crossing and RCEs.		Pic 4 Desc. Approximately 14751+50. Overview of stream crossing, equipment bridge and ECDs at stream S-A22.			
					
GPS Location 0		GPS Location 0			
Field Station# 14716+50		Field Station# 14737+68			
Pic 5 Desc. Approximately 14716+50. Overview of wetland crossing, equipment bridge and ECDs at wetland W-H11. Crews have installed new and additional ECDs to try and prevent further		Pic 6 Desc. Approximately 14737+68. Overview of ROW. Third party timber harvesting activities continue. Will continue to monitor.			

AFE 124300139	Date/Time 9/2/2022 3:06 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 9/2/2022 3:06 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41728	
Inspector Ben Davenport		Date/Time 9/2/2022 12:46 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14311+57	
State VA	Inspection Area Partial	Station End 14454+22	
County Franklin	Ground Dry	Temperature (°F) 80.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
Rain Accumulation Time (days)			0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Temporary Diversion Berm	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Sediment Filter Log	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

-Available for work
 -Received instruction from Lead EI for daily tasks
 -Sunny with dry ground conditions during inspection
 -Performed SWPPP inspection on portion of MVP Spread I section
 -Covered territory between station# 14311+57 — 14454+22 (Farm View Rd to Webster Rd)
 -Walked ROW making note of condition of ROW and environmental controls
 -Verified the completion and accuracy of punch list items in covered area from previous inspections
 -Perimeter controls and ECD's were inspected; no issues identified
 -Inspection observed condition of equipment bridges and surrounding ECDs around stream crossings and resource buffers; no issues identified
 -Inspection observed condition of RCEs and culverts in section; no issues identified
 -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
 -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
 -Continue to monitor ROW for signs of erosion
 -No items added to environmental punch list

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	9/2/2022 12:46 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures

			
<small>37°22'31" N 79°48'19" W 193°S COURSE 161° GPS 1807 Golden View Rd, Glade Hill, VA 24092, United States 09.02.2022 10:30:21 Accur +/-15.4 Ft ALT 1223 Ft</small>		<small>37°2'16" N 79°48'16" W 304°NW COURSE 336° GPS 1804 Golden View Rd, Glade Hill, VA 24092, United States 09.02.2022 10:24:15 Accur +/-15.5 Ft ALT 1140 Ft</small>	

GPS Location	1	GPS Location	2
Field Station#	14329+00	Field Station#	14334+00
Pic 1 Desc.	Perimeter CFS in good condition.	Pic 2 Desc.	Temporary diversion berm stabilized and vegetated.

			
<small>37°2'16" N 79°48'16" W 97°E COURSE -1° GPS 1804 Golden View Rd, Glade Hill, VA 24092, United States 09.02.2022 10:24:04 Accur +/-14.0 Ft ALT 1141 Ft</small>		<small>37°1'44" N 79°46'30" W 297°NW COURSE 289° GPS Glade Hill, VA 24092, United States 09.02.2022 10:47:36 Accur +/-43.3 Ft ALT 1027 Ft</small>	

GPS Location	3	GPS Location	4
Field Station#	14338+56	Field Station#	14434+01
Pic 3 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	Pic 4 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.

			
<small>37°1'48" N 79°46'38" W 157°SE COURSE 316° GPS Glade Hill, VA 24092, United States 09.02.2022 10:50:34 Accur +/-15.1 Ft ALT 1067 Ft</small>		<small>37°1'50" N 79°46'40" W 22°N COURSE 288° GPS Glade Hill, VA 24092, United States 09.02.2022 10:54:10 Accur +/-15.4 Ft ALT 1007 Ft</small>	

GPS Location	5	GPS Location	6
Field Station#	14429+00	Field Station#	14438+33
Pic 5 Desc.	Rock end treatment performing intended function.	Pic 6 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.

AFE 124300139	Date/Time 9/2/2022 12:46 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 9/2/2022 12:46 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 41720	
Inspector John White		Date/Time 9/2/2022 10:14 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15584+23	
State VA	Inspection Area Full	Station End 15647+03	
County Pittsylvania	Ground Dry	Temperature (°F) 82.00	
Municipality Chatham	Weather Sunny	Rain Gauge (in) 0.30	
Rain Accumulation Time (days)			4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Communication	Contractor performed maintenance		9/2/2022
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter Outlet	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	9/2/2022 10:14 AM	Report #	41720
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There was one issue identified and repaired by the Contractor upon discovery. Other than that there were no issues to report at the time of Inspection.
PPL crews identified issues. Items will be added to punchlist for repairs.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	9/2/2022 10:14 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	15590+00	Field Station#	15595+60
-----------------------	----------	-----------------------	----------


Pic 1 Desc.	Observing temporary stabilization and water bars	Pic 2 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's
--------------------	--	--------------------	--



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	15610+00	Field Station#	15619+48
-----------------------	----------	-----------------------	----------




Pic 3 Desc.	Observing temporary stabilization	Pic 4 Desc.	Observing road crossing and RCE's
--------------------	-----------------------------------	--------------------	-----------------------------------



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	15623+00	Field Station#	15636+45
-----------------------	----------	-----------------------	----------

Pic 5 Desc.	Observing temporary stabilization and water bars	Pic 6 Desc.	Observing geo tech that required maintenance
--------------------	--	--------------------	--

AFE	124300139	Date/Time	9/2/2022 10:14 AM	Report #	
Pictures					
		<p>ert image here</p>			
		<p>ert image here</p>			
GPS Location	O	GPS Location	O		
Field Station#	15636+45	Field Station#	15640+00		
Pic 7 Desc.	Observing the Contractor performing maintenance		Pic 8 Desc.	Observing temporary stabilization, sump and end treatment	
		<p>Insert image here</p>			
GPS Location	O	GPS Location			
Field Station#	15630+00	Field Station#			
Pic 9 Desc.	Observing temporary stabilization, CWD outlet and ECD's		Pic 10 Desc.		
<p>Insert image here</p>			<p>Insert image here</p>		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.			Pic 12 Desc.		

A/E	124300139	Date/Time	9/2/2022 10:14 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name Transco Interconnect Station		AFE 124300113	Spread Transco Interconnect Sta
Contractor Kanahwa		Report # 41675	
Inspector John White		Date/Time 9/1/2022 9:26 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	00+00
State VA	Inspection Area Full	Station End	00+00
County Pittsylvania	Ground Dry	Temperature (°F)	70.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.10
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Housekeeping	Acceptable			
Rock Filter	Acceptable			
Rock Construction Entrance	Acceptable			
Sediment Basin	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

A/E	124300113	Date/Time	9/1/2022 9:26 AM	Report #	41675
------------	-----------	------------------	------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on the Transco Facility and Lay down yard. There was one issue identified and added to the punch list. Other than that there were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300113		Date/Time 9/1/2022 9:26 AM	Report #
Pictures			
GPS Location	O	GPS Location	O
Field Station#	00+00	Field Station#	00+00
Pic 1 Desc.	Observing RCE	Pic 2 Desc.	Observing safety fence that requires maintenance
GPS Location	O	GPS Location	O
Field Station#	00+00	Field Station#	00+00
Pic 3 Desc.	Observing lay down yard	Pic 4 Desc.	Observing temporary stabilization and rock drain
GPS Location	O	GPS Location	O
Field Station#	00+00	Field Station#	00+00
Pic 5 Desc.	Observing temporary stabilization and sediment basin	Pic 6 Desc.	Observing temporary stabilization, storm water pond and ECD's

AFE 124300113	Date/Time 9/1/2022 9:26 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300113	Date/Time 9/1/2022 9:26 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	