



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40732	
Inspector Justin Burch		Date/Time 8/8/2022 9:17 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15260+00
State VA	Inspection Area Full	Station End	15370+62
County Pittsylvania	Ground Wet	Temperature (°F)	90.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	1.20
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Compost Filter Sock	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15260+00 to 15370+62 (Pigg River HDD Exit to Snowberry Road). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection.
- The EI observed that the contractor has worked in the area since the last SWPPP inspection and addressed punch list items.
- Since the last SWPPP inspection the inspection area has received rainfall events with a total of 1.20" at Snowberry Road.
- The ROW ground condition is wet.
- At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15355+00 to 15370+00.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/8/2022 9:17 AM		Report #			
Pictures							
☉ 292°W (T) ● 17 N 631381 4088077 ±26ft ▲ 725ft 			☉ 350°N (T) ● 17 N 630308 4088518 ±32116ft ▲ 718ft 				
GPS Location		0		GPS Location		0	
Field Station#		15318+00		Field Station#		15317+00	
Pic 1 Desc.		Temporary vegetative stabilization in acceptable condition		Pic 2 Desc.		Waterbar in acceptable condition	
☉ 335°NW (T) ● 17 N 631341 4088089 ±22ft ▲ 696ft 			☉ 115°SE (T) ● 17 N 635871 4090772 ±14967ft ▲ 678ft 				
GPS Location		0		GPS Location		0	
Field Station#		15317+00		Field Station#		15314+00	
Pic 3 Desc.		Waterbar end treatment in acceptable condition		Pic 4 Desc.		CFS and sensitive resource buffer in acceptable conditions	
☉ 157°SE (T) ● 17 N 630775 4088276 ±239ft ▲ 777ft 			☉ 152°SE (T) ● 17 N 630825 4088363 ±22ft ▲ 767ft 				
GPS Location		0		GPS Location		0	
Field Station#		15300+00		Field Station#		15297+00	
Pic 5 Desc.		P1 silt fence in acceptable condition		Pic 6 Desc.		Waterbar in acceptable condition	

AFE	124300139	Date/Time	8/8/2022 9:17 AM	Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	15297+00	Field Station#	15330+00		
Pic 7 Desc.	Waterbar end treatment and perimeter CFS in acceptable conditions		Pic 8 Desc.	Temporary vegetative stabilization in acceptable condition	
GPS Location	0	GPS Location	0		
Field Station#	15358+00	Field Station#	15369+00		
Pic 9 Desc.	Permanent vegetative stabilization in acceptable condition		Pic 10 Desc.	Permanent vegetative stabilization in acceptable condition	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

AFE 124300139	Date/Time 8/8/2022 9:17 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40739	
Inspector Ben Farmer		Date/Time 8/8/2022 12:00 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13958+31	
State VA	Inspection Area Partial	Station End 14062+17	
County Franklin	Ground Damp	Temperature (°F) 75.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/8/2022 12:00 PM	Report # 40739
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 75F)
 Rain Gauge= 0.0"
 13958+31-14062+17







- This section remains stabilized.
- CWD/CWD inlets are in good condition and functioning as intended
- Equipment bridge ECDs are in good condition
- MVP-ATWS-1446 remains stabilized with controls in place.
- P1 is in good condition at all stream and wetland buffers.
- No evidence of 3rd party pond discharging onto ROW at 14000+00
- Resource buffers remain well vegetated.
- Slope on the CIS of Highway 220 remains stabilized with controls in place.
- Waterbars/end treatments are functioning as intended.
- CFS is in good condition
- Slope drain is functioning as intended at 14058+00
- Rock check dams are functioning at 14059+00.
- Vegetation continues to fill in throughout this section

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/8/2022 12:00 PM		Report #	
Pictures					
					
GPS Location See photo		GPS Location See photo			
Field Station# 13960+00		Field Station# 13970+00			
Pic 1 Desc. CWDs are functioning as intended		Pic 2 Desc. Vegetation continues to fill in throughout this section			
					
GPS Location See photo		GPS Location See photo			
Field Station# 13997+50		Field Station# 14000+00			
Pic 3 Desc. P1 is in good condition at all stream and wetland buffers		Pic 4 Desc. No evidence of 3rd party pond discharging onto ROW.			
					
GPS Location See photo		GPS Location See photo			
Field Station# 14009+11		Field Station# 14018+47			
Pic 5 Desc. SSF is in good condition		Pic 6 Desc. RCEs are in good condition at all stream and wetland buffers			

AFE	124300139	Date/Time	8/8/2022 12:00 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures

			
GPS Location	See photo	GPS Location	See photo
Field Station#	14027+00	Field Station#	14033+00
Pic 7 Desc.	CFS is in good condition throughout this section	Pic 8 Desc.	Waterbars are in good condition
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14033+00	Field Station#	14035+00
Pic 9 Desc.	End treatments are functioning as intended	Pic 10 Desc.	Resource buffers remain well vegetated
			
GPS Location	See photo	GPS Location	See photo
Field Station#	14050+00	Field Station#	14057+00
Pic 11 Desc.	Equipment bridge ECDs are functioning as intended	Pic 12 Desc.	Slope drain is in good condition and functioning

AFE 124300139	Date/Time 8/8/2022 12:00 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40686	
Inspector Ben Davenport		Date/Time 8/8/2022 1:40 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14454+22	
State VA	Inspection Area Partial	Station End 14546+75	
County Franklin	Ground Damp	Temperature (°F) 90.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Compost Filter Sock	Acceptable			
Rock Construction Entrance	Acceptable			
Erosion Control Blanket	Acceptable			
Equipment Bridge	Acceptable			
Sump Pit	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/8/2022 1:40 PM	Report # 40686
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- Available for work
- Received instruction from Lead EI for daily tasks
- Sunny with damp ground conditions during inspection
- Performed SWPPP inspection on portion of MVP Spread I section
- Covered territory between station# 14454+22 — 14546+75 (Webster Rd to Tobacco Rd)
- Precision environmental crew in section during inspection
- Walked ROW making note of condition of ROW and environmental controls
- Verified the completion and accuracy of punch list items in covered area from previous inspections
- Perimeter controls and ECDs were inspected; no issues identified
- Inspection observed condition of equipment bridges and surrounding ECDs around stream crossings and resource buffers; no issues identified
- Inspection observed condition of RCEs and culverts in section; no issues identified
- Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
- Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
- Continue to monitor ROW for signs of erosion
- No items added to environmental punch list in section

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/8/2022 1:40 PM		Report #	
Pictures					
					
<small>37°1'24" N 79°45'54" W 169°S COURSE 144° GPS 08.08.2022 12:10:42 Glade Hill, VA 24092, United States Accur +/-12.2 Ft ALT 1056 Ft</small>			<small>37°1'11" N 79°45'44" W 175°S COURSE 228° GPS 08.08.2022 12:17:25 Glade Hill, VA 24092, United States Accur +/-15.5 Ft ALT 922 Ft</small>		
GPS Location	1		GPS Location	2	
Field Station#	14470+95		Field Station#	14485+00	
Pic 1 Desc.	ROW stabilized and vegetated in temporary area.		Pic 2 Desc.	Contractor repaired erosion and replaced perimeter P1 silt fence per punch list item.	
					
<small>37°1'11" N 79°45'43" W 217°SW COURSE 134° GPS 08.08.2022 12:17:10 Glade Hill, VA 24092, United States Accur +/-15.5 Ft ALT 922 Ft</small>			<small>37°0'40" N 79°45'15" W 239°SW COURSE 354° GPS 08.08.2022 10:49:27 1594-1682 SR-674, Glade Hill, VA 24092, United States Accur +/-11.6 Ft ALT 1011 Ft</small>		
GPS Location	3		GPS Location	4	
Field Station#	14486+68		Field Station#	14524+76	
Pic 3 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.		Pic 4 Desc.	RCE at Timber Ridge Rd in good condition.	
					
<small>37°0'33" N 79°45'15" W 262°W COURSE 165° GPS 08.08.2022 10:45:58 1694 SR-674, Glade Hill, VA 24092, United States Accur +/-15.4 Ft ALT 1000 Ft</small>			<small>37°0'37" N 79°45'16" W 179°S COURSE 254° GPS 08.08.2022 10:44:02 1694 SR-674, Glade Hill, VA 24092, United States Accur +/-15.5 Ft ALT 1038 Ft</small>		
GPS Location	5		GPS Location	6	
Field Station#	14531+58		Field Station#	14542+00	
Pic 5 Desc.	Contractor removed damaged equipment bridge at stream crossing and installed new ECDs in resource buffer.		Pic 6 Desc.	Sump pit and CFS end treatment performing intended functions.	

AFE 124300139	Date/Time 8/8/2022 1:40 PM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300139	Date/Time	8/8/2022 1:40 PM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40740	
Inspector Charles Head		Date/Time 8/8/2022 12:02 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14802+19	
State VA	Inspection Area Full	Station End 14928+52	
County Franklin	Ground Damp	Temperature (°F) 86.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 2.40	
			Rain Accumulation Time (days) 2.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
3rd Party Damages	Communication	Repair livestock damage to P-1		
Compost Filter Sock	Acceptable			
Equipment Bridge	Communication	Remove sediment		
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	Repair livestock damage		

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/8/2022 12:02 PM	Report # 40740
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. Maintenance issues observed during inspection can be found below and on daily punch list.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/8/2022 12:02 PM	Report #
Pictures			
			
GPS Location	0	GPS Location	0
Field Station#	14823+54	Field Station#	14813+00
Pic 1 Desc.	Approximately 14823+54. Overview of stream crossing, equipment bridge and ECDs at stream S-A13.	Pic 2 Desc.	Approximately 14813+00. Overview of ROW. Permanent vegetation.
			
GPS Location	0	GPS Location	0
Field Station#	14907+57	Field Station#	14897+00
Pic 3 Desc.	Approximately 14907+57. Overview of stream crossing, equipment bridge and ECDs at stream S-DD3.	Pic 4 Desc.	Approximately 14897+00. Overview of ROW.
			
GPS Location	0	GPS Location	0
Field Station#	14923+00	Field Station#	14870+00
Pic 5 Desc.	Approximately 14923+00. P-1 requires maintenance along drainage feature. Damaged by livestock.	Pic 6 Desc.	Approximately 14870+00. Equipment bridge requires maintenance. Remove sediment.

AFE 124300139	Date/Time 8/8/2022 12:02 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

A/E	124300139	Date/Time	8/8/2022 12:02 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40731	
Inspector John White		Date/Time 8/8/2022 9:02 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15647+03
State VA	Inspection Area Full	Station End	15772+27
County Pittsylvania	Ground Dry	Temperature (°F)	77.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/8/2022 9:02 AM	Report #	40731
------------	-----------	------------------	------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/8/2022 9:02 AM		Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15770+00	Field Station#	15735+00		
Pic 1 Desc.	Observing temporary stabilization and water bar	Pic 2 Desc.	Observing temporary stabilization, CWD outlet and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15693+89	Field Station#	15700+40		
Pic 3 Desc.	Observing road crossing and RCE's	Pic 4 Desc.	Observing temporary stabilization, buffer, equipment crossing and ECD's		
GPS Location	O	GPS Location	O		
Field Station#	15690+00	Field Station#	15650+00		
Pic 5 Desc.	Observing temporary stabilization and water bars	Pic 6 Desc.	Observing temporary stabilization, sump and end treatment		

AFE 124300139	Date/Time 8/8/2022 9:02 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE	124300139	Date/Time	8/8/2022 9:02 AM	Report #	
------------	-----------	------------------	------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40789	
Inspector Justin Burch		Date/Time 8/9/2022 11:48 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15370+62
State VA	Inspection Area Full	Station End	15480+67
County Pittsylvania	Ground Damp	Temperature (°F)	91.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	1.20
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Temporary)	Acceptable			
Compost Filter Sock	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Equipment Bridge	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Sump Pit	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/9/2022 11:48 AM	Report # 40789
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15370+62 to 15480+67 (Snowberry Road to Toshes Road). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection.
- The EI observed that stream water at S-G4 (15426+54) was running clear. This stream has been impacted in the past by upstream activities not related to MVP.
- The EI observed that the contractor has worked in the area since the last SWPPP inspection and addressed punch list items.
- The EI observed that the solar farm perimeter ECDs on the CIS of Toshes Road appeared to be in acceptable condition.
- Since the last SWPPP inspection the inspection area has received one rain event with a total of 1.20" at Snowberry Road.
- The ROW ground condition is damp.
- At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15438+00 to 15445+00.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/9/2022 11:48 AM		Report #	
Pictures					
					
GPS Location 0		GPS Location 0			
Field Station# 15373+00		Field Station# 15375+00			
Pic 1 Desc. Temporary vegetative stabilization in acceptable condition		Pic 2 Desc. CFS and temporary vegetative stabilization in acceptable conditions			
					
GPS Location 0		GPS Location 0			
Field Station# 15383+00		Field Station# 15414+13			
Pic 3 Desc. P1 silt fence in acceptable condition		Pic 4 Desc. Equipment bridge in acceptable condition			
					
GPS Location 0		GPS Location 0			
Field Station# 15416+00		Field Station# 15416+00			
Pic 5 Desc. Waterbar in acceptable condition		Pic 6 Desc. Waterbar end treatment and perimeter CFS in acceptable conditions			

AFE 124300139		Date/Time 8/9/2022 11:48 AM		Report #	
Pictures					
  <p>15445+00 08-09-2022 10:28:27</p>				  <p>15453+00 08-09-2022 10:37:21</p>	
GPS Location	0	GPS Location	0		
Field Station#	15445+00	Field Station#	15453+00		
Pic 7 Desc.	Permanent vegetative stabilization and perimeter CFS in acceptable conditions		Pic 8 Desc.	Clean water diversion pipe in acceptable condition	
  <p>15426+54 08-09-2022 13:19:48</p>		Insert image here			
GPS Location	0	GPS Location			
Field Station#	15426+54	Field Station#			
Pic 9 Desc.	Stream water in S-G4 is running clear.		Pic 10 Desc.		
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.			Pic 12 Desc.		

AFE 124300139	Date/Time 8/9/2022 11:48 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40800	
Inspector Frank Craycroft		Date/Time 8/9/2022 3:39 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	13670+00
State VA	Inspection Area Full	Station End	13748+30
County Franklin	Ground Damp	Temperature (°F)	90.00
Municipality N/A	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/9/2022 3:39 PM	Report # 40800
----------------------	-----------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted SWPPP inspection of ROW from Spread H/I break to Green Level Rd. Vegetation is generally excellent to full with dense stand of perennial grasses. All perimeter ECDs observed were functional and in good condition. All resource buffers in area are intact and show no signs of erosion or sedimentation of resource. Equipment bridges are free of mud and sediment buildup. Waterbars and sumps in area are functional and show no signs of erosion or sediment buildup. No signs of erosion or washing were observed.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/9/2022 3:39 PM	Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	13693+00		Field Station#	13689+00	
Pic 1 Desc.	GAS S-E28 Banks and channel		Pic 2 Desc.	CIS Grassy Hill Rd ATWS CFS	
					
GPS Location	0		GPS Location	0	
Field Station#	13697+00		Field Station#	13700+00	
Pic 3 Desc.	GAS W-E7 Silt fence		Pic 4 Desc.	Temporary vegetation	
					
GPS Location	0		GPS Location	0	
Field Station#	13705+25		Field Station#	13706+00	
Pic 5 Desc.	GAS S-E28 Banks and channel		Pic 6 Desc.	GAS S-E28 Buffer zone ECDs	

AFE 124300139		Date/Time 8/9/2022 3:39 PM		Report #	
Pictures					
 <p>211°S (T) • 37.082584, -79.944293 ±12ft ▲ 1068ft</p>		 <p>52°NE (T) • 37.082426, -79.943822 ±12ft ▲ 1066ft</p>		ert image here	
GPS Location 0		GPS Location 0			
Field Station# 13708+00		Field Station# 13708+50			
Pic 7 Desc. Sump		Pic 8 Desc. Sump outlet			
 <p>318°NW (T) • 37.092115, -79.9431 ±12ft ▲ 1104ft</p>		 <p>150°SE (T) • 37.079206, -79.941934 ±12ft ▲ 1040ft</p>		ert image here	
GPS Location 0		GPS Location 0			
Field Station# 13712+00		Field Station# 13720+00			
Pic 9 Desc. Perimeter CFS		Pic 10 Desc. Perimeter SSF			
 <p>262°W (T) • 37.078963, -79.941749 ±12ft ▲ 998ft</p>		 <p>348° (T) • 37.077772, -79.939453 ±12ft ▲ 1112ft</p>		ert image here	
GPS Location 0		GPS Location 0			
Field Station# 13728+50		Field Station# 13735+00			
Pic 11 Desc. GAS S-EF4 Banks		Pic 12 Desc. Perimeter CFS			

A/E	124300139	Date/Time	8/9/2022 3:39 PM	Report #	
Pictures					
Insert image here			Insert image here		
GPS Location		GPS Location		GPS Location	
Field Station#		Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.		Pic 15 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		GPS Location	
Field Station#		Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.		Pic 17 Desc.	
Insert image here			Insert image here		
GPS Location		GPS Location		GPS Location	
Field Station#		Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.		Pic 19 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40798	
Inspector Ben Farmer		Date/Time 8/9/2022 12:51 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14062+17	
State VA	Inspection Area Partial	Station End 14171+36	
County Franklin	Ground Dry	Temperature (°F) 75.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	P1 has been damaged and needs to		
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Communication	ROW has been damaged by 3rd par		
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/9/2022 12:51 PM	Report # 40798
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.







Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 75F)
 Rain Gauge= 0.0"
 14062+17-14171+36

- RCE are in good condition at all road crossings.
- P1 has been damaged by 3rd party and needs to be replaced at 14066+77/14105+20.
- P1 has been damaged and needs to be replaced at 14103+00/14103+25.
- Equipment bridge ECDs are in good condition and functioning.
- CWDs are functioning as intended.
- MVP-FR-309.05 is in good condition with controls in place.
- Resource buffers remain well vegetated.
- CFS is in good condition throughout this section
- ROW has been damaged by 3rd party and needs to be re-stabilized at 14127+55.
- Waterbars/end treatments are in good condition and functioning
- Slope drain is functioning as intended at 14157+00.


*Issues identified in the field have been added to the punch list to be addressed by the contractor.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/9/2022 12:51 PM		Report #	
Pictures					
					
GPS Location See photo		GPS Location See photo			
Field Station# 14062+17		Field Station# 14066+77			
Pic 1 Desc. RCEs are in good condition at all road crossings		Pic 2 Desc. P1 has been damaged by 3rd party and needs to be replaced			
					
GPS Location See photo		GPS Location See photo			
Field Station# 14070+00		Field Station# 14103+00			
Pic 3 Desc. CWDs are functioning as intended		Pic 4 Desc. P1 has been damaged and needs to be replaced			
					
GPS Location See photo		GPS Location See photo			
Field Station# 14103+25		Field Station# 14105+20			
Pic 5 Desc. P1 has been damaged and needs to be replaced		Pic 6 Desc. P1 has been damaged by 3rd party and needs to be replaced			

AFE	124300139	Date/Time	8/9/2022 12:51 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	See photo	GPS Location	See photo
Field Station#	14109+00	Field Station#	14109+00
Pic 7 Desc.	Waterbars are in good condition	Pic 8 Desc.	End treatments are functioning as intended



GPS Location	See photo	GPS Location	See photo
Field Station#	14120+00	Field Station#	14127+55
Pic 9 Desc.	CFS is in good condition throughout this section	Pic 10 Desc.	ROW has been damaged by 3rd party and needs to be replaced



GPS Location	See photo	GPS Location	See photo
Field Station#	14156+00	Field Station#	14157+55
Pic 11 Desc.	Slope drain is in good condition and functioning	Pic 12 Desc.	Resource buffers remain well vegetated

AFE 124300139	Date/Time 8/9/2022 12:51 PM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	
---------------------	-----------	---------------------	--

Field Station#	14157+55	Field Station#	
-----------------------	----------	-----------------------	--


Pic 13 Desc.	Equipment bridge ECDs are functioning as intended	Pic 14 Desc.	
---------------------	---	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 15 Desc.		Pic 16 Desc.	
---------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 17 Desc.		Pic 18 Desc.	
---------------------	--	---------------------	--



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40749	
Inspector Ben Davenport		Date/Time 8/9/2022 12:31 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14546+75	
State VA	Inspection Area Partial	Station End 14649+67	
County Franklin	Ground Damp	Temperature (°F) 88.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Equipment Bridge	Acceptable			
Erosion Control Blanket	Acceptable			
Waterbar	Acceptable			
Sump Pit	Acceptable			
Waterbar End Treatment	Acceptable			
Temporary Diversion Berm	Acceptable			
Sediment Filter Log	Acceptable			

- 5. Site Conditions**
- Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. No
 - Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? Yes
 - Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? Yes
 - Has a new slip/slide been observed? (If yes, complete Slide Report Form) No

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- Available for work
- Received instruction from Lead EI for daily tasks
- Sunny with damp ground conditions during inspection
- Performed SWPPP inspection on portion of MVP Spread I section
- Covered territory between station# 14546+75 — 14649+67 (Tobacco Rd to Hwy 40 crossing)
- Walked ROW making note of condition of ROW and environmental controls
- Verified the completion and accuracy of punch list items in covered area from previous inspections
- Perimeter controls and ECDs were inspected; no issues identified
- Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified
- Inspection observed condition of RCEs and culverts in section; no issues identified
- Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
- Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
- Continue to monitor ROW for signs of erosion
- No items added to environmental punch list in covered area

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/9/2022 12:31 PM		Report #	
Pictures					
					
<small>37°0'18" N 79°45'6" W 154°SE COURSE 116' GPS 08.09.2022 10:19:41 594 Tobacco Rd, Glade Hill, VA 24092, United States Accur +/-15.5 Ft ALT 964 Ft</small>			<small>37°0'13" N 79°45'4" W 341°N COURSE 164' GPS 08.09.2022 10:22:15 594 Tobacco Rd, Glade Hill, VA 24092, United States Accur +/-42.2 Ft ALT 965 Ft</small>		
GPS Location	1		GPS Location	2	
Field Station#	14548+00		Field Station#	14552+00	
Pic 1 Desc.	Perimeter CFS in good condition and ROW stabilized and vegetated in temporary extra workspace.		Pic 2 Desc.	Equipment bridge over natural drainage area performing intended function.	
					
<small>37°0'1" N 79°44'31" W 293°W COURSE 35' GPS 08.09.2022 10:08:47 Glade Hill, VA 24092, United States Accur +/-15.5 Ft ALT 869 Ft</small>			<small>36°59'57" N 79°44'26" W 308°NW COURSE 304' GPS 08.09.2022 10:02:22 753 Simmons Creek Rd, Union Hall, VA 24176, United States Accur +/-17.3 Ft ALT 914 Ft</small>		
GPS Location	3		GPS Location	4	
Field Station#	14584+96		Field Station#	14593+00	
Pic 3 Desc.	CFS triple stack in place and functional.		Pic 4 Desc.	Temporary diversion berm stabilized and vegetated.	
					
<small>36°59'54" N 79°44'21" W 317°NW COURSE 336' GPS 08.09.2022 10:00:19 753 Simmons Creek Rd, Union Hall, VA 24176, United States Accur +/-15.1 Ft ALT 952 Ft</small>			<small>36°59'47" N 79°44'11" W 224°SW COURSE 201' GPS 08.09.2022 09:52:38 Sorry no results found Accur +/-15.5 Ft ALT 907 Ft</small>		
GPS Location	5		GPS Location	6	
Field Station#	14595+00		Field Station#	14608+00	
Pic 5 Desc.	Erosion control blanket in throat of water bar performing intended function.		Pic 6 Desc.	Sump pit and CFS end treatment in good condition.	

AFE 124300139	Date/Time 8/9/2022 12:31 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/9/2022 12:31 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40799	
Inspector Charles Head		Date/Time 8/9/2022 12:56 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14928+52	
State VA	Inspection Area Full	Station End 15063+85	
County Franklin/Pittsylvania	Ground Dry	Temperature (°F) 88.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/9/2022 12:56 PM	Report # 40799
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/9/2022 12:56 PM	Report #
Pictures			
 <p>84°E (T) ● 36°58'3"N, 79°38'14"W ±705ft 09 Aug 2022, 11:41:05</p>		 <p>104°E (T) ● 36°58'11"N, 79°37'53"W ±1171ft 09 Aug 2022, 11:47:41</p>	
GPS Location	0	GPS Location	0
Field Station#	14939+00	Field Station#	14950+47
Pic 1 Desc.	Approximately 14939+00. Overview of ROW.	Pic 2 Desc.	Approximately 14950+47. Overview of stream crossing, equipment bridge and ECDs at stream S-G13.
 <p>288°W (T) ● 36°57'56"N, 79°37'17"W ±29ft 09 Aug 2022, 12:14:47</p>		 <p>88°E (T) ● 36°57'56"N, 79°37'13"W ±78ft 09 Aug 2022, 12:16:18</p>	
GPS Location	0	GPS Location	0
Field Station#	14971+00	Field Station#	14981+55
Pic 3 Desc.	Approximately 14971+00. Overview of ROW. Permanent vegetation.	Pic 4 Desc.	Approximately 14981+55. Overview of road crossing and RCEs.
 <p>61°NE (T) ● 36°57'56"N, 79°36'20"W ±13ft 09 Aug 2022, 12:26:30</p>		 <p>292°W (T) ● 36°57'53"N, 79°35'46"W ±29ft 09 Aug 2022, 12:45:07</p>	
GPS Location	0	GPS Location	0
Field Station#	15026+00	Field Station#	15054+00
Pic 5 Desc.	Approximately 15026+00. Overview of stream crossing, equipment bridge and ECDs at stream S-D3.	Pic 6 Desc.	Approximately 15054+00. Overview of ROW.

AFE 124300139	Date/Time 8/9/2022 12:56 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/9/2022 12:56 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40783	
Inspector John White		Date/Time 8/9/2022 9:14 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15772+27	
State VA	Inspection Area Full	Station End 15947+64	
County Pittsylvania	Ground Dry	Temperature (°F) 80.00	
Municipality Chatham	Weather Sunny	Rain Gauge (in) 0.00	
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Waterbar	Communication	Repair erosion and stabilize, install (
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Filter Outlet	Acceptable			
Sediment Filter Log	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. No
 - Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? Yes
 - Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? Yes
 - Has a new slip/slide been observed? (If yes, complete Slide Report Form) No

A/E	124300139	Date/Time	8/9/2022 9:14 AM	Report #	40783
------------	-----------	------------------	------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There was one issue identified and added to the punch list. The Contractor is working on repairing the identified issue. Other than that there were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/9/2022 9:14 AM	Report #
Pictures			

AFE 124300139		Date/Time 8/9/2022 9:14 AM		Report #	
Pictures					
GPS Location	O	GPS Location	O		
Field Station#	15846+00	Field Station#	15870+00		
Pic 7 Desc.	Observing temporary stabilization and ECD's	Pic 8 Desc.	Observing temporary stabilization, CWD outlet and ECD's		
				Insert image here	
GPS Location	O	GPS Location	O		
Field Station#	15910+00	Field Station#	15934+00		
Pic 9 Desc.	Observing temporary stabilization, sump and end treatment	Pic 10 Desc.	Observing temporary stabilization, CWD outlet and ECD's		
		Insert image here			
GPS Location	O	GPS Location			
Field Station#	15942+00	Field Station#			
Pic 11 Desc.	Observing erosion at water bar that needs to be repaired and stabilized	Pic 12 Desc.			

AFE 124300139	Date/Time 8/9/2022 9:14 AM	Report #
----------------------	-----------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-603 Pipeline Spread I		AFE 124300139	Spread H-603 Pipeline Spread I
Contractor Precision		Report # 40832	
Inspector John White		Date/Time 8/10/2022 10:36 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	00+00
State VA	Inspection Area Full	Station End	24+53
County Pittsylvania	Ground Dry	Temperature (°F)	84.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/10/2022 10:36 AM	Report #	40832
------------	-----------	------------------	--------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this line. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/10/2022 10:36 AM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	14+00	Field Station#	22+00
-----------------------	-------	-----------------------	-------

Pic 1 Desc.	Observing temporary stabilization and ECD's	Pic 2 Desc.	Observing temporary stabilization and buffer
--------------------	---	--------------------	--



GPS Location	O	GPS Location	O
---------------------	---	---------------------	---

Field Station#	12+00	Field Station#	6+00
-----------------------	-------	-----------------------	------

Pic 3 Desc.	Observing temporary stabilization, sump, end treatment and ECD's	Pic 4 Desc.	Observing temporary stabilization and water bar
--------------------	--	--------------------	---

<p>Insert image here</p>	<p>Insert image here</p>
--------------------------	--------------------------

GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 5 Desc.		Pic 6 Desc.	
--------------------	--	--------------------	--

AFE 124300139	Date/Time 8/10/2022 10:36 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/10/2022 10:36 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 13 Desc.	Pic 14 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 15 Desc.	Pic 16 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40841	
Inspector Justin Burch		Date/Time 8/10/2022 11:20 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15480+67	
State VA	Inspection Area Full	Station End 15584+23	
County Pittsylvania	Ground Damp	Temperature (°F) 90.00	
Municipality Chatham	Weather Sunny	Rain Gauge (in) 1.20	
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Communication			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Cleanwater Diversion Berm	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Equipment Bridge	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/10/2022 11:20 AM	Report # 40841
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15480+67 to 15584+23 (Toshes Road to Anderson Mill Road 1). Five issues were submitted for the punch list which consisted of two locations where perimeter CFS was damaged by a solar farm fencing crew and three locations where CFS was damaged by farm equipment. Other inspected ECDs were observed as being in compliance at the time of inspection.
- The EI observed that the solar farm crews had skid loader forks and fence posts staged on MVP ROW.
- The EI observed that stream water in S-MM8 at 15521+00 was running clear and the water in S-CC5 at 15542+19 was turbid entering the MVP ROW due upstream activities not related to MVP.
- The EI observed that the solar farm ECDs adjacent to the ROW on GAS of Climax Road appeared to be in acceptable condition and that solar farm grading is continuing between Toshes Road and Climax Road.
- The EI did not observe that the contractor has worked in the area since the last SWPPP inspection.
- Since the last SWPPP inspection the inspection area has received one rain event with a total of 1.20" at Snowberry Road.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion.
- At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15482+00 to 15495+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/10/2022 11:20 AM		Report #			
Pictures							
GPS Location		0		GPS Location		0	
Field Station#		15481+00		Field Station#		15494+00	
Pic 1 Desc.		Perimeter CFS damaged by solar farm fencing crew		Pic 2 Desc.		Perimeter CFS damaged by solar farm fencing crew	
GPS Location		0		GPS Location		0	
Field Station#		15494+00		Field Station#		15493+00	
Pic 3 Desc.		Perimeter CFS damaged by farm equipment (south side of the ROW)		Pic 4 Desc.		Perimeter CFS damaged by farm equipment (south side of the ROW)	
GPS Location		0		GPS Location		0	
Field Station#		15491+00		Field Station#		15516+00	
Pic 5 Desc.		Perimeter CFS damaged by farm equipment (south side of the ROW)		Pic 6 Desc.		Waterbar in acceptable condition	

AFE 124300139		Date/Time 8/10/2022 11:20 AM		Report #	
Pictures					
222°SW (T) ● 36.903722°, -79.469595° ±13ft ▲ 859ft 		304°NW (T) ● 36.899935°, -79.463435° ±226ft ▲ 806ft 			
GPS Location 0		GPS Location 0			
Field Station# 15516+00		Field Station# 15538+00			
Pic 7 Desc. Waterbar end treatment in acceptable condition		Pic 8 Desc. Temporary vegetative stabilization in acceptable condition			
302°NW (T) ● 36.898054°, -79.459628° ±13ft ▲ 853ft 		139°SE (T) ● 36.895866°, -79.453191° ±78ft ▲ 754ft 			
GPS Location 0		GPS Location 0			
Field Station# 15552+00		Field Station# 15573+00			
Pic 9 Desc. Clean water diversion berm and temporary vegetative stabilization in acceptable conditions		Pic 10 Desc. P1 silt fence and sensitive resource buffer in acceptable conditions			
49°NE (T) ● 36.903137°, -79.468209° ±337ft ▲ 807ft 		226°SW (T) ● 36.899291°, -79.462428° ±36ft ▲ 774ft 			
GPS Location 0		GPS Location 0			
Field Station# 15521+00		Field Station# 15542+50			
Pic 11 Desc. Stream running clear at S-MM8		Pic 12 Desc. Elevated turbidity in stream S-CC5 due to upstream activities not related to MVP			

AFE 124300139	Date/Time 8/10/2022 11:20 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40850	
Inspector Frank Craycroft		Date/Time 8/10/2022 3:42 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	0+00
State VA	Inspection Area Partial	Station End	0+00
County Franklin	Ground Dry	Temperature (°F)	90.00
Municipality N/A	Weather Light Rain	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Secondary Containment	Acceptable			
Timber Mat	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waste Management	Acceptable			
3rd Party Damages	Communication	3rd party soil stockpile in ANC-006 i		

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | N/A |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/10/2022 3:42 PM	Report # 40850
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired






7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Conducted SWPPP inspection of LY-032, -033, -048, and ANC-006. All perimeter ECDs were functional and in good condition. All stormwater drain inlets had appropriate perimeter protection and were free of loose debris and vegetation. All portable equipment and hazardous materials were maintained within secondary containment. All sites were free of loose debris and waste and on-site dumpsters had adequate additional storage capacity.

At ANC-006, unknown third party has soil stockpile along northwest corner. Stockpile is not stabilized nor is there any perimeter ECDs around it. Thus, during rain event runoff from stockpile is washing some soil across asphalt to Stormwater drain inlet which has perimeter protection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.


AFE	124300139	Date/Time	8/10/2022 3:42 PM	Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	0+00		Field Station#	0+00	
Pic 1 Desc.	LY-032 Rock construction entrance during shower		Pic 2 Desc.	LY-032 Secondary containment	
					
GPS Location	0		GPS Location	0	
Field Station#	0+00		Field Station#	0+00	
Pic 3 Desc.	LY-033 Secondary containment		Pic 4 Desc.	LY-033 Rock construction entrance during shower	
					
GPS Location	0		GPS Location	0	
Field Station#	0+00		Field Station#	0+00	
Pic 5 Desc.	ANC-006 Stormwater drain inlet		Pic 6 Desc.	ANC-006 Third party soil stockpile with runoff during shower	

AFE 124300139	Date/Time 8/10/2022 3:42 PM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	0	GPS Location	0
Field Station#	0+00	Field Station#	0+00
Pic 7 Desc.	LY-048 Temporary stabilization	Pic 8 Desc.	LY-048 South perimeter CFS



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/10/2022 3:42 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40851	
Inspector Frank Craycroft		Date/Time 8/10/2022 3:47 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13748+30	
State VA	Inspection Area Full	Station End 13853+45	
County Franklin	Ground Dry	Temperature (°F) 90.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Communication	SN 13811+90 GAS Brick Church Rd	Addressed	
Plunge Pool	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Communication	SN 13812+10 Replace damaged silt	Addressed	
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/10/2022 3:47 PM	Report # 40851
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired







7. Identify all remedial measures that have been taken since the previous inspection was conducted.





Comments (Reference above questions as appropriate.)

Conducted SWPPP inspection of ROW from Green Level Rd to MVP-FR-303.01. Vegetation was generally good to excellent with predominantly annual grains and self starters. No signs of erosion or washing was observed. Resource buffers in area are well vegetated and intact showing no signs of erosion or sedimentation from ROW. Waterbars and sumps are functioning properly with no signs of erosion within channel or sediment buildup. Equipment bridges at resources are clean and show no signs of sediment accumulation.
 General maintenance is needed on GAS of Brick Church Rd to repair damaged silt fence and remove damaged CFS in fully vegetated borrow ditch. Maintenance was completed today. Otherwise all perimeter ECDs observed were functional and in good condition.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/10/2022 3:47 PM	Report #	
Pictures					
					
GPS Location	0		GPS Location	0	
Field Station#	13812+10		Field Station#	13811+90	
Pic 1 Desc.	Replace damaged silt fence and CFS between Brick Church Rd and private driveway.		Pic 2 Desc.	Remove damaged CFS in borrow ditch	
					
GPS Location	0		GPS Location	0	
Field Station#	13848+00		Field Station#	13840+00	
Pic 3 Desc.	GAS S-C16 Buffer zone Super Silt fence		Pic 4 Desc.	Perimeter Super Silt fence	
					
GPS Location	0		GPS Location	0	
Field Station#	13834+50		Field Station#	13830+00	
Pic 5 Desc.	S-C14 Banks and channel		Pic 6 Desc.	Perimeter CFS	

AFE 124300139		Date/Time 8/10/2022 3:47 PM		Report #	
Pictures					
				<p>ert image here</p>	
GPS Location 0		GPS Location 0			
Field Station# 13815+00		Field Station# 13805+00			
Pic 7 Desc. Cleanwater diversion plunge pool		Pic 8 Desc. CIS S-D18 Travel lane vegetation and buffer zone ECDs			
				<p>ert image here</p>	
GPS Location 0		GPS Location 0			
Field Station# 13801+00		Field Station# 13791+00			
Pic 9 Desc. Sump and J-hook		Pic 10 Desc. S-D23 Banks and channel			
				<p>ert image here</p>	
GPS Location 0		GPS Location 0			
Field Station# 13795+50		Field Station# 13783+50			
Pic 11 Desc. GAS S-D22 Buffer zone and silt fence		Pic 12 Desc. Rock lined Waterbar outlets and CFS			

AFE 124300139		Date/Time 8/10/2022 3:47 PM		Report #	
Pictures					
 <p>GPS: 355°N (T) • 37.069382, -79.933991 ±12ft ▲ 986ft 10 Aug 2022, 10:34:20</p>				 <p>GPS: 306°NW (T) • 37.073363, -79.939676 ±12ft ▲ 983ft 10 Aug 2022, 10:22:56</p>	
GPS Location	0	GPS Location	0	Field Station#	13780+50
Field Station#	13780+50	Field Station#	13756+50	Pic 13 Desc.	CIS S-RR15 Buffer zone ECDs
Pic 13 Desc.	CIS S-RR15 Buffer zone ECDs	Pic 14 Desc.	GAS S-EF12 Buffer zone silt fence and vegetation	Pic 14 Desc.	GAS S-EF12 Buffer zone silt fence and vegetation
 <p>GPS: 328°NW (T) • 37.070578, -79.936963 ±12ft ▲ 1013ft 10 Aug 2022, 10:29:48</p>				 <p>GPS: 298°W (T) • 37.074668, -79.941148 ±12ft ▲ 1018ft 10 Aug 2022, 10:20:12</p>	
GPS Location	0	GPS Location	0	Field Station#	13771+50
Field Station#	13771+50	Field Station#	13750+00	Pic 15 Desc.	GAS S-MM42 Silt fence and buffer zone vegetation
Pic 15 Desc.	GAS S-MM42 Silt fence and buffer zone vegetation	Pic 16 Desc.	GAS Green Level Rd S-EF7 Perimeter silt fence	Pic 16 Desc.	GAS Green Level Rd S-EF7 Perimeter silt fence
Insert image here			Insert image here		
GPS Location		GPS Location		Field Station#	
Field Station#		Field Station#		Pic 17 Desc.	
Pic 17 Desc.		Pic 18 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40846	
Inspector Ben Farmer		Date/Time 8/10/2022 1:18 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14171+36	
State VA	Inspection Area Partial	Station End 14311+57	
County Franklin	Ground Dry	Temperature (°F) 75.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Communication	Equipment bridge sideboard needs t		
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Other - Explain in Comments	Communication	Electric fence/fence gap needs to be		

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/10/2022 1:18 PM	Report # 40846
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 75F)
 Rain Gauge= 0.0"
 14171+36-14311+57


- RCEs are in good condition at all road crossings.
- CWDs are functioning as intended.
- SSF is in good condition
- Fence has been damaged and needs to be repaired at 14205+00.
- Equipment bridge sideboard needs to be reattached at 14213+75.
- P1 is in good condition at all stream and wetland buffers
- Waterbars are in good condition throughout this section.
- Slope drain is in good condition and functioning at 14232+00
- Resource buffers remain well vegetated.
- CFS is in good condition throughout this section
- Topsoil berms remain stabilized

*Issues identified in the field have been added to the punch list to be addressed by the contractor

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/10/2022 1:18 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	14171+36	Field Station#	14180+00
-----------------------	----------	-----------------------	----------

Pic 1 Desc.	RCEs are in good condition at all road crossings	Pic 2 Desc.	CWDs are functioning as intended
--------------------	--	--------------------	----------------------------------



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	14181+00	Field Station#	14190+00
-----------------------	----------	-----------------------	----------







Pic 3 Desc.	SSF is in good condition	Pic 4 Desc.	P1 is in good condition at all stream and wetland buffers
--------------------	--------------------------	--------------------	---



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	14205+00	Field Station#	14213+75
-----------------------	----------	-----------------------	----------

Pic 5 Desc.	Fence needs to be repaired	Pic 6 Desc.	Equipment bridge sideboard needs to be reattached
--------------------	----------------------------	--------------------	---

AFE	124300139	Date/Time	8/10/2022 1:18 PM	Report #	
Pictures					
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14223+41		Field Station#	14232+00	
Pic 7 Desc.	MVP-FR-311 is in good condition with controls in place		Pic 8 Desc.	Slope drain is in good condition and functioning	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14294+00		Field Station#	14300+00	
Pic 9 Desc.	CFS is in good condition		Pic 10 Desc.	Waterbars are in good condition	
					
GPS Location	See photo		GPS Location	See photo	
Field Station#	14300+00		Field Station#	14305+00	
Pic 11 Desc.	End treatments are functioning as intended		Pic 12 Desc.	Topsoil berms remain stabilized	

AFE 124300139	Date/Time 8/10/2022 1:18 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name		H-600 Pipeline Spread I		AFE	124300139	Spread	H-600 Pipeline Spread I	
Contractor		Precision				Report #	40848	
Inspector		Glenn Mike Renfro				Date/Time	8/10/2022 1:56 PM	
Permit #	TBD	Inspection Type	VA SWPP		Station Begin	0000+00		
State	VA	Inspection Area	Full		Station End	0000+00		
County	Franklin	Ground	Wet		Temperature (°F)	75.00		
Municipality	N/A	Weather	Heavy Rain		Rain Gauge (in)	1.25		
					Rain Accumulation Time (days)	6.00		

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Housekeeping	Acceptable			
Other - Explain in Comments	Acceptable	Inlet protection for catch basins		
Rock Construction Entrance	Acceptable			
Compost Filter Sock	Acceptable			
Secondary Containment	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | N/A |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | N/A |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/10/2022 1:56 PM	Report #	40848
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- Performed SWPPP inspections of Spread I laydown yards MVP-LY-045 and MVP-LY-046 in Rocky Mount, Va.
- The locations have received 1.25" of rainfall since the last inspection and site conditions were wet.
- All perimeter ECD's were inspected and no issues were observed.
- The inlet protection for the catch basins at LY-046 were found to be in acceptable condition.
- All secondary containment structures were inspected and no issues were identified at the time of inspection.
- The RCE at LY-045 was in good condition.
- All equipment at both locations were inspected and no leaks were observed the during inspection.
- The General Construction permits and contact information are posted at the entrance of LY-046 as required.
- There ware no problems identified during today's inspection.


Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139	Date/Time 8/10/2022 1:56 PM	Report #
----------------------	------------------------------------	-----------------

Pictures



GPS Location	See picture	GPS Location	See picture
Field Station#	0000+00	Field Station#	0000+00
Pic 1 Desc.	RCE at LY-045 in good condition.	Pic 2 Desc.	Perimeter ECD's on west side of LY-045 near employee parking area.



GPS Location	See picture	GPS Location	See picture
Field Station#	0000+00	Field Station#	0000+00
Pic 3 Desc.	Secondary containment structure on north end of LY-045 in good condition.	Pic 4 Desc.	Equipment inspected at LY-045 no leaks observed during inspection.



GPS Location	See picture	GPS Location	See picture
Field Station#	0000+00	Field Station#	0000+00
Pic 5 Desc.	Perimeter ECD's on south end of LY-046 in good condition.	Pic 6 Desc.	Secondary containment structure for fuel cell at LY-046 in good condition.

AFE 124300139	Date/Time 8/10/2022 1:56 PM	Report #
----------------------	------------------------------------	-----------------


Pictures



GPS Location	See picture	GPS Location	See picture
---------------------	-------------	---------------------	-------------

Field Station#	0000+00	Field Station#	0000+00
-----------------------	---------	-----------------------	---------


Pic 7 Desc.	Inlet protection for catch basin and perimeter ECD's on west side of LY-046 in good condition.	Pic 8 Desc.	Perimeter ECD's on south end of LY-046 in good condition.
--------------------	--	--------------------	---



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 9 Desc.		Pic 10 Desc.	
--------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 11 Desc.		Pic 12 Desc.	
---------------------	--	---------------------	--

AFE 124300139	Date/Time 8/10/2022 1:56 PM	Report #
----------------------	------------------------------------	-----------------

Pictures			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40840	
Inspector Charles Head		Date/Time 8/10/2022 11:11 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15063+85	
State VA	Inspection Area Full	Station End 15142+66	
County Pittsylvania	Ground Dry	Temperature (°F) 86.00	
Municipality Chatham	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/10/2022 11:11 AM	Report # 40840
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/10/2022 11:11 AM	Report #
Pictures			
GPS Location	0	GPS Location	0
Field Station#	15103+45	Field Station#	15098+00
Pic 1 Desc.	Approximately 15103+45. Overview of stream crossing, equipment bridge and ECDs at stream S-G8.	Pic 2 Desc.	Approximately 15098+00. Overview of ROW. Permanent vegetation. Livestock grazing area.
GPS Location	0	GPS Location	0
Field Station#	15092+95	Field Station#	15186+00
Pic 3 Desc.	Approximately 15092+95. Overview of stream crossing, equipment bridge and ECDs at stream S-G9.	Pic 4 Desc.	Approximately 15186+00. Overview of ROW.
GPS Location	0	GPS Location	0
Field Station#	15067+00	Field Station#	15113+50
Pic 5 Desc.	Approximately 15067+00. Overview of ROW.	Pic 6 Desc.	Approximately 15113+50. Overview of road crossing and RCES.

AFE 124300139	Date/Time 8/10/2022 11:11 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/10/2022 11:11 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40797	
Inspector Ben Davenport		Date/Time 8/10/2022 12:50 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14649+67	
State VA	Inspection Area Partial	Station End 14694+77	
County Franklin	Ground Damp	Temperature (°F) 88.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Vegetative Stabilization (Permanent)	Acceptable			
Equipment Bridge	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Sediment Filter Log	Acceptable			
Compost Filter Sock	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Rock Construction Entrance	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/10/2022 12:50 PM	Report # 40797
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

-Available for work
 -Received instruction from Lead EI for daily tasks
 -Sunny with damp ground conditions during inspection
 -Performed SWPPP inspection on portion of MVP Spread I section
 -Covered territory between station# 14649+67 — 14694+77 (Hwy 40 crossing to Jacks Creek Rd)
 -Walked ROW making note of condition of ROW and environmental controls
 -Verified the completion and accuracy of punch list items in covered area from previous inspections
 -Perimeter controls and ECDs were inspected; no issues identified
 -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified
 -Inspection observed condition of RCEs and culverts in section; no issues identified
 -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
 -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
 -Continue to monitor ROW for signs of erosion
 -No items added to environmental punch list in section

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/10/2022 12:50 PM	Report #	
------------	-----------	------------------	--------------------	-----------------	--

Pictures



GPS Location	1	GPS Location	2
Field Station#	14654+00	Field Station#	14656+87
Pic 1 Desc.	ROW stabilized and vegetated in final cleanup area.	Pic 2 Desc.	Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.



GPS Location	3	GPS Location	4
Field Station#	14669+50	Field Station#	14683+00
Pic 3 Desc.	ROW stabilized and vegetated in temporary area; perimeter controls in place and functional.	Pic 4 Desc.	Sump pit and CFS end treatment performing intended functions.



GPS Location	5	GPS Location	6
Field Station#	14692+00	Field Station#	14694+77
Pic 5 Desc.	Water bars performing intended functions.	Pic 6 Desc.	RCE at Jacks Creek Rd in good condition.

AFE 124300139	Date/Time 8/10/2022 12:50 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/10/2022 12:50 PM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40838	
Inspector John White		Date/Time 8/10/2022 10:57 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15947+64	
State VA	Inspection Area Full	Station End 16027+46	
County Pittsylvania	Ground Dry	Temperature (°F) 85.00	
Municipality Chatham	Weather Sunny	Rain Gauge (in) 0.00	
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Berm	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Communication	Repair erosion and stabilize		

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/10/2022 10:57 AM	Report #	40838
------------	-----------	------------------	--------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)


Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. The Contractor is working on repairing the identified issues. Other than that there were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.


AFE	124300139	Date/Time	8/10/2022 10:57 AM	Report #	
Pictures					
	 <p>127°SE (T) ● 36°49'59"N, 79°21'34"W ±13175ft ▲ 603ft</p>		 <p>225°SW (T) ● 36°49'55"N, 79°21'32"W ±114ft ▲ 656ft</p>		
GPS Location	O	GPS Location	O		
Field Station#	15966+00	Field Station#	15970+00		
Pic 1 Desc.	Observing temporary stabilization, erosion control blanket, water bar and CFS check	Pic 2 Desc.	Observing temporary stabilization and CWD berm		
	 <p>226°SW (T) ● 36°49'50"N, 79°21'26"W ±170ft ▲ 641ft</p>		 <p>175°S (T) ● 36°49'47"N, 79°21'20"W ±78ft ▲ 642ft</p>		
GPS Location	O	GPS Location	O		
Field Station#	15977+35	Field Station#	15982+00		
Pic 3 Desc.	Observing temporary stabilization, water bar, equipment crossing and ECD's	Pic 4 Desc.	Observing CWD outlet and ECD's		
	 <p>201°S (T) ● 36°49'44"N, 79°21'15"W ±101ft ▲ 638ft</p>		 <p>10°N (T) ● 36°49'43"N, 79°21'13"W ±1450ft ▲ 638ft</p>		
GPS Location	O	GPS Location	O		
Field Station#	15987+31	Field Station#	15987+00		
Pic 5 Desc.	Observing temporary stabilization, water bar, erosion control blanket, cfs check, equipment crossing, buffer and ECD's	Pic 6 Desc.	Observing erosion that needs to be repaired and stabilized		

AFE 124300139	Date/Time 8/10/2022 10:57 AM	Report #
----------------------	-------------------------------------	-----------------


Pictures



GPS Location	O	GPS Location	O
Field Station#	15995+00	Field Station#	15999+80
Pic 7 Desc.	Observing erosion that needs to be repaired and stabilized	Pic 8 Desc.	Observing temporary stabilization, signage, buffer and ECD's



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	



GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/10/2022 10:57 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 13 Desc.	Pic 14 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 15 Desc.	Pic 16 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40890	
Inspector Justin Burch		Date/Time 8/11/2022 11:57 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15142+66
State VA	Inspection Area Full	Station End	15260+00
County Pittsylvania	Ground Damp	Temperature (°F)	81.00
Municipality Chatham	Weather Cloudy	Rain Gauge (in)	1.20
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Vegetative Stabilization (Permanent)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Sump Pit	Acceptable			
Slope Drain Pipe	Acceptable			
Rock Construction Entrance	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/11/2022 11:57 AM	Report # 40890
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15142+66 to 15260+00 (Rock Creek Road to the Pigg River HDD Exit). No issues were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection.
- The EI did not observe any contractor activity in the area since the last SWPPP inspection.
- Since the last SWPPP inspection the area has received one rain event with a total of 1.20" at Snowberry Road.
- The ROW ground condition is damp.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion
- At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15145+00 to 15153+00 and from 15173+00 to 15260+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/11/2022 11:57 AM		Report #	
Pictures					
GPS Location		0		GPS Location	
Field Station#		15194+00		Field Station#	
Pic 1 Desc.		CFS checks in acceptable condition		Pic 2 Desc.	
				Waterbar in acceptable condition	
GPS Location		0		GPS Location	
Field Station#		15192+00		Field Station#	
Pic 3 Desc.		Waterbar end treatment in acceptable condition		Pic 4 Desc.	
				Permanent vegetative stabilization in acceptable condition	
GPS Location		0		GPS Location	
Field Station#		15171+00		Field Station#	
Pic 5 Desc.		Waterbar in acceptable condition		Pic 6 Desc.	
				Waterbar end treatment in acceptable condition	

AFE 124300139		Date/Time 8/11/2022 11:57 AM		Report #	
Pictures					
337°NW (T) ● 36.943613°, -79.570578° ±13ft ▲ 790ft  15170+00 08-11-2022, 10:27:50			312°NW (T) ● 36.934544°, -79.544361° ±344ft ▲ 786ft  15255+00 08-11-2022, 11:20:51		
GPS Location 0			GPS Location 0		
Field Station# 15170+00			Field Station# 15255+00		
Pic 7 Desc. Temporary vegetative stabilization in acceptable condition			Pic 8 Desc. Permanent vegetative stabilization in acceptable condition		
166°S (T) ● 36.945163°, -79.573900° ±26ft ▲ 786ft  15162+00 08-11-2022, 11:49:15			79°E (T) ● 36.945625°, -79.574824° ±167ft ▲ 799ft  15159+00 08-11-2022, 11:44:55		
GPS Location 0			GPS Location 0		
Field Station# 15162+00			Field Station# 15159+00		
Pic 9 Desc. P1 silt fence in acceptable condition			Pic 10 Desc. Temporary vegetative stabilization in acceptable condition		
185°S (T) ● 36.943693°, -79.571321° ±13ft ▲ 731ft  15169+00 08-11-2022, 11:55:28			151°SE (T) ● 36.948109°, -79.578543° ±229ft ▲ 886ft  15142+75 08-11-2022, 12:09:23		
GPS Location 0			GPS Location 0		
Field Station# 15169+00			Field Station# 15142+75		
Pic 11 Desc. Sump pit and slope drain pipe in acceptable conditions			Pic 12 Desc. Rock construction entrance in acceptable condition		

AFE 124300139	Date/Time 8/11/2022 11:57 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40892	
Inspector Ben Farmer		Date/Time 8/11/2022 12:19 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13853+45	
State VA	Inspection Area Partial	Station End 13958+31	
County Franklin	Ground Damp	Temperature (°F) 70.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.60	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Communication	Access road needs additional stone		
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Communication	Area needs to be restabilized.		

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/11/2022 12:19 PM	Report # 40892
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP Inspection (Cloudy, 70F)
 Rain Gauge= 0.6"
 13853+45-13958+31

- MVP-FR-303.01 needs additional stone. (13852+46)
- Resource buffers remain well vegetated at all stream and wetland crossings.
- CWDs are in good condition and functioning as intended
- Equipment bridge ECDs are in good condition and functioning.
- CFS is in good condition throughout this section.
- Steep slope at 13889+00 remains stabilized.
- ROW needs additional stabilization at 13892+45.
- P1 is in good condition at all stream and wetland buffers.
- Topsoil berms remain stabilized.
- Sediment trap at 13897+00 is in good condition with no evidence of discharge.
- Waterbars/end treatments are in good condition.
- Slope drain is functioning at 13955+00.

*Issues identified in the field have been added to the punch list to be addressed by the contractor.


Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/11/2022 12:19 PM		Report #	
Pictures					
GPS Location	See photo		GPS Location	See photo	
Field Station#	13852+46		Field Station#	13863+00	
Pic 1 Desc.	MVP-FR-303.01 needs additional stone		Pic 2 Desc.	Resource buffers remain well vegetated	
GPS Location	See photo		GPS Location	See photo	
Field Station#	13875+73		Field Station#	13876+00	
Pic 3 Desc.	Equipment bridge ECDs are functioning as intended		Pic 4 Desc.	P1 is in good condition at all stream and wetland buffers	
GPS Location	See photo		GPS Location	See photo	
Field Station#	13888+00		Field Station#	13943+00	
Pic 5 Desc.	Slope drain is in good condition and functioning		Pic 6 Desc.	Topsoil berms remain stabilized	

AFE	124300139	Date/Time	8/11/2022 12:19 PM	Report #	
Pictures					
GPS Location	See photo	GPS Location	See photo		
Field Station#	13892+45	Field Station#	13897+00		
Pic 7 Desc.	Restabilized denuded area	Pic 8 Desc.	Sediment trap is functioning as intended		
GPS Location	See photo	GPS Location	See photo		
Field Station#	13907+00	Field Station#	13942+00		
Pic 9 Desc.	CFS is in good condition throughout this section	Pic 10 Desc.	CWDs are functioning as intended		
GPS Location	See photo	GPS Location	See photo		
Field Station#	13947+00	Field Station#	13953+00		
Pic 11 Desc.	SSF is in good condition	Pic 12 Desc.	Slope drain outlet is in good condition and functioning		

AFE 124300139	Date/Time 8/11/2022 12:19 PM	Report #
----------------------	-------------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	
---------------------	-----------	---------------------	--

Field Station#	13955+00	Field Station#	
-----------------------	----------	-----------------------	--


Pic 13 Desc.	Waterbars are in good condition	Pic 14 Desc.	
---------------------	---------------------------------	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 15 Desc.		Pic 16 Desc.	
---------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 17 Desc.		Pic 18 Desc.	
---------------------	--	---------------------	--



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40853	
Inspector Ben Davenport		Date/Time 8/11/2022 1:45 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14311+57	
State VA	Inspection Area Partial	Station End 14454+22	
County Franklin	Ground Damp	Temperature (°F) 78.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.10	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Equipment Bridge	Acceptable			
Sediment Filter Log	Acceptable			
Sensitive Resource Buffer	Acceptable			
Erosion Control Blanket	Acceptable			
Rock-lined Channel	Acceptable			
Plunge Pool	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/11/2022 1:45 PM	Report # 40853
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

-Available for work
 -Received instruction from Lead EI for daily tasks
 -Checked rain gauges in covered area
 -Cloudy with damp ground conditions during inspection
 -Performed SWPPP inspection on portion of MVP Spread I section
 -Covered territory between station# 14311+57 — 14454+22 (Farm View Rd to Webster Rd)
 -Walked ROW making note of condition of ROW and environmental controls
 -Verified the completion and accuracy of punch list items in covered area from previous inspections
 -Perimeter controls and ECD's were inspected; no issues identified
 -Inspection observed condition of equipment bridges and surrounding ECD's around stream crossings and resource buffers; no issues identified
 -Inspection observed condition of RCEs and culverts in section; no issues identified
 -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
 -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
 -Continue to monitor ROW for signs of erosion
 -No items added to environmental punch list

-Rain Gauge Totals:
 +Farm View: 0.10 inches recorded
 +Timber Ridge: 0.10 inches recorded

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/11/2022 1:45 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location 1	GPS Location 2
Field Station# 14314+79	Field Station# 14316+00
Pic 1 Desc. Equipment bridge and surrounding ECDs in place and functional at stream crossing and resource buffer.	Pic 2 Desc. Erosion control blanket in throat of water bar performing intended function.



GPS Location 3	GPS Location 4
Field Station# 14401+00	Field Station# 14410+00
Pic 3 Desc. Rock lined channel in good condition.	Pic 4 Desc. Plunge pool performing intended function.



GPS Location 5	GPS Location 6
Field Station# 14417+00	Field Station# 14426+00
Pic 5 Desc. Slope drain pipe performing intended function.	Pic 6 Desc. Sump pit and CFS end treatment performing intended functions.

AFE 124300139	Date/Time 8/11/2022 1:45 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/11/2022 1:45 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40900	
Inspector Charles Head		Date/Time 8/11/2022 1:37 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14694+77	
State VA	Inspection Area Full	Station End 14802+19	
County Franklin	Ground Damp	Temperature (°F) 81.00	
Municipality N/A	Weather Cloudy	Rain Gauge (in) 0.25	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/11/2022 1:37 PM	Report # 40900
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/11/2022 1:37 PM	Report #
Pictures			
GPS Location	0	GPS Location	0
Field Station#	14788+77	Field Station#	14766+11
Pic 1 Desc.	Approximately 14788+77. Overview of stream crossing, equipment bridge and ECDs at stream S-H25.	Pic 2 Desc.	Approximately 14766+11. Overview of stream crossing, equipment bridge and ECDs at stream S-MM44.
GPS Location	0	GPS Location	0
Field Station#	14757+75	Field Station#	14729+19
Pic 3 Desc.	Approximately 14757+75. Overview of road crossing and RCEs.	Pic 4 Desc.	Approximately 14729+19. Overview of stream crossing, equipment bridge and ECDs at stream S-A20.
GPS Location	0	GPS Location	0
Field Station#	14744+00	Field Station#	14701+00
Pic 5 Desc.	Approximately 14744+00. Overview of ROW.	Pic 6 Desc.	Approximately 14701+00. Overview of ROW.

AFE 124300139		Date/Time 8/11/2022 1:37 PM		Report #	
Pictures					
GPS Location	0	GPS Location	0		
Field Station#	14758+00	Field Station#	14718+00		
Pic 7 Desc.	Approximately 14758+00. Overview of bar ditch. Third party moving has taken place along Indian Cave Road.		Pic 8 Desc.	Approximately 14718+00. Landowner adjacent to ROW is stockpiling fill/soil directly uphill of wetland W-H11.	
GPS Location	0	GPS Location	0		
Field Station#	14716+50	Field Station#	14716+50		
Pic 9 Desc.	Approximately 14716+50. Sediment and debris continue to accumulate at the north side of wetland W-H11. Fill/dirt described in previous		Pic 10 Desc.	Approximately 14716+50. Sediment and debris continue to accumulate at the north side of wetland W-H11.	
Insert image here			Insert image here		
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

A/E	124300139	Date/Time	8/11/2022 1:37 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40876	
Inspector John White		Date/Time 8/11/2022 9:12 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15584+23	
State VA	Inspection Area Full	Station End 15647+03	
County Pittsylvania	Ground Wet	Temperature (°F) 74.00	
Municipality Chatham	Weather Light Rain	Rain Gauge (in) 0.10	
Rain Accumulation Time (days)			6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/11/2022 9:12 AM	Report # 40876
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)







PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. Checked rain gauges, Anderson Mill #2=.10", Mill Creek =.10", Transco =.9". There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/11/2022 9:12 AM	Report #	
Pictures					
					
GPS Location	O	GPS Location	O		
Field Station#	15616+00	Field Station#	15614+94		
Pic 1 Desc.	Observing temporary stabilization, sump and end treatment	Pic 2 Desc.	Observing temporary stabilization, signage, buffer, equipment crossing and ECD's		
					
GPS Location	O	GPS Location	O		
Field Station#	15610+00	Field Station#	15623+00		
Pic 3 Desc.	Observing temporary stabilization	Pic 4 Desc.	Observing temporary stabilization and water bars		
					
GPS Location	O	GPS Location	O		
Field Station#	15625+00	Field Station#	15647+03		
Pic 5 Desc.	Observing temporary stabilization, CWD outlet and ECD's	Pic 6 Desc.	Observing road crossing and RCE's		

AFE	124300139	Date/Time	8/11/2022 9:12 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/11/2022 9:12 AM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40948	
Inspector Justin Burch		Date/Time 8/12/2022 11:37 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	15260+00
State VA	Inspection Area Full	Station End	15370+62
County Pittsylvania	Ground Damp	Temperature (°F)	79.00
Municipality Chatham	Weather Cloudy	Rain Gauge (in)	0.00
Rain Accumulation Time (days)			4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Plunge Pool	Acceptable			
Cleanwater Diversion Pipe	Acceptable			
Waterbar	Acceptable			
Waterbar End Treatment	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/12/2022 11:37 AM	Report # 40948
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		







7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

- The EI performed a SWPPP inspection from 15260+00 to 15370+62 (Pigg River HDD Exit to Snowberry Road). No items were submitted for the punch list due to the inspected ECDs being in compliance at the time of inspection.
- The EI did not observe any contractor activity in the area since the last SWPPP inspection.
- Since the last SWPPP inspection the inspection area has not received any rainfall.
- The ROW ground condition is damp.
- At the time of inspection temporary vegetative stabilization was adequately established to inhibit erosion.
- At the time of inspection permanent vegetative stabilization was adequately established to inhibit erosion from 15355+00 to 15370+00.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/12/2022 11:37 AM		Report #			
Pictures							
GPS Location		0		GPS Location		0	
Field Station#		15360+00		Field Station#		15338+00	
Pic 1 Desc.		CFS and equipment bridge in acceptable conditions		Pic 2 Desc.		Plunge pool and clean water diversion pipe in acceptable conditions	
GPS Location		0		GPS Location		0	
Field Station#		15343+00		Field Station#		15343+00	
Pic 3 Desc.		Waterbar in acceptable condition		Pic 4 Desc.		Waterbar end treatment in acceptable condition	
GPS Location		0		GPS Location		0	
Field Station#		15345+00		Field Station#		15313+00	
Pic 5 Desc.		Super silt fence in acceptable condition		Pic 6 Desc.		P1 silt fence in acceptable condition	

AFE 124300139		Date/Time 8/12/2022 11:37 AM		Report #	
Pictures					
					
GPS Location 0		GPS Location 0			
Field Station# 15311+00		Field Station# 15311+00			
Pic 7 Desc. Waterbar in acceptable condition		Pic 8 Desc. Waterbar end treatment in acceptable condition			
					
GPS Location 0		GPS Location 0			
Field Station# 15311+00		Field Station# 15304+00			
Pic 9 Desc. Waterbar end treatment in acceptable condition		Pic 10 Desc. Temporary vegetative stabilization in acceptable condition			
					
GPS Location 0		GPS Location 0			
Field Station# 15311+50		Field Station# 15346+00			
Pic 11 Desc. Temporary vegetative stabilization in acceptable condition		Pic 12 Desc. P1 silt fence in acceptable condition			

AFE 124300139	Date/Time 8/12/2022 11:37 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures			
-----------------	--	--	--

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40947	
Inspector Ben Farmer		Date/Time 8/12/2022 11:30 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 13958+31	
State VA	Inspection Area Partial	Station End 14062+17	
County Franklin	Ground Damp	Temperature (°F) 70.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Slope Drain Pipe	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/12/2022 11:30 AM	Report # 40947
----------------------	-------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation remains in go		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.







Comments (Reference above questions as appropriate.)

SWPPP Inspection (Sunny, 70F)
 Rain Gauge= 0.0"
 13958+31-14062+17

- This section remains stabilized.
- CWD/CWD inlets are in good condition and functioning as intended
- Equipment bridge ECDs are in good condition
- MVP-ATWS-1446 remains stabilized with controls in place.
- P1 is in good condition at all stream and wetland buffers.
- No evidence of 3rd party pond discharging onto ROW at 14000+00
- Resource buffers remain well vegetated.
- Slope on the CIS of Highway 220 remains stabilized with controls in place.
- Waterbars/end treatments are functioning as intended.
- CFS is in good condition
- Slope drain is functioning as intended at 14058+00
- Rock check dams are functioning at 14059+00.
- Vegetation continues to fill in throughout this section

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/12/2022 11:30 AM	Report #
Pictures			
GPS Location	See photo	GPS Location	See photo
Field Station#	13960+00	Field Station#	13970+00
Pic 1 Desc.	CWDs are functioning as intended	Pic 2 Desc.	Topsoil berms remain stabilized
GPS Location	See photo	GPS Location	See photo
Field Station#	13997+50	Field Station#	13998+15
Pic 3 Desc.	P1 is in good condition at all stream and wetland buffers	Pic 4 Desc.	Equipment bridge ECDs are in good condition and functioning
GPS Location	See photo	GPS Location	See photo
Field Station#	14000+00	Field Station#	14009+11
Pic 5 Desc.	No evidence of 3rd party pond discharging onto ROW	Pic 6 Desc.	SSF is in good condition

AFE	124300139	Date/Time	8/12/2022 11:30 AM	Report #	
Pictures					
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14018+47	Field Station#	14027+00		
Pic 7 Desc.	RCEs are in good condition at all road crossings	Pic 8 Desc.	CFS is in good condition throughout this section		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14033+00	Field Station#	14033+00		
Pic 9 Desc.	Waterbars are in good condition	Pic 10 Desc.	End treatments are functioning as intended		
					
GPS Location	See photo	GPS Location	See photo		
Field Station#	14035+00	Field Station#	14050+00		
Pic 11 Desc.	Resource buffers remain well vegetated	Pic 12 Desc.	Slope remains stabilized with controls in place		

AFE 124300139	Date/Time 8/12/2022 11:30 AM	Report #
----------------------	-------------------------------------	-----------------


Pictures



GPS Location	See photo	GPS Location	See photo
---------------------	-----------	---------------------	-----------

Field Station#	14057+00	Field Station#	14060+00
-----------------------	----------	-----------------------	----------


Pic 13 Desc.	Slope drain outlet is in good condition	Pic 14 Desc.	Rock check dams are functioning as intended
---------------------	---	---------------------	---



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 15 Desc.		Pic 16 Desc.	
---------------------	--	---------------------	--



GPS Location		GPS Location	
---------------------	--	---------------------	--

Field Station#		Field Station#	
-----------------------	--	-----------------------	--

Pic 17 Desc.		Pic 18 Desc.	
---------------------	--	---------------------	--



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40898	
Inspector Ben Davenport		Date/Time 8/12/2022 1:24 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14454+22	
State VA	Inspection Area Partial	Station End 14546+75	
County Franklin	Ground Dry	Temperature (°F) 77.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 0.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Cleanwater Diversion Pipe	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Silt Fence (Reinforced Filter Fabric Fence)	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Plunge Pool	Acceptable			
Waterbar	Acceptable			
Compost Filter Sock	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent Vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

-Available for work
 -Received instruction from Lead EI for daily tasks
 -Sunny with dry ground conditions during inspection
 -Performed SWPPP inspection on portion of MVP Spread I section
 -Covered territory between station# 14454+22 — 14546+75 (Webster Rd to Tobacco Rd)
 -Precision environmental crew in section during inspection
 -Walked ROW making note of condition of ROW and environmental controls
 -Verified the completion and accuracy of punch list items in covered area from previous inspections
 -Perimeter controls and ECDs were inspected; no issues identified
 -Inspection observed condition of equipment bridges and surrounding ECDs around stream crossings and resource buffers; no issues identified
 -Inspection observed condition of RCEs and culverts in section; no issues identified
 -Inspection observed condition of water bars, sumps, and end treatments along ROW; no issues identified
 -Inspection observed condition of temporary stabilization and vegetation in section; no issues identified
 -Continue to monitor ROW for signs of erosion
 -No items added to environmental punch list in section

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139	Date/Time	8/12/2022 1:24 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures



GPS Location	1	GPS Location	2
Field Station#	14506+00	Field Station#	14517+00
Pic 1 Desc.	CWD pipe in good condition.	Pic 2 Desc.	Perimeter SSF in place and functional.



GPS Location	3	GPS Location	4
Field Station#	14521+00	Field Station#	14533+00
Pic 3 Desc.	Travel lane recently seeded and stabilized.	Pic 4 Desc.	Plunge pool performing intended function.



GPS Location	5	GPS Location	6
Field Station#	14534+00	Field Station#	14545+83
Pic 5 Desc.	Water bar performing intended function; ROW stabilized and vegetated in temporary area.	Pic 6 Desc.	Sensitive resource buffer and signage visible and intact. P1 silt fence in good condition.

AFE 124300139	Date/Time 8/12/2022 1:24 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/12/2022 1:24 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40958	
Inspector Charles Head		Date/Time 8/12/2022 2:39 PM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 14802+19	
State VA	Inspection Area Full	Station End 14928+52	
County Franklin	Ground Dry	Temperature (°F) 77.00	
Municipality N/A	Weather Sunny	Rain Gauge (in) 0.00	
			Rain Accumulation Time (days) 1.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Rock Construction Entrance	Acceptable			
Sensitive Resource Buffer	Acceptable			
Sensitive Resource Signage	Acceptable			
Silt Fence (Filter Fabric Fence)	Acceptable			
Silt Fence (Reinforce Filter Fence)	Acceptable			
Waterbar	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE 124300139	Date/Time 8/12/2022 2:39 PM	Report # 40958
----------------------	------------------------------------	-----------------------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Other	Acceptable	Permanent vegetation		

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

SWPPP inspection of Spread I. Inspection was conducted of LOD and resource boundary ECDs, resources, road crossings, RCEs, water bars, sumps, end treatments, CWDs, stabilization and seeding activities, and general ROW conditions. BMPs listed above. Seeding and stabilization practices are progressing. Contractor has addressed and continues to address maintenance issues. Streams running clean and clear of sediment at time of inspection. No maintenance issues observed during inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/12/2022 2:39 PM	Report #
Pictures			
GPS Location	0	GPS Location	0
Field Station#	14812+00	Field Station#	14845+68
Pic 1 Desc.	Approximately 14812+00. Overview of ROW. Permanent vegetation.	Pic 2 Desc.	Approximately 14845+68. Overview of road crossing and RCEs.
GPS Location	0	GPS Location	0
Field Station#	14916+11	Field Station#	14888+69
Pic 3 Desc.	Approximately 14916+11. Overview of stream crossing, equipment bridge and ECDs at stream S-G16.	Pic 4 Desc.	Approximately 14888+69. Overview of stream crossing, equipment bridge and ECDs at stream S-AB8.
GPS Location	0	GPS Location	0
Field Station#	14900+00	Field Station#	14832+80
Pic 5 Desc.	Approximately 14900+00. Overview of ROW.	Pic 6 Desc.	Approximately 14832+80. Overview of stream crossing, equipment bridge and ECDs at stream S-A11.

A/E	124300139	Date/Time	8/12/2022 2:39 PM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300139	Date/Time 8/12/2022 2:39 PM	Report #
----------------------	------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 13 Desc.	Pic 14 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 15 Desc.	Pic 16 Desc.

Insert image here	Insert image here
-------------------	-------------------

GPS Location	GPS Location
Field Station#	Field Station#
Pic 17 Desc.	Pic 18 Desc.



Visual Site Inspection Report

Project Name H-600 Pipeline Spread I		AFE 124300139	Spread H-600 Pipeline Spread I
Contractor Precision		Report # 40936	
Inspector John White		Date/Time 8/12/2022 8:26 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin 15647+03	
State VA	Inspection Area Full	Station End 15772+27	
County Pittsylvania	Ground Damp	Temperature (°F) 74.00	
Municipality Chatham	Weather Cloudy	Rain Gauge (in) 0.10	
			Rain Accumulation Time (days) 4.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Silt Fence (Filter Fabric Fence)	Communication	Perform maintenance		
Waterbar	Communication	Seed and stabilize		
Cleanwater Diversion Pipe	Acceptable			
Compost Filter Sock	Acceptable			
Equipment Bridge	Acceptable			
Housekeeping	Acceptable			
Rock Construction Entrance	Acceptable			
Rock Filter Outlet	Acceptable			
Sensitive Resource Buffer	Acceptable			

- 5. Site Conditions**
- | | |
|---|-----|
| Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator. | No |
| Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? | Yes |
| Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? | Yes |
| Has a new slip/slide been observed? (If yes, complete Slide Report Form) | No |

AFE	124300139	Date/Time	8/12/2022 8:26 AM	Report #	40936
------------	-----------	------------------	-------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on this section. There were issues identified and added to the punch list. Other than that there were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300139		Date/Time 8/12/2022 8:26 AM	Report #
Pictures			
GPS Location	O	GPS Location	O
Field Station#	15652+00	Field Station#	15656+00
Pic 1 Desc.	Observing temporary stabilization and water bar	Pic 2 Desc.	Observing end of water bar that needs to be seeded and stabilized
GPS Location	O	GPS Location	O
Field Station#	15660+00	Field Station#	15665+50
Pic 3 Desc.	Observing end of water bar that needs to be seeded and stabilized	Pic 4 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's
GPS Location	O	GPS Location	O
Field Station#	15674+00	Field Station#	15676+00
Pic 5 Desc.	Observing temporary stabilization	Pic 6 Desc.	Observing temporary stabilization,CWD outlet and ECD's

AFE 124300139		Date/Time 8/12/2022 8:26 AM		Report #	
Pictures					
 360°N (T) ● 36°53'0"N, 79°25'32"W ±6440ft ▲ 724ft  <small>Your Watermark 12 Aug 2022, 08:08:06</small>		 93°E (T) ● 36°52'53"N, 79°25'22"W ±13ft ▲ 796ft  <small>Your Watermark 12 Aug 2022, 08:11:56</small>		Insert image here	
GPS Location	O	GPS Location	O		
Field Station#	15682+00	Field Station#	15688+00		
Pic 7 Desc.	Observing temporary stabilization and water bars	Pic 8 Desc.	Observing P1 that requires maintenance		
 17°N (T) ● 36°52'40"N, 79°24'44"W ±6007ft ▲ 793ft  <small>Your Watermark 12 Aug 2022, 08:15:12</small>		 347°N (T) ● 36°52'48"N, 79°25'18"W ±1282ft ▲ 828ft  <small>Your Watermark 12 Aug 2022, 08:16:23</small>		Insert image here	
GPS Location	O	GPS Location	O		
Field Station#	15693+89	Field Station#	15700+40		
Pic 9 Desc.	Observing road crossing and RCE's	Pic 10 Desc.	Observing temporary stabilization,buffer, equipment crossing and ECD's		
Insert image here		Insert image here			
GPS Location		GPS Location			
Field Station#		Field Station#			
Pic 11 Desc.		Pic 12 Desc.			

AFE	124300139	Date/Time	8/12/2022 8:26 AM	Report #	
------------	-----------	------------------	-------------------	-----------------	--

Pictures					
-----------------	--	--	--	--	--

Insert image here			Insert image here		
-------------------	--	--	-------------------	--	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here		Insert image here	
-------------------	--	-------------------	--

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	



Visual Site Inspection Report

Project Name Transco Interconnect Station		AFE 124300113	Spread Transco Interconnect Sta
Contractor Kanahwa		Report # 40835	
Inspector John White		Date/Time 8/10/2022 10:46 AM	
Permit # TBD	Inspection Type VA SWPP	Station Begin	00+00
State VA	Inspection Area Full	Station End	00+00
County Pittsylvania	Ground Dry	Temperature (°F)	85.00
Municipality Chatham	Weather Sunny	Rain Gauge (in)	0.00
			Rain Accumulation Time (days) 6.00

1. Are the approved (stamped) E&S Plan and PCSM Plan present on site? Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.) No
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.) Yes
4. **E&S BMPs** (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

E&S BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
Housekeeping	Acceptable			
Rock Check Dam	Acceptable			
Rock Filter	Acceptable			
Sediment Basin	Acceptable			
Vegetative Stabilization (Temporary)	Acceptable			
Compost Filter Sock	Acceptable			

5. Site Conditions

Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.	No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?	Yes
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?	Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)	No

AFE	124300113	Date/Time	8/10/2022 10:46 AM	Report #	40835
------------	-----------	------------------	--------------------	-----------------	-------

6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)

PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired

7. Identify all remedial measures that have been taken since the previous inspection was conducted.

Comments (Reference above questions as appropriate.)

Performed SWPPP Inspection on the Transco Facility and Lay down yard. There were no issues to report at the time of Inspection.

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE 124300113		Date/Time 8/10/2022 10:46 AM		Report #	
Pictures					
GPS Location O		GPS Location O			
Field Station# 00+00		Field Station# 00+00			
Pic 1 Desc. Observing RCE		Pic 2 Desc. Observing temporary stabilization and rock check dams			
GPS Location O		GPS Location O			
Field Station# 00+00		Field Station# 00+00			
Pic 3 Desc. Observing temporary stabilization and rock drain		Pic 4 Desc. Observing temporary stabilization and sediment basin			
GPS Location O		GPS Location O			
Field Station# 00+00		Field Station# 00+00			
Pic 5 Desc. Observing temporary stabilization and sediment basin		Pic 6 Desc. Observing lay down yard			

AFE 124300113	Date/Time 8/10/2022 10:46 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 7 Desc.		Pic 8 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 9 Desc.		Pic 10 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 11 Desc.		Pic 12 Desc.	

AFE 124300113	Date/Time 8/10/2022 10:46 AM	Report #
----------------------	-------------------------------------	-----------------

Pictures

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 13 Desc.		Pic 14 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 15 Desc.		Pic 16 Desc.	

Insert image here	Insert image here
-------------------	-------------------

GPS Location		GPS Location	
Field Station#		Field Station#	
Pic 17 Desc.		Pic 18 Desc.	