			Visual Site Inspection Report									
Project Nan	ne H-600 Pipe	eline Spread G		A	FE	12430	0137	Spr	read	H-600 Pipelir	ie Sp	oread G
Contract	or Precision			•				Repo	ort #	8029		
Inspect	or Clinton Ba	nks						Date/T	ime	9/18/2018	7:35	5 AM
Permit #	TBD		Inspection	Туре	VA	SWPP		Station	n Beg	j <b>in</b> +28		
State	VA		Inspection	Area	Full			Stati	on Ei	nd +26		
County	Giles		Gro	ound	We	t		1	Гетр	erature (º	F)	67.00
Municipality	N/A		Wea	ather	Clo	udy			Rain	n Gauge (i	n)	0.10
GPS Location	37.334237583	80164, -80.802	8947190203				Rain Ac	cumula	tion	Time (day	s)	1.00
1. Are the appro	oved (stampe	d) E&S Plan	and PCSM Pla	an pre	sent	t on sit	e?					Yes
2. Are there act (If yes, notify		-	the limits of di ermitting Coor				•		-	2		No
<b>3.</b> Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							)	Yes				
4. E&S BMPs ( is required.)	(List BMPs and	d note if insta	Illed and maint	ained	as	per the	e plan. If c	corrective	e acti	on is need	ed,	a picture
E&S BMPs		C	Compliance Level	Corrective Action					rective Frame	R	Date epaired	
Safety Fence		Acc	ceptable									
Compost Filter Sock		Acc	ceptable									
Housekeeping		Acc	Acceptable									
Rock Construction Entrance		Acc	Acceptable									
Fuel Containment		Acc	Acceptable									
Compost Filter Sock		Acc	ceptable									
Housekeeping		Acc	ceptable									
Rock Construction Entrance		Acc	ceptable									
5. Site Conditi	ons											
Is an unauthoriz beyond defined a photo and imn	limits of distu	rbance resulti	ing from earth	distur	ban	ce acti	vity or inef	-				No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?								Yes				
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?								Yes				
Has a new slip/slide been observed? (If yes, complete Slide Report Form)									No			

AFE 124300137	Date/Tir	<b>ne</b> 9/18/2018 7:35 AM	Report # 802	29
<ol> <li>PCSM BMPs (List BMPs and note if picture is required.)</li> </ol>	installed and ma	intained as per the plan. If corre	ctive action is nee	eded, a
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired
7. Identify all remedial measures that h	ave been taken s	since the previous inspection was	conducted.	
,		i		
Comments (Reference above questions		)		
Conducted Weekly VA SWPP at LY 26 & 28	3.			
Note: It is a condition of National Polluta	ant Discharge Eli	mination System and Erosion an	d Sediment perm	its that a
maintenance program be conducted to weekly basis and after each stormwater	provide for the op	peration and maintenance of all E	MPs to be inspec	cted on a
replacement are needed or have been r inspection may result in permit suspens	nade for BMPs a ion or the imposi	s a result of the inspection. Failution of civil penalties. If supplem	ure to conduct the ental monitoring i	required
as part of a permit condition this form m	ay be used to me	eet those monitoring requirement	IS.	

AFE	124300137	7	Date/Time	9/18/2018 7:35 A	N	Report #	8029	
			Pict	ures				
	izira & Timae Tina, Seep (18), izarifara a 1007.2021/357 / - 4 Ultrada 1928/01 izimara izimaraka				BB0 657394 4W 5973mits (True) ©			
GPS L		37.3342234595095, -80.8029641	1211785	GPS Location			4118696904	
Des	Description			Description	Fuel Containment at LY 26			
GPS L	-ocation	Insert image here		GPS Location	Insert im	age here		
	scription			Description				
		Insert image here			Insert im	age here		
GPS L	ocation			GPS Location				
Des	scription			Description				