Mountain Valley			Visual Site Inspection Report										
Project Name H-600 Pipeline Sp		eline Spread	G	Al	AFE 124300137			Spre	Spread H-600 Pipeline Sprea			oread G	
Contractor Precision					•				Repor	rt#	8827		
Inspector Clinton Banks								Date/Ti	ate/Time 10/4/2018 7:46 AM				
Permit #	Permit # TBD			Inspection Type VA SWPP				Station Begin +26					
State	VA			Inspection	Area	Full			Station End +26				
County	County Giles			Ground		Dry			Temperature (°F)				61.00
Municipality	nicipality N/A			We	ather	Clo	Cloudy		Rain Gauge (in)			0.00	
GPS Location 37.3192879814419, -80.65			572668254206	•		cumulati	cumulation Time (days)			1.00			
Are the approved (stamped) E&S Plan				n and PCSM Pla	and PCSM Plan present on site?								Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)										No			
3. Is Constructing followed? (If4. E&S BMPs (is required.)	No,	notify MV	P Environn	nental Permitting	g Coor	dina	tor and	d explain i	in comme	nts.)		_	Yes a picture
Εŧ	E&S BMPs			Compliance Level		Corrective Action					rective Frame	R	Date epaired
Compost Filter So	ock		Δ	cceptable									
Fuel Containment			Δ	cceptable									
Housekeeping			Δ	cceptable									
Rock Construction Entrance			Δ	cceptable									
Safety Fence			Δ	cceptable									
5. Site Conditi	ons	;											
Is an unauthoriz beyond defined a photo and imn	limi	ts of distu	bance resu	ulting from earth	distur	band	ce activ	vity or inef	-				No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?									Yes				
Are slopes 3:1 a	nd	greater sta	abilized with	n appropriate BN	MPs as	s per	E&S	olans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)									No				

MVP-34 REV 0 Page 1 of 3

AFE 124300137	Date/Ti	me 10/4/2018 7:46 AM	Report # 8827						
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)									
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired					
7. Identify all remedial measures that have been taken since the previous inspection was conducted.									
Comments (Reference above questions as appropriate.)									
Conducted Weekly VA SWPP at LY 26.Did not observed any Deficiencies at LY 26 during inspection.									
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a									
maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or									
replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required									

MVP-34 REV 0 Page 2 of 3

inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required

as part of a permit condition this form may be used to meet those monitoring requirements.



MVP-34 REV 0 Page 3 of 3