Mour Mour	valle	y	Visual S	Site I	ns	specti	on Repo	ort	t			
Project Name H-600 Pipeline Spread G		AFE 124300137		Spread	H-600 Pipeline Spread (pread G					
Contractor Precision				Report #	2847							
Inspector Timothy Watson						Date/Time	6/9/2018 2:48 PM		PM			
Permit #	Permit # TBD		Inspection Type VA SWPP			Station Beg	Begin 10000+00					
State	VA		Inspection Area	Full			Station E	End 10000+01				
County	Giles		Ground	Dry			Temp	nperature (ºF) 85.0		85.00		
Municipality	N/A		Weather	Sunny			Raiı	n Gauge (in) 0.0		0.01		
SPS Location	37.349280	961824, -80.6526	366156346			Rain Ac	cumulation Time (days) 1.00			1.00		
. Are the appr	oved (stam	ped) E&S Plan	and PCSM Plan pre	sent on	site	e?	Yes					
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)								No				
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)								Yes				
is required.)	(List BMPs	and note if insta	illed and maintained	as per	the	plan. If o	corrective act	ion	is needed,	a pictu		
E&S BMPs			Compliance Level			Correc	Corrective Action			Corrective Time Frame		
Compost Filter Sock			Acceptable	N/A				See Co	See Comments			
5. Site Conditi		()				- \						
eyond defined	limits of dis	sturbance resulti	iment, gravel, oil, HI ing from earth disturl ironmental Permittin	bance a	ctiv	vity or ine	•			No		
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?								Yes				
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?							Yes					
Has a new slip/alida been absented? (If you complete Slida Deport Form)								NI-				

MVP-34 REV 0 Page 1 of 3

No

Has a new slip/slide been observed? (If yes, complete Slide Report Form)

AFE 124300137	Date/Time 6/9/201	8 2:48 PM	Report #	2847									
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a													
picture is required.)	O-mulion			O a mus ating									
PCSM BMPs	Compliance Level	Corrective Ad	ction	Corrective Time Frame									
7. Identify all remedial measures that have been taken since the previous inspection was conducted.													
7. Identify an remedial measures that have been taken since the previous inspection was conducted.													
Comments (Reference above questions as appropriate.)													
Completed visual inspection of yard 28 in Narrows, Va. walked perimeter of both access points along that has access from and off Hwy 460, all filter sock stable with no issues. Acceptable conditions													
Chécked main yard 26, in Pembroke, Va. upper and lower lots along perimeter, no issues, all filter sock acceptable.													

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

MVP-34 REV 0 Page 2 of 3

MVP-34 REV 0 Page 3 of 3