Mour 🏹	Nalley		Visual	Sit	e Ins	specti	on Repo	ort			
Project Nar	ne H-600 Pipe	eline Spread G		AFE	124300	137	Spread	H-60	0 Pipeline S	pread G	
Contract	tor Precision		•				Report #	4136	6		
Inspect	tor Timothy W	atson					Date/Time	7/6/2	2018 12:50	6 PM	
Permit #	твр		Inspection Typ	e VA	SWPP		Station Beg	gin 1	10510+78		
State	VA		Inspection Are	a Pa	rtial		Station E	nd	11236+90		
County	Giles		Groun	d Dr	y		Temp	perat	ture (ºF)	92.00	
Municipality	N/A		Weathe	er Su	nny		Raiı	n Ga	uge (in)	0.01	
GPS Location	37.301729293	5749, -80.502	3402907704			Rain Ac	cumulation	Time	e (days)	1.00	
1. Are the appr	oved (stampe	d) E&S Plan	and PCSM Plan p	reser	nt on site	ə?				Yes	
			the limits of distur ermitting Coordina					?		No	
followed? (If	No, notify MV	P Environme	e construction not ntal Permitting Co	ordin	ator and	d explain i	n comments.	.)	Ũ	Yes	
4. E&S BMPs (is required.)	(List BMPs and	d note if insta	Illed and maintain	ed as	per the	e plan. If c	corrective act	ion is	s needed,	a picture	
	E&S BMPs		Compliance Level	9		Correct	tive Action			rective e Frame	
Compost Filter So	ock		Acceptable		See Co	omments					
Rock Constructio	n Entrance		Acceptable		See Co	omments					
Silt Fence (Filter	Fabric Fence)		Acceptable		See Co	omments					
Waterbar			Acceptable		See Co	omments					
Silt Fence (Filter Fabric Fence)			Problem Area		See Comments below			48 Hou	48 Hours		
Waterbar	√aterbar		Problem Area		See Comments b		elow		48 Hou	48 Hours	
5. Site Conditi	ons										
beyond defined	limits of distu	bance resulti	iment, gravel, oil, ing from earth dist ironmental Permit	urbar	nce activ	vity or inef	•			No	
Have inactive di	sturbed areas	s (stockpiles,	final grade) been s	stabili	zed per	state req	uirements?			Yes	
Are slopes 3:1 a	and greater sta	abilized with a	appropriate BMPs	as pe	er E&S p	olans?				Yes	
Has a new slip/s	slide been obs	erved? (If ye	es, complete Slide	Repo	ort Form	ı)				No	

AFE 124300137	Date/Time 7/6/201	8 12:56 PM	Report #	4136				
 PCSM BMPs (List BMPs and note if insta picture is required.) 	alled and maintained a	s per the plan. If correc						
PCSM BMPs	Compliance Level	Corrective Ac	tion	Corrective Time Frame				
7. Identify all remedial measures that have I	been taken since the p	revious inspection was	conducted.					
Comments (Reference above questions as a	appropriate.)							
Spread G 8 Checked access 234 crew installing gravel and culverts for access toward ROW. No issues in progress. Station 10510+78 Mp 198.9 checked access 235 and 236, completed to ATWS no issues. Station10526+62 Mp 199.1, and station 10535+82 Mp 199.4. Checked access 237 Gravely Hill Rd. Station 10563+92 199.8. Big Stoney Creek &RR 10592+80 Mp200.5 Norcross Rd, crossing 10599+95+95 Mp 200.6 no issues Access 238 no issues station 10602+18 Mp 200.7. Access 240 no issues 10670+17 Mp 201.9 Big Stoney Creek Rd crossing , no issues, Station 10675+04 ,Mp 202 Buffalo Anklet Rd and access 241 no issues. Station 10695+77 Mp 202.4 Spread 9 Kow Camp Rd #2 no issue on RCE 10883+56 Mp 206.9. Dow Creek Rd RCE ok 10929+71 Mp 206.9 Mountain Lake Rd 249.01 (sift fence needs repair on j hooks)11167+83 Mp 211.2 Access 249 ok Access road (needs temporary water bars station along steep hill on Access Rd to Row. Station11151+27 Mp 211.1 242.01, 243.01, off Mtn Lake Rd Mp 207.6 to 208.4 ok no issues Winding Way Access Rd super silt fence installed along Road, area on Row getting forward Ecds installed silt fence and filter sock, with temporary water Bars starting at station 11236+90 to 11216+12. Mp 212.6 to212.2								
Note: It is a condition of National Pollutant D maintenance program be conducted to provi weekly basis and after each stormwater ever replacement are needed or have been made inspection may result in permit suspension o as part of a permit condition this form may be	de for the operation and nt. Please list in the sp of BMPs as a result or the imposition of civi	nd maintenance of all B bace provided comment of the inspection. Failu penalties. If supplement	MPs to be ins ts to note if re re to conduct ental monitorin	spected on a epairs or the required				

AFE	12430013 ⁻	7	7/6/2018 12:56 P	M	Report # 4136		
			Pict	ures			
di Perta Al Di Sector Al Di Al Di Sector Al Di Al Di Sector Al Di Al Di A	ale A Time Fic Jud & 10 autor. 4037 22 14/44 - 1 Minude 12941 Julin - WOS-94 A Garang 168 - 5 A Garang 168 - 6 A Garang 168 - 6 A Garang 16 A Garang 1	04 31 EDT 2018 (bb) xd 56 697 4E 2951mils (True)		CONTRACTOR NEW YORK AND ADDRESS OF			
GPS L	ocation	37.3016988672663, -80.5023119		GPS Location	1		
Des	cription	Access 235 and 236 meets good water bar on road use photo gps	temporary	Description	Silt fence down a Rd use photo gp:	iccess 249.0 s	1 off Mtn Lake
Po Al Da Az Elo	tate & Timer PJ ud S(P) selfer, PJ ud S(P) atom, PJ ud S(- 080 '40.43 31		Durit de faite a durant de la constant de la consta	102209-DDT 2018 Hobe 4027 73		
GPS L	ocation	37.3005230957989, -80.5034178	3682421	GPS Location	37.30061726648	11, -80.5035	498832171
Des	cription	Note: access 234 land owner dis along and adjacent to LOD	turbance	Description	Access 234 towa	rd Rogers R	d
				Date & Time: Fri Jul & 13 Position - 43/71 & 6.30 / Altitude=R000ft Datum 40/66 - 40 Azimuth/Bearing: 28 / Eleviting Crade - 0117 - 200m AX - access of f. Wind in pullave	15.27 EDT 2018: -060/10/0 6.43* 78W 4597/mits (True): 		
GPS L	ocation	37.3005020153125, -80.5034020)264451	GPS Location	37.30166039433	08, -80.5023	3190007363
Des	cription	Off Hwy 460 Access. 249.02 tem lane for clearing temporary water Use photo gps	porary travel r bars installed		Off Winding way gps and station #	installing silt	