•	itain Valle	y _{uc}	Visual	Sit	e Ins	specti	on Repo	or	t		
Project Nar	ne H-600 F	Pipeline Spread G	1	ΙFΕ	124300	137	Spread	H-6	00 Pipeline S	pread G	
Contractor Precision							Report #	6412			
Inspector Timothy Watson						Date/Time	8/1	0 PM			
Permit # TBD		Inspection Type VA SWPP			Station Begin 1		10510+78	10510+78			
State	VA		Inspection Area	Partial		Station E	End 11237+00				
County	Giles		Ground	Dr	у		Temp	Temperature (°F) 88		88.00	
Municipality	N/A		Weather	Su	nny		Rain Gauge (in)		0.01		
GPS Location 37.3192481967955, -80.657			3169930854 Rai			Rain Ad	Accumulation Time (days)			0.01	
1. Are the appre	. Are the approved (stamped) E&S Plan and PCSM Plan present on site?									Yes	
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)									No		
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)									Yes		
4. E&S BMPs (is required.)	(List BMPs	and note if insta	lled and maintaine	d as	per the	plan. If o	corrective act	ion	is needed,	a pictu	
E&S BMPs			Compliance Level			Corrective Action				Corrective Time Frame	
Compost Filter So	ock		Acceptable		See co	mments					
Housekeeping			Acceptable		See comments						
Rock Construction Entrance			Acceptable		See comments						
Silt Fence (Filter Fabric Fence)			Acceptable		See comments						
Silt Fence (Reinforced Filter Fabric Fence)			Communication		See comments			Addres	Addressed		
Waterbar			Acceptable		See comments						
5. Site Conditi	ons										
beyond defined	limits of dis	turbance resulti	iment, gravel, oil, H ing from earth distu ironmental Permitti	rbar	nce acti	vity or ine				No	
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?									Yes		

MVP-34 REV 0 Page 1 of 3

No

Has a new slip/slide been observed? (If yes, complete Slide Report Form)

ΔFF	124300137	Date/Time 8/15/20	18 6·20 PM	Report #	6412						
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)											
PCSM BMPs		Compliance Level	Corrective A	ction	Corrective Time Frame						
7. Identify all remedial measures that have been taken since the previous inspection was conducted.											
Comr	Comments (Reference above questions as appropriate.)										
Compl Bia Sta	eted VASWPP, checked area off Rogers oney Creek Rd. Mp 202 to Henderson Rd	Rd Mp198.9, Gravely Hill . Mp 203.4 area stabilized	Rd 199.1, off Norcross F	Rd 200.5, straw.							
Check Check	ed Northern Yard 29, no issues. ed area from north off Kow Camp Rd 1 M	p 205.6 to Kow Camp Rd	2 Mp 205.9								
Checked area from North off Row Camp Rd 1 Mp 200.0 to Row Camp Rd 2 Mp 200.9 Checked area Access 245.01 off Brickyard Rd Mp209.3 to Mtn Lake Rd.Mp211 to Winding Way Mp212.7 Issues on bridge repaired station 11064+84 removed geo and replaced.											
No iss	ues items on punch list completed.										

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

MVP-34 REV 0 Page 2 of 3

MVP-34 REV 0 Page 3 of 3