Mountain Valley Visual Site Inspection Report											
Project Name H-600 Pipeline Spread F		line Spread H	AFE 124300138			Spread	H-60	00 Pipeline S _l	oread H		
Contractor Precision						Report #	725				
Inspector Pat Davis							Date/Time	te/Time 4/2/2018 4:52			
Permit #	# TBD			Inspection Type Weekly			Station Beg	jin	12543+56		
State	VA			Inspection Area	Partial		Station End 12012+69				
County	Mor	ntgomery		Ground	Wet		Temperature (ºF)			62.00	
Municipality	N/A			Weather	Cloudy		Rain Gauge (in)			0.00	
GPS Location	37.2	278814553	833, -80.0291	112229498		Rain Ad	cumulation	2.00			
1. Are the appro	1. Are the approved (stamped) E&S Plan a				sent on si	te?				No	
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)										No	
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)								No			
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)											
E&S BMPs			Compliance Level		Correc	Corrective Action			Corrective Time Frame		
5. Site Condition	ons				'						
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.											
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?									No		
Are slopes 3:1 a	ınd (greater sta	abilized with a	ppropriate BMPs as	per E&S	plans?				N/A	
Has a new slip/s	lide	been obs	erved? (If ye	s, complete Slide R	eport For	m)				No	

MVP-34 REV 0 Page 1 of 3

AFE 124300138	Date/Time 4/2/201	8 4:52 PM	Report #	725								
6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)												
PCSM BMPs	Compliance Level	Corrective Ac	Corrective Action									
7. Identify all remedial measures that have been taken since the previous inspection was conducted.												
Comments (Reference above questions as	appropriate.)											
Attended morning spread meeting. Meet with L to MP 237.5. No impact to VDOT roadways from the empty.		ection Report. Preform W Check rain gauge on Yello	eekly Inspection	on from MP 229.0 gauge was								

Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

MVP-34 REV 0 Page 2 of 3

AFE 124300138 Date/Time 4/2/2018 4:52 PM Report # 725 **Pictures** 37.2789530494757, -80.0292709934504 37.2789563719149, -80.0292730982024 **GPS Location GPS Location** Yellow Finch Road and Cove Hollow Road. MVP-MN-274 and Bradshaw Road no impact No impact to VDOT Road from access road. from access road. Looking NW. see photo for Description Description Looking SW. See photo for correct gps correct gps location. 7°15'35", -80°16'52", 424.0m, 358 °16'29", -80°15'8", 379.0m, 33 **GPS Location GPS Location** 37.2789644636561, -80.0287714787573 37.2789708339025, -80.0287318323553 MVP-MN-272 and Flatwoods Road no impact MVP-MN-276 and Bradshaw Road. No impact from access road. Looking E. See photo for from access road. Looking E. See photo for Description Description correct gps location. correct gps location. 37°15'17", -80°17'7", 378.0m, 321 37°14'2", -80°14'23", 362.0m, 13° 04/02/2018 11:00:29 AM 04/02/2018 10:10:46 AM GPS Location 37.2789921658461, -80.0286757574231 **GPS Location** 37.2789921658461, -80.0286757574231 MVP-MN-270.01 and Flatwoods Road. No MVP-MN-276.03 and North Fork Road no impact from access road. Looking NE. See impact from access road. Looking NW. See Description Description photo for correct gps location. photo for correct gps location

MVP-34 REV 0 Page 3 of 3