Moun	Mountain Valley Visual Site Inspection Report									
Project Name H-600 Pipeline Spread H		AFE 124300138		Spread	H-600 Pipeline Spread H		oread H			
Contractor Precision			•			Report # 925				
Inspect	Inspector Pat Davis						Date/Time 4/12/2018 7:45			
Permit #	TBD		Inspection Type Weekly			Station Beg	ion Begin 12005+00			
State	VA		Inspection Area Full			Station E	nd 13			
County	Franklin		Ground Wet			Temperature (°F)			71.00	
Municipality	N/A		Weather	Sunny		Rain Gauge (in) 0.00			0.00	
GPS Location	37.278855103	3579, -80.0288°	154109652		Rain Ac	ccumulation Time (days) 4.00			4.00	
1. Are the appro	oved (stampe	d) E&S Plan a	and PCSM Plan pre	sent on sit	e?				Yes	
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)									No	
3. Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes			
4. E&S BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)										
ı	E&S BMPs		Compliance Level		Corrective Action				rective Frame	
5. Site Condition		(augh ca ac-li	ment ground all LIF)D fluid -4		ing to waters	ustl-	ndo or		
Is an unauthorized discharge (such as sediment, gravel, oil, HDD fluid, etc.) occurring to waters, wetlands, or beyond defined limits of disturbance resulting from earth disturbance activity or ineffective BMP? If yes, take a photo and immediately contact MVP Environmental Permitting Coordinator.										
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?									N/A	
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans?									N/A	
Has a new slip/s	slide been obs	served? (If ye	s, complete Slide R	eport Forn	٦)				No	

MVP-34 REV 0 Page 1 of 3


AFE 124300138	Date/Time 4/12/20)18 7:45 PM	Report # 925							
PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a picture is required.)										
PCSM BMPs	Compliance Level	Corrective Ac	Corrective Time Frame							
7. Identify all remedial measures that have been taken since the previous inspection was conducted.										
Comments (Reference above questions as										
Attended morning spread inspectors meeting. I 12005+00. Checked access roads entrances a Hill Road (.0), Calloway Road (.0), Yellow Finch										
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a										

replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or

MVP-34 REV 0 Page 2 of 3

AFE 124300138 Date/Time 4/12/2018 7:45 PM Report # 925 **Pictures** STREAM CROSSING 37°7'24", -80°7'16", 744.0m, 04/12/2018 08:33:53 37.2787406790478, -80.0290260386848 37.279001176392, -80.0286786072702 GPS Location **GPS Location** MVP-FR-289 & 290_041218 @ Calloway 13260+66_041218 feature S-114 no impact Road. Looking SW. No impact to VDOT from tree cutters. Looking W. See photo for Description Description roadways. See photo for correct gps location. correct gps location. STREAM CROSSING STREAM CROSSING GPS Location 37.2789354622711, -80.0286659505964 **GPS Location** 37.2789354622711, -80.0286659505964 13415+19 041218 feature S-IJ3 looking NE. MVP-MN-278.01 041218 feature S-KL32 no See photo for correct gps location. impact from access road. Looking W. See Description Description photo for correct gps location.



MVP-34 REV 0 Page 3 of 3