
Mountain Valley		Visual Site Inspection Report										
Project Name H-600 Pipeline Spread				Al	FE 124300138			Spread H		H-600 Pipeline Spread H		
Contractor Precision			•				Repo	port # 2767				
Inspector Tracey Hilbun							<b>Date/Time</b> 6/5/2018 4:54 PM				PM	
Permit #	Permit # TBD			Inspection Type VA SWPP				Station Begin 13415+26				
State	VA		Inspection Area		Full			Station End 13670+00				
County	ty Franklin		Ground		Damp		Temperature (°F)				80.00	
Municipality	N/A		We	Veather Sunny Rain Gauge (in				n)	0.00			
GPS Location	37.059375145	50057, -79.882	5501823866	Rain Accumulation Time (days)				s)	0.00			
1. Are the appre	1. Are the approved (stamped) E&S Plan a			and PCSM Plan present on site?								Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings?  (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)									No			
<ul><li>3. Is Constructi followed? (If</li><li>4. E&amp;S BMPs (is required.)</li></ul>	No, notify MV	P Environme	ntal Permittinឲ្	g Coor	dinator	and	d explain	in comm	ents.)	)		Yes a picture
Εŧ	E&S BMPs		ompliance Level		Corrective Action					rective Frame	R	Date epaired
Compost Filter So	ock	Acc	eptable									
Housekeeping		Acc	eptable									
Rock Construction Entrance		Acc	eptable									
Silt Fence (Filter Fabric Fence)		Acc	eptable									
Silt Fence (Reinfo	orced Filter Fab	oric Fence) Acc	eptable									
Sump Pit		Acc	eptable									
5. Site Conditi	ons											
Is an unauthoriz beyond defined a photo and imn	limits of distu	rbance resulti	ng from earth	distur	bance a	activ	ity or ine	-				No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements?									Yes			
Are slopes 3:1 a	and greater sta	abilized with a	ppropriate BN	/IPs as	per E8	&S p	olans?					Yes
Has a new slip/slide been observed? (If yes, complete Slide Report Form)									No			

MVP-34 REV 0 Page 1 of 3

<b>AFE</b> 124300138	Date/T	i <b>me</b> 6/5/2018 4:54 PM	Report # 2767							
•	6. PCSM BMPs (List BMPs and note if installed and maintained as per the plan. If corrective action is needed, a									
picture is required.)		1		_						
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired						
	2010.			rtopan ou						
7. Identify all remedial measures that have been taken since the previous inspection was conducted.										
Contractor has completed any repairs noted this period as well as cleaning mat bridge crossings.										
<b>Comments</b> (Reference above questions Grading operations continue on spread this			has begun on one	and an well an						
continued ECD placement and managemen compliant within 24 hour time frame given.	t as needed. A PA	A was written on mat maintenance for	cleaning. Contract	or had areas						
event.	NO ISSUES WEIE OL	served during inspection. NOW conti	nues to dry from pr	evious rain						

**Note:** It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

MVP-34 REV 0 Page 2 of 3



MVP-34 REV 0 Page 3 of 3