Mour	Ntain Valley		Visu	ual S	Site I	ns	pecti	on Re	epo	rt		
Project Name H-600 Pipeline Spread H			Α	AFE 124300138			Spre	ead H	H-600 Pipeline Spread H			
Contractor Precision							Repo	ort # 3167				
Inspect	t or Tracey Hill	bun						Date/Ti	i me 6	/11/2018 1	:37	PM
Permit # TBD		Inspection	VA SWPP		Station Begin 13415+5		51					
State VA			Inspection Area		Full		Station End 13670+		00			
County Franklin			Ground		Wet		Temperature (%		-) {	83.00		
Municipality N/A			We	Sunny			Rain Gauge (in)			0.80		
GPS Location 36.9716879465557, -79.87			0201785264 Rain Ac				cumulation Time (days)			s) ^	1.00	
1. Are the appr	oved (stampe	d) E&S Plan	and PCSM PI	an pre	sent on	site	?					Yes
2. Are there ac (If yes, notify			the limits of d ermitting Coo						ngs?			No
	No, notify MV	P Environme	ental Permitting	g Coor	dinator	and	explain i	n comme	ents.)	0		Yes
4. E&S BMPs (is required.)	(LIST BMPS and	a note if insta	alled and main	itained	as per	tne	plan. If c	corrective	actio	n is neede	e, a	a picture
E&S BMPs		C	Compliance Level	Corrective Action					ective Frame			
Compost Filter Sock		Acc	ceptable									
Housekeeping		Acc	ceptable									
Rock Construction Entrance		Со	mmunication	Place additional rock			Addressed					
Silt Fence (Filter Fabric Fence)		Acc	ceptable									
Silt Fence (Reinfo	orced Filter Fab	oric Fence) Acc	ceptable									
5. Site Conditi	ons											
Is an unauthoriz beyond defined a photo and imn	limits of distu	rbance result	ing from earth	distur	bance a	activi	ity or inef	-				No
Have inactive disturbed areas (stockpiles, final grade) been stabilized per state requirements? Yes							Yes					
Are slopes 3:1 and greater stabilized with appropriate BMPs as per E&S plans? Ye							Yes					
Has a new slip/s	slide been obs	served? (If ye	es, complete S	Slide R	eport Fo	orm))					No

AFE 124300138	Date/Tin	ne 6/11/2018 1:37 PM	Report # 316	Report # 3167				
6. PCSM BMPs (List BMPs and note picture is required.)	if installed and mai	ntained as per the plan. If co	rrective action is ne	eded, a				
PCSM BMPs	Compliance Level	Corrective Action	Corrective Time Frame	Date Repaired				
7. Identify all remedial measures that	have been taken e	inco the providue inspection y						
T. Identity all remedial measures that	Have been laken s							
Comments (Reference above questio								
The spread was inspected in this reporting for today which were addressed as observed	g period with no issue ved.	s observed. Rains over weeken	d created some mainte	enance issues				
Netes It is a condition of National Dally	itant Discharge Elir	ningtion System and Fragion	and Codiment norm	ite that a				
Note: It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a								
weekly basis and after each stormwat replacement are needed or have beer	n made for BMPs as	s a result of the inspection. F	ailure to conduct the	e required				
inspection may result in permit susper as part of a permit condition this form				s required				

AFE 12430013	8	Date/Time	6/11/2018 1:37 PM	И	Report # 3167		
	Pictures						
	Image: A constraint of the second constraint of the se				installing water bars at SN		
GPS Location	36.972091714886, -79.87002778	380578	GPS Location		886, -79.8700277880578		
Description	Rock entrance on Frith Tract		Description	Water bar insta	all at days end		
	Image: Constraint of the sector of the se			Insert im	age here		
GPS Location	36.9716921534453, -79.8700719 Mulching of spoil piles	9640739	GPS Location				
Description			Description				
	Insert image here			Insert im	age here		
GPS Location			GPS Location				
Description			Description				