Certification Statement

I certify under penalty of law that I have read and understand this document and that this document and all attachments were prepared in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Inspector's Name (printed): Mike Renfro

Inspector's Signature: Mike Karl

Date: 9-12-18

Spread I Laydown Yard Report # 7630 5WIN 1369

ESIN 0946

Project Name H-600 Pipeline Spread			ad I	AFE 124300139			Sprea	Spread H-600 Pipeline Spread		Spread I
Contractor Precision							Report	eport # 7630		
Inspector Glenn Mike Renfro								ate/Time 9/12/2018 2:13 PM		3 РМ
Permit # TBD			Inspection	Inspection Type VA SWPP			Station Begin 0000+00			
State	VA		Inspection	n Area	Full		Station End 0000+00			
County	Fra	anklin	G	round	Wet		Temperature (°F)		77.00	
Municipality	N/	A	W	eather	Cloudy		Rain Gauge (in)			3.00
GPS Location	Location 36.9699195446791, -79.8682164587824 Rain Accumulation Time (day				iys)	3.00				
		ed (stamped) E&S								Yes
Are there ac (If yes, notify	tivi th	ties occurring outsi e MVP Environmer	de of the limits of ntal Permitting Coo	disturba ordinato	ance show or and expl	n on the pain in cor	olan drawing: mments.)	5?		No
3. Is Construct followed? (If	ion	sequence outlined , notify MVP Enviro	in the construction	n notes na Coor	of the E&: dinator an	S plan se d explain	t or PCSM pl	an set beir	ng	Yes
	(Lis	st BMPs and note if				THE RESERVE OF THE PERSON NAMED IN			ded,	a pictu
E&S BMPs		Compliance Level		Corrective Action			orrective ne Frame	R	Date epaired	
Housekeeping			Acceptable							
Compost Filter Sock			Communication	Maintenance required						
Rock Constructio	n E	ntrance	Acceptable	- mari				Santania (Santania)		
Silt Fence (Filter Fabric Fence)			Acceptable	W ₁ = 3	1175	motor LC				
			Sept a Fr	V- 1-93		a de d		territa	111	ring Kaba
									T	700
5. Site Condition										
evond defined I	imit	discharge (such as s of disturbance re ately contact MVP	sulting from earth	n disturb	ance activ	ity or ine	ring to waters ffective BMF	s, wetlands ? If yes, t	s, or ake	No
		bed areas (stockpil					quirements?		7-11	N/A
re slopes 3:1 ar	nd g	greater stabilized w	ith appropriate BN	MPs as	per E&S p	olans?	10 p. 10 p. 1			N/A

Compliance Level It have been taken sin	Corrective Action	Corrective Time Frame	Date Repaire
Level			
Level			
at have been taken sin			
nt have been taken sin			
nt have been taken sin			
nt have been taken sir			
nt have been taken sir			
nt have been taken sir	as the province increasing		
it have been taken sir	so the province increation w		
it have been taken sir	so the provious increation w		
IL Have been taken sir		as sandusted	
			1
ons as appropriate.)		Jan Jan B	
ear of any debris. There eds to be secured with s	was also a potential issue with tand bags. All secondary contain	the drain inlet protection ment structures were	on on the
1	ydown yard in Rocky Mo FS on the west side of the ear of any debris. There eds to be secured with s	ydown yard in Rocky Mount, Va. All perimeter ECD's we FS on the west side of the paved laydown yard is dama ear of any debris. There was also a potential issue with eds to be secured with sand bags. All secondary contain	ons as appropriate.) ydown yard in Rocky Mount, Va. All perimeter ECD's were inspected and one IFS on the west side of the paved laydown yard is damaged and requires mai ear of any debris. There was also a potential issue with the drain inlet protectiveds to be secured with sand bags. All secondary containment structures were replaced on a punch list and given to the contractor to be addressed.

replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required as part of a permit condition this form may be used to meet those monitoring requirements.

AFE	124300139		Date/Time	9/12/2018 2:13 Pi	A Repo	ort # 7630		
	Pictures							
GPS	Location	37.486027693001, -79.17813499			37.4856086774147, -79	.1777390801154		
De	escription	Secondary containment for pump generators in good condition.	os and	Description	RCE in good condition.	- 15		
GPS	Location	37.4856506288401, -79.1777168			37.4855691986508, -79			
D€	escription	Drain inlet protection needs to be sand bags.	e secured with	Description	Perimeter ECD's in good	d condition.		
					Insert image here			
GPS		37.4856884312234, -79.1777681		GPS Location				
Des	scription	Perimeter ECD's at employee par good condition.	rking area in	Description				

MVP-34 REV 0 Page 3 of 3