






Start Spread 10 6-20-18

Signature ¹ : 		Date: 5-21-18
Printed Name: Randy Clark		Title: LEI
Revision +	Revision Description: Upgrade ECD to P1 Silt Fence Sta 12951+00 ES SHT NO 14.24 ES	

Signature ¹ : 		Date: 5-23-18
Printed Name: Randy Clark		Title: LEI
Revision 2	Revision Description: Upgraded ECD to P1 Silt Fence Sta. 12949+00 ES SHT 14.24 ES	


Signature ¹ : 		Date: 5-25-18
Printed Name: Randy Clark		Title: LEI
Revision 3	Revision Description: Upgraded ECD to Super Silt Fence (SSF) Sta. 12963+00 ES SHT NO 14.24 ES	


Signature ¹ : 		Date: 5-25-18
Printed Name: Randy Clark		Title: LEI
Revision 4	Revision Description: Upgraded ECD to SSF Sta. 12965+00 ES SHT NO. 14.24 ES	


Signature ¹ : 		Date: 5-25-18
Printed Name: Randy Clark		Title: LEI
Revision 5	Revision Description: Upgraded ECD ECD to SSF Sta. 12965+00 SHT NO 14.25	


¹ Certification will be signed by a responsible corporate officer or by a duly authorized representative of that person. Specific requirements and responsibilities of the responsible corporate officer or duly authorized representative as well as delegate of authority to SWPPP Coordinator are discussed in detail in below.


Start Spread 10 6-20-18

Signature ¹ : 	Date: 5-21-18
Printed Name: Randy Clark	Title: LEI
Revision 1	Revision Description: Upgrade ECD to P1 Silt Fence Sta 12951+00 ES SHT NO 14.24 ES


Signature ¹ : 	Date: 5-23-18
Printed Name: Randy Clark	Title: LEI
Revision 2	Revision Description: Upgraded ECD to P1 Silt Fence Sta. 12949+00 ES SHT 14.24 ES


Signature ¹ : 	Date: 5-25-18
Printed Name: Randy Clark	Title: LEI
Revision 3	Revision Description: Upgraded ECD to Super Silt Fence (SSF) Sta. 12963+00 ES SHT NO 14.24 ES


Signature ¹ : 	Date: 5-25-18
Printed Name: Randy Clark	Title: LEI
Revision 4	Revision Description: Upgraded ECD to SSF Sta. 12965+00 ES SHT NO. 14.24 ES


Signature ¹ : 	Date: 5-25-18
Printed Name: Randy Clark	Title: LEI
Revision 5	Revision Description: Upgraded ECD ECD to SSF Sta. 12965+00 SHT NO 14.25


¹ Certification will be signed by a *responsible corporate officer* or by a *duly authorized representative* of that person. Specific requirements and responsibilities of the responsible corporate officer or duly authorized representative as well as delegate of authority to SWPPP Coordinator are discussed in detail in below.

Signature ¹ : 		Date: 5-25-18
Printed Name: Randy Clark		Title: LEI
Revision <u>4</u>	Revision Description: Upgraded ECD to PI SHT SHT Fence (SF) Sta. 12966+00 ^{ES} to Sta. 12972+00 ES	

Signature ¹ : 		Date: 5-25-18
Printed Name: Randy Clark		Title: LEI
Revision <u>7</u>	Revision Description: Upgraded ECD to PI SF Sta. 12967+00 to Sta. 12978+00 ES SHT NO 14.25 ES	


Signature ¹ : 		Date: 5-25-18
Printed Name: Randy Clark		Title: LEI
Revision <u>8</u>	Revision Description: Upgraded ECD to SF Sta. 12980+00 ES SHT 14.25 ES	


Signature ¹ : 		Date: 5-25-18
Printed Name: Randy Clark		Title: LEI
Revision <u>9</u>	Revision Description: Upgraded ECD to 12" CFS Sta. 2+00 ES SHT 14.28	


Signature ¹ : 		Date: 5-26-18
Printed Name: Randy Clark		Title: LEI
Revision <u>10</u>	Revision Description: Upgraded ECD PI SF, FR-288 SHT NO. 14.67	


¹ Certification will be signed by a *responsible corporate officer* or by a *duly authorized representative* of that person. Specific requirements and responsibilities of the responsible corporate officer or duly authorized representative as well as delegate of authority to SWPPP Coordinator are discussed in detail in below.


 6/20/18

Signature ¹ : 		Date: 5-31-18
Printed Name: Randy Clark		Title: LEI
Revision <u>11</u>	Revision Description: Upgraded ECD to PI from 12" Sta. 12976+00 ES to Sta 12979+00 SHT NO 14.25 ES	

Signature ¹ : 		Date: 5-31-18
Printed Name: Randy Clark		Title: LEI
Revision <u>12</u>	Revision Description: Upgraded Upgraded ECD to SSF Sta. 12980+00 ES SHT NO 14.25 ES	


Signature ¹ : 		Date: 6-2-18
Printed Name: Randy Clark		Title: LEI
Revision <u>13</u>	Revision Description: Added H2O Bar @ Sta. 12979+00 ES SHT NO 14.25 ES	


Signature ¹ : 		Date: 6-2-18
Printed Name: Randy Clark		Title: LEI
Revision <u>14</u>	Revision Description: Upgraded ECD to PI SF, Upgraded to PI SF @ Sta 12986+00 + Sta 12987+00 ES SHT NO 14.25 ES	


Signature ¹ : 		Date: 6-3-18
Printed Name: Randy Clark		Title: LEI
Revision <u>15</u>	Revision Description: Upgraded ECD to PI SF ^{On} PI SF added to 12" CFS Sta. 12959+00 ES SHT NO 14.24 ES	


¹ Certification will be signed by a *responsible corporate officer* or by a *duly authorized representative* of that person. Specific requirements and responsibilities of the responsible corporate officer or duly authorized representative as well as delegate of authority to SWPPP Coordinator are discussed in detail in below.


ML 6/21/18

Signature ¹ : 		Date: 6-3-18
Printed Name: Randy Clark		Title: LEI
Revision <u>16</u>	Revision Description: Upgraded ECD to SSF Sta 12994+00 ES SHT NO 14.26	

Signature ¹ : 		Date: 6-3-18
Printed Name: Randy Clark		Title: LEI
Revision <u>17</u>	Revision Description: Upgraded to P1 SF @ Sta 12997+00 ES SHT NO 14.25 14.25	


Signature ¹ : 		Date: 6-4-18
Printed Name: Randy Clark		Title: LEI
Revision <u>18</u>	Revision Description: Upgraded ECD to P1 SF @ 12982+00 ES @ 12984+00 ES @ Sta. 12981+00 ES @ 12983+00 ES SHT NO 14.25 ES	


Signature ¹ : 		Date: 6-4-18
Printed Name: Randy Clark		Title: LEI
Revision <u>19</u>	Revision Description: Added straw bales as ECD Sta 12984+00 ES SHT 14.25	


Signature ¹ : 		Date: 6-4-18
Printed Name: Randy Clark		Title: LEI
Revision <u>20</u>	Revision Description: Double stacked straw bales added as ECD measure. Sta 12985+00 ES to Sta. 12989+00 ES SHT NO 14.25 ES	


¹ Certification will be signed by a *responsible corporate officer* or by a *duly authorized representative* of that person. Specific requirements and responsibilities of the responsible corporate officer or duly authorized representative as well as delegate of authority to SWPPP Coordinator are discussed in detail in below.




Signature ¹ : 		Date: 6-2-18
Printed Name: Randy Clark		Title: LEI
Revision <u>21</u>	Revision Description: Added H ₂ O Base @ Sta 13027+00 Sta 12947+00 ES SHT NO 14.24 ES	

Signature ¹ : 		Date: 6-7-18
Printed Name: Randy Clark		Title: LEI
Revision <u>22</u>	Revision Description: Upgraded ECO to P1 SF Sta 12998+00 ES to Sta 13088+00 ES SHT NO 14.25	


Signature ¹ : 		Date: 6-8-18
Printed Name: Randy Clark		Title: LEI
Revision <u>23</u>	Revision Description: Upgraded ECO @ Dillons Mill to P1 SF, added straw bale Sta. 13120+00 ES * SHT NO 14.30 ES	


Signature ¹ : 		Date: 6-18-18
Printed Name: Randy Clark		Title: LEI
Revision <u>24</u>	Revision Description: Remove (will not install) Clean H ₂ O diversion drain & pipe. Sta. 12989+00 in SHT NO 14.25	


Signature ¹ : 		Date: 6-19-18
Printed Name: Randy Clark		Title: LEI
Revision <u>25</u>	Revision Description: Upgraded ECO to P1 SF SHT NO 14.67 S-Q20 geotech & side boards replaced 12" CFS FR-288	


¹ Certification will be signed by a responsible corporate officer or by a duly authorized representative of that person. Specific requirements and responsibilities of the responsible corporate officer or duly authorized representative as well as delegate of authority to SWPPP Coordinator are discussed in detail in below.


ML 6/21/18

Signature ¹ : 		Date: 6-19-18
Printed Name: Randy Clark		Title: LEI
Revision <u>26</u>	Revision Description: Upgraded ECD to P1 SF on MVP-FR-292 @ Sta. 4+00 to 3+00	

Signature ¹ : 		Date: 6-19-18
Printed Name: Randy Clark		Title: LEI
Revision <u>27</u>	Revision Description: MVP-FR-291 Added CFS 12" across logging Rd. Upgraded to P1 SF below 12" CFS Sta 17+00 to Sta 28+00	


Signature ¹ : 		Date: 6-19-18
Printed Name: Randy Clark		Title: LEI
Revision <u>28</u>	Revision Description: MVP-FR-291 Upgraded/added 12" CFS ATWS-1249 & ATWS 1250 Upgraded to P1 SF water bars 5@S' Upgraded to P1 SF along W-EP3, added P1 SF on bridge	


Signature ¹ : 		Date: 6-19-18
Printed Name: Randy Clark		Title: LEI
Revision <u>29</u>	Revision Description: FR-291 Installed P1 SF below 12" CFS 12" CFS across logging Rd	


Signature ¹ : 		Date: 6-19-18
Printed Name: Randy Clark		Title: LEI
Revision <u>30</u>	Revision Description: Flaudens Rd Added 12" CFS Sta. 13181 to 0E5; Upgraded P1 SF ATWS Omitted Diversion Berm (previously listed)	


¹ Certification will be signed by a responsible corporate officer or by a duly authorized representative of that person. Specific requirements and responsibilities of the responsible corporate officer or duly authorized representative as well as delegate of authority to SWPPP Coordinator are discussed in detail in below.


ML 6/21/18

Signature ¹ : 		Date: 6-19-18
Printed Name: Randy Clark		Title: LEI
Revision <u>31</u>	Revision Description: Upgraded/Added P1 SF Sta 13120+00 ES SSSF added @ Sta 13120+00 ES @ Dillon's Mill SSSF added @ Sta 13120+00 ES & Sta. 13121+00 ES	

Signature ¹ : 		Date: 6-19-18
Printed Name: Randy Clark		Title: LEI
Revision <u>32</u>	Revision Description: Wade's Gap Upgraded ECD to P1 SF along S-GH7	


Signature ¹ : 		Date: 6-19-18
Printed Name: Randy Clark		Title:
Revision <u>33</u>	Revision Description: Crew graded off LOP @ Cove Hollow Rd, recorded noncompliance, stabilized ~ Sta 12450+80	


Signature ¹ : 		Date: 6-23-18
Printed Name: Randy Clark		Title: LEI
Revision <u>34</u>	Revision Description: Upgrade to triple stack @ Sta 12918+00 ES	


Signature ¹ : 		Date: 6-23-18
Printed Name: Randy Clark		Title:
Revision <u>35</u>	Revision Description: Upgrade to P1 SF from Sta. 12914+00 to 12917+00 ES (Hwy 221)	


¹ Certification will be signed by a responsible corporate officer or by a duly authorized representative of that person. Specific requirements and responsibilities of the responsible corporate officer or duly authorized representative as well as delegate of authority to SWPPP Coordinator are discussed in detail in below.


6/21/18
ML

Signature ¹ : 		Date: 6-20-18
Printed Name: Randy Clark		Title: LEI
Revision <u>36</u>	Revision Description: Upgrade to #1 SF @ Sta. 13182+00 ES	

Signature ¹ : 		Date: 6-24-18
Printed Name: Randy Clark		Title: LEI
Revision <u>37</u>	Revision Description: Extended SSF 250 in place of 18" CFS due to slope falling to slide Sta 13189+00 to Sta 13191+00 ES	

Signature ¹ : 		Date: 6-26-18
Printed Name: Randy Clark		Title: LEI
Revision <u>38</u>	Revision Description: Upgrade to SSF @ Sta 13184+00	

Signature ¹ : 		Date: 7-25-18
Printed Name: Randy Clark		Title: LEI
Revision <u>39</u>	Revision Description: New project Drawings approved by DEQ. ES 56.2 / 42.1 / 61.1 / 61 / 60 / 59 / 42 / 17.1 / 58 / 56.2A	

Signature ¹ : 		Date: 7-25-18
Printed Name: Randy Clark		Title: LEI
Revision <u>40</u>	Revision Description: Curlexed swales to extend down fill slope. E+S (12947+00 to 12948+00) 14.24ES	

¹ Certification will be signed by a *responsible corporate officer* or by a *duly authorized representative* of that person. Specific requirements and responsibilities of the responsible corporate officer or duly authorized representative as well as delegate of authority to SWPPP Coordinator are discussed in detail in below.

ML 6/29

SM
7-22-18

Signature ¹ :	<i>Randy Clark</i>	Date:	7-30-18
Printed Name:	Randy Clark	Title:	LEI
Revision <u>41</u>	Revision Description: Installed (3) erosion control blanketed swales down fill slopes leading to sumps as an extension of the slope breakers (E+S 14.24) (12941+50 to 12943+50)		

Signature ¹ :	<i>Randy Clark</i>	Date:	8-18-18
Printed Name:	Randy Clark	Title:	LEI
Revision <u>42</u>	Revision Description: Installed bridge & curter lined channel to direct spring seep flow across the LOD. Triple stack 12" CFS installed along channel. E+S (14.32) (13182+50) ALS PA-FRVA-H600-05 (13261+20)		

DB
8-21

Signature ¹ :	<i>Randy Clark</i>	Date:	9-25-18 Spread 10
Printed Name:	Randy Clark	Title:	LEI
Revision <u>43</u>	Revision Description: 18" CFS added near entrance (RCE - moved from Adney Gap entrance to Row), ADP SSF (~550'), triple stack 18" (390') Sta No ~ 13115+00 ES		

Signature ¹ :	<i>Randy Clark</i>	Date:	8-15-18
Printed Name:	Randy Clark	Title:	LEI
Revision <u>43</u>	Revision Description: Add PI SF; install sump $\frac{1}{2}$ add CFS; Add PI w/ water bar. Sta N. ~ 11984+00		

Signature ¹ :	<i>Randy Clark</i>	Date:	8-28-18
Printed Name:	Randy Clark	Title:	LEI
Revision <u>44</u>	Revision Description: Install MVP-35 at every third breaker and MVP-43A in remaining breakers from MP 227.5 to 227.51 Sta. No 11941+75 ES		

¹ Certification will be signed by a responsible corporate officer or by a duly authorized representative of that person. Specific requirements and responsibilities of the responsible corporate officer or duly authorized representative as well as delegate of authority to SWPPP Coordinator are discussed in detail in below.

Scanned 8-20-18
DR

Rainfall tracker MVP Spread H

INSTALLED ***NOT INSTALLED ***

	Milepost	227	229	234.1	237.4	246	252		259		
	Location	Catawba Road	Half Acre Rock Rd. Access Road MVP-MN-	YARD 006	Yellow Finch Road Access Road MVP-MN-278.01	Callaway Road Access Road MVP-FR-289	Cahas Mountain Road 1st crossing	YARD 049	Grassy Hill Access Road MVP-FR-296		
DATE:	INSPECTION TYPE										AVERAGE TOTAL
3/7/2018	POST-STORM	0.2	N/A	N/A	0.1	0.2	N/A	N/A	0 (GH)	0.13	
3/8/2018	POST-STORM	0.2	N/A	N/A	0.2	0.0	N/A	N/A	0 (GH)	0.2	
3/16/2018	POST-STORM	1.3	N/A	N/A	1.7	1.8	N/A	N/A	1.1 (GH)	1.48	
4/24/2018	Mid Rain Event	0.7	N/A	N/A	1.3	2.8	1.8	N/A	moved to Cahas	1.65	
4/25/2018	Mid Rain Event	0.7	N/A	N/A	1.4	1.8	1.4	N/A	when spread I took	1.33	
4/26/2018	POST-STORM	0.1	N/A	N/A	0.2	0.2	0.3	N/A	over the last five miles	0.2	
5/7/2018	POST-STORM	0.5	N/A	0.0	0.0	0.0	0.1	N/A	N/A	0.12	
5/11/2018	POST-STORM	0.2	N/A	0.0	0.0	0.1	0.0	N/A	N/A	0.06	
5/16/2018	POST-STORM	0.1	N/A	0.4	0.6	0.4	0.2	N/A	N/A	0.32	
5/17/2018	POST-STORM	1.9	N/A	1.6	1.9	1.4	2.4	N/A	N/A	1.84	
5/18/2018	SWPPP	0.8	N/A	1.4	1.0	2.0	1.7	N/A	N/A	1.38	
5/21/2018	POST-STORM	0.5	N/A	0.7	0.5	0.5	0.1	N/A	N/A	0.46	
5/22/2018	POST-STORM	0.4	N/A	0.7	0.5	0.3	0.4	N/A	N/A	0.4	
5/27/2018	POST-STORM	0.6	N/A	0.3	0.3	0.3	0.8	N/A	N/A	0.46	
5/28/2018	POST-STORM	1.0	N/A	1.0	1.6	0.2	0.3	N/A	N/A	0.82	
5/29/2018	POST-STORM	0.0	N/A	0.0	0.1	0.0	0.1	N/A	N/A	0.04	
5/30/2018	SWPPP	0.0	N/A	0.0	0.0	0.4	0.1	N/A	N/A	0.1	
5/31/2018	POST-STORM	0.0	N/A	0.0	0.0	0.2	0.6	N/A	N/A	0.16	
6/1/2018	POST-STORM	0.0	N/A	0.3	0.2	1.1	0.2	N/A	N/A	0.35	
6/11/2018	SWPPP	1.0	N/A	0.1	0.0	1.0	1.3	N/A	N/A	0.68	
6/15/2018	SWPPP	0.0	N/A	0.0	0.0	0.0	0.0	N/A	N/A	0	
6/21/2018	SWPPP	0.0	N/A	0.0	0.0	0.0	0.0	N/A	N/A	0	
6/22/2018	POST-STORM	1.0	N/A	1.1	1.2	0.1	0.7	N/A	N/A	0.82	
6/25/2018	POST-STORM	1.0	N/A	1.2	1.1	0.9	0.7	N/A	N/A	1.05	
6/26/2018	POST-STORM	0.7	N/A	1.0	0.9	1.7	2.0	N/A	N/A	1.26	
7/7/2018	SWPPP	0.0	N/A	0.0	0.0	0.3	0.1	N/A	N/A	0.08	
7/8/2018	POST-STORM	0.7	N/A	0.8	0.4	0.3	0.3	N/A	N/A	0.5	
7/22/2018	POST-STORM	1.3	N/A	0.6	0.2	1.3	0.4	N/A	N/A	0.76	
7/23/2018	POST-STORM	0.6	N/A	N/A	0.3	0.9	1.0	0.3	N/A	0.62	
7/24/2018	POST-STORM	0.3	N/A	0.1	0.1	0.4	0.4	0.2	N/A	0.25	
7/31/2018	POST-STORM	0.5	N/A	0.0	0.2	1.0	2.2	0.2	N/A	0.68	
8/1/2018	POST-STORM	0.4	N/A	0.2	0.2	0.1	0.2	0.1	N/A	0.2	
8/2/2018	POST-STORM	1.9	N/A	0.5	0.5	0.8	0.4	0.5	N/A	0.77	
8/8/2018	POST-STORM	0.5	0.2	0.9	0.6	0.4	0.2	0.1	N/A	0.41	
8/11/2018	POST-STORM	0.4	0.3	0.4	0.2	0.0	0.0	0.1	N/A	0.19	
8/13/2018	POST-STORM	0.1	0.1	1.0	1.1	0.1	0.0	0.8	N/A	0.46	
8/21/2018	POST-STORM	0.5	N/A	0.4	0.4	0.5	1.9	0.5	N/A	0.70	
8/28/2018	SWPPP	0.5	0.0	0.0	0.7	0.0	0.8	0.3	N/A	0.33	
8/31/2018	POST-STORM	0.0	0.5	0.4	0.6	0.1	0.3	0.5	N/A	0.34	
9/1/2018	POST-STORM	0.0	0.0	0.0	0.0	0.3	0.0	0.0	N/A	0.04	
9/4/2018	SWPPP	0.9	0.2	0.0	0.0	0.3	0.4	0.0	N/A	0.26	
9/8/2018	POST-STORM	0.6	2.4	0.3	0.1	0.0	0.0	0.0	N/A	0.49	
9/9/2018	POST-STORM	0.8	1.3	0.6	0.5	1.4	3.4	0.3	N/A	1.18	
9/10/2018	POST-STORM	0.3	0.1	0.2	0.1	0.4	0.8	0.5	N/A	0.34	
9/12/2018	POST-STORM	0.2	0.1	1.3	0.1	0.9	1.3	0.2	N/A	0.59	
9/13/2018	SWPPP	0.0	0.0	0.2	0.5	0.1	0.1	0.0	N/A	0.13	
9/14/2018	STORM EVENT	0.0	0.0	0.0	0.0	0.0	0.0	0.0	N/A	0.00	
9/15/2018	STORM EVENT	0.3	0.2	0.4		1.2	0.8	0.5	N/A	0.57	
9/16/2018	STORM EVENT	0.3	0.4	0.9	1.0	1.9	0.6	0.3	N/A	0.77	
9/17/2018	STORM EVENT	3.8	3.0	2.7	4.7	6.0+	3.3	3.7	N/A	3.53	
9/23/2018	STORM EVENT	knocked over	1.7	2.5	2.9	2.7	2.9	2.6	N/A	3.90	