Visual Site Inspection Report										
Project Name H-600 Pipeline Spread G			AFE	AFE 124300137		Spread	H-60	H-600 Pipeline Spread G		
Contractor Precision			•				Report #	2803		
Inspect	tor Clinton Ba	inks					Date/Time	6/8/2	2018 11:09	9 AM
Permit # TBD		Inspection Type VA SWPP		SWPP		Station Begin 120		12005+00	2005+00	
State VA		Inspection Area		Full		Station E	<b>nd</b> 11976+94			
County Montgomery		Ground		Dry		Temperature (°F		ture (ºF)	85.00	
Municipality	N/A		Weathe	er Su	<b>r</b> Sunny		Rain Gauge (in)		uge (in)	0.00
GPS Location	37.21224909	59108, -80.440	3249160178			Rain Ac	ccumulation Time (days)			5.00
1. Are the appr	oved (stampe	ed) E&S Plan	and PCSM Plan p	reser	nt on site	e?				Yes
2. Are there activities occurring outside of the limits of disturbance shown on the plan drawings? (If yes, notify the MVP Environmental Permitting Coordinator and explain in comments.)							No			
	<b>3.</b> Is Construction sequence outlined in the construction notes of the E&S plan set or PCSM plan set being followed? (If No, notify MVP Environmental Permitting Coordinator and explain in comments.)							Yes		
	(List BMPs an	d note if insta	lled and maintain	ed as	per the	e plan. If c	orrective acti	ion is	s needed,	a picture
is required.)			Compliance	•					Cor	rective
I	E&S BMPs		Level	e		Correct	rective Action		e Frame	
									_	
									_	
E Olta Oranditi										
5. Site Conditi		(	in ant manual all		41	- )			landa an	
beyond defined	limits of distu	rbance resulti	iment, gravel, oil, ing from earth dist ironmental Permit	turbar	nce activ	vity or inef	-			No
Have inactive di	sturbed areas	s (stockpiles,	final grade) been	stabil	zed per	state req	uirements?			Yes
Are slopes 3:1 a	and greater st	abilized with a	appropriate BMPs	as pe	er E&S p	olans?				Yes
Has a new slip/s	slide been ob	served? (If ye	es, complete Slide	Repo	ort Form	ı)				No

AFE 124300137	Date/Time 6/8/201	8 11:09 AM	Report #	2803		
6. PCSM BMPs (List BMPs and note if insta	alled and maintained a	s per the plan. If correc	tive action is	needed, a		
picture is required.)	Oomelianaa			Oorresting		
PCSM BMPs	Compliance Level	Corrective Ac	tion	Corrective Time Frame		
7. Identify all remedial measures that have	been taken since the p	revious inspection was	conducted.			
<b>Comments</b> (Reference above questions as	appropriate.)					
Check sand blasting crew to made sure crew had	d containment under pipe	before blasting .Got with	Foreman to le	t him know.		
That before the end of the day Waterbar will nee today.	d to put back in, also brid	ge will need to be clean o	off before crew	could leave tor		
Went from M.P. 227.0 To M.P. 226.5						
Note: It is a condition of National Pollutant F	Visabarra Elimination S	water and Erasion and	- Codimont n	ito that a		
<b>Note:</b> It is a condition of National Pollutant Discharge Elimination System and Erosion and Sediment permits that a maintenance program be conducted to provide for the operation and maintenance of all BMPs to be inspected on a						
weekly basis and after each stormwater event. Please list in the space provided comments to note if repairs or						
replacement are needed or have been made for BMPs as a result of the inspection. Failure to conduct the required inspection may result in permit suspension or the imposition of civil penalties. If supplemental monitoring is required						
as part of a permit condition this form may be used to meet those monitoring requirements.						

<b>AFE</b> 1243	300137	7	Date/Time	6/8/2018 11:09 AI	M Report # 2803		
	Pictures						
GPS Loca		37.2124180933901, -80.4399951		GPS Location	37.2604814175315, -80.3849882650455		
Descrip		End of Spread G Station 12005+	-00	Description	Clean Water Diversion Station 11976+94		
		Insert image here					
GPS Loca	ation			GPS Location	37.270098882762, -80.3231185209754		
Descrip	ption			Description	Clean Water Diversion Station 11976+94		
		Insert image here			Insert image here		
GPS Loca	ation			GPS Location			
Descrip	ption			Description			