

625 Liberty Avenue, Suite 1700 | Pittsburgh, PA 15222 844-MVP-TALK | mail@mountainvalleypipeline.info www.mountainvalleypipeline.info

January 25, 2018

Ms. Kimberly D. Bose, Secretary Federal Energy Regulatory Commission 888 First Street NE Washington, DC 20426

Re: Mountain Valley Pipeline, LLC Docket No. CP16-10-000 Weekly Status Report No. 12

Dear Ms. Bose:

On October 13, 2017, the Federal Energy Regulatory Commission issued an order granting a Certificate of Public Convenience and Necessity to Mountain Valley Pipeline, LLC for the Mountain Valley Pipeline Project in the above-identified docket. In compliance with Environmental Condition Nos. 8 and 14, Mountain Valley submits its status report for the prior calendar week.

If you have any questions, please do not hesitate to contact me at (412) 553-5786 or meggerding@eqt.com. Thank you.

Respectfully submitted,

MOUNTAIN VALLEY PIPELINE, LLC by and through its operator, EQM Gathering Opco, LLC

By: Att E

Matthew Eggerding Counsel, Midstream

Attachments

cc: All Parties Paul Friedman, OEP Lavinia DiSanto, Cardno, Inc. Doug Mooneyhan, Cardno, Inc.

#### FEDERAL AUTHORIZATIONS

All federal authorizations have been received.

### **CONSTRUCTION STATUS**

Construction has not commenced. After construction commences, Mountain Valley will update the construction activities and progress in the table in Appendix A.

### WORK PLANNED FOR NEXT REPORTING PERIOD

Mountain Valley is awaiting approval of requests for notices to proceed.

#### SCHEDULE CHANGES

After construction commences, Mountain Valley will include any required schedule changes for waterbody crossings or work in other environmentally sensitive areas.

### **ENVIRONMENTAL ISSUES**

None. Construction has not commenced.

After construction commences, Mountain Valley will summarize problem area reports (PAR) and noncompliance reports (NCR) issued for the Project during the reporting period, as well as corrective actions taken to resolve the issue, in Table 1 below.

Table 1 – Environmental Compliance					
Compliance	Spread Location		Description and Date	Correction and Date	
Note: PAR – Probl	em Area Report; NC	CR – Noncompliance F	Report.		

### LANDOWNER RESOLUTIONS

None. Construction has not commenced.

After construction commences, Mountain Valley will identify landowner concerns and how they were resolved in Table 2 below.

	Table 2 - Landowner Concerns				
Tract ID	Spread / Facility	Station/ MP	Date of Concern	Date of Resolution	Issue and Resolution



## **Construction Status**

Docket No. CP16-10-000

Weekly Report No. 12

vity Name	Activity Status	% Comple
Compressor Stations	I	0%
Bradshaw		0%
Bradshaw Civil - Tree Felling	Not Started	0%
Bradshaw Civil - Road Construction	Not Started	0%
Bradshaw Civil - Site Construction	Not Started	0%
Bradshaw Civil - Post Site Constructio	n/Reclamation Not Started	0%
Bradshaw Mechanical - Office Building	Area Not Started	0%
Bradshaw Mechanical - Discharge Filte	er Area Not Started	0%
Bradshaw Mechanical - Auxiliary Equip	oment Area Not Started	0%
Bradshaw Mechanical - Blowdown Sile	encer Area Not Started	0%
Bradshaw Mechanical - Gas Cooler Ar	ea Not Started	0%
Bradshaw Mechanical - Compressor B	uilding Area Not Started	0%
Bradshaw Mechanical - Suction Filter	Area Not Started	0%
Bradshaw Mechanical - Launcher/Rece	eiver Area Not Started	0%
Bradshaw Mechanical - Produced Fluid	ds Area Not Started	0%
Bradshaw Mechanical - Site Work Area	a Not Started	0%
Bradshaw Mechanical - Commissionin	g Not Started	0%
Harris		0%
Harris Civil - Tree Felling	Not Started	0%
Harris Civil - Road Construction	Not Started	0%
Harris Civil - Site Construction	Not Started	0%
Harris Civil - Post Site Construction/Re	eclamation Not Started	0%
Harris Mechanical - Office Building Are	ea Not Started	0%
Harris Mechanical - Discharge Filter Ar	rea Not Started	0%
Harris Mechanical - Auxiliary Equipmer		0%
Harris Mechanical - Blowdown Silence		0%
Harris Mechanical - Gas Cooler Area	Not Started	0%
Harris Mechanical - Compressor Buildi	ng Area Not Started	0%
Harris Mechanical - Suction Filter Area	Not Started	0%
Harris Mechanical - Launcher/Receive	r Area Not Started	0%
Harris Mechanical - Produced Fluids A	rea Not Started	0%
Harris Mechanical - Site Work Area	Not Started	0%
Harris Mechanical - Commissioning	Not Started	0%
Stallworth		0%
Stallworth Civil - Tree Felling	Not Started	0%
Stallworth Civil - Road Construction	Not Started	0%
Stallworth Civil - Site Construction	Not Started	0%
Stallworth Civil - Post Site Constructio	n/Reclamation Not Started	0%
Stallworth Mechanical - Office Building	Area Not Started	0%
Stallworth Mechanical - Discharge Filte	er Area Not Started	0%
Stallworth Mechanical - Auxiliary Equip	oment Area Not Started	0%
Stallworth Mechanical - Blowdown Sile	encer Area Not Started	0%
Stallworth Mechanical - Gas Cooler Are	ea Not Started	0%
Stallworth Mechanical - Compressor B	uilding Area Not Started	0%
Stallworth Mechanical - Suction Filter	Area Not Started	0%
Stallworth Mechanical - Launcher/Rece	eiver Area Not Started	0%
Stallworth Mechanical - Produced Fluid	ds Area Not Started	0%
Stallworth Mechanical - Site Work Area	a Not Started	0%
Stallworth Mechanical - Commissionin	g Not Started	0%



**Construction Status** 

Docket No. CP16-10-000

Weekly Report No. 12

ctivity Name		Activity Status	% Complet
Interconnects		1	0%
Mobley			0%
Mobley Civil - Tree Felling		Not Started	0%
Mobley Civil - Road Construction		Not Started	0%
Mobley Civil - Site Construction		Not Started	0%
Mobley Civil - Post Site Construction	bley Civil - Post Site Construction/Reclamation		0%
Mobley Mechanical - GC Building A	rea	Not Started	0%
Mobley Mechanical - CV Building A		Not Started	0%
Mobley Mechanical - Meter Building	g Area	Not Started	0%
Mobley Mechanical - Filter Area		Not Started	0%
Mobley Mechanical - Launcher/Rec	eiver Area	Not Started	0%
Mobley Mechanical - Site Work Are	a	Not Started	0%
Mobley Mechanical - Commissionir	ng	Not Started	0%
Sherwood			0%
Sherwood Civil - Tree Felling		Not Started	0%
Sherwood Civil - Road Construction	)	Not Started	0%
Sherwood Civil - Site Construction	- -	Not Started	0%
Sherwood Civil - Post Site Construe	ction/Reclamation	Not Started	0%
Sherwood Mechanical - GC Building		Not Started	0%
Sherwood Mechanical - CV Building	•	Not Started	0%
Sherwood Mechanical - Meter Build	-	Not Started	0%
Sherwood Mechanical - Filter Area	0	Not Started	0%
Sherwood Mechanical - Launcher/R	Receiver Area	Not Started	0%
Sherwood Mechanical - Site Work A	Area	Not Started	0%
Sherwood Mechanical - Commissio	oning	Not Started	0%
WB			0%
WB Civil - Tree Felling		Not Started	0%
WB Civil - Road Construction		Not Started	0%
WB Civil - Site Construction		Not Started	0%
WB Civil - Post Site Construction/F	Reclamation	Not Started	0%
WB Mechanical - GC Building Area		Not Started	0%
WB Mechanical - CV Building Area		Not Started	0%
WB Mechanical - Meter Building An		Not Started	0%
WB Mechanical - Filter Area		Not Started	0%
WB Mechanical - Launcher/Receive	er Area	Not Started	0%
WB Mechanical - Site Work Area		Not Started	0%
WB Mechanical - Commissioning		Not Started	0%
Transco			0%
Transco Civil - Tree Felling		Not Started	0%
Transco Civil - Road Construction	-		0%
Transco Civil - Site Construction		Not Started Not Started	0%
Transco Civil - Post Site Construction/Reclamation		Not Started	0%
Transco Mechanical - GC Building Area		Not Started	0%
Transco Mechanical - CV Building Area		Not Started	0%
Transco Mechanical - CV Building Alea		Not Started	0%
Transco Mechanical - Filter Area			0%
Transco Mechanical - Launcher/Re	ceiver Area	Not Started Not Started	0%
Transco Mechanical - Site Work Ar		Not Started	0%
Transco Mechanical - Commissioni		Not Started	0%



**Construction Status** 

Docket No. CP16-10-000

Weekly Report No. 12

ivity Name	Activity Status	% Complete
Spreads		0%
Spread A		0%
Spread A - Tree Felling	Not Started	0%
Spread A - Clearing	Not Started	0%
Spread A - Prepare right-of-way	Not Started	0%
Spread A - Trenching	Not Started	0%
Spread A - Stringing	Not Started	0%
Spread A - Welding	Not Started	0%
Spread A - Coating & Wrapping	Not Started	0%
Spread A - Backfilling & Tying-in	Not Started	0%
Spread A - Internal Cleaning	Not Started	0%
Spread A - Final Restoration	Not Started	0%
		0%
Spread B	Net Cterted	
Spread B - Tree Felling	Not Started	0%
Spread B - Clearing	Not Started	0%
Spread B - Prepare right-of-way	Not Started	0%
Spread B - Trenching	Not Started	0%
Spread B - Stringing	Not Started	0%
Spread B - Welding	Not Started	0%
Spread B - Coating & Wrapping	Not Started	0%
Spread B - Backfilling & Tying-in	Not Started	0%
Spread B - Internal Cleaning	Not Started	0%
Spread B - Final Restoration	Not Started	0%
Spread C		0%
Spread C - Tree Felling	Not Started	0%
Spread C - Clearing	Not Started	0%
Spread C - Prepare right-of-way	Not Started	0%
Spread C - Trenching	Not Started	0%
Spread C - Stringing	Not Started	0%
Spread C - Welding	Not Started	0%
Spread C - Coating & Wrapping	Not Started	0%
Spread C - Backfilling & Tying-in	Not Started	0%
Spread C - Internal Cleaning	Not Started	0%
Spread C - Final Restoration	Not Started	0%
Spread D		0%
Spread D - Tree Felling	Not Started	0%
Spread D - Clearing	Not Started	0%
Spread D - Prepare right-of-way	Not Started	0%
Spread D - Trenching	Not Started	0%
Spread D - Stringing	Not Started	0%
Spread D - Welding	Not Started	0%
Spread D - Coating & Wrapping	Not Started	0%
Spread D - Backfilling & Tying-in	Not Started	0%
Spread D - Internal Cleaning	Not Started	0%
Spread D - Final Restoration	Not Started	0%
Spread E		0%
Spread E - Tree Felling	Not Started	0%
Spread E - Clearing	Not Started	0%
Spread E - Prepare right-of-way	Not Started	0%
Spread E - Trenching	Not Started	0%
Spread E - Stringing	Not Started	0%
Spread E - Welding	Not Started	0%
Spread E - Coating & Wrapping	Not Started	0%



### **Construction Status**

Docket No. CP16-10-000

Weekly Report No. 12

<u> </u>	1	
Activity Name	Activity Status	% Complete
Spread E - Backfilling & Tying-in	Not Started	0%
Spread E - Internal Cleaning	Not Started	0%
Spread E - Final Restoration	Not Started	0%
Spread F	-	0%
Spread F - Tree Felling	Not Started	0%
Spread F - Clearing	Not Started	0%
Spread F - Prepare right-of-way	Not Started	0%
Spread F - Trenching	Not Started	0%
Spread F - Stringing	Not Started	0%
Spread F - Welding	Not Started	0%
Spread F - Coating & Wrapping	Not Started	0%
Spread F - Backfilling & Tying-in	Not Started	0%
Spread F - Internal Cleaning	Not Started	0%
Spread F - Final Restoration	Not Started	0%
Spread G		0%
Spread G - Tree Felling	Not Started	0%
Spread G - Clearing	Not Started	0%
Spread G - Prepare right-of-way	Not Started	0%
Spread G - Trenching	Not Started	0%
Spread G - Stringing	Not Started	0%
Spread G - Welding	Not Started	0%
Spread G - Coating & Wrapping	Not Started	0%
Spread G - Backfilling & Tying-in	Not Started	0%
Spread G - Internal Cleaning	Not Started	0%
Spread G - Final Restoration	Not Started	0%
Spread H	1	0%
Spread H - Tree Felling	Not Started	0%
Spread H - Clearing	Not Started	0%
Spread H - Prepare right-of-way	Not Started	0%
Spread H - Trenching	Not Started	0%
Spread H - Stringing	Not Started	0%
Spread H - Welding	Not Started	0%
Spread H - Coating & Wrapping	Not Started	0%
Spread H - Backfilling & Tying-in	Not Started	0%
Spread H - Internal Cleaning	Not Started	0%
Spread H - Final Restoration	Not Started	0%
Spread I	-	0%
Spread I - Tree Felling	Not Started	0%
Spread I - Clearing	Not Started	0%
Spread I - Prepare right-of-way	Not Started	0%
Spread I - Trenching	Not Started	0%
Spread I - Stringing	Not Started	0%
Spread I - Welding	Not Started	0%
Spread I - Coating & Wrapping	Not Started	0%
Spread I - Backfilling & Tying-in	Not Started	0%
Spread I - Internal Cleaning	Not Started	0%
Spread I - Final Restoration	Not Started	0%



## **Construction Status**

Docket No. CP16-10-000

Weekly Report No. 12

ctivity Name	Activity Status	% Complete
Contractor Yards	I	0%
West Virginia Locations		0%
MVP-LY-024	Not Started	0%
MVP-RD-001A	Not Started	0%
MVP-RD-001B	Not Started	0%
MVP-LY-001	Not Started	0%
MVP-LY-003	Not Started	0%
MVP-LY-013	Not Started	0%
MVP-LY-016	Not Started	0%
MVP-LY-017	Not Started	0%
MVP-LY-018	Not Started	0%
MVP-AP-001	Not Started	0%
MVP-LOG-001	Not Started	0%
MVP-SA-001	Not Started	0%
MVP-AP-002	Not Started	0%
MVP-LY-001A	Not Started	0%
MVP-LY-021	Not Started	0%
MVP-LY-004	Not Started	0%
MVP-LY-005	Not Started	0%
MVP-LY-022	Not Started	0%
MVP-LY-025	Not Started	0%
MVP-LY-030	Not Started	0%
Virginia Locations		0%
MVP-PY-005	Not Started	0%
MVP-LY-034	Not Started	0%
MVP-LY-032	Not Started	0%
MVP-LY-033	Not Started	0%
MVP-LY-035	Not Started	0%