Baseline Assessment – Stream Attributes

Reach S-CD23 (Timber Mat Crossing) Ephemeral Spread F Summers County, West Virginia

| Data | Included |
|--|---|
| Photos | ✓ |
| SWVM Form | |
| FCI Calculator and HGM Form | |
| RBP Physical Characteristics Form | |
| Water Quality Data | |
| RBP Habitat Form | Proxy Stream Information Utilized; Refer to |
| RBP Benthic Form | Master Stream Summary Table |
| Benthic Identification Sheet | |
| Wolman Pebble Count | |
| Reference Reach Software Pebble Count Data | |
| Longitudinal Profile and Cross Sections | |

Spread F Stream S-CD23 (Timber Mat Crossing) Summers County



Photo Type: US Edge of LOD, US View
Location, Orientation, Photographer Initials: Upstream Edge of Limit of Disturbance, Upstream View,
ABK/EW/WP



Photo Type: US Edge of LOD, DS View
Location, Orientation, Photographer Initials: Upstream Edge of Limit of Disturbance, Downstream View,
ABK/EW/WP

Spread F Stream S-CD23 (Timber Mat Crossing) Summers County



Photo Type: CP, US View Location, Orientation, Photographer Initials: Center Right of Way, Upstream View, ABK/EW/WP



Photo Type: CP, DS View
Location, Orientation, Photographer Initials: Center Right of Way, Downstream View, ABK/EW/WP

Spread F Stream S-CD23 (Timber Mat Crossing) Summers County



Photo Type: Under TMB, US View Location, Orientation, Photographer Initials: Under Timber Mat Bridge, Upstream View, ABK/EW/WP



Photo Type: Above TMB, DS View
Location, Orientation, Photographer Initials: Above Timber Mat Bridge, Downstream View, ABK/EW/WP

"Q:\Charleston\2021 Projects\21-0244- MVP- STREAM AND WETLAND CONDITIONS ASSESSMENT AND SURVEY PLAN\002 - Pre-Crossing Monitoring\Spread F\S-CD23"