



625 Liberty Avenue, Suite 1700 | Pittsburgh, PA 15222  
844-MVP-TALK | mail@mountainvalleypipeline.info  
www.mountainvalleypipeline.info

February 22, 2018

Ms. Kimberly D. Bose, Secretary  
Federal Energy Regulatory Commission  
888 First Street NE  
Washington, DC 20426

Re: Mountain Valley Pipeline, LLC  
Docket No. CP16-10-000  
Weekly Status Report No. 16

Dear Ms. Bose:

On October 13, 2017, the Federal Energy Regulatory Commission issued an order granting a Certificate of Public Convenience and Necessity to Mountain Valley Pipeline, LLC (“Mountain Valley”) for the Mountain Valley Pipeline Project in the above-identified docket. On October 31, 2017, Mountain Valley submitted its Implementation Plan for the Project. In compliance with Environmental Condition Nos. 8 and 14, Mountain Valley submits its status report for the prior calendar week.

If you have any questions, please do not hesitate to contact me at (412) 553-5786 or meggerding@eqt.com. Thank you.

Respectfully submitted,  
MOUNTAIN VALLEY PIPELINE, LLC  
by and through its operator,  
EQM Gathering OPCO, LLC

By:   
Matthew Eggerding  
Senior Counsel, Midstream

Attachments

cc: All Parties  
Paul Friedman, OEP  
Lavinia DiSanto, Cardno, Inc.  
Doug Mooneyhan, Cardno, Inc.

## **FEDERAL AUTHORIZATIONS**

---

All federal authorizations have been received.

## **CONSTRUCTION STATUS**

---

Construction activities and progress are included in Appendix A.

## **WORK PLANNED FOR NEXT REPORTING PERIOD**

---

Tree felling will continue on Spread A. Site construction will also continue at the authorized compressor stations and interconnects in West Virginia. Road construction will continue in West Virginia. Tree Felling activity will commence on Spreads F & G.

## **SCHEDULE CHANGES**

---

There are no required schedule changes for waterbody crossings or work in other environmentally sensitive areas.

## **ENVIRONMENTAL ISSUES**

---

The table in Appendix B summarizes problem area reports (PAR) and noncompliance reports (NCR) issued for the Project during the reporting period, as well as corrective actions taken to resolve the issue (including the cost and effectiveness of the corrective actions).

In the event Mountain Valley receives correspondence from other federal, state, or local permitting agencies concerning instances of noncompliance during the reporting period, Mountain Valley will include or reference such correspondence, as well as Mountain Valley's response thereto, in Appendix C.

## **LANDOWNER RESOLUTIONS**

---

The table in Appendix D includes information regarding landowner concerns and how they were resolved.

**APPENDIX B****ENVIRONMENTAL COMPLIANCE**

The following table summarizes problem area reports (PAR) and noncompliance reports (NCR) issued for the Project during the reporting period, as well as corrective actions taken to resolve the issue (including the cost and effectiveness of the corrective actions).

| <b>Compliance</b> | <b>Spread</b> | <b>Location</b> | <b>Description and Date</b> | <b>Correction and Date</b> |
|-------------------|---------------|-----------------|-----------------------------|----------------------------|
| NONE              | NONE          | NONE            | NONE                        | NONE                       |
|                   |               |                 |                             |                            |
|                   |               |                 |                             |                            |
|                   |               |                 |                             |                            |
|                   |               |                 |                             |                            |
|                   |               |                 |                             |                            |
|                   |               |                 |                             |                            |

Note: PAR – Problem Area Report; NCR – Noncompliance Report.

**APPENDIX C**  
**AGENCY CORRESPONDENCE AND RESPONSES**

None.

**APPENDIX D**  
**LANDOWNER CONCERNS**

The following table includes information regarding landowner concerns and how they were resolved.

| <b>Tract ID</b> | <b>Spread / Facility</b> | <b>Station/ MP</b> | <b>Date of Concern</b> | <b>Date of Resolution</b> | <b>Issue and Resolution</b> |
|-----------------|--------------------------|--------------------|------------------------|---------------------------|-----------------------------|
| NONE            | NONE                     | NONE               | NONE                   | NONE                      | NONE                        |
|                 |                          |                    |                        |                           |                             |
|                 |                          |                    |                        |                           |                             |
|                 |                          |                    |                        |                           |                             |

| Activity Name | Activity Status | % Complete |
|---------------|-----------------|------------|
|---------------|-----------------|------------|

### Compressor Stations

#### Bradshaw

|   |             |       |
|---|-------------|-------|
| Bradshaw Civil - Tree Felling                       | In Progress | 40%   |
| Bradshaw Civil - Road Construction                  | In Progress | 16.9% |
| Bradshaw Civil - Site Construction                  | In Progress | 3.41% |
| Bradshaw Civil - Post Site Construction/Reclamation | Not Started | 0%    |
| Bradshaw Mechanical - Office Building Area          | Not Started | 0%    |
| Bradshaw Mechanical - Discharge Filter Area         | Not Started | 0%    |
| Bradshaw Mechanical - Auxiliary Equipment Area      | Not Started | 0%    |
| Bradshaw Mechanical - Blowdown Silencer Area        | Not Started | 0%    |
| Bradshaw Mechanical - Gas Cooler Area               | Not Started | 0%    |
| Bradshaw Mechanical - Compressor Building Area      | Not Started | 0%    |
| Bradshaw Mechanical - Suction Filter Area           | Not Started | 0%    |
| Bradshaw Mechanical - Launcher/Receiver Area        | Not Started | 0%    |
| Bradshaw Mechanical - Produced Fluids Area          | Not Started | 0%    |
| Bradshaw Mechanical - Site Work Area                | Not Started | 0%    |
| Bradshaw Mechanical - Commissioning                 | Not Started | 0%    |

#### Harris

|   |             |        |
|---|-------------|--------|
| Harris Civil - Tree Felling                       | In Progress | 95%    |
| Harris Civil - Road Construction                  | In Progress | 28.59% |
| Harris Civil - Site Construction                  | In Progress | 5.27%  |
| Harris Civil - Post Site Construction/Reclamation | Not Started | 0%     |
| Harris Mechanical - Office Building Area          | Not Started | 0%     |
| Harris Mechanical - Discharge Filter Area         | Not Started | 0%     |
| Harris Mechanical - Auxiliary Equipment Area      | Not Started | 0%     |
| Harris Mechanical - Blowdown Silencer Area        | Not Started | 0%     |
| Harris Mechanical - Gas Cooler Area               | Not Started | 0%     |
| Harris Mechanical - Compressor Building Area      | Not Started | 0%     |
| Harris Mechanical - Suction Filter Area           | Not Started | 0%     |
| Harris Mechanical - Launcher/Receiver Area        | Not Started | 0%     |
| Harris Mechanical - Produced Fluids Area          | Not Started | 0%     |
| Harris Mechanical - Site Work Area                | Not Started | 0%     |
| Harris Mechanical - Commissioning                 | Not Started | 0%     |

#### Stallworth

|   |             |        |
|---|-------------|--------|
| Stallworth Civil - Tree Felling                       | In Progress | 11.11% |
| Stallworth Civil - Road Construction                  | In Progress | 0.6%   |
| Stallworth Civil - Site Construction                  | Not Started | 0%     |
| Stallworth Civil - Post Site Construction/Reclamation | Not Started | 0%     |
| Stallworth Mechanical - Office Building Area          | Not Started | 0%     |
| Stallworth Mechanical - Discharge Filter Area         | Not Started | 0%     |
| Stallworth Mechanical - Auxiliary Equipment Area      | Not Started | 0%     |
| Stallworth Mechanical - Blowdown Silencer Area        | Not Started | 0%     |
| Stallworth Mechanical - Gas Cooler Area               | Not Started | 0%     |
| Stallworth Mechanical - Compressor Building Area      | Not Started | 0%     |
| Stallworth Mechanical - Suction Filter Area           | Not Started | 0%     |
| Stallworth Mechanical - Launcher/Receiver Area        | Not Started | 0%     |
| Stallworth Mechanical - Produced Fluids Area          | Not Started | 0%     |
| Stallworth Mechanical - Site Work Area                | Not Started | 0%     |
| Stallworth Mechanical - Commissioning                 | Not Started | 0%     |

| Activity Name | Activity Status | % Complete |
|---------------|-----------------|------------|
|---------------|-----------------|------------|

### Interconnects

#### Mobley

|   |             |       |
|---|-------------|-------|
| Mobley Civil - Tree Felling                       | Completed   | 100%  |
| Mobley Civil - Road Construction                  | In Progress | 1.16% |
| Mobley Civil - Site Construction                  | Not Started | 0%    |
| Mobley Civil - Post Site Construction/Reclamation | Not Started | 0%    |
| Mobley Mechanical - GC Building Area              | Not Started | 0%    |
| Mobley Mechanical - CV Building Area              | Not Started | 0%    |
| Mobley Mechanical - Meter Building Area           | Not Started | 0%    |
| Mobley Mechanical - Filter Area                   | Not Started | 0%    |
| Mobley Mechanical - Launcher/Receiver Area        | Not Started | 0%    |
| Mobley Mechanical - Site Work Area                | Not Started | 0%    |
| Mobley Mechanical - Commissioning                 | Not Started | 0%    |

#### Sherwood

|   |             |    |
|---|-------------|----|
| Sherwood Civil - Tree Felling                       | Not Started | 0% |
| Sherwood Civil - Road Construction                  | Not Started | 0% |
| Sherwood Civil - Site Construction                  | Not Started | 0% |
| Sherwood Civil - Post Site Construction/Reclamation | Not Started | 0% |
| Sherwood Mechanical - GC Building Area              | Not Started | 0% |
| Sherwood Mechanical - CV Building Area              | Not Started | 0% |
| Sherwood Mechanical - Meter Building Area           | Not Started | 0% |
| Sherwood Mechanical - Filter Area                   | Not Started | 0% |
| Sherwood Mechanical - Launcher/Receiver Area        | Not Started | 0% |
| Sherwood Mechanical - Site Work Area                | Not Started | 0% |
| Sherwood Mechanical - Commissioning                 | Not Started | 0% |

#### WB

|   |             |        |
|---|-------------|--------|
| WB Civil - Tree Felling                       | In Progress | 98%    |
| WB Civil - Road Construction                  | In Progress | 22.97% |
| WB Civil - Site Construction                  | In Progress | 7.14%  |
| WB Civil - Post Site Construction/Reclamation | Not Started | 0%     |
| WB Mechanical - GC Building Area              | Not Started | 0%     |
| WB Mechanical - CV Building Area              | Not Started | 0%     |
| WB Mechanical - Meter Building Area           | Not Started | 0%     |
| WB Mechanical - Filter Area                   | Not Started | 0%     |
| WB Mechanical - Launcher/Receiver Area        | Not Started | 0%     |
| WB Mechanical - Site Work Area                | Not Started | 0%     |
| WB Mechanical - Commissioning                 | Not Started | 0%     |

#### Transco

|  |             |    |
|--|-------------|----|
| Transco Civil - Tree Felling                       | Not Started | 0% |
| Transco Civil - Road Construction                  | Not Started | 0% |
| Transco Civil - Site Construction                  | Not Started | 0% |
| Transco Civil - Post Site Construction/Reclamation | Not Started | 0% |
| Transco Mechanical - GC Building Area              | Not Started | 0% |
| Transco Mechanical - CV Building Area              | Not Started | 0% |
| Transco Mechanical - Meter Building Area           | Not Started | 0% |
| Transco Mechanical - Filter Area                   | Not Started | 0% |
| Transco Mechanical - Launcher/Receiver Area        | Not Started | 0% |
| Transco Mechanical - Site Work Area                | Not Started | 0% |
| Transco Mechanical - Commissioning                 | Not Started | 0% |

| Activity Name | Activity Status | % Complete |
|---------------|-----------------|------------|
|---------------|-----------------|------------|

### Spreads

#### Spread A

|                                   |             |       |
|-----------------------------------|-------------|-------|
| Spread A - Tree Felling           | In Progress | 4.25% |
| Spread A - Clearing               | Not Started | 0%    |
| Spread A - Prepare right-of-way   | Not Started | 0%    |
| Spread A - Trenching              | Not Started | 0%    |
| Spread A - Stringing              | Not Started | 0%    |
| Spread A - Welding                | Not Started | 0%    |
| Spread A - Coating & Wrapping     | Not Started | 0%    |
| Spread A - Backfilling & Tying-in | Not Started | 0%    |
| Spread A - Internal Cleaning      | Not Started | 0%    |
| Spread A - Final Restoration      | Not Started | 0%    |

#### Spread B

|                                   |             |    |
|-----------------------------------|-------------|----|
| Spread B - Tree Felling           | Not Started | 0% |
| Spread B - Clearing               | Not Started | 0% |
| Spread B - Prepare right-of-way   | Not Started | 0% |
| Spread B - Trenching              | Not Started | 0% |
| Spread B - Stringing              | Not Started | 0% |
| Spread B - Welding                | Not Started | 0% |
| Spread B - Coating & Wrapping     | Not Started | 0% |
| Spread B - Backfilling & Tying-in | Not Started | 0% |
| Spread B - Internal Cleaning      | Not Started | 0% |
| Spread B - Final Restoration      | Not Started | 0% |

#### Spread C

|                                   |             |    |
|-----------------------------------|-------------|----|
| Spread C - Tree Felling           | Not Started | 0% |
| Spread C - Clearing               | Not Started | 0% |
| Spread C - Prepare right-of-way   | Not Started | 0% |
| Spread C - Trenching              | Not Started | 0% |
| Spread C - Stringing              | Not Started | 0% |
| Spread C - Welding                | Not Started | 0% |
| Spread C - Coating & Wrapping     | Not Started | 0% |
| Spread C - Backfilling & Tying-in | Not Started | 0% |
| Spread C - Internal Cleaning      | Not Started | 0% |
| Spread C - Final Restoration      | Not Started | 0% |

#### Spread D

|                                   |             |    |
|-----------------------------------|-------------|----|
| Spread D - Tree Felling           | Not Started | 0% |
| Spread D - Clearing               | Not Started | 0% |
| Spread D - Prepare right-of-way   | Not Started | 0% |
| Spread D - Trenching              | Not Started | 0% |
| Spread D - Stringing              | Not Started | 0% |
| Spread D - Welding                | Not Started | 0% |
| Spread D - Coating & Wrapping     | Not Started | 0% |
| Spread D - Backfilling & Tying-in | Not Started | 0% |
| Spread D - Internal Cleaning      | Not Started | 0% |
| Spread D - Final Restoration      | Not Started | 0% |

#### Spread E

|                                 |             |    |
|---------------------------------|-------------|----|
| Spread E - Tree Felling         | Not Started | 0% |
| Spread E - Clearing             | Not Started | 0% |
| Spread E - Prepare right-of-way | Not Started | 0% |
| Spread E - Trenching            | Not Started | 0% |



## Appendix A Construction Status

| Activity Name                     | Activity Status | % Complete |
|-----------------------------------|-----------------|------------|
| Spread E - Stringing              | Not Started     | 0%         |
| Spread E - Welding                | Not Started     | 0%         |
| Spread E - Coating & Wrapping     | Not Started     | 0%         |
| Spread E - Backfilling & Tying-in | Not Started     | 0%         |
| Spread E - Internal Cleaning      | Not Started     | 0%         |
| Spread E - Final Restoration      | Not Started     | 0%         |
| <b>Spread F</b>                   |                 |            |
| Spread F - Tree Felling           | Not Started     | 0%         |
| Spread F - Clearing               | Not Started     | 0%         |
| Spread F - Prepare right-of-way   | Not Started     | 0%         |
| Spread F - Trenching              | Not Started     | 0%         |
| Spread F - Stringing              | Not Started     | 0%         |
| Spread F - Welding                | Not Started     | 0%         |
| Spread F - Coating & Wrapping     | Not Started     | 0%         |
| Spread F - Backfilling & Tying-in | Not Started     | 0%         |
| Spread F - Internal Cleaning      | Not Started     | 0%         |
| Spread F - Final Restoration      | Not Started     | 0%         |
| <b>Spread G</b>                   |                 |            |
| Spread G - Tree Felling           | Not Started     | 0%         |
| Spread G - Clearing               | Not Started     | 0%         |
| Spread G - Prepare right-of-way   | Not Started     | 0%         |
| Spread G - Trenching              | Not Started     | 0%         |
| Spread G - Stringing              | Not Started     | 0%         |
| Spread G - Welding                | Not Started     | 0%         |
| Spread G - Coating & Wrapping     | Not Started     | 0%         |
| Spread G - Backfilling & Tying-in | Not Started     | 0%         |
| Spread G - Internal Cleaning      | Not Started     | 0%         |
| Spread G - Final Restoration      | Not Started     | 0%         |
| <b>Spread H</b>                   |                 |            |
| Spread H - Tree Felling           | Not Started     | 0%         |
| Spread H - Clearing               | Not Started     | 0%         |
| Spread H - Prepare right-of-way   | Not Started     | 0%         |
| Spread H - Trenching              | Not Started     | 0%         |
| Spread H - Stringing              | Not Started     | 0%         |
| Spread H - Welding                | Not Started     | 0%         |
| Spread H - Coating & Wrapping     | Not Started     | 0%         |
| Spread H - Backfilling & Tying-in | Not Started     | 0%         |
| Spread H - Internal Cleaning      | Not Started     | 0%         |
| Spread H - Final Restoration      | Not Started     | 0%         |
| <b>Spread I</b>                   |                 |            |
| Spread I - Tree Felling           | Not Started     | 0%         |
| Spread I - Clearing               | Not Started     | 0%         |
| Spread I - Prepare right-of-way   | Not Started     | 0%         |
| Spread I - Trenching              | Not Started     | 0%         |
| Spread I - Stringing              | Not Started     | 0%         |
| Spread I - Welding                | Not Started     | 0%         |
| Spread I - Coating & Wrapping     | Not Started     | 0%         |
| Spread I - Backfilling & Tying-in | Not Started     | 0%         |
| Spread I - Internal Cleaning      | Not Started     | 0%         |
| Spread I - Final Restoration      | Not Started     | 0%         |



## Appendix A Construction Status

Docket No. CP16-10-000  
Weekly Report No. 16  
Report Period: 02/10/18 - 02/16/18

| Activity Name | Activity Status | % Complete |
|---------------|-----------------|------------|
|---------------|-----------------|------------|

### Contractor Yards

#### West Virginia Locations

|             |             |    |
|-------------|-------------|----|
| MVP-LY-024  | Not Started | 0% |
| MVP-RD-001A | Not Started | 0% |
| MVP-RD-001B | Not Started | 0% |
| MVP-LY-001  | Not Started | 0% |
| MVP-LY-003  | Not Started | 0% |
| MVP-LY-013  | Not Started | 0% |
| MVP-LY-016  | Not Started | 0% |
| MVP-LY-017  | Not Started | 0% |
| MVP-LY-018  | Not Started | 0% |
| MVP-AP-001  | Not Started | 0% |
| MVP-LOG-001 | Not Started | 0% |
| MVP-SA-001  | Not Started | 0% |
| MVP-AP-002  | Not Started | 0% |
| MVP-LY-001A | Not Started | 0% |
| MVP-LY-021  | Not Started | 0% |
| MVP-LY-004  | Not Started | 0% |
| MVP-LY-005  | Not Started | 0% |
| MVP-LY-022  | Not Started | 0% |
| MVP-LY-025  | Not Started | 0% |
| MVP-LY-030  | Not Started | 0% |

#### Virginia Locations

|            |             |    |
|------------|-------------|----|
| MVP-PY-005 | Not Started | 0% |
| MVP-PY-006 | Not Started | 0% |
| MVP-LY-032 | Not Started | 0% |
| MVP-LY-033 | Not Started | 0% |
| MVP-LY-034 | Not Started | 0% |
| MVP-LY-035 | Not Started | 0% |